The Great Grid Upgrade Grimsby to Walpole

Preliminary Environmental Information Report

Volume 3 Part B Section Specific Assessments

Section 4 New Lincolnshire Connection Substation B to Refined Weston Marsh Substation Siting Zone

Chapter 5 Historic Environment

Appendices

June 2025

Contents

- 5A. Known Heritage Assets
- 5B. Preliminary Summary of Likely Non-Significant Effects

Grimsby to Walpole Document control

Document Properties	
Organisation	Arup AECOM
Approved by	National Grid
Title	Preliminary Environmental Information Report Volume 3 Part B Section Specific Assessments Section 4 New LincoInshire Connection Substation B to Refined Weston Marsh Substation Siting Zone Chapter 5 Historic Environment Appendices
Document Register ID	GWNC-ARUP(AEC)-ENV-REP-0002
Data Classification	Public

Version History						
Date	Version	Status	Description / Changes			
June 2025	1.0	Final	First Issue			

5A. Known Heritage Assets

nationalgrid

Contents

5A.	Known H	eritage Assets	1
	List of Abbi	reviations	1
	Table 5A.5.1	Designated Heritage Assets within the 3 km Study Area	2
	Table 5A.5.2	Designated Heritage Assets of high value within the 3-5 km Study Area Designated heritage assets of high value beyond the 5 km Study Area with potential	29
	Table 5A.4	impacts Non-designated Heritage Assets within the draft Order Limits and the 1 km Study Area	36 37

5A. Known Heritage Assets

- 5A.1.1 The gazetteer tables presented in this appendix identify the following heritage assets relevant to Section 4 New Lincolnshire Connection Substation (LCS) B to Refined Weston Marsh Substation Siting Zone (Section 4) of the Grimsby to Walpole Project (the Project):
 - Designated heritage assets within the 3 km Study Area surrounding the draft Order Limits (Table 5A.5.1);
 - Designated heritage assets of high value within the 3 5 km Study Area surrounding the draft Order Limits (Table 5A.5.2);
 - designated heritage assets of high value beyond the 5 km Study Area with potential to be impacted by the Project (Table 5A.5.3); and
 - Non-designated heritage assets within the draft Order Limits and the surrounding 1km Study Area (**Table 5A.4**).
- 5A.1.2 Designated and non-designated heritage assets are shown in relation to the draft Order Limits on the accompanying drawings:
 - PEI Report Volume 2 Part B Section 4 Figure 5.1 Designated Heritage Assets; and
 - PEI Report Volume 2 Part B Section 4 Figure 5.2 Non-designated Heritage Assets.

List of Abbreviations

- NHLE: National Heritage List for England
- HER: Historic Environment Record

NHLE No.	Designation and Grade	Name	Description	Period	NGR
1003615	Scheduled monument	Butterbump round barrow cemetery	Remains of Butterbump round barrow cemetery in Willoughby with Sloothby.	Prehistoric	TF 49212 72350
1003609	Scheduled monument	Cock Hill, Saxon burial mound	Buried remains of a Saxon burial mound at Cock Hill, Burgh Le Marsh	Early Medieval	TF 49936 65010
1018687	Scheduled monument	Swineshead Abbey	The monument includes the known extent of the earthwork and buried remains of part of the inner precinct and an associated dylings field system of the Abbey of St Mary, a Cistercian monastery founded in the early 12 th century by the lord of the manor, Robert de Gresley. The abbey occupies a slightly raised area in the marshland approximately 1 km north east of the medieval town of Swineshead. In the raised area in the north eastern part of the monument, partly overlain by Abbey Farm, are the buried remains of the abbey's inner court where the church, cloister, dormitory and other claustral buildings would have been located. Adjacent to the west is another raised area, partly overlain by the present lane, where the remains of the abbey's outer court are located; these would include stables, barns and other agricultural and service buildings, together with the principal gatehouse of the abbey through which the complex would have been approached from the west.	Medieval	TF 24889 40689
1014423; 1359710	Scheduled monument; Grade II listed	Churchyard cross, St Thomas of Canterbury's churchyard	Churchyard cross. C14. Ashlar. Octagonal base supports square tapering cross shaft with facetted angles and stop chamfers.	Medieval	TF 51569 74410
1016045	Scheduled monument	Manor Farm moated site	The monument includes the remains of a medieval moated site in the village of Orby, located immediately to the east of Manor Farm. The remains take the form of a moat partly enclosing an asymmetric, curvilinear island measuring approximately 80 m by 70 m. On its south western, southern, eastern and northern sides the moat is up to 15 m in width and about 3 m in depth and has steep, well-defined sides. A counterscarp bank, which follows the eastern edge of the moat for approximately 25 m, is considered to be of the same date as the moat and is comprised of spoil from the moat ditch being placed along the outer lip.	Medieval	TF 49147 67150
1004933	Scheduled monument	Shrunken medieval village	Buried remains of a shrunken medieval village in Sutterton.	Medieval	TF 29107 35346
1018684	Scheduled monument	The Manwar Ings: remains of a motte and bailey castle	The monument includes a medieval motte and bailey castle at The Manwar Ings. Situated approximately 1 km to the north east of the village of Swineshead, it is believed to have been constructed in the 12 th century by the de Gresley family, lords of the manor of Swineshead. The remains of the castle take the form of a series of substantial earthworks and buried features, including a circular motte and bailey with inner and outer moats, now dry. The motte is represented by a raised circular platform, now largely level, standing to a height of nearly 2 m above the surrounding fields. On this platform would have stood the domestic and service buildings of the castle, while a slight internal bank may indicate the position of a former wall or palisade. Brick-lined shelters were inserted into the motte during World War II. The motte is surrounded by a deep inner moat about 15 m wide, in turn encircled by the bailey which varies between 7 m and 15 m in width. The inner moat is crossed on the eastern side by an earthen causeway which is believed to occupy the site of a former bridge; a raised area on the bailey at the east end of the causeway may represent the site of a gatehouse.	Medieval	TF 24325 40979

Table 5A.5.1 Designated Heritage Assets within the 3 km Study Area

NHLE No.	Designation and Grade	Name	Description	Period	NGR
			Surrounding the bailey is an outer moat 7 m-10 m in width, originally circular in plan but partly truncated on the eastern side by modern ploughing. It is crossed on the north west side by a modern trackway, beneath which it is partly infilled.		
1014939; 1267205	Scheduled monument; Grade II listed building	Churchyard cross, St Andrew's churchyard	Cross. C15, C19. Limestone ashlar. Rectangular plinth partially buried, broached octagonal pedestal and tapering shaft, the upper sections of which and the cap being C19. Moulded knop with C15 figures of Virgin and Saint with C19 gable above.	Medieval	TF 43362 63544
1015162; 1224487	Scheduled monument; Grade II listed building	Churchyard cross, St Mary's churchyard	Cross shaft. C14. Limestone ashlar. Octagonal shaft approximately 1 metre high with broached stops at ground level, and tapering towards the top.	Medieval	TF 47112 58654
1010674; 1232863	Scheduled monument; Grade II listed building	Stump Cross	Cross shaft. C14. Ashlar. Square base, tapering octagonal shaft rising via stop chamfers.	Medieval	TF 23935 39717
1013828; 1063535	Scheduled monument; Grade I listed building	Sibsey Trader Windmill	Tower windmill. 1877 by Saunderson of Louth. Restored 1970 and 1981 by the Department of the Environment. Tarred brick. Ogee cupola with small ball finial. Fan-tail and 6 double sided sails. Dentil and moulded eaves. 5 storeys with decorative wrought iron balcony to the second floor. South side with doorway 6 steps up with plank double door, on the second floor is a cambered arched doorway with part glazed door.	Post-medieval	TF 34465 50963
1019173	Scheduled monument	Castle Hill: a motte castle 250 m east of Hanby Hall Farm	The motte takes the form of a large mound, approximately 5 m high, enclosed by a ditch. The motte is sub-rectangular in plan, measuring 50 m by 40 m at its base, with rounded corners and steep sides to the north and east. The top of the motte measures up to 30 m in length, sloping gently down to the south-west; a level platform, 10 m in width, at north eastern corner may indicate post-medieval alteration. The ditch enclosing the motte on the east and north sides is visible as a depression measuring up to 6 m in width and up to 0.5 m deep.	Medieval	TF 47673 69809
1014422; 1204885	Scheduled monument	Churchyard cross, St Nicholas's churchyard	Churchyard cross. C14. Ashlar. Square base on 2 steps rising via stop chamfers to octagonal stem.	Medieval	TF 55102 69080
1009978	Scheduled monument	Medieval field system 250 m north of Church End Farm	The monument includes part of a field system of medieval date, known as a dyling, located on siltland and visible as earthworks under pasture. The site lies 220 m north of Quadring parish church and was formerly within that parish, although now the parish boundary runs along the southern edge of the monument.	Medieval	TF 22594 34497
			The system comprises three separate but adjoining sets of parallel field strips, aligned at right angles to an old water channel between 7 m and 10 m wide, which follows a slightly meandering course east-west across the northern half of the monument, then turns south along its western edge. Ditches, which have become partly infilled, but which are visible as linear hollows approximately 3 m wide and 0.75 m to 1 m deep, separate the strips, which range in width from 5 m to 34 m and are variously rounded, flattened or very slightly dished in profile.		
1013532	Scheduled monument	Churchyard cross, Old Church	The monument includes the remains of a standing stone cross located in the churchyard of the Old Church at Great Steeping, formerly the Church of All Saints. The cross is medieval in date and is constructed of limestone. The monument includes the base of the cross and a fragment of the shaft.	Medieval	TF 43478 63921

NHLE No.	Designation and Grade	Name	Description	Period	NGR
7608	Conservation Area	Wigtoft	Wigtoft Conservation Area covering the historic core of the village.		TF 26237 36172
7606	Conservation Area	Kirton Holme	Kirton Holme Conservation Area covering the historic core of the village.		TF 26184 42092
4521	Conservation Area	Burgh le Marsh	Burgh le Marsh Conservation Area covering the historic core of the village.		TF 50070 65064
7600	Conservation Area	Bicker	Bicker Conservation Area covering the historic core of the village.		TF 22519 37705
7605	Conservation Area	Kirton	Kirton Conservation Area covering the historic core of the village		TF 30528 38531
4861	Conservation Area	Gosberton	Gosberton Conservation Area covering the historic core of the village		TF 23861 31720
4533	Conservation Area	Wainfleet	Wainfleet Conservation Area covering the historic core of the village		TF 49849 59085
7607	Conservation Area	Swineshead	Swineshead Conservation Area covering the historic core of the village		TF 23723 40221
1000992	Grade II Registered Park and Garden	Well Hall	Parkland of early C18 origins, surrounding the possible remains of an early C18 garden which forms the setting for an early C18 country house.	Post-medieval	TF4430973380
1237405	Grade I listed building	Church Of St Peter and St Paul	Parish church. C12, C13, late C13, C14, C15, restoration 1891. Ashlar, squared coursed limestone rubble, lead roofs. Western tower, nave with clerestory, aisles, south porch, chancel. 3 stage tower with plinth, chamfered string course, battlemented parapet, stepped buttresses and octagonal south western stair turret. Recessed spire with lucarnes.	Medieval	TF 26283 36230
1223215	Grade I listed building	Church Of All Saints	Parish church. C14, C15. Greenstone rubble, limestone ashlar, some red brick patching. Lead roofs with parapets and embattled clerestory. West tower, nave with north and south arcades and south porch; chancel. Late C14 west tower with moulded plinth and string courses, and 4 stage angle buttresses, the south-west buttress with plaque inscribed with the names of the vicar and 2 church wardens, and the date 1656.	Medieval	TF 50925 61847
1223796	Grade I listed building	Church Of St Peter	Parish church. c.1200, late C13, C14, C15, C16, restored C19. Greenstone and limestone rubble, limestone ashlar. Lead roofs with stone coped gables and eastern cross finial. West tower, nave with north and south aisles, south porch and clerestory, chancel. Mid C14 west tower with moulded plinth, moulded string courses defining the 3 stages; 3 stage angle buttresses.	Medieval	TF 48497 60684
1222732	Grade I listed building	Dobson's Windmill	Windmill. 1813 by Oxleys of Alford, restored 1947. Tarred brick. Wooden ogee shaped cap with moulded brick eaves, ball finials, fantail and 5 'left handed' patent sails. 5 storeys. Steps lead up on each side of north-east doorway which has a segmental head and double panelled doors. 4 two light sliding sashes, one above the other above. South-east and north-west sides each with 3 two light sliding sashes, one above the other.	Post-medieval	TF 50376 64972
1063629	Grade I listed building	Church Of St Helen	Parish church. Early C14, late C14-early C15, 1846, 1880 by James Fowler of Louth. Squared coursed greenstone rubble, limestone ashlar rubble, red brick patching, slate and lead roofs. Western tower, clerestoried nave, aisles, chancel, south porch. 3 stage tower with bell moulded plinth, 2 moulded chamfered string courses, parapet with octagonal angle finials.	Medieval	TF 47344 71962
1222765	Grade I listed building	Church Of St Peter And St Paul	Parish church. c.1500, 1702, late C18, restored c.1871. Limestone ashlar, greenstone rubble and some red brick. Lead and slate roofs with stone coped gables and eastern gable cross finial. 4 stage ashlar west tower with richly moulded plinth and multi-staged angle buttresses.	Medieval	TF 50083 65010

NHLE No.	Designation and Grade	Name	Description	Period	NGR
1204944	Grade I listed building	Church Of St Thomas Of Canterbury	Parish church. C13, C14, C15, 1874 chancel rebuilt. Limestone ashlar. Squared limestone and greenstone rubble. Slate roofs. Western tower, clerestoried nave, aisles, south porch, chancel. C15 ashlar tower with bell moulded plinth, chamfered string courses, battlemented parapet, crocketed corner pinnacles, angle grotesques, stepped corner buttresses. To belfry stage 2 light cusped openings with panel tracery and hood moulds and below a cusped single light to all faces.	Medieval	TF 51563 74433
1360009	Grade I listed building	Church Of St Margaret	Parish church. C13, C14, C15, C18 and restorations of 1869, 1882 and 1910. Squared greenstone and coursed limestone rubble, ashlar, brick patching, slate roofs. Western tower, nave with clerestory, aisles, chancel, south porch. The C13 4 stage tower in greenstone and limestone rubble has 2 string courses and battlemented parapet. It was raised in C14.	Medieval	TF 51152 76421
1360517	Grade I listed building	Church Of St Mary	Parish church. Late C12, C13, late C13, C14, C15, 1602, 1787 spire rebuilt, and tower, spire, aisles and south transept remodelled by Edward Browning 1861-3. Squared limestone rubble, ashlar, slate and lead roofs. Crossing tower, nave with clerestory, aisles, transepts, chancel. 5 light west window with segmental head and outlandish reticulated tracery. In the gable parapet above the date 1602 and initials BW and WF.	Medieval	TF 28492 35558
1164857	Grade I listed building	Church Of St Peter And St Paul	Parish church. Late C12, early C13, C14, late C15, restored by R. C. Carpenter, 1850-4. Ashlar, lead roofs. Clerestoried nave, aisles, crossing tower, clerestoried transepts with west aisles, chancel, south and north porches, vestry. C14	Medieval	TF 29124 35289
1063615	Grade I listed building	Church Of St Mary	Parish church. C12, early C13, late C15, 1607, C19. Chancel rebuilt 1870. Restorations 1853, 1910. Limestone and chalk ashlar. Limestone and greenstone coursed and squared rubble, red brick with ashlar dressings, slate and lead roofs. Western tower, clerestoried nave, aisles, chancel, south porch. 3 stage C12 tower has tall lower stage, roll and concave moulded string courses, battlemented parapet, clasping buttresses to lower stage only.	Medieval	TF 53416 72216
1359681	Grade I listed building	Church Of St Nicholas	Parish church. C15, 1706, 1736, 1875 restoration. Ashlar and brick with lead roofs. Western tower, clerestoried nave, aisles, south porch, chancel removed in 1706. 3 stage C15 tower with bell moulded plinth, chamfered string courses, embattled parapet with corner pinnacles, stepped corner buttresses.	Medieval	TF 55089 69095
1062022	Grade I listed building	Church Of St Peter And St Paul	Parish church. Mid C12, late C12, C13, C14, C15, c.1500 crossing tower and transepts demolished, and chancel shortened 1805 by William Haywood and stonework used for building west tower and extending aisles. 1900 restoration by Hodgson Fowler, 1907. Limestone ashlar and lead roofs. Western tower, nave and chancel, clerestory, aisles, south porch. Tall 4 stage tower rebuilt in 1805 from materials of former crossing tower, with bell moulded plinth, string courses, quatrefoil frieze to belfry stage, battlemented parapet with gargoyles and corner pinnacles.	Medieval	TF 30493 38527
1062014	Grade I listed building	Church Of St Swithin	Parish church. Early C12, late C12, early C13, late C13, C14, C15, C16, restoration 1876-1911. Limestone ashlar, lead roofs. Truncated nave with clerestory, aisles, central tower, transepts, chancel with clerestory and aisles, south porch. C19 west window is of 4 lights with reticulated tracery and fleurons above, in C16 rectangular surround.	Medieval	TF 22457 37863

NHLE No.	Designation and Grade	Name	Description	Period	NGR
1223593	Grade II* listed building	Church Of All Saints	Parish church. Mid C13, C15, remodelled 1770, restored 1886, C20. Greenstone and limestone rubble, limestone ashlar, red brick. Slate roofs with stone coped gables and eastern cross finial. West tower, nave and chancel in one, north vestry. Medieval greenstone tower almost completely remodelled in red brick in 1770, of 2 battered stages, with 4 stage angle buttresses.	Medieval	TF 46846 63758
1223594	Grade II* listed building	The Cottage	Cottage. Mid C18 with C19 alterations. Colourwashed mud and stud with brick plinth. Half hipped thatched roof under corrugated iron sheeting. Main 3 window front, with central plank door flanked by single glazing bar sash windows with segmental heads.	Post-medieval	TF 43207 63028
1280972	Grade II* listed building	Church Of All Saints	Parish church. C13, C14, C15, C16, C17 porch, chancel rebuilt 1888. Greenstone ashlar, squared greenstone, sandstone and chalk, coursed rubble, red brick, lead roofs. Western tower, clerestoried nave, south aisle and porch, chancel.	Medieval	TF 49064 67248
1359286	Grade II* listed building	Wykes Manor	Farmhouse. 1680, built by Thomas Cowley, founder of Donington School, altered and extended C18 and C19. Red brick in English bond, machine plain tiled and pantile roof, large axial ridge stack. T-plan. Two storey and garret, irregular three bay front, originally five, with plinth, first floor band, two tall margin light sashes to ground floor, one glazing bar sash lighting stair mezzanine at the centre.	Post-medieval	TF2314835407
1063536	Grade II* listed building	Church Of St Helen	Parish church. C13, C14, C15, restorations 1830, 1853 by Fowler, 1863 and 1881. Ashlar, some red brick. Slate roofs. Coped gables with single ridge crosses to the east nave, east chancel and south porch. Buttressed. Tower, nave, aisles, south porch and chancel. C15 angle buttressed tower set on a moulded plinth of 4 stages with bands. Brick parapet with single corner gargoyles.	Medieval	TF 35192 60038
1063538	Grade II* listed building	Church Of St Luke	Parish church. C13, C15, restored 1793, 1887 and 1900 by Bassett Smith. Ashlar and red brick. Plain tile roofs to nave and chancel, lead roof to south aisle. Single stacks to the vestry and north chancel. Coped gables with single ridge crosses to the east nave, east chancel and porch. Buttressed. Tower, nave, south aisle, south porch, north aisle, vestry and chancel.	Medieval	TF 34344 57073
1267204	Grade II* listed building	Church Of St Andrew	Parish church. Mid C14, C15, 1638, 1701, restored C19 and C20. Greenstone rubble, red brick, limestone ashlar dressings, some render. Concrete tiled roofs with stone coped gables and cross finials. West tower, nave with south aisle and south porch, chancel with north vestry.	Medieval	TF 43358 63556
1224403	Grade II* listed building	Church Of St Mary	Parish church. Late C12, early C13, early C15, C18, restored 1875-92. Limestone coursed rubble and ashlar dressings, some red brick, some render. Lead roofs with stone coped gables with kneelers and cross finials. West tower, nave with north and south aisles, south porch, chancel with north organ chamber.	Medieval	TF 47111 58672
1360477	Grade II* listed building	Frampton House	Small country house, now an Old Persons home. Built for Thomas Tunnard. 1792 with minor C20 alterations. Red brick in Flemish bond with ashlar and yellow brick dressings. Hipped slate roof with lead dressings, 2 red brick ridge stacks. 3 storey, 5 bay front, arranged 1:3:1, the central bays advanced and pedimented. Short ashlar plinth, first and second floor ashlar bands, dentillated frieze, cornice, ashlar balustraded parapet. Central half glazed door in panelled reveals with traceried fanlight with ashlar architrave, with	Post-medieval	TF 30268 39850

NHLE No.	Designation and Grade	Name	Description	Period	NGR
			open pedimented and dentillated doorcase, supported on Doric columns, flanked by pairs of glazing bar sashes. To first floor are 5 similar windows, and to second floor 5 smaller windows. All windows have flat moulded brick arched heads and stepped fluted keyblocks.		
1267661	Grade II* listed building	Church Of St Peter And St Paul	Parish church. Early C14, early C15, 1747, restored and chancel rebuilt 1844 and restored 1890. Greenstone, limestone rubble and ashlar, red brick. Slate roofs with stone coped gables and cross finials. West tower, nave with north and south aisles, south porch and clerestory, chancel.		TF 47460 65020
1267241	Grade II* listed building	Old Church Of All Saints	Parish church, now redundant. 1748 on medieval base, restored 1908. Red brick with limestone ashlar dressings, greenstone rubble. Plain tiled roof with stone coped gables; parapet with ashlar band and weatherboarded rectangular west bellcote of 1908 with rectangular slatted openings on each side and small pyramidal roof. Nave and chancel under single roof, west bellcote.	Post-medieval	TF 43476 63943
1359723	Grade II listed building	Bridge Over Twenty Foot Drain	Road bridge. c.1812, under the direction of John Rennie. C20 restorations. Red brick with ashlar dressings. Basket arch with red brick band over. Bowed swept walls terminating in single square piers. Ashlar coped parapet. Some C20 red brick. patching.	Post-medieval	TF 30330 52793
1267366	Grade II listed building	Clarey's Bridge	Road bridge over drainage channel. c.1812 by John Rennie. Red brick with some ashlar. Semi-circular archway with flat band running above. Ashlar coped parapet with sweeping sides terminating in coped rectangular piers.	Post-medieval	TF 41875 60591
1063655	Grade II listed building	Brick Kiln	Former brick kiln, now store. Mid C19, extended late C19. Brown/orange brick, pantile roofs. Scotch kiln. Single storey with externally battered walls, rectangular opening to kiln chamber with timber lintel. 8 stoke holes and pent roofed stoking chambers to each side. In the opposite end is an arched opening. Farlesthorpe yellow bricks were used in the locality during C19.	Post-medieval	TF 47995 73943
1232867	Grade II listed building	Coach House, Gin House, Granary, Gate Piers, Gate And Screen At Casterton Farm	Coach house, gin house, granary, gate piers, gate and screen. Early C19, late C19, altered C20. Red brick in Flemish bond, hipped asbestos roofs. Cast iron. Rectangular coach house block with 2 projecting gabled single storeyed wings with beyond a gin house linked to large granary. 3 storey, 4 bay coach house with off-centre double planked door beneath elliptical rubbed brick arch with Gothick fanlight, to left a 2 light window with Gothick tracery.	Post-medieval	TF 25744 36682
1232910	Grade II listed building	Casterton House, Ha Ha Wall, Gates And Railings	House,ha-ha wall, gates and railings. Late C18, refronted and refitted c.1830. Ashlar faced. Red brick, slate roofs, behind parapet on the front. 2 stone gable stacks, the left hand one reduced, copper roofed verandah, cast iron railings and gates. 3 storey, 3 bay front with plinth, first floor band, parapet, centre bay slightly advanced, end pilasters.	Post-medieval	TF 25756 36671
1359743	Grade II listed building	Church Of St Peter	Parish church, formally closed for worship in 2014. Built 1819. Probably by Jeptha Pacey. Red brick with ashlar dressings. Slate roof with bracketed eaves. Moulded cornice forming open pediments in the nave gables. Clasping pilaster strips. Further pilaster strips defining the bays of the north and south sides. Plinth. Nave and short chancel.	Post-medieval	TF 38470 57032
1146546	Grade II listed building	The Gables	Farmhouse. 1692, altered C19 and C20. Rough cast rendered brick, stucco quoins, steeply pitched slate roof with coped gables. 2 gable stacks. 2 storey, 3 bay front, with rusticated stucco quoins, with 2 margin light sashes	Post-medieval	TF2740830983

NHLE No.	Designation and Grade	Name	Description	Period	NGR
			with splayed lintels with keystones to each floor. Between the first floor windows a blocked opening. On the left hand gable stack an inscribed datestone "BRE 1692". C20 windows to rear range.		
1276845	Grade II listed building	Pigeoncote At Casterton Farm, In Gardens East Of The House	Pigeoncote. Early C19. Red brick in English bond. Conical slate roof with lead ball finial and weather vane. Circular plan. 2 storey with planked door and to the upper stage a 2 light opening. Splayed flat brick arches to both openings. Interior retains timber floor, brick nesting boxes.	Post-medieval	TF 25818 36692
1204902	Grade II listed building	Church Of St Andrew	Parish church. c.1800, restored 1881, chancel rebuilt 1912, 1953 restoration. Farlesthorpe yellow brick, red brick, ashlar dressings, slate roof. Nave with bellcote, west porch, facetted chancel. Added c.1912 gabled red brick porch with ashlar kneelers and dentillated eaves course. Pointed doorway, double planked doors. Broad 6 panelled inner door of c.1800. Above the porch a plaque recording the restoration of 1953, the date of the single bellcote to the gable.	Post-medieval	TF 47532 74024
1307150	Grade II listed building	Witham House	House. Early C18, remodelled early C19, C20 additions. Rendered brick. Steeply pitched hipped slate roof. 2 lateral rendered stacks. 2 storeys plus attic, 3 bays. Central doorway with panelled door and traceried fanlight, open porch with single pilasters supporting an open pediment. To left and right are single glazing bar sashes with cambered heads, 3 similar sashes above, that over the doorway being narrower	Post-medieval	TF 26635 47582
1232868	Grade II listed building	The Old Vicarage	Former vicarage, now house. Early C19. Stucco, with hipped slate roof, slightly overhanging eaves, stucco wall stacks. 2 storey, 3 bay front with slightly advanced centre bay. Central half glazed panelled door with plain fanlight, set in fluted semi-circular surround with roundels, narrow hood over, flanked by single glazing bar sashes. To first floor 3 shorter similar windows. All windows have shallow cambered heads. To rear a single storey service wing.	Post-medieval	TF 26210 36104
1168163	Grade II listed building	Bridge Over Barlode Drain Next Bell Water Bridge	Road bridge. c.1812, under the direction of John Rennie. Red brick with ashlar dressings. Basket arch with red brick band over. Bowed swept walls terminating in single square piers. Ashlar coped parapet.	Post-medieval	TF 38552 58080
1264133	Grade II listed building	Milepost South Of Green Lane	Milestone. Early C19. Ashlar. Inscribed on the sides 'Boston 8 miles and Spalding 8 miles, Wigtoft, London 108 miles'.	Post-medieval	TF 26285 33771
1359281	Grade II listed building	Ivy House	Farmhouse. Late C18, altered mid C19 and C20. Red brick in English bond, concrete tiled roof, 2 C19 brick gable stacks. 2 storey, 3 bay front with half glazed C19 door and overlight, with gabled hood having decorative bargeboard and knop on carved brackets. Flanked by single margin light sashes with segmental brick heads. To first floor a central blank opening is flanked by single margin light sashes with flat timber lintels.	Post-medieval	TF 26805 31403
1147406	Grade II listed building	Brothertoft Hall	House. c.1780, substantially extended and altered c.1850. Yellow brick, partly colourwashed and rendered. Hipped slate roof, red brick wall stacks. 3 storey, 5 bay front, the side elevations are canted bays.	Post-medieval	TF 26972 46394
1360445	Grade II listed building	Church Of St Gilbert	Former Chapel of Ease, dedicated as a Parish Church in 1922. Medieval stonework. Rebuilt 1847 by S. Lewin, chancel added 1854, in Perpendicular style. Squared limestone rubble, slate roofs, stone coped gables. Nave with western bellcote and chancel.	Post-medieval	TF 27023 46264

NHLE No.	Designation and Grade	Name	Description	Period	NGR
1223096	Grade II listed building	Old Marsh Chapel	Mission chapel with schoolroom below. 1865-7, restored 1884. Red brick with ashlar dressings. Pantile roof with stone coped gables; the east gable with cross finial; the west gable with gabled bellcote with single pointed opening and cross finial. Plinth and 4 dentillated bands, the upper bands running under eaves of north and south fronts. 2 storeys, 3 bay south front with slightly projecting gabled doorway to left with higher plinth, pointed inner doorway with alternating brick and ashlar voussoirs, plank door.	Post-medieval	TF 52652 64188
1360497	Grade II listed building	Holmes Farmhouse	Farmhouse. c.1800, altered late C19. Red brick in Flemish bond, pantile roof, 2 gable stacks. T-plan. 3 storey, 3 bay front having central half glazed door with plain overlight, flanked by single C19 canted bay windows and flat roofs. To first and second floors 3 glazing bar sashes.	Post-medieval	TF 28039 41498
1360472	Grade II listed building	Barn At Elms Farm	Former barn with saddlery attached, now partly loose box and stores. Early C18, altered C20. Red brick in English bond, steeply pitched pantile roof with brick coped tumbled gables. 2 storey with plinth, having 3 offsets on top and corbelled out eaves. On the front are later brick lean-to addition, incorporating original advanced entry bay.	Post-medieval	TF 27202 43713
1062057	Grade II listed building	Stable And Store At Elms Farm	Stables and store. Mid C18. Red brick in English bond, steeply pitched pantile roof with brick coped tumbled gables. 2 storey with garret and short plinth, 4 bay front, having 2 planked stable doors to ground floor and 4 two light glazing bar fixed lights to first floor. All openings have segmental heads. To the left a later lean-to addition.	Post-medieval	TF 27204 43731
276849	Grade II listed building	Stanhope Cottage	Cottage. Late C18. Timber framed and red brick in English garden wall bond of 3, with half hipped pantile roof, central rendered brick stack. Lobby entry plan. Single storey plus garret, 3 bay front with central planked door, flanked by single 2 light glazing bar sashes, one fixed, one sliding, all openings have brick segmental heads. To the rear a single storey service wing. Some internal evidence of the timber frame survives.	Post-medieval	TF 26464 36105
232900	Grade II listed building	Coach House At Easthorpe Court	Former coach house, now garage. c.1804, altered C20. Rendered brick, hipped slate roof with ashlar dressings having central decorative diamond. 2 storey, 3 bay front. To ground floor central segmental arch, flanked by single semi-circular arches, covered by C20 sliding garage doors. To first floor 3 semi- circular 2 light fixed windows.	Post-medieval	TF 26675 36778
1232864	Grade II listed building	Easthorpe Court	Farmhouse. C18, refronted and largely rebuilt 1804 with minor C20 alterations. Rendered brick, Welsh slate roof with stone coped gables and 2 rendered gable stacks. L-plan. 2 storey, 3 bay front, with first floor band and moulded wooden cornice to parapet. Centre bay canted and advanced. Central C20 door with traceried overlight flanked by single fixed glazing bar lights with pointed Gothick heads. Beyond to either side are single canted bay windows with moulded cornices, each containing 3 glazing bar sashes. To first floor the central canted bay is supported on slender cast iron columns, it has a moulded cornice and single glazing bar sash, and is flanked by single similar windows.	Post-medieval	TF 26637 36754
267487	Grade II listed building	The Hollies Farmhouse	Farmhouse. Mid C18. Red brick, some painted stone dressings. Pantile roof with brick coped and tumbled gables and gable stacks. T-plan. 2 storeys and attic, 3 bay front with first floor band and eaves band on return walls. Central bay projects slightly and contains doorway with overlight and fielded panelled	Post-medieval	TF 50002 63104

NHLE No.	Designation and Grade	Name	Description	Period	NGR
			door. Doorway flanked by single, glazing bar sashes, with 3 similar windows above. All openings with segmental heads and raised, painted keystones.		
1168221	Grade II listed building	Northlands Bridge	Road bridge. c.1812, under the direction of John Rennie. C20 restorations. Red brick with ashlar dressings. Basket arch with red brick band over. Bowed swept walls terminating in single square piers. Ashlar coped parapet. Some C20 brick patching to the north side. The area was drained and enclosed by the engineer John Rennie 1802-12.	Post-medieval	TF 34449 53234
1360495	Grade II listed building	Kitchen Garden Wall To Hubberts Bridge Farmhouse	Garden wall. Late C19. Red brick with tile coping. Crinkle crankle wall to 6'0" height, around two and half sides of a walled garden.	Post-medieval	TF 26731 43780
1232947	Grade II listed building	Hubbert's Bridge Farmhouse	House. c.1750-1770, altered early C19. Red brick in Flemish bond with tuck pointing, painted ashlar dressings. Welsh slate roof with stone coped gables and 2 gable stacks. L-plan. 3 storey, 5 bay front arranged 2:1:2, the centre bay slightly advanced and separately gabled. Plinth, first floor band, modillion wooden cornice. Central 4 panel door with overlight, panelled reveals, early C19 pilastered doorcase with open pediment, flanked by pairs of lengthened tall glazing bar sashes; to first floor 5 glazing bar sashes and to second floor 5 smaller similar windows. All windows have segmental heads and stepped keyblocks. To the rear, a 2 storey service wing.	Post-medieval	TF 26735 43768
1232866	Grade II listed building	Burtoft Manor Farmhouse	Farmhouse. Early C18, with minor C19 alterations and C20 extensions. Roughcast rendered brick, slate roof with stone coped gables, 2 partly external brick stacks. 2 storey with garret, 5 bay front having first floor band. Central glazed double doors covered by C20 hipped roofed glazed porch, flanked by pairs of plain sashes. To first floor 5 similar windows. All windows have plain stucco splayed lintels.	Post-medieval	TF 26683 35176
1308503	Grade II listed building	Mile Stone East Of Baker's Bridge	Milestone. Early C19. Limestone post with pyramidal top. Inscribed "Boston 3 miles, Sleaford 15 miles".	Post-medieval	TF 28546 42811
1165111	Grade II listed building	Barn To Hubbert's Bridge Farm	Former barn, now store. Mid C18, altered C19 and C20. Red brick with pantile roof and raised brick coped gables with plain kneelers. 6 bays divided by flat brick buttresses with tiled copings, the penultimate bays are broader and contained wide tall arched entrances, now blocked. Dentillated eaves course. Large panelled double doors to left, beneath relieving arch, to right a 3 light glazing bar fixed window, beyond a blocked circular opening, a further small fixed light and a planked door. Above a further 3 light window is flanked by planked doors with to right 2 planked smaller openings. All openings have brick segmental heads.	Post-medieval	TF 26660 43742
1224571	Grade II listed building	Bland's Farmhouse	Farmhouse, 1779. Red brick with pantile roofs and brick rumbled and coped gables with kneelers plus 2 gable stacks. T-plan. 2 storey, 5 bay front with central panel door with ornate glazed overlight, flanked by 2 glazing bar sashes. Above plain brick band, then 5 smaller glazing bar sashes. All openings have segment headed painted wedge brick lintels. Rear catslide roof with a single segment lopped dormer window with glazing bar sash. East gable wall has ashlar plaque inscribed 'J.K. 1799'.	Post-medieval	TF5048463717
1062092	Grade II listed building	Mile Stone (Midway Between Frampton Lane And Baker's Bridge)	Milestone. Early C19. Painted limestone ashlar. Rectangular post with domed top with seating inscribed "Boston 4 miles, Sleaford 14 miles", also with 2 bench marks.	Post-medieval	TF 26933 42558

NHLE No.	Designation and Grade	Name	Description	Period	NGR
1223830	Grade II listed building	Lymm Bank Farmhouse	Cottage. c.1740, mid C19, C20. Red brick. Slate roof with brick coped and tumbled gables, dentillated eaves continued as band across return walls, and single central C19 ridge stack. Lobby entrance. One and a half storeys, 3 bay front with central doorway with plank door. Doorway flanked by single C20 casements, all 3 ground floor openings with segmental heads. Single small glazing bar sliding sash above doorway.	Post-medieval	TF 49493 61614
1267406	Grade II listed building	The Old Vicarage	Vicarage, now house. c.1820. Red brick. Hipped slate roof with overhanging eaves and 2 ridge stacks. 2 storeys, 3 bay front with central doorway with semi-circular head and overlight; 4 steps lead up to deepest, three-quarter glazed door. Doorway flanked by single glazing bar sashes with 3 glazing bar sashes above, all with segmental heads. South side with ornate Venetian arched conservatory-porch with small glazing bars, and flanked by single glazing bar sashes, with 3 cross casements above, all with segmental heads.	Post-medieval	TF 50882 61834
1062054	Grade II listed building	Corner Cottage	Cottage. Late C18. Red brick in English garden wall bond of 5. Concrete pantile roof with tumbled brick coped gables and 2 brick gable stacks. L-plan. Single storey plus garret, 3 bay front with brick dentillated eaves, central planked door flanked by single margin light sashes under brick segmental heads.	Post-medieval	TF 26796 43412
1267365	Grade II listed building	Bridge House	Farmhouse. Mid C18, late C19. Red brick. Pantile roof with brick coped and tumbled gables and gable stacks. 2 storeys with garret, 3 bay front with central doorway with C19 latticework porch and partially glazed door. Doorway flanked by single plain sashes with 3 plain sashes above, all with wooden lintels.	Post-medieval	TF 51319 62106
223749	Grade II listed building	The Cottage (To The West Of No 8)	2 cottages, now cottage. c.1800. Red brick. Pantile roof with brick coped and tumbled gables and central ridge stack. Single storey and garret, 4 bay front with doorway to left with plank door, wooden lintel and hood. 2 two light fixed windows beyond, both with segmental heads. Single doorway beyond with plank door, wooden lintel and wooden hood.	Post-medieval	TF 42849 60972
204901	Grade II listed building	Church Of St Helen	Parish church, now closed. C13, C14, C15, 1838 rebuilding. Squared greenstone and limestone rubble, red brick patching and overbuilding, and render, slate roofs, lead covered turret and spire. Nave with western bellcote turret and spire, chancel, vestry. The 3 light west window has C19 tracery in C14 surround. Octagonal lead covered bell turret with pointed gabled louvred openings and short spire. The north side is rendered and has 2 three light reticulated traceried windows with hood moulds.	Medieval	TF 50627 73739
1360501	Grade II listed building	Lade Bank Lock, Pumping Station And Chimney	Lock, pumping station and chimney. 1805 by John Rennie and 1867. Red brick, red and yellow brick, slate roofs with raised stone coped gables and kneelers. Originally consisting of a lock of 4 cutwaters and 2 abutments all of keeled plan with gritstone cappings, with grooves and fixings for lock gates. In 1867 an engine house and pumping station with tall chimney was built above. Single storey, 7 bay front, with plinth, arranged 4:3, the right hand 3 bays being set back and built on arches over the earlier lock.	Post-medieval	TF 37933 54489
1267163	Grade II listed building	Holly Tree Cottage	House. c.1800. Red brick. Pantile roof with brick coped and tumbled gables and 2 gable stacks. 2 storeys, 3 bay front with central doorway with partially glazed door. Doorway flanked by single, glazing bar sashes. 2 glazing bar sashes flank single fixed glazing bar light over doorway. All the openings have segmental heads.	Post-medieval	TF 46674 60657

NHLE No.	Designation and Grade	Name	Description	Period	NGR
223275	Grade II listed building	War Memorial 5 Metres South Of The Church Of St Andrew	Cross. C15, remodelled war memorial in c.1918. Limestone ashlar. 2 square steps lead up to rectangular plinth with chamfered corners and broached stops, inscription and chamfered top edge. Tapering rectangular shaft with broached stops, the lower one and a half meters C15, the remainder, including cross head, C20.	Medieval	TF 45509 62617
223351	Grade II listed building	Cross Base Half A Metre East Of The South Porch Of The Church Of St Andrew	Cross base. C14. Limestone ashlar. Octagonal plinth with broached corners.	Medieval	TF 45512 62624
267350	Grade II listed building	Church Of St Andrew	Parish church. 1856 by G. E. Street. Limestone ashlar. Plain tiled roofs with stone coped gables and cross finials. Gabled west bellcote with 2 pointed openings each containing a bell, and gablet kneelers and weathervane. Nave with west bellcote and south porch, apsidal chancel with north vestry.	Post-medieval	TF 45512 62636
1359711	Grade II listed building	Manor House	Farmhouse. Late C18, with mid C19 alterations. Red brick in Flemish bond, C19 slate roof with overhanging eaves and bargeboard. 2 gable stacks. L-plan. 2 storey, 3 bay front having central panel door with plain overlight, wooden pilastered surround, narrow leaded hood, scrolled brackets and paterae, flanked by single glazing bar sashes with segmental brick heads. To first floor are 3 similar windows to eaves. Rear wing has a Venetian window.	Post-medieval	TF 47499 72309
223276	Grade II listed building	Firsby Manor House	House. Early C19, mid C19. Red brick with colourwashed stucco dressings. Slate roofs with 2 gable stacks and 2 stacks to rear. T-plan. 2 storeys, 5 bay front with first floor band. Central doorway with simple pilastered doorcase, wedge lintel, overlight and partially glazed door. 2 glazing bar sashes on each side of doorway, with 3 glazing bar sashes above. All with cambered heads and wedge lintels. 3 bay west front with 2 mid C19 bays attached to left. Doorway to right with pilastered doorcase, small bracketed hood, overlight and panelled door. 2 glazing bar sashes to left with 2 more beyond, and 5 above, all with cambered heads.	Post-medieval	TF 45622 62714
1063571	Grade II listed building	The Grange	House. Early C19. Stock brick. Hipped slate roof. 4 rear stacks. Single corner pilaster strips with single similar strips flanking the single central bay. 2 storeys, 3 bays. Central doorway with panelled door and overlight flanked by single Doric pilasters with entablature and pediment. Either side are single glazing bar sashes with C20 shutters. 3 similar smaller sashes above.	Post-medieval	TF 26336 48382
1223745	Grade II listed building	The Manor House	Vicarage. Mid C18, remodelled c,1825. Red brick. Slate roofs with brick coped gables, 2 gable and a single ridge stacks. 2 storeys with garret, 7 bay front with 2 bays to left projecting with garret in gable and 2 C19 bays beyond. Plinth and first floor band, second floor band on return walls and projecting gabled bay. C19 doorway in re-entrant angle of projecting bays, to the right; set in canted porch with flat band; with semi- circular head, glazing bar fanlight and door. 2 glazing bar sashes in projecting bays to left, with 2 more beyond. 2 smaller glazing bar sashes to right of doorway, all with cambered heads. 3 small glazing bar sashes above, with wooden lintels. 4 glazing bar sashes to left, all with cambered heads. Central garret window with small glazing bar sash with cambered head.	Post-medieval	TF 48488 60774
1434782	Grade II listed building	Thorpe St Peter War Memorial	War Memorial was unveiled on 15 August 1920. It is of Portland stone, c2.7 m tall. It has a square base, with a two-stage plinth (square on plan). A square pedestal with a quadripartite gabled capping stands on the plinth, from which a small wheel-head cross rises to form the top of the memorial.	Modern	TF4842360697

NHLE No.	Designation and Grade	Name	Description	Period	NGR
1062024	Grade II listed building	Holme House	House. Mid C18, altered C19 and C20. Red brick in Flemish bond, ashlar dressings, concrete tiled roof, stone coped gables to front, brick coped to rear, 2 brick gable stacks. T-plan. 2 storey with attic, 3 bay front with first floor ashlar band and quoins.	Post-medieval	TF2611242061
1165222	Grade II listed building	Stable Block At Holme House	Former stable and trap house block with granary over. C18. Red brick, ashlar dressings, hipped slate roof, 2 storey, 5 bay front, the central bay is pedimented. A wide central segmental arched opening flanked by 2 single similar windows and doors, all with ashlar keystones and now blocked. To first floor 3 blocked semi-circular windows. To right a brick staircase to first floor granary.	Post-medieval	TF2609142041
1061993	Grade II listed building	The Mill	Tower mill. c.1840. Red brick partly tarred, tapering tower, with plinth and moulded brick cornice. 5 storeys with planked double doors with 4 steps, above are single glazing bar windows to each floor, all with brick segmental heads. Not inspected internally. No machinery or stones remain. The mill worked until 1921 when the sails were removed.	Post-medieval	TF 27257 35905
1223172	Grade II listed building	Old Chequer's Inn	Inn. Early to mid C18, late C19, C20. Red brick. Pantile roof with large brick ridge stack and tall external lateral stack on main front. Single storey and garret, 5 bay front with plinth and eaves band on return walls. T-plan. Lobby entrance. Central doorway with C19 bracketed and gabled hood with decorative barge boards and panelled door. 2 glazing bar casements to left, both with segmental heads. Blocked rectangular window opening to right with a single glazing bar casement beyond. All the windows with C20 shutters.	Post-medieval	TF 50344 61170
1359745	Grade II listed building	Stickney Grange	House. Early C19. Red brick, some blue brick. Slate roof. single gable stacks. Moulded wooden eaves band. First floor sill band. 2 storeys plus attic, 5 bays. Central doorway with panelled door, overlight, pilastered doorcase and bracketed hood. Either side are 2 glazing bar sashes with 5 similar above, all under flat heads. In the attic are 2 dormers each with single glazing bar sash. Attached to the left is a single storey red brick and pantile range with brick coped gables.	Post-medieval	TF 33902 55706
1267317	Grade II listed building	Outbuilding To Rear Of The Old Manor House	Stable, now outbuilding. Late C18 with C20 alterations. Red brick. Pantile roof with single gable stack. Single storey with garret. South side with single 3 light C20 casement with segmental head. West return with doorway with segmental head and plank door. Single lunette in gable above, with radiating spokes.	Post-medieval	TF 45457 62913
1223277	Grade II listed building	The Old Manor House	House. Mid C18, altered late C19. Red brick with C19 hipped slate roof with large central C18 ridge stack. L-plan, lobby entrance. 2 storeys, 5 bay front with first floor band broken above central doorway. The latter with pilaster strip doorcase with bracketed hood, blind overlight and panelled door. Doorway flanked by 2 C19 casements on each side with 5 similar casements above, all having flush wedge lintels. South front of 2 bays with first floor band. 2 C19 casements with flush wedge lintels with 2 C18 blind openings with segmental openings, above. That to the right with small glazing bar casement inserted.	Post-medieval	TF 45442 62917
1223015	Grade II listed building	1-3, Jackson's Lane	Cottage. Late C18, raised c.1830. Red brick. Hipped pantile roof with single C20 ridge stack. One and a half storey, 4 bay front with doorway to right with plank door. 3 glazing bar sashes to left with 4 very small plain sashes above. Single sliding sashes in return walls. All the openings with segmental heads.	Post-medieval	TF5020865097

NHLE No.	Designation and Grade	Name	Description	Period	NGR
1223053	Grade II listed building	10, The Market Place	2 cottages, now single cottage. Early C19. Red brick. Steeply pitched pantile roof with single ridge stack. 2 storeys, 4 bay front with doorway to left with glazing bar door. Single glazing bar sashes to right flank another doorway, now blocked and with glazing bar casement inserted. 2 glazing bar sashes above. All the openings with segmental heads.	Post-medieval	TF5017765137
1267483	Grade II listed building	11, The Market Place	Shop with accommodation above, now house. Mid C18. Red brick. Very steeply pitched pantile roof with wooden eaves and single stack to rear. 2 storeys, 2 bay front with bay to right projecting slightly and containing segmental bowed shop window with 3 glazing bar sashes, those flanking being narrower, and with reeded pilasters and broad bracketed entablature. Doorway to left with segmental head and partially glazed fielded panelled door. 2 glazing bar sashes above with segmental heads and raised painted stone keystones.	Post-medieval	TF5017465134
1232852	Grade II listed building	The Chestnuts	Farmhouse. c.1800 with minor C20 alterations. Red brick in Flemish bond, concrete tiled roof with raised brick coped gables, partial tumbling, 2 gable stacks. 2 storey, 3 bay front having brick dentillated eaves, central C20 door with plain overlight, flanked by single margin light sashes. To first floor are 3 similar windows. All openings have cambered rubbed brick arched heads. To the left is a single storey pent roofed dairy.	Post-medieval	TF2592342114
1062021	Grade II listed building	The Mill	Tower mill. 1833. Red brick, tarred. Tapering tower of 4 storeys with corbelled eaves band. To ground floor a doorway up 3 steps and 2 fixed glazing bar lights. To first floor a similar window and to second and third floor single planked openings. All openings have segmental brick heads. Interior not inspected. No machinery remains, only 3 stones. It was erected to replace a post mill and worked until c.1936 when the sails were removed.	Post-medieval	TF 28947 40234
1062030	Grade II listed building	Chestnut Farmhouse	Cottage. Late C18. Red brick, pantile roof with brick coped gables and 2 brick gable stacks. L-plan. Single storey plus attics, 3 bay front with brick dentillated eaves. Central 2 panel door with overlight, flanked by single plain sashes. In the roof are 2 gabled dormer glazing bar sash windows with brick cheeks and boarded heads. Above the door a fire insurance plaque. 4 bay rear service range with 2 doors and 2 glazing bar sashes. All openings have brick segmental arches.	Post-medieval	TF 28987 38693
1222672	Grade II listed building	12, High Street	3 cottages with shop, now single cottage with shop. Mid C18, raised to north in early C19, C20. Thickly rendered brick. Pantile roof hipped to west and with single ridge and gable stacks. West front with single storey and attic, 5 bay front including 2 storey bay to left.	Post-medieval	TF 50162 65073
1450521	Grade II listed building	New Leake, Eastville, And Midville War Memorial	The war memorial was unveiled on 30 October 1921. It consists of a rough- hewn Latin cross of granite with an incised cross decorating the front face. The cross stands on a two-stage square plinth, standing on a two-stepped square base.	Modern	TF4026657193
1223032	Grade II listed building	The Fleece Inn	2 houses, now inn. Late C18, early C19, C20. Thickly rendered, colourwashed brick with painted stucco dressings. Pantile roofs, that of house to left is slightly higher; continuous C19 moulded wooden eaves, gable stacks and single ridge stack. 2 storeys, 6 bay front with painted plinth. 3 bays to right of late C18; 3 bays to left, early C19. Doorway to right with pilastered doorcase with panelled reveal, entablature, overlight and panelled door. Doorway flanked by single glazing bar sashes with segmental heads.	Post-medieval	TF 50131 65141

NHLE No.	Designation and Grade	Name	Description	Period	NGR
			Doorway to left with stucco wedge lintel with voussoirs and partially glazed panelled door. This doorway is also flanked by single glazing bar sashes with cambered heads. 6 glazing bar sashes above. The 3 to the right being smaller.		
1222683	Grade II listed building	2, The Market Place	House. Late C18. Red brick. Slate roof with single gable and ridge stacks, the latter defining the extent of the property. 2 storeys with cellar, 3 bay front with high plinth and first floor band. Cellar opening in plinth to left with segmental head and plank door.	Post-medieval	TF5012765133
1222681	Grade II listed building	Holmes' Butcher's Shop And Number 1 The Market Place	Shop with 3 attached houses, now shop with attached house. c.1800, C20. Red brick. Slate roof hipped to south with single ridge stack. L-plan. 2 storeys with basement, 5 bay south west front with plinth and first floor band. Doorway with reeded doorcase and panelled door. Glazing bar sash with segmental head, to left, with archway to through-passage, beyond, with semi-circular head and double plank doors. Plain sash to right of doorway, inserted in blocked doorway, and with segmental head. C20 shop front on corner, beyond, with central doorway with double stable doors and flanking rectangular windows each, in turn flanked by reeded pilasters and with fixed glazing bars. Above 2 glazing bar sashes alternate with 2 blind panels, plus another glazing bar sash to the left, all with segmental heads.	Post-medieval	TF5012465124
1267650	Grade II listed building	10, The Churchyard	House. Mid C18, C20. Thickly rendered brick. Steeply pitched pantile roof with coped gables and single gable stack. 2 storeys, 3 bay front with central doorway with panelled door. Doorway flanked by single glazing bar sashes with doorway to through passage to left with plank door. 3 glazing bar sashes above. All the windows with segmental heads. First floor band on return wall.	Post-medieval	TF 50145 65035
1450494	Grade II listed building	Langrick War Memorial	The memorial was unveiled on 15 August 1920. It is in the form of a 3.7 m tall Latin cross bearing a crucifixion, built in Weldon Stone. It has a two- stepped octagonal base on which stands an octagonal plinth. There are shields carved in relief on four of the plinth sides. The cross shaft is square in section, tapering throughout its length. The stone carved figure of Christ crucified is on the eastern face of the memorial, looking towards the main road.	Modern	TF2615248691
1204983	Grade II listed building	Covells Farm House	House. Originally late C16, largely rebuilt in early C18, altered early C19 and C20. Red brick in Flemish bond, stucco dressings, pantile roof with late C16 axial brick stack with bands. Lobby entry plan. 2 storey. irregular 3 bay front having short plinth and first floor band. Central glazed door with margin overlight flanked by single glazing bar sashes. Openings have sgemental heads and splayed stucco lintels.	Post-Medieval	TF 47144 72122
1222671	Grade II listed building	West View	Cottage. 1785, C20. Colourwashed brick. Pantile roof with coped and tumbled gables continuing in tumbled catslide to north return; single ridge and gable stacks. Single storey and attic, 3 bay front with central doorway with raised keystone inscribed "GB 1785" and partially glazed panelled door. Doorway flanked by single glazing bar sashes with raised keystones. All three openings with segmental heads. 2 C20 gabled dormers above with 2 light casements under segmental heads.	Post-medieval	TF 50133 65011
1222948	Grade II listed building	33, High Street	Cottage. c.1700, mid C19, C20. Red brick with some painted ashlar dressings. Slate roof with central axial ridge stack and dentillated band just below eaves. Single storey and attic, 3 bay front with central bay projecting slightly. Ashlar coping above. Central doorway with reeded doorcase, blind	Post-medieval	TF 50094 65111

NHLE No.	Designation and Grade	Name	Description	Period	NGR
			overlight and panelled door. Doorway flanked by single, glazing bar sashes with raised, painted keystones and C20 shutters. 2 dormers above with segmental heads and 2 light sliding sashes.		
1267666	Grade II listed building	The Old Vicarage	Vicarage, now house. Mid C18, mid C19. Red brick. Pantile roof with coped and tumbled gables and gable stacks. L-plan. 2 storey, 3 bay front with first floor band. Central doorway with C19 reeded architrave, paterae and partially glazed panelled door. Doorway flanked by single 3 light casements. 2 light casement above door flanked by single 3 light casements. All the windows with C19 moulded architraves and paterae which break through the segmental heads of original C18 windows.	Post-medieval	TF 50102 65065
1359725	Grade II listed building	Church Of St Margaret	Parish church. 1828, probably by Jeptha Pacey, repaired and altered 1885. Red brick, some render to plinth. Slate roofs. Brick coped gables with kneelers. Modillion frieze under the eaves. Moulded plinth. Buttressed. Nave, west porch and small chancel. West bellcote with 4 centred arch flanked by single piers with single narrow blind recessed arched panels to each side.	Post-medieval	TF 26109 48695
1222677	Grade II listed building	17, High Street	Cottage. Late C18, early C19. Red brick. Steeply pitched hipped pantile roof with 2 brick gable stacks to rear. 2 storeys, 3 irregular bays with first floor band. Central doorway with gabled, open porch, segmental head and 5 panel door. Single glazing bar sash with segmental head, to left.	Post-medieval	TF5005165054
1063628	Grade II listed building	Bridge At The Rectory	Bridge over moat. Late C18. Red brick with ashlar coping. Single semi- circular brick arch, band above, ashlar coped parapet with splayed ends.	Post-medieval	TF 47301 71900
1450497	Grade II listed building	Burgh Le Marsh War Memorial	The war memorial was unveiled in 1920. It is a 4.1 m tall Calvary cross in Portland Stone. It stands on a square of concrete and has a square base. Above this there is a three-stage plinth: the lowest stage is square on plan, supporting the octagonal middle and upper stages. A carved wreath marks the transition between the middle and upper stages. The cross shaft is octagonal in section with an incised floral design on the east and west sides. The hooded cross-head, rising from a moulded collar, bears the carved figure of Christ crucified.	Modern	TF5005565024
1267668	Grade II listed building	Burgh House	House. Early C18, altered c.1830. Red brick with painted stucco dressings. Slate roof with overhanging bracketed wooden eaves and 2 hip stacks. 3 storeys, 5 bay front with first and second floor flat bands. Central doorway with porch with C19 open pediment. 2 long glazing bar sashes on each side of the doorway with possible remnants above of blinds. 5 glazing bar sashes above and 3 smaller glazing bar sashes above them. All the windows with painted wedge lintels.	Post-medieval	TF5004565040
1222674	Grade II listed building	Lych Gate	Lychgate. 1899. Wood and ashlar. Bell canted hipped plain tile roof with ashlar ridge and small gablets inscribed: '1899'; sprocketed eaves and wrought iron cross finial. 2 parallel, low chamfered, ashlar walls with wooden, iron-spiked gates. Walls topped with open wooden framework with curved braces, supporting roof.	Post-medieval	TF 50049 65019
1204980	Grade II listed building	The Rectory	Rectory. Mid C18 with early C19 alterations, extension and alterations by Bejamin Broadbent in 1856 and James Fowler 1875. Red brick in Flemish bond, Farlesthorpe yellow brick, slate roof. Single axial brick stack with moulded top. 2 storey with garret, 3 bay front having plinth and eaves band, central panelled door with plain fanlight in Cl9 Farlesthorpe brick added porch with flat roof.	Post-medieval	TF 47319 71869

NHLE No.	Designation and Grade	Name	Description	Period	NGR
1267571	Grade II listed building	The Little House	Shop with accommodation, now cottage. Late C18, C20. Red brick. Steeply pitched hipped roof with single central ridge stack. 2 storeys, 2 bay front with doorway integrated with small shop front to left. Doorway with panelled door, to right; fixed shop window with glazing bars to left, with continuous entablature above and segmental relieving arch. Single glazing bar sash to right. 2 glazing bar casements above. All the windows with segmental heads.	Post-medieval	TF 50035 65027
1062032	Grade II listed building	The Old Windmill	Former public house, now house. Early CI9 with minor C20 alterations. Red brick in Flemish bond, concrete tiled roof, brick coped gables, 2 gable and single ridge stacks. 2 storey, 3 bay front having off-centre planked door with margin light, to left a single and to right a pair of glazing bar sashes. To first floor 3 glazing bar sashes. All openings have brick segmental heads. To rear a catslide roof.	Post-medieval	TF 29112 40175
1317352	Grade II listed building	Milestone Near Junction With Fenhouses Drove	Milestone. Early C19. Painted ashlar. Square plan with pyramidal top. Inscribed "Boston 5 miles, Sleaford 13 miles."	Post-medieval	TF2559141854
1307173	Grade II listed building	Church Of St Peter	Parish church. 1821. Probably by Jeptha Pacey. Red and yellow brick, painted ashlar dressings. Slate roof with wide eaves overhang. Moulded cornice forming open pediments in the gables. Clasping pilaster strips, further pilaster strips defining the bays of the north and south sides. Shallow plinth. Nave and chancel under the same roof.	Post-medieval	TF 31570 50781
1360482	Grade II listed building	Pigeoncote At Dovecote Farm	Pigeoncote. Early C19. Painted brickwork, conical slate roof topped by a square wooden turret containing 8 small arched flight holes to each side, pyramidal slate roof. Circular plan. 2 storey with brick dogtoothed eaves. Single planked opening to ground floor. Blocked openings to upper floors.	Post-medieval	TF 29473 44797
1147909	Grade II listed building	Carrington House	House. Early C19. Red brick, some ashlar. Hipped slate roof with bracketed eaves. 2 lateral red brick stacks. Corner pilaster strips. Ashlar plinth. First floor sill band. 2 storeys, 3 bays. The central bay slightly projects. Central doorway, with panelled door, decorative overlight, reveal and reeded surround with paterae. Open porch with fluted Doric columns, entablature with triglyphs and guttae. Either side are single C20 glazing bar sashes with 3 similar smaller sashes above, all with flush wedge brick lintels.	Post-medieval	TF 31034 55056
1359287	Grade II listed building	Traphouse To Woodlands Farm House	Traphouse. Late C18. Red brick in Flemish bond, corrugated asbestos roof. Tumbled raised gables. brick dentillated eaves to sides. Basket arch with double doors. Circular light over. To the side an external flight of steps to upper floor.	Post-medieval	TF2527332512
1166294	Grade II listed building	Woodlands Farm House	House. Late C18, extended and altered early C19. Red brick in Flemish bond, ashlar dressings, Westmorland slate roof, stone coped tumbled gables, 2 brick gable stacks. L-plan. 3 storeys, 5 bay front with plinth and moulded ashlar cornice and parapet.	Post-medieval	TF 25270 32498
1064464	Grade II listed building	Bank House	Former house, now Old People's Home. c.1830, minor C20 alterations. Stucco, hipped Welsh slate roof, 2 wall and 2 ridge yellow brick stacks. 2 storey, 5 bay front with plinth, overhanging paired bracketed eaves and pilasters, and the central bay is slightly advanced and separately gabled.	Post-medieval	TF2531732215
1223034	Grade II listed building	Hanson's Windmill	Towermill. 1855. Tarred red brick. Corrugated roof with moulded eaves. 5 storeys. East side with doorway with cambered head and double plank doors. 2 window openings above, one above the other. South and north sides each with 3 window openings one above the other. West side with 2	Post-medieval	TF 49796 65062

NHLE No.	Designation and Grade	Name	Description	Period	NGR
			window openings one above the other. All the windows with segmental heads. Most of the machinery removed in 1964 and taken to Brixton Mill in London. Flour dresser remains inside.		
1308671	Grade II listed building	Granary To Bresby House	Granary. c.1831. Red brick, hipped pantile roof. 2 storey, 5 bay front with dogtooth eaves. Planked door with plain tympanum and semi-circular head, flanked by single blocked semi-circular headed openings. To left a further planked door and similar blocked opening. To first floor a planked door with segmental brick head with to left a single and to right 3 semi-circular openings with Y tracery timber mullions. All openings have ashlar keyblocks.	Post-medieval	TF2481633378
1359280	Grade II listed building	Bresby House	Farmhouse. Mid C18, refronted c.1830. White brick front with painted stucco dressings, slate roof, stone coped gables, 2 gable stacks. L-plan. 2 storey, 5 bay front, with slightly advanced entry bay containing 6 panel door with traceried fanlight, panelled reveals, semi-circular head, small Doric portico with flat lead roof, flanked by pairs of glazing bar sashes. To first floor 5 glazing bar sashes.	Post-medieval	TF2479933334
1359721	Grade II listed building	Church Of St Paul	Parish church. 1816, probably by Jeptha Pacey, 1872. Red brick with yellow brick dressings to chancel, painted ashlar dressings. Slate roofs. Wide eaves overhang being bracketed to the nave and forming open pediments at the east and west ends. Chancel with dogtooth eaves. Pilaster strips to the nave, defining the bays. Nave, north vestry, and chancel.	Post-medieval	TF 31141 55241
1308385	Grade II listed building	Bridge Over Lade Bank Drain Number 2	Bridge. c.1805. Probably by John Rennie. Red brick with gritstone capping. Single span. Deep elliptical arch, brick band, battered curved sides, parapet rebuilt C19, curves to end piers. Cast iron plate bearing raised number 2 in centre of arch. One of a number of similar bridges, laid out by John Rennie when the Fens were drained.	Post-medieval	TF 39653 54657
1413112	Grade II listed building	War Memorial, Carrington	Unveiled in April 1920. Built of Portland stone the memorial takes the form of a Latin cross, 15 foot tall with a downturned sword fixed to the centre of the shaft. The cross stands on a tapered stepped base and plinth.	Modern	TF3107355305
1168240	Grade II listed building	Memorial Clock Tower	Memorial clock tower. 1914-19. Ashlar. 2 rectangular steps surmounted by a smaller rectangular plinth with shaped plaque to the south side and moulded band over. Topped with tapering rectangular column with shaped plaque to the south side and shaped recessed panels to the remaining sides. Decorated band over surmounted by rectangular block with single clock face to each side apart from the north. The cap with small gable to each face.	Modern	TF 35735 60184
1454311	Grade II listed building	Sutterton War Memorial	First World War memorial, 1920, with Second World War additions. It takes the form of a tall, white granite pillar with a two-tiered pyramidal top surmounting a square capital with a deeply moulded cornice underneath. The pillar terminates in a moulded, square block foot upon a chamfered, square base. The inscriptions and names are in incised lettering, painted gold, to arched panels of red Aberdeen granite affixed to the pillar.	Modern	TF2852235292
1223940	Grade II listed building	Thorpe Farmhouse	Farmhouse with attached bakehouse, now storeroom, c.1670, mid C18, c.1820, C20. Stock brick, red brick. Slate roofs with brick coped gables with kneelers; single large ridge stack, single projecting gable stack. L-plan plus 2 storey porch in re- entrant angle, and projecting staircase bay to rear, with C20 covered passage leading to attached mid C18 bakehouse. Plinth. 2 storeys with garret, 4 bay west front encased in stock brick and remodelled in C19.	Post-medieval	TF5030060423

NHLE No.	Designation and Grade	Name	Description	Period	NGR
165368	Grade II listed building	Swineshead Abbey	House, on the site of a former Cistercian Abbey, built in 1607 for Sir John Lockton, reusing abbey remains. Altered early C19 and C20. Coursed and squared limestone rubble, lined stucco, hipped slate roof, limestone rendered ridge and wall stacks, and brick gable stack. L-plan. Garden front of 2 storey plus attics, 5 irregular bays, with tall plinth, ashlar first floor band and moulded wooden eaves board, off-centre recessed C20 half glazed door in contemporary wooden surround, with to right a single and to left 3 glazing bar sashes with splayed ashlar lintels and keystones. To first floor are 4 similar windows.	Post-medieval	TF 24945 40722
1063618	Grade II listed building	Field House	Cottage. c.1800. Red brick. English garden wall bond of 3. Coped tumbled gables, pantile roof, single gable stack. Brick dentillated eaves. Single storey and garret, 2 bay front. Planked doorway covered by C20 glazed and timber porch. To left a 2 light casement. To the garret a single similar window.	Post-medieval	TF 51670 73933
1360519	Grade II listed building	Mile Post South Of Old Junction With A52	Milepost. Mid C19. Cast iron. Triangular plan with square base. In raised cast letters on the sides, "Sleaford 13 miles, Holbeach 13 miles", also "Howden Iron, Boston" and an illegible date on the top and "Swineshead" on the base.	Post-medieval	TF 24204 38813
062036	Grade II listed building	Bridge To Hunston House Farmhouse	Access bridge. c.1796. Red brick with gritstone cappings. Single span. Narrow semi-circular headed brick arch. Brick band. Tightly curved parapets to square end piers.	Post-medieval	TF 38601 53616
360500	Grade II listed building	Hunston House	House. 1796, altered c.1844. Red brick, front in lined stucco, slate roof, stone coped gables, 2 yellow brick gable stacks. L- plan. 2 storey plus attics, 3 bay front having C20 door covered by C19 canted porch, flanked by single C19 lead roofed canted bays with plain sashes. To first floor the central bay is advanced and separately gabled with moulded kneelers. Central plain sash, flanked by single glazing bar sashes.	Post-medieval	TF 38611 53622
062053	Grade II listed building	West End Farmhouse	Farmhouse. Mid C18. Red brick in Flemish bond, pantile roof with brick coped gables and kneelers, 3 gable stacks. L-plan. 2 storey, 5 bay front with first floor band and corbelled out eaves. Central half glazed door with overlight is flanked by pairs of plain sashes. All ground floor openings have brick segmental heads. To first floor are 3 further sashes to eaves, the end windows set centrally over the ground floor pair. To the left is a single storey service bay, also brick coped, with 2 plain sashes.	Post-medieval	TF 30042 41404
317365	Grade II listed building	Thatched Cottage	Cottage. Late C17, altered C20, painted brick, thatched roof, single ridge and gable red brick stacks. Lobby entry, 2 unit plan, with added parlour and service block. Single storey plus attics, 3 bay front, the left hand end bay recessed. Off-centre C20 door covered by open rustic thatched porch, with to right a single and to left a pair of 2 light casements with segmental heads. To the roof 2 two light casement thatched dormers.		TF 28187 35648
1147238	Grade II listed building	Cross In Churchyard, South Side	Cross. C14 with addition of 1895. Ashlar. Square base supports octagonal shaft via stop chamfers, with C19 gabled crucifix.	Medieval	TF 51161 76405
1061992	Grade II listed building	Lodge	Former gate lodge and walls. Early C19, altered C20. In Cottage ornee style. Painted brick, conical plain tiled roof with central circular dentillated stack. Kidney shaped plan with small lean-to at rear, altered C20. Single storey plus attics, 5 bay front around the perimeter, with step out between third and fourth bays, dogtoothed eaves course. 3 pointed openings with 2 light casements, blocked pointed door to left, and round headed window to right.		TF 28543 35424

NHLE No.	Designation and Grade	Name	Description	Period	NGR
1063616	Grade II listed building	Somerleyton Cottage	Farm cottage. Early C19. Red brick in Flemish bond, some whitewashed. Pantile roof with brick coped tumbled gables, single brick gable stacks. Lower rear wing also with gable stack. 2 storey, 2 bay front with brick dentillated eaves, off- centre planked door with to right a margin light sash, both with segmental brick heads. To first floor 2 similar windows with flat heads.		TF 53392 70641
1223754	Grade II listed building	Primrose Farmhouse	Farmhouse. Mid C18, mid C19, C20. Red brick, some render. Pantile roofs, steeply pitched rear roof with coped and tumbled gable, single ridge stacks on front and rear ranges, and single lateral stack to rear. T-plan. Rendered south front of 2 storeys, 3 bays, rendered and with lobby entrance. Central doorway with partially glazed door. Doorway flanked by single glazing bar sashes. All the ground floor openings with segmental heads. 3 plain sashes above. Rear range with single storey and attic. Doorway to left with plank door; single glazing bar sash to right; both with segmental heads. Single C20 dormer above, with segmental head.	Post-medieval	TF5003460246
1317371	Grade II listed building	Outbuildings To Georgian House	Outbuildings. C18. Red brick with raised brick coped gables and pantile roof. Single storey, blank front. In the gable end a planked doorway and glazing bar window both with segmental brick heads.	Post-medieval	TF 28508 35494
1204994	Grade II listed building	Hogsbeck House	House, now divided into 2 houses. 1796. Red brick in Flemish bond, concrete tile roof with ashlar kneelers, 2 brick gable stacks. Double depth central entrance plan; Three storey, three bay front, plinth, first floor band. Central 8 panel door covered by a possibly later Doric fluted porch, flanked by tripartite glazing bar sashes with segmental ribbed brick heads. To first floor similar window to left, one to right with raised cill and plain casements, flank a tall narrow semi-circular headed stair window with 21 panes. Above is a datestone "GW1796".	Post-medieval	TF 48151 70959
1062085	Grade II listed building	Anton's Gowt Lock	Pound-lock on the Fen drains. 1802-12 by John Rennie. Altered 1848 when GNR Lincolnshire loop line was constructed. Ashlar, some wood and iron. Lock with two gates, battered pecked gritstone ashlar side walls having wide curved gate rebates. Two sets of massive wood and iron lock gates.	Post-medieval	TF3002247453
1061991	Grade II listed building	The Georgian House	House. Early C18, altered C20. Red brick in Flemish bond, concrete tiled roof, 2 gable stacks. 2 storey and attics, 5 bay front with first floor band and central half glazed door, flanked by pairs of glazing bar sashes. To first floor 5 similar windows all with brick segmental heads. in the roof 2 C20 dormer windows with painted tin cheeks and roofs.	Post-medieval	TF 28507 35508
1204890	Grade II listed building	Cottage Farmhouse	Farmhouse. c.1840. Red brick, pantile roof. Single gable brick stack. 2 storey,2 bay front having 4 panel door with to left a glazing bar sash. To first floor a single similar window. All openings have brick cambered heads.	Post-medieval	TF 54332 69362
1168251	Grade II listed building	Stickney Mill, Occupied By Mill Head Engineering	Tower windmill now store. 1842. Tarred red brick. Embattled parapet, rebuilt at a later date. 5 storeys. The west side with single glazing bar casement and 4 Yorkshire sashes above, one over the other, all windows with segmental arches. Over the second floor opening is a plaque inscribed 'W.B. 1842'. The south and north sides with single similar sashes and the east side with 4 similar sashes, one over the other. No milling machinery survives internally.		TF 34548 56877
1307179	Grade II listed building	Milestone Beside Wortley's Lane	Milestone. Early C19. Painted ashlar. Square post with pyramidal top, inscribed "Sleaford 16 miles, Boston 2 miles".	Post-medieval	TF3013743046

NHLE No.	Designation and Grade	Name	Description	Period	NGR
1224402	Grade II listed building	Wainfleet Bank	Primitive Methodist Chapel. 1838. Red brick. Hipped pantile roof with decorative eaves. Single storey. South end with semi- circular headed doorway with traceried fanlight and partially glazed door. Plaque above inscribed: "Primitive Methodist Chapel. 1838".	Post-medieval	TF 47090 59199
1308374	Grade II listed building	Bridge Number 10 (Station Bridge)	Bridge. c.1805. Probably by John Rennie. Red brick, with gritstone coping. Single span, elliptical brick arch, brick band, central panel recessed, curved parapet to end piers. In the centre of the arch a cast iron plate bears the number in raised letters. One of a series of bridges on the Hobhole Drain, laid out by John Rennie when the Fens were drained.	Post-medieval	TF 37507 52665
1063619	Grade II listed building	Manor Farmhouse	Farmhouse. c.1660, altered and extended c.1830, C19, C20. Red brick in English bond, pantile roof with steeply pitched, raised brick coped tumbled gables and moulded kneelers. 2 gable stacks with moulded tops and central vertical strips. Single narrower ridge stack. 2 storey with garret, 4 bay front, having plinth, first floor band.	Post-medieval	TF 49092 67178
1168237	Grade II listed building	Pixie Dale	Cottage. Mid C18. Mud and stud encased in colourwashed red brick. Half hipped thatched roof. Single central ridge red brick stack. Lobby entry plan. single storey plus garret, 3 bays. Central doorway with plank door. Either side are single glazing bar Yorkshire sashes. All openings are under flat heads with wooden lintels.	Post-medieval	TF 35406 60298
1308586	Grade II listed building	Warehouse At Huttoft Mill	Mill warehouse. 1872. T. Wilson and E. Wheatcroft, engineers. Red brick with yellow brick dressings. Hipped slate roof. 4 storeys, 2 bay front, having string courses, rusticated quoins and decorated eaves in yellow brick. Central planked double doors flanked by single glazing bar sashes. To first and second floors are 2 blank openings and to third floor are 2 smaller openings, also blank. All openings have yellow brick keyed arched heads with imposts. Above the door is a rectangular stone plaque inscribed "1872 T. Wilson, E. Wheatcroft, engineer".	Post-medieval	TF 51360 76626
1165317	Grade II listed building	Milestone By Struggs Hill	Milestone. Early C19. Limestone, ashlar. Square post with pyramidal top inscribed on sides "Boston 5 miles, Spalding 11 miles, London 111 miles and Sutterton".	Post-medieval	TF 29270 37207
1166255	Grade II listed building	Traphouse And Pigeoncote To Wykes Manor Farm	Former traphouse, stables, granary and pigeoncote, now garage and store. 1810, altered C20. Red brick in English bond, pantile roof, raised brick coped tumbled gables with gable stack to left. Traphouse and stables to ground floor, granary and pigeoncote to first floor. Two storey, five bay front with brick dentillated eaves.	Post-medieval	TF2317835410
1063008	Grade II listed building	Huttoft Mill	Tower mill. Early C19 with C20 alterations. Black bitumen painted brick. 5 storeys with C20 castellated parapet and C20 juggernaut weather vane. Double planked doors with single fixed C20 lights to first, third and fourth storey, and on the second floor a C20 planked door opens onto a wooden gallery with C20 wrought iron railings.	Post-medieval	TF 51371 76657
1433521	Grade II listed building	Stickney War Memorial	First World War memorial, 1920, with later additions for the Second World War. It is constructed of local Weldon stone in the form of a spired obelisk with a Celtic cross on the top.		TF3434157010
1062043	Grade II listed building	South Cottage, Village Hall And Church View Cottage And Garden Wall	Formerly schoolmasters' houses and school, now 2 cottages and Village Hall, and garden walls. By Sir G. G. Scott, patron Rev. B. Beridge, 1856. Squared, coursed limestone rubble with ashlar quoins and dressings,	Post-medieval	TF 29112 35167

NHLE No.	Designation and Grade	Name	Description	Period	NGR
			Westmoreland slate roof with stone coped gables, moulded kneelers. 2 shaped ridge stacks. E-plan, school in centre flanked by cottages. Single storey, 9 bay front, with chamfered plinth, centre bay is an advanced and gabled porch with spired bellcote.		
1360518	Grade II listed building	Struggs Hill Farmhouse	Farmhouse. c.1838 with later C19 additions. Red brick in Flemish bond, hipped slate roof, 2 brick wall stacks. 2 storey, 3 bay front with short plinth and slightly corbelled out eaves band and overhanging eaves. Central 6 panel door with fanlight set in recessed semi-circular headed opening, flanked by single glazing bar sashes with splayed flat rubbed brick arches. To first floor 3 similar windows. To right a later pent roofed extension and to the rear a further hipped roofed wing.	Post-medieval	TF 29360 37198
1317357	Grade II listed building	Chapel House	Former Baptist Chapel, now house. Rebuilt 1826, altered C20. Red brick in Flemish bond, hipped concrete tile roof on double bracketed overhanging eaves. 2 storey, 3 bay front with central 8 panel door and plain fanlight set in pilastered doorcase with dentillated open pediment, flanked by single tall semi-circular headed glazing bar sashes with Gothick heads to the lights.	Post-medieval	TF 28641 36088
1063530	Grade II listed building	The Windmill	Tower windmill. Mid C19, raised late C19. Red brick with faded colourwash to the base, some black brick. Concrete top with chain railings extending the circumference. Moulded eaves band of black brick headers. 4 storeys including the top late C19 storey. East side has a single segmental arched window opening with a single similar blocked opening above. North side with 2 similar openings, the upper glazed and with glazing bars.	Post-medieval	TF 35193 51440
062033	Grade II listed building	Milestone (South Of Tudor Lodge)	Milestone. Early Cl9. Painted ashlar. Rectangular pillar with facetted head inscribed "London 188 miles, Boston 6 miles, Spalding 10 miles and Sutterton".	Post-medieval	TF 28555 35880
1062050	Grade II listed building	Bowles Farmhouse	Cottage. Late C18. Red brick in Flemish bond, pantile roof, one brick coped gable, 2 gable stacks. Single storey plus attics, 3 bay front with central half glazed door flanked by single plain sashes. All openings have brick segmental heads. In the roof are 2 raking dormers with plain sashes, slate roof and cheeks. To the rear a catslide roof.	Post-medieval	TF 24579 43992
1147659	Grade II listed building	Church Of St Michael	Private chapel to Tunnard family at Frampton House, now Chapel of Ease. 1863 by James Fowler. In Geometric Decorated style. Rock faced limestone ashlar, with plain ashlar dressings, plain tiled roof with decorative ridge tiles. Nave with western bellcote, facetted chancel, south porch and vestry.	Post-medieval	TF 30162 40527
165248	Grade II listed building	The Cottage	Cottage. Late C18 with C19 and C20 alterations. Red brick in English garden wall bond of 3. Pantile roof, brick coped gables, 2 gable brick stacks, one rebuilt C20. Single storey plus attics. 3 bay front having central C20 door flanked by 2 CI9 plain sashes. All openings have segmental brick heads. In the roof are 3 segmental headed dormers with casement windows, leaded cheeks and roofs.	Post-medieval	TF 29931 37917
1063652	Grade II listed building	Bede Cottages	Cottage, now a pair of cottages. Late C17, altered C18 and C19. Red brick with brick coped tumbled gables with kneelers, corrugated tin roof over original thatch, having axial brick stack. Single storey with garret, 4 bay front having 2 planked doors flanked by added brick buttresses and single 2 light sliding glazing bar sashes.	Post-medieval	TF 54720 69158

NHLE No.	Designation and Grade	Name	Description	Period	NGR
1215325	Grade II listed building	Pigeoncote At Waite Farm	Pigeoncote. Early C19. Red brick in Flemish bond. Low conical slate roof with leaded top. Circular plan. 2 storey, single bay front having planked door with segmental head and above a semi- circular headed opening with 3 tiers of wooden flight holes.	Post-medieval	TF 26635 52074
1224273	Grade II listed building	Crows Bridge Over Steeping River	Road bridge over drainage channel. c.1812, by John Rennie. Red brick with limestone ashlar dressings. Eliptical arch, slightly askew with brick band above. Ashlar coped curved brick parapet terminates in rectangular coped piers. The area was drained and enclosed by the engineer John Rennie, 1802-1812.	Post-medieval	TF 48157 59217
1147808	Grade II listed building	Washdyke Cottage	Cottage, Fen half house type. Early C19. Red brick in English garden wall bond of 3, pantile roof, brick coped partly tumbled gables, single brick gable stack. Single storey, single bay front, with margin light sash to both floors. To the right a blocked doorway. All openings have brick segmental heads.	Post-medieval	TF 39146 53238
1146640	Grade II listed building	Gosberton Baptist Church	Baptist church. Founded 1666, rebuilt C18, altered C20. Red brick in Flemish bond, pantile roof, brick coped gable. Single storey irregular 4 bay front, with 4 panel door, flanked by single glazing bar sashes, all with segmental brick heads.	Post-medieval	TF 24409 31334
1064466	Grade II listed building	Milestone Opposite Baptist Church	Milestone. Early C19. Ashlar, painted. On the sides inscribed "Boston 10, Spalding 5" and "Gosberton" on the top.	Post-medieval	TF2440731375
1062031	Grade II listed building	Old Vicarage	Former vicarage, now house. 1850. Red brick in Englishbond, hipped slate roof, overhanging eaves, 3 ridge stacks. 2 storey, 3 bay front, 4 bays on side. Central half glazed door flanked by single glazing bar sashes. To first floor are 3 glazing bar sashes.	Post-medieval	TF 30294 39018
1168173	Grade II listed building	Stable Block At Sibsey House	Stable block. Mid C18, altered early C19. Red brick. Hipped pantile roof. Dogtooth eaves. 2 storeys, 3 bays. The single central bay is early C19, slightly projects, is gabled and is 2 storeys plus attic. Central large basket arched doorway with plank double door and overlight. Either side are single round arched doorways each with plank door and plain fanlight. Above are 3 semi-circular fixed lights. In the attic is a small round arched doorway with plank door.	Post-medieval	TF 35204 51192
1063537	Grade II listed building	Shaw's Mill	Tower windmill. 1820. Red brick. Moulded brick eaves topped with remains of the cap frame. Band to top floor, broken by the openings. 3 storeys. Segmental arched doorway with plank door to the west, on the top floor is a single segmental arched 2 light casement.	Post-medieval	TF 34642 58866
1280940	Grade II listed building	Boothby Farmhouse	Farmhouse. Late C18. Red brick in English bond. Pantile roof with brick coped gables, 2 gable brick stacks. L-plan. 2 storey, 3 bay front with corbelled eaves band. Central planked door flanked by single glazing bar sashes now boarded. To first floor are 3 similar windows. All openings have segmental brick heads. To the rear a service wing with outshut to dairy.	Post-medieval	TF 48350 69193
1062016	Grade II listed building	Morley House	House. Late C18, altered C19 and 1919. Red brick in Flemish bond, slate roof, raised stone coped gables, 2 gable stacks. 'U' plan. 2 storey, 3 bay front having dentillated wooden cornice, with 3 tall glazing bar sashes, with flat rubbed brick arches, the central one with a key block. To first floor 3 similar shorter windows. to the right hand side a recessed entry bay has 6 panelled door with traceried fanlight, open pedimented and pilastered surround.	Post-medieval	TF 22698 37489

NHLE No.	Designation and Grade	Name	Description	Period	NGR
			Above a keyed oval recessed panel contains an ashlar lozenge with the date 1919. Originally 3 storey but reduced in 1919.		
1165295	Grade II listed building	Willington House	House. Early C18, altered C19 and C20. Red brick in Flemish bond, slate roof and 2 brick gable stacks. 2 storey plus attics, 5 bay front arranged 2:1:2, with plinth having ashlar coping, first floor band. Central C19 door with overlight with wooden pilasters, narrow lead hood on scrolled brackets, flanked by single canted bay windows with wooden pilasters, moulded cornices and flat lead roofs. To first floor are 5 margin light sashes all with cambered brick heads.	Post-medieval	TF 30332 38862
1062026	Grade II listed building	Gates To Number 96	Gate piers, gate and railings. c.1830. Cast iron. Pair of square openwork iron gate piers, rounded tops containing acanthi. The gate has baluster verticals, tulip finials and the stiles have open circles. To either side are splayed screens also with baluster uprights and terminating in wreathed ends. made by Tuxfords of Boston.	Post-medieval	TF 30191 38044
1147673	Grade II listed building	80 Yards Of Wall To Frampton House	Garden wall. Late C18. Brick with ashlar copings. 5'0" high wall, with castellated top. At the left hand end it terminates in a splayed re-entrant and at the right hand end in a square pier.	Post-medieval	TF 30230 39845
1063531	Grade II listed building	Sibsey House	House. Early C19. Red brick. Hipped slate roof. Bracketed and moulded eaves, single rear ridge red brick stack. Set on a plinth. 2 storeys, 3 bays. Central doorway with part glazed door, and either side are single glazing bar sashes. 3 similar sashes above.	Post-medieval	TF 35222 51157
1223035	Grade II listed building	Windmill	Tower mill. 1814, raised 1859, 1949. Tarred red brick with brick battlements. 4 storeys, raised to 7 storeys in 1859, but reduced to 4 storeys with battlements in 1949.	Post-medieval	TF5006859615
1063651	Grade II listed building	Addlethorpe House	House. Late C17, altered early C19 and C20. Red brick in Flemish bond with concrete tiled roof, having reduced tumbled gables, and single square panelled ridge stack with moulded top. L-plan. 2 storey plus garret, 3 bay front with plinth, moulded first floor band with double corbelled eaves cornice and gable bands.	Post-medieval	TF 54943 68977
1223036	Grade II listed building	Granary To East Of Tower Mill	Granary, now warehouse. c,1814. Red brick. Hipped pantile roof. 3 storeys, 2 bays with doorway to right with a plank door and segmental head. Single plain sash to left. 2 glazing bar sashes above with 2 shuttered openings above them. Single storey lean-to to left.	Post-medieval	TF5008059610
1062015	Grade II listed building	The Red Lion Inn	Public house. 1665, in Fen Artisan Mannerist style, altered C19 and C20. Red brick in English bond, rendered, with concrete tiled roof and 2 projecting gabled stacks. 2 storey plus garret, 3 bay front with plinth, rusticated quoins and gable bands, the centre bay advanced and gabled. Central bow window flanked by single 2 light glazing bar casements and also to left a C20 planked door. To first floor are 3 similar windows, all openings have segmental heads.	Post-medieval	TF 22648 37419
1165228	Grade II listed building	96, London Road	Lodge. c.1830, extended late C19. Yellow brick with hipped slate roof with lead dressings, central panelled ridge stack; cast iron railings and supports. Single storey, 3 bay front, 2 bay sides with central blocked doorway, flanked by single 3 light casements. To the sides are 2 similar windows.	Post-medieval	TF 30205 38024

NHLE No.	Designation and Grade	Name	Description	Period	NGR
1168177	Grade II listed building	Summerhouse Or Gazebo At Sibsey House	Summerhouse. C15, C19. Ashlar and red brick. Roof not visible. Single storey, single bay. South side with pointed arched doorway, plank door and C19 hood mould with decorative label stops. To the right and set higher is a C15 gargoyle. East wall with single C15 arched window with 3 cusped lights and panel tracery, west wall with inverted window with cusped reticulated tracery. Probably built of materials from parish church during the restorations of 1855.	Medieval	TF 35218 51136
1450436	Grade II listed building	Wainfleet St Mary War Memorial Cross	First World War memorial, unveiled 1920, with later additions for the Second World War. t is a 4.3 m high stone Calvary cross in the style of a traditional Lincolnshire wayside cross.	Modern	TF4715758611
1359718	Grade II listed building	The Lilacs	Mid C18. Red brick in Flemish bond, pantile roof, brick coped tumbled gables, 2 gable stacks. L-plan. Central C20 6 panel door plus overlight, C19 stone surround with bracketed hood, flanked by single glazing bar sashes. To first floor 3 glazing bar sashes.	Post-medieval	TF 40591 62984
1359708	Grade II listed building	Saracen's Head	Public house. Early C18, altered early C19 and C20. Rendered and colourwashed, pantile roof, brick coped gables, 2 rendered gable stacks. 2 storey, 3 bay front with first floor band. Central C20 door flanked by single tripartite plain sashes. To first floor are 3 glazing bar sashes.	Post-medieval	TF 53446 72248
1062018	Grade II listed building	Morley Cottages	House, later converted to pair of cottages. C16, possibly incorporating earlier core, altered C18, C19. Timber frame, mud and stud, coursed limestone rubble, red brick and render. Pantile roof with one raised coped gable and one half hip, originally over thatch. Single axial ridge and gable stacks. Originally lobby entry plan. 2 storey, 5 bay front.	Post-medieval	TF 22617 37511
1063617	Grade II listed building	28, South End	House. 1774 with mid C19 alterations. Red brick in English garden wall bond of 2. Pantile roof with brick coped tumbled gables and kneelers, 2 brick gable stacks. 2 storey, 3 bay front with central half glazed C19 door and plain overlight, flanked by single plain sashes. The keystone over the door is inscribed WM 1774. To first floor 3 similar windows. All openings have segmental brick heads.	Post-medieval	TF 53480 71969
062025	Grade II listed building	Kirton House	Former house, now office. Early C19. Red brick in Flemish bond with Westmoreland slate roof, stone coped gables, 2 gable brick stacks. L-plan. 3 storey, 3 bay front with plinth and dentillated wooden eaves cornice. Central 6 panel door with pointed Gothick fanlight, wooden panelled reveals, open pedimented wooden doorcase, flanked by single canted bay windows with flat lead roofs, and pilasters to angles. To first floor 3 plain sashes and to second floor 3 smaller similar windows.	Post-medieval	TF 30296 38089
232862	Grade II listed building	The Chestnuts	House. Late C18, altered C19 and C20. Red brick in Flemish bond, concrete pantiled roof, brick coped gables, 2 gable stacks. 2 storey, 3 bay front with central C20 6 panel door, plain overlight, flanked by single tripartite plain sashes. To first floor are 3 similar windows. All openings have cambered rubbed brick arched heads. To rear a catslide roof to outshot.	Post-medieval	TF 23898 39840
416760	Grade II listed building	Cottage To Rear Of Kirkby House	Cottage. 1690, with early-19 th century addition and later alterations. Mud and stud on a brick plinth with a thatched roof covered in corrugated iron sheeting. Single storey. Brick chimney stack with owl-hole and ledge. Main entrance front has slightly off-centre doorway flanked by single irregularly	Post-medieval	TF3469758008

NHLE No.	Designation and Grade	Name	Description	Period	NGR
			spaced two-light casement windows, with beyond to left a small shuttered opening.		
1062035	Grade II listed building	Bridge Number 9	Bridge. c.1805. Probably by John Rennie. Red brick, with gritstone coping. Single span, elliptical brick arch, brick band, central panel recessed, curved parapet to end piers. In the centre of the arch a cast iron plate bears the number in raised letters. One of a series of bridges on the Hobhole Drain, laid out by John Rennie when the Fens were drained.	Post-medieval	TF 37306 51957
1317387	Grade II listed building	9 And 11, Willington Road	Almshouses, formerly 4 now 2. Founded by Robert Hunt in 1664, altered C19 and C20. Red brick with pantile roof and 2 brick gable stacks. Single storey, 6 bay front with plinth. At each end are planked doors with 4 glazing bar sash windows and 2 further blocked openings in the middle. All openings have segmental brick heads. An ashlar datestone with initials RHA and date of 1664.	Post-medieval	TF 30436 38604
1317400	Grade II listed building	Milestone In Centre Of Village	Milestone. Early C19. Painted ashlar. Square pillar with pyramidal top inscribed "Boston 4 miles, London 112 miles, 12 miles Spalding and Kirton".	Post-medieval	TF 30411 38327
1267659	Grade II listed building	Manor Farmhouse	Farmhouse. Mid C18, late C19. Colourwashed red brick. Pantile roof with gable stacks. 2 storeys and attic, 3 bay front with plinth and first floor band. Central doorway in C19 porch with stepped gable and semi-circular headed doorway; inner partially glazed door. Doorway flanked by single glazing bar sashes. 3 narrower glazing bar sashes above. 3 dormers above with segmental heads and glazing bar sashes.	Post-medieval	TF 47287 64940
1165050	Grade II listed building	The Villa	House. c.1800. Red brick in English bond with painted ashlar dressings, slate roof with 2 brick gable stacks. 2 storey, 3 bay front with central 6 panel door with fanlight, set in recessed- semi-circular headed brick surround with painted ashlar key and impost blocks, flanked by single glazing bar sashes. To first floor 3 similar windows. All windows have brick segmental heads. Interior retains shutters, stick baluster stair with ramped handrail.	Post-medieval	TF 22544 37510
1063625	Grade II listed building	Boothby Hall	Small country house. c.1700, c.1770, extended c.1830, altered late C19. Buff orange brick, red brick dressings, early C19 hipped slate roof with deeply overhanging eaves, moulded baluster brackets. 2 storey, 5 bay front with plinth and first floor band.	Post-medieval	TF 48514 68628
1168924	Grade II listed building	Gates And Piers To Well Vale Park	Gate piers c1730. Ashlar. Two ashlar gate piers in the form of obelisks with fluted circular bases with lions heads. Pineapple knops and on the sides human head masks with dependant foliage and moulded shells. The gate piers formerly stood in the forecourt to Well Hall and were moved in the late C20 to near to the kitchen garden entrance, and again in around 2004 to their present location.	Post-medieval	TF4490073797
1267660	Grade II listed building	Stable Block At Manor Farmhouse	Stable block. 1825. Red brick. Hipped pantile roof. Single storey, 6 bay front. Doorway to left with basket arch and plank door. Single semi-circular window beyond with pivitol glazing bar casement. 2 similar windows to right of doorway with stone set in between inscribed "P.M, 1825". Doorway beyond with basket arch and double stable doors. Semi-circular window to right with pivitol glazing bar casement.	Post-medieval	TF 47261 64941
1448483	Grade II listed building	Bicker War Memorial	First World War memorial cross, unveiled 1920, with later additions. It is a stone monument in the style of a traditional Lincolnshire wayside cross, with	Modern	TF2258937687

NHLE No.	Designation and Grade	Name	Description	Period	NGR
			a square, three-stepped base. Polished granite plaques are fixed to the uppermost block.		
063002	Grade II listed building	Wexham Farm	Farmhouse. c.1800 with C19 alterations and additions. Red brick in English garden wall bond of 3, with plain stucco dressings. Pantile roof with brick coped partly tumbled gables and 2 gable stacks. T-plan, the rear range is a C19 addition. 2 storey, 3 bay front.	Post-medieval	TF 52131 75357
222666	Grade II listed building	Barn At Manor Farmhouse	Threshing barn. c.1830. Red brick. Hipped pantile roof. Single storey, 3 bay front with rounded corners. Single opening with basket arch and double plank doors.	Post-medieval	TF 47259 64961
224572	Grade II listed building	K6 Telephone Kiosk	Telephone kiosk. Type K6. Designed 1935 by Sir Giles Gilbert Scott. Made by various contractors. Cast iron. Square kiosk with domed roof. Unperforated crowns to top panels and margin glazing to windows and door.	Modern	TF 47491 65004
165134	Grade II listed building	Churchyard Cross, In Churchyard Of Church Of St Peter And St Paul	Churchyard cross. C14, altered C18. Limestone ashlar and wrought iron. Weathered square base supports lower section of cross with stop chamfered angles. A circular iron plate has been fixed to the top supporting a metal spike with 2 twists.	Medieval	TF 30479 38511
063567	Grade II listed building	The Cottage About 300 M East Of Carrington County Primary School	Cottage. Mid C18, some C20 alterations. Colourwashed brick encasing mud and stud. Half hipped pantile roof. Single central red brick ridge stack. Dentil eaves. Lobby entry plan. Single storey, 3 bays. Central doorway with plank door. Either side are single C20 Yorkshire sashes. All openings with wooden lintels. To the right is a lean-to with hipped roof and single fixed light.	Post-medieval	TF 31293 56376
317419	Grade II listed building	Gravestone 7 Paces From South Porch In Churchyard, Church Of St Peter And St Paul	Gravestone. 1815. Ashlar. To Anthony Parker. Cambered head with cut away corners. On the upper part are allegorical carvings of broken obelisk and spire with resurrection scene. Inscription panel below.	Post-Medieval	TF 30506 38510
359682	Grade II listed building	Addlethorpe Mill	Tower mill. c.1830. Red brick, tarred, tapering 6 stage tower with corbelled eaves, cap missing. Planked double doors above which are single openings to each side, planked and fixed glazing bar lights. Interior retains lower part of upright shaft with spur wheel, gearing and fittings to 2 pairs of grey stones, with kibbler, engine and drive shafts. The tower mill was built to replace a post mill.	Post-medieval	TF 55115 67623
360496	Grade II listed building	Churchyard Wall And Mounting Steps, On South And West Sides, Church Of St Peter And St Paul	Churchyard wall and mounting steps. C18. Red brick in English garden wall bond, with ashlar coping. 3 mounting steps on churchyard side.	Post-medieval	TF 30524 38496
1360498	Grade II listed building	30, London Road	House. Mid C18, altered C19. Red brick in Flemish bond, Westmoreland slate roof. with stone coped tumbled gables and 2 C20 gable brick stacks. L- plan with single storey rear service wing. 2 storey, 5 bay front arranged 2:1:2, with short plinth, first floor band and dentillated wooden eaves course. Central 6 panelled door with panelled reveals having pedimented Doric doorcase, flanked by pairs of plain sashes with brick segmental heads. To first floor are 5 similar windows.	Post-medieval	TF 30524 38447
062047	Grade II listed building	Manor House	House. Mid C17, altered C19, and extended C19 and C20. Red brick in Fen Artisan Mannerist style, pantile roof, 2 gable stacks. T-plan with projecting 2 storied porch. 2 storey, 3 bay front, with tall plinth, first floor band,	Post-medieval	TF 30038 34279

NHLE No.	Designation and Grade	Name	Description	Period	NGR
			dogtoothed eaves. The separately gabled central porch has rusticated quoins and decorative corbels.		
1062023	Grade II listed building	The Old King's Head	Former public house, now house. Early C16, 1599, cross wing 1661, major alterations in Fen Artisan Mannerist style, with C19 and C20 alterations. Red brick in English bond, ashlar dressings and stucco, with pantile roof over thatch. Raised brick coped gables with corbelled out kneelers, single axial triple stack with diagonally set shafts with dentillated tops. T-plan, of hall block with gabled cross wing of 1599. Originally Lobby entry. 2 storey with garret, 5 bay front, the right hand bay advanced and gabled.	Post-medieval	TF 30540 38472
1165199	Grade II listed building	1, King Street	House. Mid C18. Altered early C19, C20. Red brick in Flemish bond, Welsh slate roof, brick coped gables with 2 C20 brick gable stacks. L-plan. 2 storey, 5 bay front arranged 2:1:2. First floor band. Central 6 panel door with traceried overlight, panelled reveals, pedimented door case with fluted architraves and angle paterae, flanked by pairs of glazing bar sashes with to first floor 5 similar windows all with flat rubbed brick arched heads.	Post-medieval	TF 30538 38426
1146816	Grade II listed building	Westfield Farmhouse	Cottage. Early C18, altered and extended C19. Mud and stud, underbuilt partly in brick, rendered, pantile roof, axial ridge stack. Lobby entry plan. L-plan, rear range added C19. Single storey plus garret, 3 bay front. Central planked door, flanked by single glazing bar sashes with segmental heads.	Post-medieval	TF 36597 61868
1064465	Grade II listed building	10-14, Mill Lane	Row of 3 houses. c.1830. Lined stucco, slate roof, 3 ridge stacks, overhanging bracketed eaves. Rusticated stucco quoins. 2 storey, 6 bay front arranged each house with a semi-circular headed doorway, panelled door and reveals, with semi-circular headed panels, radiating fanlight.	Post-medieval	TF 24120 31638
1454912	Grade II listed building	Gosberton War Memorial	First World War memorial designed by Sir Walter Tapper, unveiled 23 May 1920. Constructed in Clipsham Stone, the memorial comprises a lantern cross at the highest point of an octagonal tapering column.	Modern	TF2409831621
1165195	Grade II listed building	The Peacock	Public house. Mid C18 with C19 and C20 alterations. Red brick in Flemish bond, ground floor colourwashed, concrete tiled roof, 2 gable stacks. 2 storey, 5 bay front arranged 2:1:2, with first floor band. Central C20 door, plain overlight, flanked by pairs of plain sashes. To first floor 5 similar windows. All openings have segmental rubbed brick heads with key blocks.	V	TF 30597 38530
1222670	Grade II listed building	The Elms Farmhouse	Farmhouse Late C18, C20. Red brick. Pantile roof with brick coped gables and gable stacks. T-plan. 2 storeys, 3 bay front with plinth and central bay with giant order, recessed, blind, semi-circular headed arch. Central doorway with partially glazed door, flanked by single glazing bar sashes. Small fixed glazing bar window above doorway with similar small C20 window a little above to right. Outer bays with single glazing bar sashes. All the windows with segmental heads.	Post-medieval	TF 47610 65143
1360491	Grade II listed building	Gravestone And Tombstone 10 Paces From South Transept In Churchyard, Church Of St Swithin	Chest tomb and gravestone. Limestone ashlar. 1749 and 1761. Rectangular gravestone with segmental head. Scrolled cartouche with cherubs, to William Base d.1749, beneath the cartouche an epitaph. Chest tomb to John Spur, d. 1761, with side inscription panels, gadrooned corner pilasters; on the west end a semi- circular headed niche containing a carving of Christ Triumphant.	Post-medieval	TF 22462 37846
1266923	Grade II listed building	War Memorial Cemetery Gateway	War memorial gateway. c.1918. Limestone ashlar. Rectangular gateway with moulded semi-circular headed archway with scrolled keystone and moulded imposts. Archway flanked by pairs of columns at each side with foliate	Modern	TF4986359285

NHLE No.	Designation and Grade	Name	Description	Perie
			capitals, high plinths below and plaques inscribed with the names of the fallen in between.	
1439370	Grade II listed building	Kirton War Memorial	First World War memorial, by G Maile and Sons of London and unveiled on 12 November 1922, with further names added after the Second World War. It consists of an obelisk on a square plinth and seven-stepped base.	Mode
1062028	Grade II listed building	K6 Telephone Kiosk Near Harvey House	Telephone kiosk. Type K6. Designed 1935 by Sir Giles Gilbert Scott. Made by various contractors. Cast iron. Square kiosk with domed roof. Unperforated crowns to top panels and margin glazing to window and door.	Mode
1062029	Grade II listed building	Harvey House	House. c.1720-1730, altered C20. Red brick in English bond, plain tiled roof, 2 C20 brick gable stacks. L-plan. 2 storey, 5 bay front arranged 2:1:2, the central bay being advanced and separately gabled. First floor band and dentillated wooden eaves cornice. Central 6 panel door with wood panelled reveals, and C20 pedimented surround, flanked by pairs of glazing bar sashes. To first floor are 5 similar windows.	Post

NHLE No.	Designation and Grade	Name	Description	Period	NGR
			capitals, high plinths below and plaques inscribed with the names of the fallen in between.		
1439370	Grade II listed building	Kirton War Memorial	First World War memorial, by G Maile and Sons of London and unveiled on 12 November 1922, with further names added after the Second World War. It consists of an obelisk on a square plinth and seven-stepped base.	Modern	TF3062338557
1062028	Grade II listed building	K6 Telephone Kiosk Near Harvey House	Telephone kiosk. Type K6. Designed 1935 by Sir Giles Gilbert Scott. Made by various contractors. Cast iron. Square kiosk with domed roof. Unperforated crowns to top panels and margin glazing to window and door.	Modern	TF 30624 38548
1062029	Grade II listed building	Harvey House	House. c.1720-1730, altered C20. Red brick in English bond, plain tiled roof, 2 C20 brick gable stacks. L-plan. 2 storey, 5 bay front arranged 2:1:2, the central bay being advanced and separately gabled. First floor band and dentillated wooden eaves cornice. Central 6 panel door with wood panelled reveals, and C20 pedimented surround, flanked by pairs of glazing bar sashes. To first floor are 5 similar windows.	Post-medieval	TF 30644 38516
		of high value within the 3-5 km	•		
NHLE No.	Designation and Grade	Name	Description	Period	NGR
1009218	Scheduled monument	Butter cross, Swineshead	The remains of a market cross, which stands on the north side of a modern war memorial in the former market place. The cross is of stepped form, is medieval in date with later alterations. The monument includes the base, of three steps.	Medieval	TF 23788 40250
1014424	Scheduled monument	Churchyard cross, St Andrew's churchyard	Cross shaft. C14. Ashlar. Facetted base with pyramidal angles, supporting octagonal shaft via stop chamfers.	Medieval	TF 52346 75437
1010677	Scheduled monument	Churchyard cross, St Margaret's churchyard	The cross is medieval in date and is constructed of limestone. The monument includes the base of the cross and part of the shaft. The base is composed of two stones. The lower stone, which is partially buried, takes the form of a shallow plinth with a chamfer; it is approximately 0.8 m square in section and stands about 0.15 m above the present ground level. The upper stone is a socket stone, approximately 0.7 m square in section with chamfered upper corners, standing to a height of 0.28 m. The shaft fragment is set into the centre of the socket stone and is rectangular in section at the base rising through chamfered corners in tapering octagonal section to a height of about 0.45 m.	Medieval	TF 35447 50725
		Churchyard cross, St Peter's	The cross is medieval in date and is constructed of limestone. The monument	Medieval	TF 40380 63441
1013535	Scheduled monument	churchyard	includes the base of the cross and part of the shaft. C14. Ashlar. Square shaft rises via stop chamfers. Square base with carved angles.		
1013535 1013530; 1223766	Scheduled monument; Grade II* listed			Medieval	TF 49833 58958

NHLE No.	Designation and Grade	Name	Description	Period
			causeway about 2.5 m in width crosses the eastern side of the moat and represents the original access to the island. Brickwork visible within the southern edge of the causeway is considered to represent the remains of revetting	
1015769	Scheduled monument	Bowl barrow at Mill Hill Quarry, 350 m north west of Claxby church	The monument includes a Bronze Age burial mound situated on the eastern edge of Mill Hill Quarry, 350 m north west of Claxby church. The mound would originally have been a prominent feature in an open landscape. However, quarrying for chalk during the late 19th and early 20th centuries has cut a long ravine running south east to north west, and the barrow now occupies an overhanging ledge at the top of, and midway along, the north eastern face of this ravine. The circular barrow mound is c.15.7 m in diameter with a rounded profile and stands to a height of c.1.3 m.	Prehistoric
1014427	Scheduled monument	Churchyard cross, St Mary's churchyard, Winthorpe	The cross is medieval in origin with modern additions, all of limestone. The monument includes the base, comprising three steps and a socket stone, the shaft, knop and head.	Medieval
			The base includes three steps, all square in plan and composed of rectangular blocks held together by mortar. On the top step rests the socket stone, a single block of square section with a chamfered upper edge. On each side of the socket stone is carved a quatrefoil panel. The steps and socket stone are all of medieval date. Attached to the socket stone is a series of modern bronze plaques recording the restoration of the cross as a war memorial in 1920. Set into the socket stone with mortar is the lower part of the shaft, rectangular in section at the base and rising above moulded and chamfered corners in tapering octagonal section to a height of 0.93 m. This part of the shaft is also medieval. The remainder of the shaft, which brings it to a height of 1.91 m, is modern. The knop is octagonal in section and supports a small plinth on which stands a gabled cross of tapering octagonal section with openwork decoration between the arms; both the knop and head are modern. The full height of the cross is approximately 4.8 m.	
1004931; 1224243	Scheduled monument; Grade I listed	The Magdalen College School	School, now public library. 1484, restored 1585, 1608, 1755, 1856, C20. Red brick with some burnt brick diaper decoration and some limestone ashlar dressings. Lead roof hidden behind high ashlar coped parapets. 2 external stacks on the north wall, that to the right with 3 tall, ornate, polygonal C19 shafts; that to the left, of 2 similar shafts. Plinth runs round entire building. 2 storeys. West front with large octagonal 3 storey angle towers; that to the left, a staircase tower; that to the right, a bell tower. Towers with first floor moulded brick bands and second floor ashlar bands. Central pointed ashlar dressed doorway, restored in C19, with continuous moulded surround, hood mould and plank door.	Medieval
1019098	Scheduled monument	Decoy Wood decoy pond	The monument includes the buried and earthwork remains of a post-medieval decoy pond located in Decoy Wood. The water-filled pond is roughly star- shaped in plan, measuring approximately 80 m by 55 m, covering an area of about 0.4ha (1 acre). Six channels, known as pipes, curve outward in a clockwise direction, from the angles of the pond. Each pipe, measuring up to 80 m in length, narrows as it curves away from the pond, tapering to a point.	Post-medie
1017464	Scheduled monument	Neolithic long barrow 525 m north east of Valley House:	Neolithic long barrow located 480 m north-east of Valley House. The buried remains of a Neolithic long barrow were identified by aerial photography as an oval-shaped enclosure defined by a single ditch measuring around 39 m long	Prehistoric

TF 44699 71949

TF 46378 57190

st-medieval

TF 49888 58766

TF 55906 65832

TF 45036 71730

NGR

NHLE No.	Designation and Grade	Name	Description	Period	NGR
		one of a group known as Deadmen's Graves	and 22 m wide, aligned north-east to south-west. The north-eastern end appears to be defined by a thinner ditch than the rest of the enclosure.		
1013923	Scheduled monument	Neolithic long barrow 495 m north of Moon Wood, one of a pair of long barrows known as Deadmen's Graves	The monument includes the earthwork and buried remains of a Neolithic long barrow. The barrow mound, aligned east – west, is visible on aerial photographs as an elongated and tapering earthwork. It measures around 63 m in length and around 28 m in width to the east of centre where the mound is prominent; the mound tapers to the west end to a width of around 15 m. The mound has been damaged by past quarrying and appears as a rounded 'mound' at the eastern end, up to 1.5 m high, with a low 'spine' (around 0.4 m high) along part of the northern edge, which peters out to the west end to the same level as the surrounding ground on the north side of the monument.	Prehistoric	TF 44582 71899
1013921	Scheduled monument	Neolithic long barrow 575 m NNW of Moon Wood, one of a pair of long barrows known as Deadmen's Graves	The mound measures approximately 50 m in length and its width decreases from around 14 m at the east end to around 10 m at the west end. The earthwork is prominent when viewed from the south (down slope). A broad hollow or saddle across the width of the earthwork, around 20 m from the east end, gives the appearance of two 'separate mounds' when viewed from the north where the base of the hollow is at ground level.	Prehistoric	TF 44421 71981
1010678	Scheduled monument	Churchyard cross, All Saints' churchyard	The monument includes the remains of a standing stone cross located in the churchyard of All Saints' Church, Fosdyke, approximately 8.5 m south of the south porch. The cross is medieval in date and is constructed of limestone. The monument includes the base of the cross, which takes the form of a socket stone.	Medieval	TF 31512 33306
1018398	Scheduled monument	King's Hill motte and bailey castle	The remains take the form of a series of substantial earthworks located in the fenland approximately 2.5 km north west of St Mary and St Nicholas' Church. In the northern part of the monument is the motte, a large earthen mound of approximately circular plan, measuring about 60 m in diameter and standing about 2 m above the surrounding ground level. On the top of the mound, which is flat in profile, are the earthwork remains of a series of structures ranged around the west, north and east sides of a shallow central depression or yard. The mound is encircled by a steep-sided ditch about 2 m in depth which represents the remains of a moat.	Medieval	TF 41361 53090
1019528	Scheduled monument	Moated site 480 m north east of Wyberton West Hospital	The moated island is subrectangular in plan and is enclosed by a broad moat. The island, measuring 70 m by 50 m, is raised up to 1 m above the surrounding ground level and would have accommodated buildings such as the manor house and ancillary domestic buildings. The eastern third of the island is slightly raised above the rest of the island and distinguished from it by a linear scarp, which is thought to indicate a subdivision separating the house on the east from a yard or paddock on the western part of the island. The moat, still water-filled in places, measures up to 12 m in width and 1 m deep with low internal banks lining part of the northern and southern moat arms. The western end of the northern moat arm has been infilled and, visible as a shallow depression, will survive as a buried feature.	Medieval	TF 32101 42874
1004930	Scheduled monument	Medieval salt workings	The monument includes a medieval moated site and post-medieval garden remains located approximately 70 m south of the present Cressy Hall, which formerly lay in the parish of Surfleet. The moated island is roughly rectangular in plan, measuring 32 m by 28 m, and would have been occupied by the medieval manor house. It is enclosed by a broad moat, measuring 8 m to 12 m	Medieval	TF 49551 57432
NHLE No.	Designation and Grade	Name	Description	Period	NGR
----------	-------------------------	---	---	---------------	----------------
			across; the northern end of the eastern moat arm has been partly infilled in more recent times and survives as a buried feature, visible as a slight depression. A causeway crosses the northern arm close to the north eastern corner of the moat and is thought to indicate the position of an original access to the island. An outward curve at the south eastern corner of the moat is thought to indicate the position of a former water outlet, linking the moat with the Risegate Eau, from which it was fed.		
1019526	Scheduled monument	Medieval moated site and post-medieval gardens at Cressy Hall	The moated island is roughly rectangular in plan, measuring 32 m by 28 m, and would have been occupied by the medieval manor house. It is enclosed by a broad moat, measuring 8 m to 12 m across; the northern end of the eastern moat arm has been partly infilled in more recent times and survives as a buried feature, visible as a slight depression. A causeway crosses the northern arm close to the north eastern corner of the moat and is thought to indicate the position of an original access to the island. An outward curve at the south eastern corner of the moat is thought to indicate the position of a former water outlet, linking the moat with the Risegate Eau, from which it was fed.	Medieval	TF 22408 30398
1016044	Scheduled monument	Abbey Hills moated site	The remains include the earthworks of a broad discontinuous moat enclosing a roughly rectilinear island c.1.1ha in area. The western side of the moat is up to 2 m in depth, 10 m in width and continues for approximately 137 m on a NNW-SSE axis. The northern side of the moat runs for up to 100 m on an ENE-WSW axis, although subsequent farming activity has reduced it to only approximately 7.5 m in width. The north eastern side of the moat, similar in profile and dimensions to the western side, runs for 135 m on a NNW-SSE axis before turning sharply north east and continuing for approximately 27.5 m up to a modern field hedge.	Medieval	TF 45134 54854
1232860	Grade I listed building	Church Of St Mary	Parish church. c.1300, early C14, late C14, C15, 1767, chancel rebuilt 1848 by Stephen Lavin. Squared limestone rubble and ashlar. Lead roofs. Western tower with spire, clerestoried nave, aisles, chancel, south porch. Tall 3 stage late C14 ashlar tower with stepped corner buttresses having crocketed gablettes, topped by battlemented parapet.	Medieval	TF 23753 40193
1063533	Grade I listed building	Church Of St Margaret	Parish church. C12, C13, C14, C15, 1699, restored 1840. Chancel rebuilt and aisles and nave partly rebuilt 1855 by Kirk, repaired 1880. Ashlar, some red brick patching. Lead and plain and fish scale tile roofs, some slate. Parapets with coped gables. Single ridge cross to the east chancel, east nave with finial. Stack to vestry. Tower, nave, south aisle, south porch, north aisle, north vestry and chancel.	Medieval	TF 35446 50744
1064425	Grade I listed building	Church Of St Peter And St Paul	Parish church. C12, C14, C15, restored 1896. Squared limestone rubble and ashlar, lead roofs. Clerestoried nave, aisles, south porch, transepts, chancel, south chapel, crossing tower with spire.	Medieval	TF 23750 31759
1359700	Grade I listed building	Church Of St Margaret	Parish church. Built in 1733 in the form of a Palladian Temple on a direct axis to the front door of Well Vale House. Altered late C18, restored 1959. Red brick in English bond, painted ashlar dressings and stucco. Westmoreland slate roof with lead dressings, boarded bell cupola, with shaped felted dome, dating from restoration. Single cell plan with eastern Tuscan tetrastyle portico, consisting of 4 ashlar columns, supporting large pediment on plain brackets.	Post-medieval	TF 44405 73375
1147013	Grade I listed building	Church Of St Margaret	Parish church. C14, C15, restored 1862 by Charles Kirk of Sleaford when the chancel was largely rebuilt. Limestone ashlar, coursed and squared limestone	Medieval	TF 22424 34101

N	C	D
	U	1

NHLE No.	Designation and Grade	Name	Description	Period	NGR
			rubble, lead and plain tiled roofs. Western tower with spire, clerestoried nave, aisles, chancel, south porch.		
1229941	Grade I listed building	Church Of St Mary	Church of St Mary, C15. Finely proportioned with lofty nave arcades, clerestorey, tall West tower, aisles and South porch, chancel, stone.	Medieval	TF 55911 65851
1204941	Grade I listed building	Church Of St Peter And St Paul	Parish church. c.1200, C13, C14, C15 chancel demolished 1706, restored 1858, 1898. Ashlar and squared coursed limestone rubble. Red brick. Slate and lead roofs. Western tower, nave with clerestorey, aisles, south porch, vestry. 3 stage C14 tower with stepped angle buttresses, plain offsets and embattled parapet.	Medieval	TF 55947 68832
1064449	Grade I listed building	Church Of St Mary And The Holy Rood	Parish church. C13, C14, C15, restored in 1868 and 1896. Limestone ashlar, lead roofs. Southwestern tower and spire. Clerestoried nave, aisles, chancel. Battlemented nave, aisles with moulded copings.	Medieval	TF 20824 35943
1388844	Grade I listed building	Parish Church Of St Botolph	Parish church. 1309 work commenced on chancel, nave and aisles completed 1390, tower started c1450 and completed 1520. Restoration by Gilbert Scott in 1845 and George Place of Nottingham in 1851-53. Further restoration of 1929 by Sir Charles Nicholson. Nave altar of 1978 by Ronald Sims. Built of ashlar with lead roofs. Consists of a western tower with tall octagonal lantern called 'The Stump', nave with clerestorey, aisles, chancel, south porch and chapel, north vestry.	Medieval	TF 32692 44184
1147881	Grade I listed building	Church Of St Leodegar	Parish church. Originally late C12 rebuilt c.1420. Chancel rebuilt 1760. Restored by George Gilbert Scott Junior c.1880. Coursed limestone rubble, some ashlar and lined stucco. Western tower, clerestoried nave, aisles, facetted chancel. The original church had a crossing tower which collapsed in 1419.	Medieval	TF 32867 40831
1360476	Grade I listed building	Church Of St Mary	Parish church. Late C12, early C13, C14, 1796 restoration, restored 1890 by Hodgson Fowier. Limestone ashlar, lead and plain tiled roofs. Western tower and broach spire, nave, chancel, aisles, north and south porches, vestry, south transept.	Medieval	TF 32576 39169
1388995	Grade I listed building	Fydell House And Wall And Railings And 2 Urns	House now adult education centre, wall, railings and urns. 1726 with minor C19 alterations. Architect possibly William Sands of Spalding. Red brick in Flemish bond, ashlar dressings, plain tiled hipped roof, brick valley stacks. Double pile plan. 2 storeys plus attics, with cellar, stone capped plinth, 1st floor platt band, plain frieze with full entablature, balustraded parapet with 4 panelled piers. 6-bay front arranged 2:2:2 and divided by full height Doric pilasters.	Post-medieval	TF 32855 43876
1389007	Grade I listed building	Guildhall and attached gate	Late C14 Guildhall that survives substantially intact, including its crown post roof. Its west gable end to the street with C15 window is also intact. The interior contains detail that illustrates craftsmanship of the highest quality from the medieval period to the C18. * Historical Interest: It is possibly the earliest brick building in Lincolnshire, with internal features that illustrate Boston's social, economic and political history over at least 400 years.	Medieval to Post- medieval	TF 32865 43891
1063656	Grade I listed building	Gunby Hall	Small country house, former seat of Massingberd and Langton families, now owned by the National Trust. 1700, altered c.1730, with extensions of 1873 and 1900 of Dining Room, Servants' Hall and Service Wing. Red brick in Flemish bond, ashlar dressings, flat lead roof, 6 brick wall stacks with moulded tops. 3 storey with basement having moulded plinth, 3 moulded stone bands, panelled brick parapet with moulded stone top.	Post-medieval	TF 46718 66876

NHLE No.	Designation and Grade	Name	Description	Period	NGR
1000979	Grade II registered park and garden	Gunby Hall	An 18 th century park and garden around the 18 th century country house, Gunby Hall. The park includes the Hall and associated outbuildings to the north, a tree-lined drive approaching the hall to the north and formal gardens to the east, south and west. The parkland extends over around 32 ha with scatters of mature trees and tree plantations.	Post-medieval	TF 46752 66820
1168883	Grade II* listed building	Wellvale House	Former small country house in park, now private school. Early C17, sunstantially remodelled c.1730 for James Bateman, extended late C18, for Francis Dashwood, partly gutted by fire 1845 and rebuilt 1925 by Guy Elwes. Red brick in English and Flemish bonds, ashlar dressings, plain tiled hipped roofs with lead dressings, 4 ridge brick stacks. 2 storey plus attics, originally 2:3:2, the centre bays advanced and pedimented, in front of the left hand 2 bays which are in English bond and part of the original house.	Post-medieval	TF 44680 73550
1063661	Grade II* listed building	Claxby Hall	Mid C18, with early C19 alterations including possible re-facing to almost all the exterior, C20 alteration. Hipped C19 slate roof with overhanging eaves. Set on a plinth. Garden, probably C18 entrance front, with 2 stacks to the rear. 2 storeys, 6 bays. The central 2 bays slightly project. 2 low glazing bar sashes. Either side are 2 smaller glazing bar sashes with 6 similar sashes above, all under cambered arches.	Post-medieval	TF 45336 71472
1229943	Grade II* listed building	Church Of St Clement	A low church with a shallow pitched roof and no aisles or clerestory. The nave and chancel are mostly rendered, but the underlying masonry, a mix of brick, rubble and ashlar, is exposed in places.	Post-medieval	TF 55868 63900
1267243	Grade II* listed building	Total Submersion Font Approximately 23 Metres East Of Chapel	Total submersion font. c.1701, late Cl9, C20. Red brick, red tiles. 6 C18 brick steps descend gently from the west into a rectangular tank approximately 6 m long and 3 m wide. The tank is lined with C18, C19 and C20 tiles and has brick coped surround. Said to be one of only 2 exterior total submersion fonts in the country.	Post-medieval	TF 45042 65366
1223592	Grade II* listed building	Baptist Chapel	Baptist chapel, now redundant. 1701. Red brick. Pantile roof with recessed gables, flat band at eaves and single gable stack to east. Single storey with 2 storey east gallery. Doorway in east side with segmental head and panel door.	Post-medieval	TF 45005 65364
1063626	Grade II* listed building	Church Of St Martin	Parish church. Medieval base, rebuilt late C18, altered 1891. Coursed squared chalk to base of walls, red brick in English bond, ashlar dressings, concrete tiled roof. Western tower, nave, chancel, vestry. 3 stage tower, top stages offset, with offset plain parapet and corner lead pinnacles.	Medieval	TF 47047 68808
1064448	Grade II* listed building	36, Church Street	House. Mid C18 with early C20 alterations. Red brick in Flemish bond, painted ashlar dressings, slate roof, stone coped gables, 4 brick gable stacks. Parallel range plan. 2 storey plus attics, 3 bay front, the central bay slightly advanced, and pedimented.	Post-medieval	TF 20852 35905
1064450	Grade II* listed building	The Peacock Guest House	Former house, now guest house. Late C17, altered mid C19. Red brick, stucco front, machine plain tile roof, brick coped tumbled gables, 2 gable stacks. T-plan. 2 storey plus attics, 3 bay front, with plinth and stucco quoins, having central gabled porch with front parapet, having semi-circular opening containing C20 half glazed door, flanked by single canted bay windows, plain sashes, plain pilasters, cornices, flat lead roofs. To first floor are 3 plain sashes with splayed stucco lintels.	Post-medieval	TF 20890 35683
1359687	Grade II* listed building	Church Of St Peter	Parish church. Rebuilt 1870 in Early English style by James Fowler. Squared limestone rubble, Collyweston slate roof with decorative clay ridge tiles.	Post-medieval	TF 46876 66826

NHLE No.	Designation and Grade	Name	Description	Period	NGR
			Western tower, organ chamber, chancel, south porch, vestry. 3 stage squat tower with stepped corner buttresses, offset top stage on moulded corbels, battlemented parapet, corner griffins. 2 light bell openings with trefoils in chamfered surrounds. On south side a facetted stair tower with Caernarvon arched door.		
1062062	Grade II* listed building	Hunwell House	House. Early C18, with minor C19 alterations. Red brick in Flemish bond with slate roof having 2 brick gable stacks and tumbled brick gables. T-plan. 2 storey plus attics, 5 bay front with first floor band. Central 6 panel door with traceried overlight, wood panelled reveals, pedimented doorcase with Doric pilasters flanked by pairs of glazing bar sashes, segmental brick heads.	Post-medieval	TF 32140 39106
1359727	Grade II* listed building	Church Of St Andrew	Parish church. C14, C15, porch rebuilt 1831, aisles rebuilt 1846, tower and east end rebuilt in 1866 by J. Fowler under supervision by G. E. Street, chancel restored 1894. Limestone ashlar, squared greenstone rubble, ashlar dressings, lead roofs. Western tower, clerestoried nave, aisles, chancel, south porch.	Medieval	TF 41794 65100
1388898	Grade II* listed building	124-136, High Street	Terrace of 7 houses, some converted to flats. c1700 with early C19 alterations. Brown brick in English bond, ashlar dressings, steeply pitched hipped pantile roof with 4 large ridge stacks. 3 storeys plus cellar, palace front of 18 bays, the central 6 bays slightly advanced. Plinth with ashlar sill band. Full height pilasters divide the bays and are linked by segmental arches with keystones.	Post-medieval	TF 32737 43454
1388896	Grade II* listed building	118B, 120 And 122 High Street	Banker's house, now flats. c1770, added to late C18, early C19, altered late C19 and C20. Red brick in Flemish bond, slate roofs, ashlar dressings, red brick ridge and valley stacks. centre house of three storeys, with five bays, the three centre bays slightly advanced and pedimented. Plinth, first floor platt band, dentilled cornice, cartouche and rococo scrolls to pediment, balustraded parapet. Plain sashes with cambered heads and fluted keystones, arranged 2:1:2.	Post-medieval	TF 32742 43486
1388894	Grade II* listed building	116, High Street	House. Early C18, altered and extended late C18 and late C19. Red brick in Flemish bond, with painted ashlar dressings, stone and rendered plinth, slate and concrete tile roof, stone coped, gable stacks are reduced. 2 storeys plus cellar and attics, 5-bay front, with sill bands, stucco platt band, cornice and parapet.	Post-medieval	TF 32748 43534
1062042	Grade II* listed building	Wyberton Park	Former rectory, now house. 1689, largely rebuilt 1761 by Dr. John Shaw. Possibly by William Sands Junior of Spalding. Red brick in Flemish bond, ashlar dressings, and quoins. 2 wall stacks. Pantile roofs. T- plan. 2 storey, 7 bay front with ashlar first floor band, dentillated cornice, stone coped parapet, swept up at the centre, with central and corner urn finials.	Post-medieval	TF 32830 40730
1147586	Grade II* listed building	Frampton Hall	Small country house. Built in 1725 for Coney Tunnard, extended late C18 and skilfully remodelled in matching style in 1873. Red brick in Flemish bond with limestone ashlar and render dressings. Lead roof. Red brick wall stacks in Tudor revival style with corbelled out castellated tops. Originally 5 bay, 3 storey, plus basement, box, with moulded ashlar plinth and bands, cornice, brick panelled parapet. Rusticated giant corner pilasters.	Post-medieval	TF 32516 39352
1360474	Grade II* listed building	Gates, Screen, Piers And Wall To Frampton Hall	Gates, screen, piers and wall. 1725 with C19 extension and alteration. Red brick, ashlar and wrought iron. Pair of wrought iron C18 gates with flanking scroiled panels, supporting an overthrow bearing scrolls and leaves, surmounted by a rabbit (Coney symbol). To either side a low ashiar wall supports a screen of spearhead verticals with central scrolled panel,	Post-medieval	TF 32529 39334

NHLE No.	Designation and Grade	Name	Description	Period	NGR
			terminating in C19 brick piers. Beyond low brick walls with matching C19 wrought iron screens and reused C18 screens terminate in shorter C19 brick piers.		
1388845	Grade II* listed building	Boston Sessions House	Former Sessions House in Tudor Gothic style built in 1841-42 to the designs of Charles Kirk. Ashlared stone frontage and brown brick sides and rear with stone dressings. Lead roofs. The building is rectangular, almost square on plan. Its complicated configuration is based on the different circulation routes for different users, all of whom were to be kept separate.	Post-medieval	TF 32714 44262
1388955	Grade II* listed building	The Assembly Rooms	Assembly rooms and shops. 1822 possibly by Jeptha Pacey based on earlier designs by William Atkinson, altered later C19 and c1960s following a major fire. Stucco and painted ashlar, C20 hipped copper roof. 2 storeys, 7-bay front, with further recessed bay to right. Main front arranged 2:3:2 the centre bays advanced with shallow pediment containing garlanded clock.	Post-medieval	TF 32748 44055
1388976	Grade II* listed building	Centenary Methodist Chur And Attached Church Hall	ch Methodist church with ancillary rooms and hall. 1839 by Stephen Lewin, refronted and altered 1910 by Gordon and Gurton following a fire in 1909. Portland stone ashlar, Gault brick with ashlar and stucco dressings, red brick, slate roofs with stone coped gables. Front elevation of 1910 in ashlar, arranged with tall square towers at each end linked by a convex 2-storey front.	Post-medieval	TF 32772 44382
1388941	Grade II* listed building	Exchange Buildings, 36-39 Market Place	Gault and red-brown brick with additions in red brick. Westmoreland slate roof with lead dressings. This is a fifteen-bay rectangular building with a bowed north end, of three storeys with basement and attics.	Post-medieval	TF3278844029
			The east elevation is symmetrical, its central three bays slightly advanced with a pediment above. This has a painted relief decoration to the centre consisting of the corporation coat of arms surrounded by garlands, with the date 1772 below.		
1388991	Grade II* listed building	5, South Square	House, now offices. Mid C17, altered C19. Painted render with rusticated painted stone quoins, plinth and 1st floor band. Slate roofs, hipped to right. C19 gable and wall stacks in Gault brick. Parallel range plan. EXTERIOR: 2 storeys plus attics, 5-bay front with dentilled stone cornice, plain parapet, stone coped. Central 6-panel door, with bordered overlight with glazed lamps. Set in panelled doorcase, with plain frieze and moulded cornice, with Roman Doric half-columns. Flanked by pairs of plain sashes. To 1st floor 5 small glazing bar sashes.	Post-medieval	TF 32854 43803
1063657	Grade II* listed building	Western Stable Block, Gunby Hall	Stable block. 1736 with alterations of 1917. Red brick in Flemish bond, ashlar dressings, hipped pantile roof with lead dressings, weatherboarded timber clock tower with shaped lead roof. 2 storey, 5 bay front arranged 2:1:2, the centre bay slightly advanced.	Post-medieval	TF 46715 66932
Table 5A.5.3 I	Designated heritage assets o	of high value beyond the 5 ki	n Study Area with potential impacts		
NHLE No.	Designation and Name Grade	Desc	ription	Period	NGR
1018394			nonument includes Tattershall Castle and College, situated on the south side of the p e of Tattershall on the west bank of the River Bain. The castle originated as an enclos		TF 21147 57519

NHLE No.	Designation a Grade	and Name	Description		
1018394	Scheduled monument	Tattershall Castle and College	The monument includes Tattershall Castle and College, situated on the south side of the present village of Tattershall on the west bank of the River Bain. The castle originated as an enclosure castle constructed in the 13th century by Robert of Tattershall. In the 15th century it passed to		

NHLE No.	Designation an Grade	d Name	Description	Period	NGR
			Ralph, first Lord Cromwell, who rebuilt it as a fortified house and founded a college on the adjacent site. While the college was dissolved in 1545 and its buildings dismantled, the castle continued to be occupied until 1693; it thereafter fell into disrepair and in 1790 some of the building materials were removed and the moats largely infilled. From 1912 the castle was restored and partly excavated and in 1925 it passed into the care of the National Trust. The monument includes the standing and buried remains of the castle, college and associated features, lying to the west, south and east of Holy Trinity Church.		
1215317	Grade I listed building	Tattershall Castle	Castle, now monument owned by National Trust. c.1440 built for Ralph Cromwell, Lord High Treasurer, on site of castle built by Robert Tateshale in 1231. Restored in 1911-25 by Lord Curzon. Red brick tower in English bond, with darker lattice lozenge decorations to upper parts, ashlar dressings, leaded roofs. Rectangular plan with facetted angle towers, originally with attached hall to courtyard side. 5 storey with undercroft, irregular 3 bay front with plinth, chamfered ashlar string course and embattled parapet with machicolated base.	Medieval	TF 21056 57544
1216195	Grade I listed building	Round Towers, Tattershall Castle	Round tower bases of original castle. c.1230, built by Robert de Tatershal. Ashlar, repaired in brick. 2 round tower bases, to either side of the C15 tower, the left hand one a fragment only. The right hand one is a circle, approx. 12'0" internal diameter and standing to 4'O" within the moat.	Medieval	TF 21062 57558
1288162	Grade I listed building	Kitchen Ruins to Tattershall Castle	Footings to former kitchen. c.1440. Red brick in English bond, standing to 4'O" high, broad foundations projecting into the moat. Left hand chamber has a drain and circular stone vat base on the floor. A small addition to the right has an angle drain, and beyond again is a further massive narrow foundation.	Medieval	TF 21065 57522
1215318	Grade I listed building	Moat Walls at Tattershall Castle	Moat walls. c.1440, restored early C20. Red brick, in English bond, slightly battered, brick coped walls to the exterior of the polygonal moat. Near the bridge is a segmental headed opening to flight of steps to ground level. The wall remains around the entire circumference.	Medieval	TF 21104 57512
1215319	Grade I listed building	Stable Ruins at Tattershall Castle	Reputedly stable block, now ruins. c.1440. Red brick and ashlar dressings. 2 storey, incomplete 3 bay front with to left a segmental arched doorway and to right 2 window openings and 4 tethering rings in the wall. Left hand gable has plinth and 2 projecting stacks, one corbelled out at first floor level. In the ground floor are 2 windows and in the first floor a single window. All of 2 lights, cusped heads and moulded stone surrounds. Inside the ground floor had original basket arched fireplace, now replaced by segmental arch, flanked by single pointed niches.	Medieval	TF 21019 57562
1287738	Grade I listed building	Ticket Office and Shop, Tattershall Castle	Former guard house, now ticket office and shop. c.1440, altered c.1911. Red brick in English bond, with ashlar dressings, plain tiled roof. 2 storey, 2 bay front with plinth and dentillated eaves course.	Medieval	TF 21140 57592

Table 5A.4 Non-designated Heritage Assets within the draft Order Limits and the 1 km Study Area

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
MLI126598	Non-designated building	Former School, Bilsby	Former school building. Two storey red brick building in C-shape plan form, under a pitched gabled roof of slate. The building comprises a central east southeast-west southwest aligned range with a cross-wing at each end of the south southwest elevation. One lateral stack. Polychromatic brick banding and window lintels. The small central gable has a stone coat of arms, faded and illegible, and a datestone inscribed '1876'. The building is currently in disuse, though in good material condition.	Post-medieval	TF 47627 76282	Within 100 m of the draft Order Limits

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
MLI43379	Non-designated building	Post Medieval Bridge	There is a bridge at this location which has, on either side of it, a decorative cast plate, Surrounding the arch, with an inscription across the top 'erected 1890'	Post-medieval	TF 5078 6732	Within the 1 km Study Area
MLI89010	Non-designated building	Hubbert's Bridge, Kirton	This bridge of c.1850 replaced the original one which carried a turnpike road across the South Forty Foot Drain. Hubberts Bridge was a wooden structure carried on piles driven into the drain. This bridge having become unsafe, was taken over by the County Justices for the Parts of Holland in 1888 and was replaced at the expense of the county funds by the present brick structure having a single span of 56 feet which was erected from the designs of Mr John Kingston, the county surveyor.		TF 26948 43650	Within the 1 km Study Area
MLI13093	Non-designated building	Chantry, Easthorpe, Wigtoft	'Easthorpe' - chantry or chapel, with well-dressed limestone blocks built into the lower part of the southern wall of the house - or is the house built around the Wall	Post-medieval	TF 2670 3690	Within the 1 km Study Area
MLI43413	Non-designated building	Mumby Road Railway Station in Bilsby parish	"Mumby Road Railway Station was at a passing loop on the single track Willoughby to Sutton branch line, with a wooden signal cabin (10 feet by 12 feet) on the south platform. There was also a wooden booking hall (60 feet by 12 feet) with a small canopy on the south platform. The north platform was disused with no buildings. There was a large wooden goods shed (80 feet by 60 feet) and a brick weigh bridge hut in the yard. East of the station is the railway house. It was opened in 1886 and closed October 1970."	Post-medieval	TF 4963 7543	Within the 1 km Study Area
MLI126014	Non-designated building	Pillbox, Langrick Bridge	A Second World War pillbox is visible in this location on the Google Maps satellite and Street View imagery layers. The structure is of the hexagonal type 22 form of pillbox.	Modern	TF 2666 4748	Within 100 m of the draft Order Limits
MLI125954	Non-designated building	Pillbox, Cumberworth Road, Bonthorpe	A Second World War pillbox is located in this area to the north of Cumberworth Road. The structure is of the hexagonal type 22 form of pillbox, and was built using wooden shuttering and no internal blast wall.	Modern	TF 4882 7266	Within the 1 km Study Area
MLI43376	Non-designated building	Pillbox, Lade Bank Lock, Old Leake	Type 22 hexagonal pillbox, built of concrete with wooden shuttering. The structure has a textured upper section from the embrasures to the roof.	Modern	TF 3791 5454	Within the 1 km Study Area
MLI43375	Non-designated building	Pillbox, Midville	Type 22 hexagonal pillbox. The structure is built of concrete with wooden shuttering and has a textured roof area.	Modern	TF 38340 56914	Within 100 m of the draft Order Limits
MLI82729	Non-designated building	Pillbox, Hemholme Bridge	A Second World War pillbox is visible in this location on the Bing Maps aerial photographic and Google Maps Street View imagery layers. The structure is of the hexagonal type 22 form of pillbox.	Modern	TF 40567 58679	Within 100 m of the draft Order Limits
MLI43277	Non-designated building	Pillbox, Sloothby	A type 22 pillbox of the Second World War Coastal Crust, at Sloothby. The pillbox faces east and has no rear embrasures.	Modern	TF 5017 7104	Within 100 m of the draft Order Limits
MLI43373	Non-designated building	Pillbox, Bridge House, Midville	Type 22 hexagonal pillbox. The structure is built of concrete with wooden shuttering. It has a textured roof area, but does not have rear loops or an anti-ricochet wall.	Modern	TF 38562 58153	Within the 1 km Study Area

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
MLI43382	Non-designated building	Pillbox, Short's Corner	A three-bay type 23 Second World War pillbox with covered middle bay, covered entrance and 6 loopholes	Modern	TF 31311 52866	Within 100 m of the draft Order Limits
MLI120449	Non-designated building	Redland, Stickney	Redeveloped 19 th century farmstead. Row. The farmhouse was detached from the main working complex. Located within a loose farmstead cluster. Large modern sheds are located to the side of the site	Post-medieval	TF 3488 5458	Within 100 m of the draft Order Limits
MLI118933	Non-designated building	Southview, Willoughby with Sloothby	Redeveloped 19 th century farmstead. Regular courtyard of U plan. The farmhouse location is unclear. Isolated location. Large modern sheds are located on the site	Post-medieval	TF 5022 7121	Within 100 m of the draft Order Limits
MLI120407	Non-designated building	Hobhole Farm, Midville	Redeveloped 19 th century farmstead. Regular courtyard with linked working buildings to all four sides of the yard. The farmhouse was detached from the main working complex. Isolated location. Large modern sheds are located to the side of the site.	Post-medieval	TF 3814 5593	Within 100 m of the draft Order Limits
MLI118928	Non-designated building	Elsom Farm, Willoughby with Sloothby	Redeveloped 19 th century farmstead. Regular courtyard of L plan. The farmhouse is detached from the main working complex. Isolated location. Large modern sheds are located on the site	Post-medieval	TF 4811 7312	Within 100 m of the draft Order Limits
MLI118907	Non-designated building	Unnamed farmstead, Cumberworth	Redeveloped 19 th century farmstead. Parallel. The farmhouse location is unclear. Isolated location. Large modern sheds are located to the side of the site	Post-medieval	TF 4991 7268	Within 100 m of the draft Order Limits
MLI120400	Non-designated building	Grange Farm (The Grange), Midville	Redeveloped 19 th century farmstead. Regular courtyard of U plan. The farmhouse was detached from the main working complex. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 3786 5806	Within 100 m of the draft Order Limits
MLI123017	Non-designated building	Poplars Farm, Kirton	Redeveloped 19 th century farmstead. Regular courtyard with L- plan range plus detached buildings to the third side of the yard. The farmhouse was detached from the main working complex. Located within a loose farmstead cluster. Large modern sheds are located on the site	Post-medieval	TF 2746 3988	Within 100 m of the draft Order Limits
MLI122997	Non-designated building	Holme Lodge Farm, Kirton	Redeveloped 19 th century farmstead. L-plan. The farmhouse was attached to a range of working buildings. Located within a loose farmstead cluster. Large modern sheds are located to the side of the site	Post-medieval	TF 2701 4139	Within 100 m of the draft Order Limits
MLI122566	Non-designated building	Unnamed farmstead (Marsh Farm), Gosberton	Redeveloped 19 th century farmstead. Regular courtyard with L- plan range plus detached buildings to the third side of the yard. The farmhouse was detached with the long axis facing on to the yard. Isolated location. Large modern sheds are located to the side of the site	Post-medieval	TF 2729 3230	Within 100 m of the draft Order Limits
MLI120294	Non-designated building	Willow Farm, Thorpe St. Peter	Redeveloped 19 th century farmstead. Regular courtyard with L- plan range plus detached buildings to the third side of the yard. The farmhouse was detached from the main working complex. Isolated location. Large modern sheds are located on the site	Post-medieval	TF 4517 6110	Within 100 m of the draft Order Limits

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
MLI122352	Non-designated building	Rabbit Breeding Farm, Holland Fen with Brothertoft	Redeveloped 19 th century farmstead. Regular courtyard of T plan. The farmhouse was detached from the main working complex. Isolated location. Large modern sheds are located on the site	Post-medieval	TF 2697 4460	Within 100 m of the draft Order Limits
MLI116613	Non-designated building	Grove Farm, Bilsby	Redeveloped 19 th century farmstead. Regular courtyard of U plan. The farmhouse is detached from the main working complex. Located within or in association with a hamlet. Large modern sheds are located on the site	Post-medieval	TF 4909 7587	Within 100 m of the draft Order Limits
MLI119852	Non-designated building	Unnamed farmstead, Orby	Redeveloped 19 th century farmstead. Regular courtyard of Z plan. The farmhouse was detached from the main working complex. Isolated location. Large modern sheds are located on the site	Post-medieval	TF 5213 6769	Within 100 m of the draft Order Limits
MLI120446	Non-designated building	Arkendale, Stickney	Redeveloped 19 th century farmstead. Loose courtyard with three sides of the courtyard formed by working agricultural buildings. The farmhouse was detached with the long axis facing on to the yard. Isolated location. Large modern sheds are located on the site	Post-medieval	TF 3363 5427	Within 100 m of the draft Order Limits
MLI120445	Non-designated building	Chapel Farm, Stickney	Redeveloped 19 th century farmstead. Regular courtyard of L plan. The farmhouse was detached from the main working complex. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 3352 5426	Within 100 m of the draft Order Limits
MLI118912	Non-designated building	Poplar Farm, Cumberworth	Redeveloped 19 th century farmstead. Regular courtyard of U plan. The farmhouse is detached from the main working complex. Isolated location. Large modern sheds are located on the site	Post-medieval	TF 5071 7202	Within 100 m of the draft Order Limits
MLI124548	Non-designated building	Cherry Tree House, Sibsey	Redeveloped 19 th century farmstead. Regular courtyard of U plan. The farmhouse was detached from the main working complex. Located within a loose farmstead cluster.	Post-medieval	TF 3280 5387	Within 100 m of the draft Order Limits
MLI124651	Non-designated building	Westville Farm, Frithville and Westville	Redeveloped 19 th century farmstead. Regular courtyard with L- plan range plus detached buildings to the third side of the yard. The farmhouse was detached from the main working complex. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 3000 5284	Within 100 m of the draft Order Limits
MLI120382	Non-designated building	Engine Farm, Stickford	Engine Farm, Stickford. Redeveloped 19 th century farmstead. Regular courtyard with L-plan range plus detached buildings to the third side of the yard. The farmhouse was detached from the main working complex. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 3725 5911	Within 100 m of the draft Order Limits
MLI123066	Non-designated building	Unnamed farmstead, Frampton	Unnamed farmstead, Frampton. Redeveloped 19 th century farmstead. Regular courtyard with L-plan range plus detached buildings to the fourth side of the yard. The farmhouse was detached from the main working complex. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 2803 4239	Within 100 m of the draft Order Limits
MLI122815	Non-designated building	Spring Cottage, Wigtoft	Spring Cottage, Wigtoft. Redeveloped 19 th century farmstead. Regular courtyard of U plan. The farmhouse was detached from the main working complex. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 2623 3755	Within the 1 km Study Area

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
MLI123016	Non-designated building	Meryland, Kirton	Meryland, Kirton. Redeveloped 19 th century farmstead. Regular courtyard of U plan. The farmhouse was detached from the main working complex. Located within a loose farmstead cluster. Large modern sheds are located on the site.	Post-medieval	TF 2756 3991	Within 100 m of the draft Order Limits
MLI116615	Non-designated building	Moat House, Bilsby	Moat House, Bilsby. Redeveloped 19 th century farmstead. Regular courtyard of F plan. The farmhouse is detached from the main working complex. Located within a loose farmstead cluster. Large modern sheds are located on the site.	Post-medieval	TF 4873 7606	Within 100 m of the draft Order Limits
MLI120344	Non-designated building	Unnamed farmstead, New Leake	Unnamed farmstead, New Leake. Redeveloped 19 th century farmstead. Row with additional detached elements. The farmhouse was detached from the main working complex. Located within a loose farmstead cluster. Large modern sheds are located on the site.	Post-medieval	TF 3978 5838	Within the 1 km Study Area
MLI120369	Non-designated building	Wydal, New Leake	Wydal, New Leake. Redeveloped 19 th century farmstead. Regular courtyard of L plan. The farmhouse was detached from the main working complex. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 3547 5420	Within the 1 km Study Area
MLI120249	Non-designated building	Home Farm House, Croft	Home Farm House, Croft. Redeveloped 19 th century farmstead. Loose courtyard with L-plan range plus detached buildings to the third side of the yard. The farmhouse was detached from the main working complex. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 5024 6278	Within 100 m of the draft Order Limits
MLI122995	Non-designated building	Ivy House, Kirton	Ivy House, Kirton. Redeveloped 19 th century farmstead. Row. The farmhouse was detached from the main working complex. Located within a loose farmstead cluster. Large modern sheds are located on the site.	Post-medieval	TF 2686 4140	Within 100 m of the draft Order Limits
MLI120343	Non-designated building	Rojan, New Leake	Rojan, New Leake. Redeveloped 19 th century farmstead. Loose courtyard with three sides of the courtyard formed by working agricultural buildings. The farmhouse was detached with the long axis facing on to the yard. Located within a loose farmstead cluster. Large modern sheds are located on the site.	Post-medieval	TF 4001 5843	Within the 1 km Study Area
MLI120298	Non-designated building	Unnamed farmstead, Thorpe St. Peter	Unnamed farmstead, Thorpe St. Peter. Redeveloped 19 th century farmstead. Row with additional detached elements. The farmhouse was detached from the main working complex. Located within a loose farmstead cluster. Large modern sheds are located on the site.	Post-medieval	TF 4526 6064	Within 100 m of the draft Order Limits
MLI122328	Non-designated building	Peart's Farm Cottages (Peart's Farm), Holland Fen with Brothertoft	Peart's Farm Cottages (Peart's Farm), Holland Fen with Brothertoft. Redeveloped 19 th century farmstead. Loose courtyard with two sides of the courtyard formed by working agricultural buildings. The farmhouse was detached from the main working complex. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 2720 4618	Within the 1 km Study Area
MLI120346	Non-designated building	Unnamed farmstead, New Leake	Unnamed farmstead, New Leake. Redeveloped 19 th century farmstead. Loose courtyard with three sides of the courtyard	Post-medieval	TF 3874 5870	Within the 1 km Study Area

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
			formed by working agricultural buildings. The farmhouse was detached from the main working complex. Isolated location.			
MLI120399	Non-designated building	Unnamed farmstead, Midville	Unnamed farmstead, Midville. Redeveloped 19 th century farmstead. Loose courtyard with three sides of the courtyard formed by working agricultural buildings. The farmhouse was detached from the main working complex. Isolated location. Large modern sheds are located on the site	Post-medieval	TF 3862 5870	Within the 1 km Study Area
MLI123057	Non-designated building	Middle Farm, Frampton	Middle Farm, Frampton. Redeveloped 19 th century farmstead. Loose courtyard with three sides of the courtyard formed by working agricultural buildings. The farmhouse was detached from the main working complex. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 2801 4417	Within the 1 km Study Area
MLI124653	Non-designated building	Westville Farm, Frithville and Westville	Redeveloped 19 th century farmstead. Regular courtyard of U plan. The farmhouse was detached from the main working complex. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 2996 5165	Within the 1 km Study Area
MLI123060	Non-designated building	Unnamed farmstead, Frampton	Redeveloped 19 th century farmstead. Regular courtyard of L plan. The farmhouse was detached from the main working complex. Located within a loose farmstead cluster.	Post-medieval	TF 2724 4319	Within the 1 km Study Area
MLI122341	Non-designated building	Flatters, Holland Fen with Brothertoft	Redeveloped 19 th century farmstead. L-plan with additional detached elements. The farmhouse was attached to a range of working buildings. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 2695 4554	Within the 1 km Study Area
MLI120505	Non-designated building	Unnamed farmstead, Carrington	Redeveloped 19 th century farmstead. Regular courtyard of L plan. The farmhouse was detached from the main working complex. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 3218 5294	Within the 1 km Study Area
MLI120296	Non-designated building	Mount Pleasant Farm, Thorpe St. Peter	Mount Pleasant Farm, Thorpe St. Peter. Redeveloped 19 th century farmstead. Row with additional detached elements. The farmhouse was detached from the main working complex. Isolated location. Large modern sheds are located to the side of the site.	Post-medieval	TF 4561 6046	Within the 1 km Study Area
MLI119889	Non-designated building	St Michael's Farm, Burgh Le Marsh	Redeveloped 19 th century farmstead. Regular courtyard of L plan. The farmhouse was detached from the main working complex. Isolated location. Large modern sheds are located to the side of the site.	Post-medieval	TF 5135 6479	Within the 1 km Study Area
MLI122827	Non-designated building	Avondale, Wigtoft	Redeveloped 19 th century farmstead. Dispersed clustered plan. The farmhouse was attached to a range of working buildings. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 2509 3557	Within the 1 km Study Area
MLI120300	Non-designated building	The Fendykes, Thorpe St. Peter	Redeveloped 19 th century farmstead. Loose courtyard with two sides of the courtyard formed by working agricultural buildings. The farmhouse was detached from the main working complex. Located within a loose farmstead cluster. Large modern sheds are located on the site	Post-medieval	TF 4525 6043	Within the 1 km Study Area

_	_
2	R
	••

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
MLI122344	Non-designated building	Walnut Tree Farm, Holland Fen with Brothertoft	Redeveloped 19 th century farmstead. Regular courtyard with L- plan range plus detached buildings to the third side of the yard. The farmhouse was detached from the main working complex. Located within a loose farmstead cluster. Large modern sheds are located on the site.	Post-medieval	TF 2838 4582	Within the 1 km Study Area
MLI120321	Non-designated building	St. Catherine's Farm, Eastville	Redeveloped 19 th century farmstead. Regular courtyard with multiple regular yards. The farmhouse was detached from the main working complex. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 4142 5850	Within the 1 km Study Area
MLI118909	Non-designated building	Unnamed farmstead, Cumberworth	Redeveloped 19 th century farmstead. Row. The farmhouse is detached from the main working complex. Isolated location. Large modern sheds are located to the side of the site.	Post-medieval	TF 5075 7237	Within 100 m of the draft Order Limits
MLI120301	Non-designated building	Post Box Farm, Thorpe St. Peter	Redeveloped 19 th century farmstead. Loose courtyard with two sides of the courtyard formed by working agricultural buildings. The farmhouse was detached from the main working complex. Located within a loose farmstead cluster. Large modern sheds are located on the site.	Post-medieval	TF 4523 6037	Within the 1 km Study Area
MLI124594	Non-designated building	Neals' Old Farm, Sibsey	Redeveloped 19 th century farmstead. Regular courtyard of U plan. The farmhouse was attached to a range of working buildings. Isolated location.	Post-medieval	TF 3513 5366	Within the 1 km Study Area
MLI120336	Non-designated building	Boston Corporation Farm, New Leake	Redeveloped 19 th century farmstead. Loose courtyard with three sides of the courtyard formed by working agricultural buildings. The farmhouse was detached from the main working complex. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 3891 5968	Within the 1 km Study Area
MLI123030	Non-designated building	Pick's Barn, Kirton	Redeveloped 19 th century outfarm. Loose courtyard with a single side of the courtyard formed by working agricultural buildings. Isolated location. Large modern sheds are located to the side of the site.	Post-medieval	TF 2809 3875	Within the 1 km Study Area
MLI120499	Non-designated building	Wragg Hall Farm, Carrington	Redeveloped 19 th century farmstead. Loose courtyard with a single side of the courtyard formed by working agricultural buildings. The farmhouse was detached from the main working complex. Isolated location. Large modern sheds are located to the side of the site.	Post-medieval	TF 3125 5385	Within the 1 km Study Area
MLI124555	Non-designated building	Farmstead, Sibsey	Redeveloped 19 th century farmstead. Loose courtyard with three sides of the courtyard formed by working agricultural buildings. The farmhouse was detached with the long axis facing on to the yard. Located within or in association with a village. Large modern sheds are located to the side of the site.	Post-medieval	TF 3439 5323	Within the 1 km Study Area
MLI118935	Non-designated building	Ings Farm, Willoughby with Sloothby	Redeveloped 19 th century farmstead. Regular courtyard of L plan. The farmhouse is detached from the main working complex. Isolated location. Large modern sheds are located to the side of the site.	Post-medieval	TF 5028 7032	Within the 1 km Study Area

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
MLI120290	Non-designated building	Unnamed farmstead, Thorpe St. Peter	Redeveloped 19 th century farmstead. Regular courtyard of L plan. The farmhouse was detached from the main working complex. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 4615 6066	Within the 1 km Study Area
MLI120286	Non-designated building	School Farm Cottage, Thorpe St Peter	Redeveloped 19 th century farmstead. L-plan with additional detached elements. The farmhouse was detached from the main working complex. Isolated location.	Post-medieval	TF 47564 61294	Within the 1 km Study Area
MLI122444	Non-designated building	Timberland, Swineshead	Redeveloped 19 th century farmstead. Row with additional detached elements. The farmhouse was detached from the main working complex. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 2612 3869	Within the 1 km Study Area
MLI119886	Non-designated building	Pear Tree Farm (Peartree House), Burgh Le Marsh	Redeveloped 19 th century farmstead. L-plan with additional detached elements. The farmhouse was attached to a range of working buildings. Isolated location.	Post-medieval	TF 5104 6597	Within the 1 km Study Area
MLI122345	Non-designated building	Barley Close, Holland Fen with Brothertoft	Redeveloped 19 th century farmstead. Regular courtyard with L- plan range plus detached buildings to the third side of the yard. The farmhouse was detached from the main working complex. Located within a loose farmstead cluster. Large modern sheds are located on the site.	Post-medieval	TF 2858 4581	Within the 1 km Study Area
MLI122445	Non-designated building	Unnamed farmstead, Swineshead	Redeveloped 19 th century farmstead. Regular courtyard of F plan. The farmhouse was detached from the main working complex. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 2549 3815	Within the 1 km Study Area
MLI124694	Non-designated building	Chestnut Lodge, Thornton Le Fen	Redeveloped 19 th century farmstead. Loose courtyard with four sides of the courtyard formed by working agricultural buildings. The farmhouse was detached with the long axis facing on to the yard. Isolated location. Large modern sheds are located to the side of the site.	Post-medieval	TF 2834 5060	Within the 1 km Study Area
MLI122989	Non-designated building	Unnamed farmstead, Kirton	Redeveloped 19 th century farmstead. Loose courtyard with three sides of the courtyard formed by working agricultural buildings. The farmhouse was detached from the main working complex. Isolated location. Large modern sheds are located to the side of the site.	Post-medieval	TF 2839 4129	Within the 1 km Study Area
MLI118913	Non-designated building	North Farm, Farlesthorpe	Redeveloped 19 th century farmstead. Regular courtyard with L- plan range plus detached buildings to the third side of the yard. The farmhouse is detached from the main working complex. Located within a loose farmstead cluster. Large modern sheds are located on the site.	Post-medieval	TF 4714 7441	Within the 1 km Study Area
MLI124757	Non-designated building	Manor Farm, Langriville	Redeveloped 19 th century farmstead. Regular courtyard with linked working buildings to all four sides of the yard. The farmhouse was detached from the main working complex. Isolated location. Large modern sheds are located to the side of the site.	Post-medieval	TF 2704 4827	Within the 1 km Study Area
MLI120282	Non-designated building	Woodlands Cottage, Thorpe St. Peter	Redeveloped 19 th century farmstead. Loose courtyard with three sides of the courtyard formed by working agricultural buildings.	Post-medieval	TF 4827 6111	Within the 1 km Study Area

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
			The farmhouse was detached from the main working complex. Isolated location.			
MLI122878	Non-designated building	Vicarage Farm, Sutterton	Redeveloped 19 th century farmstead. Regular courtyard of U plan. The farmhouse was detached from the main working complex. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 2831 3227	Within the 1 km Study Area
MLI122351	Non-designated building	Creasey's Farm, Holland Fen with Brothertoft	Redeveloped 19 th century farmstead. Regular courtyard with L- plan range plus detached buildings to the third side of the yard. The farmhouse was detached from the main working complex. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 2855 4480	Within the 1 km Study Area
MLI120335	Non-designated building	Kesten Lodge, New Leake	Redeveloped 19 th century farmstead. Regular courtyard of U plan. The farmhouse was detached from the main working complex. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 4007 6018	Within the 1 km Study Area
MLI120379	Non-designated building	Bass Farm, Stickford	Redeveloped 19 th century farmstead. Regular courtyard of L plan. The farmhouse was detached from the main working complex. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 3886 6003	Within the 1 km Study Area
MLI118901	Non-designated building	Unnamed farmstead, Cumberworth	Redeveloped 19 th century farmstead. Regular courtyard of L plan. The farmhouse is detached from the main working complex. Located within or in association with a village. Large modern sheds are located on the site.	Post-medieval	TF 5065 7326	Within the 1 km Study Area
MLI120366	Non-designated building	Catchwater Cottage, New Leake	Redeveloped 19 th century farmstead. Regular courtyard of L plan. The farmhouse was detached from the main working complex. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 3496 5551	Within the 1 km Study Area
MLI118900	Non-designated building	Unnamed farmstead, Cumberworth	Redeveloped 19 th century farmstead. Linear. The farmhouse is attached to a range of working buildings. Located within or in association with a village.	Post-medieval	TF 5054 7348	Within the 1 km Study Area
MLI118893	Non-designated building	Ings Lane Farm, Cumberworth	Redeveloped 19 th century farmstead. Regular courtyard with linked working buildings to all four sides of the yard. The farmhouse is detached from the main working complex. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 5072 7332	Within the 1 km Study Area
MLI120334	Non-designated building	Unnamed farmstead, New Leake	Redeveloped 19 th century farmstead. Loose courtyard with three sides of the courtyard formed by working agricultural buildings. The farmhouse was detached from the main working complex. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 4033 6027	Within the 1 km Study Area
MLI120365	Non-designated building	Unnamed farmstead, New Leake	Redeveloped 19 th century farmstead. Dispersed clustered plan. The farmhouse was detached from the main working complex. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 3499 5561	Within the 1 km Study Area
MLI119877	Non-designated building	Middlemarsh Farm, Burgh Le Marsh	Redeveloped 19 th century farmstead. Regular courtyard of E plan. The farmhouse was detached from the main working complex. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 5283 6331	Within the 1 km Study Area
MLI123004	Non-designated building	Unnamed farmstead, Kirton	Redeveloped 19 th century farmstead. Regular courtyard with L- plan range plus detached buildings to the third side of the yard.	Post-medieval	TF 2839 3997	Within the 1 km Study Area

_	_
2	R
	••

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
			The farmhouse was detached from the main working complex. Isolated location. Large modern sheds are located on the site.			
MLI123027	Non-designated building	Woodbine Cottage, Kirton	Redeveloped 19 th century farmstead. Linear. The farmhouse was attached to a range of working buildings. Isolated location. Large modern sheds are located to the side of the site.	Post-medieval	TF 2855 3883	Within 100 m of the draft Order Limits
MLI120251	Non-designated building	Farmers Folly, Croft	Redeveloped 19 th century farmstead. Loose courtyard with three sides of the courtyard formed by working agricultural buildings. The farmhouse was detached with the gable end facing on to the yard. Isolated location. Large modern sheds are located to the side of the site.	Post-medieval	TF 5019 6146	Within the 1 km Study Area
MLI120247	Non-designated building	Brookfield, Croft	Redeveloped 19 th century farmstead. Loose courtyard with a single side of the courtyard formed by working agricultural buildings. The farmhouse was detached from the main working complex. Located within a loose farmstead cluster. Large modern sheds are located to the side of the site.	Post-medieval	TF 5137 6205	Within the 1 km Study Area
MLI124545	Non-designated building	Skirbeck Farm (Skirbeck Allotment), Sibsey	Redeveloped 19 th century farmstead. Regular courtyard of U plan. The farmhouse was detached with the gable end facing on to the yard. Isolated location. Large modern sheds are located to the side of the site.	Post-medieval	TF 3204 5450	Within the 1 km Study Area
MLI123058	Non-designated building	Slate House Farm, Frampton	Redeveloped 19 th century farmstead. Regular courtyard with multiple regular yards. The farmhouse was detached from the main working complex. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 2875 4359	Within the 1 km Study Area
MLI118894	Non-designated building	Unnamed farmstead, Cumberworth	Redeveloped 19 th century farmstead. Regular courtyard of U plan. The farmhouse is detached from the main working complex. Located within or in association with a village. Large modern sheds are located on the site.	Post-medieval	TF 5065 7374	Within the 1 km Study Area
MLI122808	Non-designated building	Unnamed farmstead, Wigtoft	Redeveloped 19 th century farmstead. Regular courtyard with L- plan range plus detached buildings to the third side of the yard. The farmhouse was detached from the main working complex. Isolated location. Large modern sheds are located to the side of the site.	Post-medieval	TF 2451 3767	Within the 1 km Study Area
MLI122816	Non-designated building	Slate House, Wigtoft	19 th century farmstead. Regular courtyard of U plan. The farmhouse is detached from the main working complex. The farmhouse is the only surviving historic structure. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 2645 3719	Within the 1 km Study Area
MLI122833	Non-designated building	Unnamed farmstead, Wigtoft	Partially extant 19 th century farmstead. Regular courtyard of U plan. The farmhouse is detached from the main working complex. There has been significant loss (greater than 50%) of traditional buildings. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 2609 3593	Within 100 m of the draft Order Limits
MLI120318	Non-designated building	West Royalty Farm (Royalty Farm), Eastville	Partially extant 19 th century farmstead. Dispersed with multiple regular yards. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of	Post-medieval	TF 4102 5925	Within 100 m of the draft Order Limits

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
			traditional buildings. Isolated location. Large modern sheds are located to the side of the site			
MLI116616	Non-designated building	Bilsby Farm, Bilsby	Partially extant 19 th century farmstead. Regular courtyard of L plan. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 4853 7600	Within 100 m of the draft Order Limits
MLI120358	Non-designated building	Unnamed farmstead, New Leake	Partially extant 19 th century farmstead. Loose courtyard with two sides of the courtyard formed by working agricultural buildings. The farmhouse is attached to a range of working buildings. There has been significant loss (greater than 50%) of traditional buildings. Isolated location. Large modern sheds are located to the side of the site.	Post-medieval	TF 3808 5559	Within 100 m of the draft Order Limits
MLI119853	Non-designated building	Unnamed farmstead, Orby	Partially extant 19 th century farmstead. L-plan with additional detached elements. The farmhouse is attached to a range of working buildings. There has been a partial loss (less than 50%) of traditional buildings. Isolated location.	Post-medieval	TF 5166 6721	Within 100 m of the draft Order Limits
MLI122327	Non-designated building	Vicarage Farm, Holland Fen with Brothertoft	Partially extant 19 th century farmstead. Regular courtyard of U plan. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Isolated location.	Post-medieval	TF 2743 4614	Within 100 m of the draft Order Limits
MLI120316	Non-designated building	Moonraker, Thorpe St. Peter	Partially extant 19 th century farmstead. Regular courtyard with L- plan range plus detached buildings to the third side of the yard. The farmhouse is detached from the main working complex. There has been significant loss (greater than 50%) of traditional buildings. Isolated location	Post-medieval	TF 4188 6056	Within 100 m of the draft Order Limits
MLI116612	Non-designated building	Thurlby House (Thurlby Grove), Bilsby	Partially extant 19 th century farmstead. Regular courtyard with linked working buildings to all four sides of the yard. The farmhouse is detached with the long axis facing on to the yard. There has been significant loss (greater than 50%) of traditional buildings. Located within a loose farmstead cluster.	Post-medieval	TF 4915 7573	Within 100 m of the draft Order Limits
MLI116617	Non-designated building	Dryby Farm, Bilsby	Extant 19 th century farmstead. Regular courtyard of U plan. The farmhouse is attached to a range of working buildings. Isolated location. Large modern sheds are located to the side of the site.	Post-medieval	TF 4851 7641	Within 100 m of the draft Order Limits
MLI122565	Non-designated building	Hill's Farm), Gosberton	19 th century farmstead. Regular courtyard of F plan. The farmhouse is detached from the main working complex. The farmhouse is the only surviving historic structure. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 2734 3139	Within 100 m of the draft Order Limits
MLI122812	Non-designated building	Unnamed farmstead, Wigtoft	Partially extant 19 th century farmstead. Regular courtyard of U plan. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Isolated location. Large modern sheds are located to the side of the site.	Post-medieval	TF 2537 3705	Within 100 m of the draft Order Limits

	_
-	D
51	T
_	

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
MLI124595	Non-designated building	Barbridge Farm, Sibsey	Partially extant 19 th century farmstead. Regular courtyard of T plan. The farmhouse is detached from the main working complex. There has been significant loss (greater than 50%) of traditional buildings. Isolated location.	Post-medieval	TF 3520 5409	Within 100 m of the draft Order Limits
MLI118905	Non-designated building	Field House Farm, Cumberworth	Partially extant 19 th century farmstead. Loose courtyard with two sides of the courtyard formed by working agricultural buildings. The farmhouse is attached to a range of working buildings. There has been a partial loss (less than 50%) of traditional buildings. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 4969 7379	Within 100 m of the draft Order Limits
MLI120304	Non-designated building	Decoy Farm, Thorpe St. Peter	Partially extant 19 th century farmstead. Dispersed with multiple regular yards. The farmhouse is detached from the main working complex. There has been significant loss (greater than 50%) of traditional buildings. Isolated location.	Post-medieval	TF 4409 6066	Within 100 m of the draft Order Limits
MLI118918	Non-designated building	School Farm, Farlesthorpe	Partially extant 19 th century farmstead. Regular courtyard of F plan. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 4816 7374	Within 100 m of the draft Order Limits
MLI122315	Non-designated building	Elm Tree Farm, Holland Fen with Brothertoft	Partially extant 19 th century farmstead. Regular courtyard with L- plan range plus detached buildings to the third side of the yard. The farmhouse is attached to a range of working buildings. There has been a partial loss (less than 50%) of traditional buildings. Located within or in association with a hamlet. Large modern sheds are located to the side of the site.	Post-medieval	TF 2672 4746	Within 100 m of the draft Order Limits
MLI119892	Non-designated building	Lloyds Farm (Marsh Farm), Burgh Le Marsh	Partially extant 19 th century farmstead. Loose courtyard with two sides of the courtyard formed by working agricultural buildings. The farmhouse is detached from the main working complex. There has been significant loss (greater than 50%) of traditional buildings. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 5124 6385	Within 100 m of the draft Order Limits
MLI120322	Non-designated building	Hemholme Farm, Eastville	19 th century farmstead. Loose courtyard with two sides of the courtyard formed by working agricultural buildings. The farmhouse is detached from the main working complex. The farmhouse is the only surviving historic structure. Isolated location.	Post-medieval	TF 4071 5866	Within 100 m of the draft Order Limits
MLI120317	Non-designated building	East Royalty Farm (Royalty Farm East), Eastville	Partially extant 19 th century farmstead. Regular courtyard with L- plan range plus detached buildings to the third side of the yard. The farmhouse is detached from the main working complex. There has been significant loss (greater than 50%) of traditional buildings. Isolated location. Large modern sheds are located to the side of the site.	Post-medieval	TF 4193 5992	Within 100 m of the draft Order Limits
MLI124549	Non-designated building	Farmstead, Sibsey	Partially extant 19 th century farmstead. Regular courtyard with L- plan range plus detached buildings to the fourth side of the yard. The farmhouse is detached from the main working complex.	Post-medieval	TF 3333 5415	Within 100 m of the draft Order Limits

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
			There has been significant loss (greater than 50%) of traditional buildings. Located within a loose farmstead cluster.			
MLI118906	Non-designated building	Cumberworth West Farm, Cumberworth	Partially extant 19 th century farmstead. Regular courtyard of L plan. The farmhouse is detached from the main working complex. There has been significant loss (greater than 50%) of traditional buildings. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 4974 7346	Within 100 m of the draft Order Limits
MLI120360	Non-designated building	The Laurels, New Leake	Partially extant 19 th century farmstead. Loose courtyard with two sides of the courtyard formed by working agricultural buildings. The farmhouse is detached from the main working complex. There has been significant loss (greater than 50%) of traditional buildings. Isolated location. Large modern sheds are located to the side of the site.	Post-medieval	TF 3665 5511	Within 100 m of the draft Order Limits
MLI122996	Non-designated building	The Moletrap, Kirton	Partially extant 19 th century farmstead. Regular courtyard with L- plan range plus detached buildings to the third side of the yard. The farmhouse is detached from the main working complex. There has been significant loss (greater than 50%) of traditional buildings. Located within a loose farmstead cluster. Large modern sheds are located on the site.	Post-medieval	TF 2697 4134	Within 100 m of the draft Order Limits
MLI119831	Non-designated building	Unnamed farmstead, Addlethorpe	Partially extant 19 th century farmstead. Regular courtyard with L- plan range plus detached buildings to the third side of the yard. The farmhouse is detached from the main working complex. There has been significant loss (greater than 50%) of traditional buildings. Isolated location.	Post-medieval	TF 5216 6873	Within 100 m of the draft Order Limits
MLI122578	Non-designated building	Woad Farm, Surfleet	Partially extant 19 th century farmstead. Regular courtyard of F plan. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Isolated location. Large modern sheds are located to the side of the site	Post-medieval	TF 2786 3048	Within 100 m of the draft Order Limits
MLI122986	Non-designated building	Fieldside, Kirton	Partially extant 19 th century farmstead. Regular courtyard of L plan. The farmhouse is attached to a range of working buildings. There has been a partial loss (less than 50%) of traditional buildings. Isolated location. Large modern sheds are located to the side of the site.	Post-medieval	TF 2753 4262	Within 100 m of the draft Order Limits
MLI124547	Non-designated building	Sycamore Farm, Sibsey	19 th century farmstead. Loose courtyard with three sides of the courtyard formed by working agricultural buildings. The farmhouse is detached with the gable end facing on to the yard. The farmhouse is the only surviving historic structure. Located within a loose farmstead cluster. Large modern sheds are located to the side of the site.	Post-medieval	TF 3272 5385	Within 100 m of the draft Order Limits
MLI122325	Non-designated building	Bamber's Farm, Holland Fen with Brothertoft	Extant 19 th century farmstead. Loose courtyard with two sides of the courtyard formed by working agricultural buildings. The farmhouse is detached with the long axis facing on to the yard. Isolated location. Large modern sheds are located to the side of the site.	Post-medieval	TF 2709 4680	Within 100 m of the draft Order Limits

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
MLI122840	Non-designated building	Goosegreen Farm (Belton Farm), Wigtoft	Partially extant 19 th century farmstead. Regular courtyard of E plan. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Isolated location. Large modern sheds are located to the side of the site.	Post-medieval	TF 2656 3395	Within 100 m of the draft Order Limits
MLI119854	Non-designated building	Marsh House Farm, Orby	Partially extant 19 th century farmstead. L-plan. The farmhouse is attached to a range of working buildings. There has been a partial loss (less than 50%) of traditional buildings. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 5129 6733	Within 100 m of the draft Order Limits
MLI122865	Non-designated building	Bank House Farm, Sutterton	Partially extant 19 th century farmstead. Regular courtyard of L plan. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Isolated location. Large modern sheds are located to the side of the site.	Post-medieval	TF 2668 3342	Within 100 m of the draft Order Limits
MLI119952	Non-designated building	Millhill Farm, Irby in the Marsh	19 th century farmstead. Row with additional detached elements. The farmhouse is detached from the main working complex. The farmhouse is the only surviving historic structure. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 4822 6186	Within 100 m of the draft Order Limits
MLI122987	Non-designated building	Unnamed farmstead, Kirton	Partially extant 19 th century farmstead. Row with additional detached elements. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Isolated location. Large modern sheds are located to the side of the site.	Post-medieval	TF 2804 4211	Within 100 m of the draft Order Limits
MLI123063	Non-designated building	The Firs, Frampton	19 th century farmstead. Loose courtyard with two sides of the courtyard formed by working agricultural buildings. The farmhouse is detached from the main working complex. The farmhouse is the only surviving historic structure. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 2800 4281	Within 100 m of the draft Order Limits
MLI120447	Non-designated building	The Cottage, Stickney	Partially extant 19 th century farmstead. Parallel. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Located within a loose farmstead cluster. Large modern sheds are located on the site.		TF 3488 5476	Within 100 m of the draft Order Limits
MLI122314	Non-designated building	Ferry Farm, Holland Fen with Brothertoft	19 th century farmstead. Regular courtyard of E plan. The farmhouse is detached from the main working complex. The farmhouse is the only surviving historic structure. Located within or in association with a hamlet. Large modern sheds are located on the site.	Post-medieval	TF 2660 4744	Within 100 m of the draft Order Limits
MLI118904	Non-designated building	Rose Cottage, Cumberworth	Partially extant 19 th century farmstead. Row. The farmhouse is attached to a range of working buildings. There has been significant loss (greater than 50%) of traditional buildings. Isolated location. Large modern sheds are located to the side of the site	Post-medieval	TF 4967 7398	Within 100 m of the draft Order Limits
MLI120408	Non-designated building	Waite's Farm, Midville	Partially extant 19 th century farmstead. Regular courtyard with L- plan range plus detached buildings to the third side of the yard.	Post-medieval	TF 3835 5657	Within the 1 km Study Area

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
			The farmhouse is detached from the main working complex. There has been significant loss (greater than 50%) of traditional buildings. Isolated location. Large modern sheds are located to the side of the site.			
MLI124702	Non-designated building	Saratoga, Thornton Le Fen	Partially extant 19 th century farmstead. Regular courtyard of L plan. The farmhouse is detached with the gable end facing on to the yard. There has been a partial loss (less than 50%) of traditional buildings. Isolated location.	Post-medieval	TF 2830 4958	Within 100 m of the draft Order Limits
MLI122836	Non-designated building	Unnamed farmstead (Parr's Cottages), Wigtoft	Partially extant 19 th century farmstead. Regular courtyard of F plan. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Isolated location. Large modern sheds are located to the side of the site.	Post-medieval	TF 2616 3425	Within the 1 km Study Area
MLI123000	Non-designated building	Sunnyside Farm, Kirton	Partially extant 19 th century farmstead. Regular courtyard of L plan. The farmhouse is detached from the main working complex. There has been significant loss (greater than 50%) of traditional buildings. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 2752 4083	Within the 1 km Study Area
MLI120283	Non-designated building	Lymn Bank Farm, Thorpe St. Peter	Partially extant 19 th century farmstead. Loose courtyard with three sides of the courtyard formed by working agricultural buildings. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 4807 6171	Within the 1 km Study Area
MLI119887	Non-designated building	Willow Lodge, Burgh Le Marsh	Partially extant 19 th century farmstead. Regular courtyard of Z plan. The farmhouse is attached to a range of working buildings. There has been a partial loss (less than 50%) of traditional buildings. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 5146 6575	Within 100 m of the draft Order Limits
MLI118916	Non-designated building	Farlesthorpe House Farm, Farlesthorpe	Partially extant 19 th century farmstead. Regular courtyard of F plan. The farmhouse is attached to a range of working buildings. There has been a partial loss (less than 50%) of traditional buildings. Located within a loose farmstead cluster. Large modern sheds are located to the side of the site	Post-medieval	TF 4770 7420	Within 100 m of the draft Order Limits
MLI122326	Non-designated building	Gee's Farm, Holland Fen with Brothertoft	19 th century farmstead. Loose courtyard with two sides of the courtyard formed by working agricultural buildings. The farmhouse is detached from the main working complex. The farmhouse is the only surviving historic structure. Isolated location. Large modern sheds are located to the side of the site	Post-medieval	TF 2719 4664	Within the 1 km Study Area
MLI122579	Non-designated building	Unnamed farmstead, Surfleet	Partially extant 19 th century farmstead. Regular courtyard of U plan. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Isolated location. Large modern sheds are located to the side of the site.	Post-medieval	TF 2717 3103	Within the 1 km Study Area

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
MLI124654	Non-designated building	Riggals Farm, Frithville and Westville	Partially extant 19 th century farmstead. Regular courtyard with L- plan range plus detached buildings to the third side of the yard. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Isolated location. Large modern sheds are located to the side of the site.	Post-medieval	TF 2935 5114	Within the 1 km Study Area
MLI119855	Non-designated building	Marsh Farm, Orby	Partially extant 19 th century farmstead. Loose courtyard with four sides of the courtyard formed by working agricultural buildings. The farmhouse is attached to a range of working buildings. There has been significant loss (greater than 50%) of traditional buildings. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 5119 6732	Within the 1 km Study Area
MLI118915	Non-designated building	Glebe Farm, Farlesthorpe	Extant 19 th century farmstead. Regular courtyard of L plan. The farmhouse is detached from the main working complex. Located within a loose farmstead cluster. Large modern sheds are located to the side of the site.	Post-medieval	TF 4754 7406	Within the 1 km Study Area
MLI123001	Non-designated building	Jubilee Farm, Kirton	Partially extant 19 th century farmstead. Regular courtyard of U plan. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 2779 4063	Within the 1 km Study Area
MLI124767	Non-designated building	Holme Farm, Langriville	19 th century farmstead. Regular courtyard of T plan. The farmhouse is attached to a range of working buildings. The farmhouse is the only surviving historic structure. Isolated location.	Post-medieval	TF 2751 4864	Within 100 m of the draft Order Limits
MLI118927	Non-designated building	Bonthorpe Farm, Willoughby with Sloothby	Partially extant 19 th century farmstead. Regular courtyard with multiple regular yards. The farmhouse is attached to a range of working buildings. There has been a partial loss (less than 50%) of traditional buildings. Isolated location. Large modern sheds are located to the side of the site.	Post-medieval	TF 4818 7295	Within the 1 km Study Area
MLI118923	Non-designated building	Unnamed farmstead, Willoughby with Sloothby	Partially extant 19 th century farmstead. L-plan with additional detached elements. The farmhouse is detached with the long axis facing on to the yard. There has been a partial loss (less than 50%) of traditional buildings. Isolated location. Large modern sheds are located to the side of the site.	Post-medieval	TF 4939 7291	Within the 1 km Study Area
MLI120241	Non-designated building	The Old Barn, Croft	Partially extant 19 th century farmstead. Dispersed clustered plan. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Isolated location. Large modern sheds are located on the site	Post-medieval	TF 5032 6305	Within the 1 km Study Area
MLI120342	Non-designated building	The Shrubbery, New Leake	19 th century farmstead. Regular courtyard of L plan. The farmhouse is detached from the main working complex. The farmhouse is the only surviving historic structure. Located within a loose farmstead cluster.	Post-medieval	TF 4006 5855	Within the 1 km Study Area

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
MLI123002	Non-designated building	The Mantles, Kirton	Extant 19 th century farmstead. Loose courtyard with three sides of the courtyard formed by working agricultural buildings. The farmhouse is attached to a range of working buildings. Isolated location. Large modern sheds are located to the side of the site.	Post-medieval	TF 2785 4067	Within the 1 km Study Area
MLI120319	Non-designated building	Bellwater Farm, Eastville	Partially extant 19 th century farmstead. Regular courtyard of U plan. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 4236 5901	Within the 1 km Study Area
MLI122814	Non-designated building	Asperton Farm, Wigtoft	Partially extant 19 th century farmstead. Regular courtyard with linked working buildings to all four sides of the yard. The farmhouse is detached from the main working complex. There has been significant loss (greater than 50%) of traditional buildings. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 2609 3796	Within 100 m of the draft Order Limits
MLI120295	Non-designated building	Thorpe House, Thorpe St. Peter	Partially extant 19 th century farmstead. Regular courtyard of L plan. The farmhouse is attached to a range of working buildings. There has been a partial loss (less than 50%) of traditional buildings. Isolated location. Large modern sheds are located to the side of the site	Post-medieval	TF 4591 6089	Within the 1 km Study Area
MLI122568	Non-designated building	Old Three Tuns Farm, Surfleet	Partially extant 19 th century farmstead. Regular courtyard of L plan. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 2815 3027	Within the 1 km Study Area
MLI120380	Non-designated building	Silver Pit Farm, Stickford	Partially extant 19 th century farmstead. Regular courtyard with L- plan range plus detached buildings to the third side of the yard. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 3877 5942	Within the 1 km Study Area
MLI123015	Non-designated building	Cottage Farm (The Cottage), Kirton	Partially extant 19 th century farmstead. Regular courtyard of Z plan. The farmhouse is detached from the main working complex. There has been significant loss (greater than 50%) of traditional buildings. Located within a loose farmstead cluster. Large modern sheds are located on the site	Post-medieval	TF 2766 3996	Within the 1 km Study Area
MLI120361	Non-designated building	Unnamed farmstead, New Leake	Partially extant 19 th century farmstead. Regular courtyard with L- plan range plus detached buildings to the fourth side of the yard. The farmhouse is detached with the long axis facing on to the yard. There has been a partial loss (less than 50%) of traditional buildings. Isolated location. Large modern sheds are located to the side of the site.	Post-medieval	TF 3680 5533	Within 100 m of the draft Order Limits
MLI124701	Non-designated building	Farmstead, Thornton Le Fen	Partially extant 19 th century farmstead. Loose courtyard with three sides of the courtyard formed by working agricultural buildings. The farmhouse is detached from the main working complex.	Post-medieval	TF 2859 4987	Within the 1 km Study Area

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
			There has been significant loss (greater than 50%) of traditional buildings. Isolated location			
MLI123019	Non-designated building	Ickle Cottage, Kirton	19 th century farmstead. Regular courtyard with L-plan range plus detached buildings to the third side of the yard. The farmhouse is detached from the main working complex. The farmhouse is the only surviving historic structure. Isolated location. Large modern sheds are located to the side of the site	Post-medieval	TF 2707 3982	Within 100 m of the draft Order Limits
MLI120504	Non-designated building	Hackerley Bridge Farm, Carrington	Partially extant 19 th century farmstead. Regular courtyard with L- plan range plus detached buildings to the third side of the yard. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Isolated location.	Post-medieval	TF 3210 5288	Within the 1 km Study Area
MLI123061	Non-designated building	The Orchards, Frampton	Extant 19 th century farmstead. Row. The farmhouse is detached from the main working complex. Located within a loose farmstead cluster. Large modern sheds are located to the side of the site.	Post-medieval	TF 2730 4324	Within the 1 km Study Area
MLI124700	Non-designated building	Middle Farm House, Thornton Le Fen	Partially extant 19 th century farmstead. Loose courtyard with two sides of the courtyard formed by working agricultural buildings. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Isolated location	Post-medieval	TF 2859 4994	Within the 1 km Study Area
MLI116614	Non-designated building	White House Farm, Bilsby	Partially extant 19 th century farmstead. Loose courtyard with three sides of the courtyard formed by working agricultural buildings. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Located within a loose farmstead cluster. Large modern sheds are located on the site	Post-medieval	TF 4941 7591	Within 100 m of the draft Order Limits
MLI119998	Non-designated building	Glebe Farm, Halton Holegate	Partially extant 19 th century farmstead. Regular courtyard of L plan. The farmhouse is detached from the main working complex. There has been significant loss (greater than 50%) of traditional buildings. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 4206 6070	Within the 1 km Study Area
MLI124693	Non-designated building	Newham Farm, Thornton Le Fen	Partially extant 19 th century farmstead. Regular courtyard with L- plan range plus detached buildings to the third side of the yard. The farmhouse is detached from the main working complex. There has been significant loss (greater than 50%) of traditional buildings. Isolated location. Large modern sheds are located to the side of the site.	Post-medieval	TF 2870 5058	Within the 1 km Study Area
MLI119884	Non-designated building	Sycamore Farm, Burgh Le Marsh	Partially extant 19 th century farmstead. Loose courtyard with two sides of the courtyard formed by working agricultural buildings. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Isolated location. Large modern sheds are located to the side of the site.	Post-medieval	TF 5164 6626	Within the 1 km Study Area

_	_
2	R
	••

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
MLI119882	Non-designated building	Nettle Hill Farm, Burgh Le Marsh	19 th century farmstead. Regular courtyard of L plan. The farmhouse is detached from the main working complex. The farmhouse is the only surviving historic structure. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 5232 6610	Within the 1 km Study Area
MLI122441	Non-designated building	Unnamed farmstead, Swineshead	Partially extant 19 th century farmstead. Regular courtyard with L- plan range plus detached buildings to the third side of the yard. The farmhouse is attached to a range of working buildings. There has been a partial loss (less than 50%) of traditional buildings. Isolated location. Large modern sheds are located to the side of the site.	Post-medieval	TF 2659 3995	Within the 1 km Study Area
MLI120293	Non-designated building	Unnamed farmstead, Thorpe St. Peter	Partially extant 19 th century farmstead. Regular courtyard of T plan. The farmhouse is detached from the main working complex. There has been significant loss (greater than 50%) of traditional buildings. Isolated location.	Post-medieval	TF 4530 6132	Within the 1 km Study Area
MLI124650	Non-designated building	Conifer Cottage, Frithville and Westville	Partially extant 19 th century farmstead. Loose courtyard with three sides of the courtyard formed by working agricultural buildings. The farmhouse is detached with the long axis facing on to the yard. There has been significant loss (greater than 50%) of traditional buildings. Isolated location. Large modern sheds are located to the side of the site.	Post-medieval	TF 2974 5277	Within the 1 km Study Area
MLI120357	Non-designated building	Unnamed farmstead, New Leake	Partially extant 19 th century farmstead. Regular courtyard with L- plan range plus detached buildings to the third side of the yard. The farmhouse is detached from the main working complex. There has been significant loss (greater than 50%) of traditional buildings. Located within a loose farmstead cluster.	Post-medieval	TF 3812 5534	Within the 1 km Study Area
MLI123020	Non-designated building	Pippinhall, Kirton	19 th century farmstead. Regular courtyard of U plan. The farmhouse is detached from the main working complex. The farmhouse is the only surviving historic structure. Isolated location. Large modern sheds are located to the side of the site.	Post-medieval	TF 2695 3972	Within the 1 km Study Area
MLI118903	Non-designated building	Oakleigh, Cumberworth	19 th century farmstead. Loose courtyard with three sides of the courtyard formed by working agricultural buildings. The farmhouse is detached from the main working complex. The farmhouse is the only surviving historic structure. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 4994 7400	Within the 1 km Study Area
MLI120347	Non-designated building	Winslow, New Leake	Partially extant 19 th century farmstead. Loose courtyard with three sides of the courtyard formed by working agricultural buildings. The farmhouse is detached with the long axis facing on to the yard. There has been a partial loss (less than 50%) of traditional buildings. Isolated location.	Post-medieval	TF 3861 5805	Within the 1 km Study Area
MLI123014	Non-designated building	Home Farm, Kirton	Partially extant 19 th century farmstead. Regular courtyard with L- plan range plus detached buildings to the third side of the yard. The farmhouse is detached with the long axis facing on to the yard. There has been a partial loss (less than 50%) of traditional buildings. Located within a loose farmstead cluster. Large modern sheds are located on the site.	Post-medieval	TF 2773 3996	Within the 1 km Study Area

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
MLI122985	Non-designated building	Barford Farm, Kirton	Partially extant 19 th century farmstead. Loose courtyard with two sides of the courtyard formed by working agricultural buildings. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 2728 4258	Within the 1 km Study Area
MLI124758	Non-designated building	Rectory Farm, Langriville		Post-medieval	TF 2824 4817	Within the 1 km Study Area
MLI120306	Non-designated building	Pape's Farm, Thorpe St. Peter	Partially extant 19 th century farmstead. Regular courtyard with linked working buildings to all four sides of the yard. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Isolated location.	Post-medieval	TF 4496 6134	Within the 1 km Study Area
MLI120503	Non-designated building	Harvest Man Inn, Carrington	Extant 19 th century farmstead. Regular courtyard with L-plan range plus detached buildings to the third side of the yard. The farmhouse is detached from the main working complex. Located within or in association with a hamlet. Large modern sheds are located to the side of the site.	Post-medieval	TF 3133 5281	Within the 1 km Study Area
MLI118910	Non-designated building	Glebe Farm, Cumberworth	Partially extant 19 th century farmstead. Regular courtyard with L- plan range plus detached buildings to the third side of the yard. The farmhouse is detached from the main working complex. There has been significant loss (greater than 50%) of traditional buildings. Isolated location. Large modern sheds are located to the side of the site.	Post-medieval	TF 5071 7229	Within the 1 km Study Area
MLI120292	Non-designated building	Unnamed farmstead, Thorpe St. Peter	19 th century farmstead. Regular courtyard of U plan. The farmhouse is detached from the main working complex. The farmhouse is the only surviving historic structure. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 4540 6147	Within the 1 km Study Area
MLI120240	Non-designated building	Tree Farm, Croft	Partially extant 19 th century farmstead. Row with additional detached elements. The farmhouse is detached from the main working complex. There has been significant loss (greater than 50%) of traditional buildings. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 5029 6322	Within the 1 km Study Area
MLI119878	Non-designated building	Vine Farm (Vine Cottage), Burgh Le Marsh	Partially extant 19 th century farmstead. Regular courtyard of L plan. The farmhouse is detached from the main working complex. There has been significant loss (greater than 50%) of traditional buildings. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 5229 6346	Within the 1 km Study Area
MLI122443	Non-designated building	Blackjack Farm, Swineshead	Partially extant 19 th century farmstead. Regular courtyard of L plan. The farmhouse is detached from the main working complex. There has been significant loss (greater than 50%) of traditional buildings. Isolated location. Large modern sheds are located to the side of the site	Post-medieval	TF 2698 3932	Within the 1 km Study Area

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
MLI124698	Non-designated building	Ranson's Farm, Thornton Le Fen	Extant 19 th century farmstead. Loose courtyard with three sides of the courtyard formed by working agricultural buildings. The farmhouse is detached with the gable end facing on to the yard. Located within or in association with a village.	Post-medieval	TF 2816 4975	Within the 1 km Study Area
MLI122820	Non-designated building	Bridge Farm (Red House), Wigtoft	Partially extant 19 th century farmstead. Regular courtyard of L plan. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Isolated location. Large modern sheds are located on the site	Post-medieval	TF 2663 3691	Within the 1 km Study Area
MLI124641	Non-designated building	Castle Dyke House, Frithville and Westville	Partially extant 19 th century farmstead. Regular courtyard of E plan. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Isolated location. Large modern sheds are located to the side of the site.	Post-medieval	TF 2898 4897	Within the 1 km Study Area
MLI120299	Non-designated building	Chapel Farm, Thorpe St. Peter	19th century farmstead. Loose courtyard with two sides of the courtyard formed by working agricultural buildings. The farmhouse is detached from the main working complex. The farmhouse is the only surviving historic structure. Located within a loose farmstead cluster. Large modern sheds are located on the site.	Post-medieval	TF 4515 6045	Within the 1 km Study Area
MLI120348	Non-designated building	Woddys Den, New Leake	Partially extant 19 th century farmstead. Loose courtyard with four sides of the courtyard formed by working agricultural buildings. The farmhouse is attached to a range of working buildings. There has been significant loss (greater than 50%) of traditional buildings. Isolated location. Large modern sheds are located to the side of the site	Post-medieval	TF 3856 5774	Within the 1 km Study Area
MLI124699	Non-designated building	Thornton Lodge, Thornton Le Fen	Extant 19 th century farmstead. Loose courtyard with two sides of the courtyard formed by working agricultural buildings. The farmhouse is attached to a range of working buildings. Located within or in association with a village.	Post-medieval	TF 2819 4981	Within the 1 km Study Area
MLI120356	Non-designated building	Whitehouse, New Leake	Partially extant 19 th century farmstead. Loose courtyard with four sides of the courtyard formed by working agricultural buildings. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Located within a loose farmstead cluster. Large modern sheds are located on the site	Post-medieval	TF 3799 5524	Within the 1 km Study Area
MLI122577	Non-designated building	Unnamed farmstead, Surfleet	19 th century farmstead. Regular courtyard with L-plan range plus detached buildings to the third side of the yard. The farmhouse is detached from the main working complex. The farmhouse is the only surviving historic structure. Isolated location. Large modern sheds are located on the site	Post-medieval	TF 2746 3043	Within the 1 km Study Area
MLI116625	Non-designated building	Hollutrix Farm, Bilsby	Extant 19 th century farmstead. Regular courtyard of U plan. Additional, prominent detached elements to the main plan. The farmhouse is detached from the main working complex. Isolated location. Large modern sheds are located to the side of the site	Post-medieval	TF 4794 7623	Within the 1 km Study Area

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
MLI120406	Non-designated building	White House Farm, Midville	Partially extant 19 th century farmstead. Regular courtyard of Z plan. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Isolated location. Large modern sheds are located on the site	Post-medieval	TF 3763 5701	Within the 1 km Study Area
MLI122813	Non-designated building	Unnamed farmstead, Wigtoft	19 th century farmstead. Regular courtyard with L-plan range plus detached buildings to the third side of the yard. The farmhouse is detached from the main working complex. The farmhouse is the only surviving historic structure. Isolated location. Large modern sheds are located to the side of the site	Post-medieval	TF 2595 3765	Within 100 m of the draft Order Limits
MLI124602	Non-designated building	Hakerley Bridge, Frithville and Westville	Partially extant 19 th century farmstead. Loose courtyard with two sides of the courtyard formed by working agricultural buildings. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Located within a loose farmstead cluster. Large modern sheds are located to the side of the site.	Post-medieval	TF 3222 5296	Within the 1 km Study Area
MLI123059	Non-designated building	The Old Farmhouse, Frampton	Partially extant 19 th century farmstead. Regular courtyard with L- plan range plus detached buildings to the third side of the yard. The farmhouse is detached from the main working complex. There has been significant loss (greater than 50%) of traditional buildings. Located within a loose farmstead cluster. Large modern sheds are located on the site	Post-medieval	TF 2715 4324	Within the 1 km Study Area
MLI124652	Non-designated building	Home Farm, Frithville and Westville	Partially extant 19 th century farmstead. Regular courtyard with L- plan range plus detached buildings to the third side of the yard. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Isolated location	Post-medieval	TF 3019 5150	Within the 1 km Study Area
MLI120285	Non-designated building	White House Farm (White Cottage), Thorpe St. Peter	Partially extant 19 th century farmstead. Regular courtyard of L plan. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Isolated location. Large modern sheds are located to the side of the site	Post-medieval	TF 4767 6140	Within the 1 km Study Area
MLI122823	Non-designated building	Unnamed farmstead, Wigtoft	Partially extant 19 th century farmstead. Regular courtyard of E plan. The farmhouse is attached to a range of working buildings. There has been a partial loss (less than 50%) of traditional buildings. Located within or in association with a village. Large modern sheds are located on the site	Post-medieval	TF 2645 3605	Within the 1 km Study Area
MLI119959	Non-designated building	Clough Farm, Firsby	19 th century farmstead. Row with additional detached elements. The farmhouse is detached from the main working complex. The farmhouse is the only surviving historic structure. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 4577 6207	Within the 1 km Study Area
MLI122993	Non-designated building	Yewtree Farmhouse, Kirton	Partially extant 19 th century farmstead. Parallel with additional detached elements. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%)	Post-medieval	TF 2667 4152	Within the 1 km Study Area

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
			of traditional buildings. Located within a loose farmstead cluster. Large modern sheds are located to the side of the site			
MLI122830	Non-designated building	Yewtree House, Wigtoft	19 th century farmstead. Loose courtyard with four sides of the courtyard formed by working agricultural buildings. The farmhouse is detached from the main working complex. The farmhouse is the only surviving historic structure. Isolated location. Large modern sheds are located to the side of the site.	Post-medieval	TF 2534 3526	Within the 1 km Study Area
MLI122313	Non-designated building	Unnamed farmstead, Holland Fen with Brothertoft	Partially extant 19 th century farmstead. Regular courtyard of L plan. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Isolated location. Large modern sheds are located to the side of the site	Post-medieval	TF 2630 4732	Within the 1 km Study Area
MLI124554	Non-designated building	The Crest, Sibsey	Partially extant 19 th century farmstead. Loose courtyard with three sides of the courtyard formed by working agricultural buildings. The farmhouse is detached from the main working complex. There has been significant loss (greater than 50%) of traditional buildings. Located within or in association with a village.	Post-medieval	TF 3463 5335	Within the 1 km Study Area
MLI124551	Non-designated building	Farmstead, Sibsey	Partially extant 19 th century farmstead. Regular courtyard of U plan. The farmhouse is detached with the long axis facing on to the yard. There has been significant loss (greater than 50%) of traditional buildings. Located within or in association with a village.	Post-medieval	TF 3465 5336	Within the 1 km Study Area
MLI120401	Non-designated building	Dovecote Farm House (Dovecote Farm), Midville	Partially extant 19 th century farmstead. Regular courtyard with L- plan range plus detached buildings to the third side of the yard. The farmhouse is detached from the main working complex. There has been significant loss (greater than 50%) of traditional buildings. Isolated location. Large modern sheds are located on the site	Post-medieval	TF 3742 5814	Within the 1 km Study Area
MLI118914	Non-designated building	Home Farm, Farlesthorpe	19 th century farmstead. Regular courtyard with L-plan range plus detached buildings to the third side of the yard. The farmhouse is detached from the main working complex. The farmhouse is the only surviving historic structure. Located within a loose farmstead cluster. Large modern sheds are located to the side of the site	Post-medieval	TF 4732 7424	Within the 1 km Study Area
MLI120410	Non-designated building	Midville House Farm (Midville House), Midville	Partially extant 19 th century farmstead. Regular courtyard with multiple regular yards. The farmhouse is detached from the main working complex. There has been significant loss (greater than 50%) of traditional buildings. Isolated location. Large modern sheds are located on the site	Post-medieval	TF 3755 5654	Within the 1 km Study Area
MLI119949	Non-designated building	Laurels, Irby in the Marsh	Partially extant 19 th century farmstead. Regular courtyard with L- plan range plus detached buildings to the third side of the yard. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Located within a loose farmstead cluster.	Post-medieval	TF 4742 6241	Within the 1 km Study Area

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
MLI120248	Non-designated building	Fendale (Fern Farm), Croft	Partially extant 19 th century farmstead. Row with additional detached elements. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Isolated location.	Post-medieval	TF 5074 6214	Within the 1 km Study Area
MLI120291	Non-designated building	Orchard Farm, Thorpe St. Peter	Partially extant 19 th century farmstead. Dispersed clustered plan. The farmhouse is detached from the main working complex. There has been significant loss (greater than 50%) of traditional buildings. Isolated location. Large modern sheds are located to the side of the site	Post-medieval	TF 4541 6176	Within the 1 km Study Area
MLI122835	Non-designated building	White House, Wigtoft	Partially extant 19 th century farmstead. Regular courtyard with L- plan range plus detached buildings to the third side of the yard. The farmhouse is detached with the gable end facing on to the yard. There has been significant loss (greater than 50%) of traditional buildings. Located within a loose farmstead cluster. Large modern sheds are located on the site.	Post-medieval	TF 2640 3520	Within the 1 km Study Area
MLI122342	Non-designated building	Ivy House, Holland Fen with Brothertoft	Partially extant 19 th century farmstead. Parallel. The farmhouse is detached from the main working complex. There has been significant loss (greater than 50%) of traditional buildings. Isolated location. Large modern sheds are located to the side of the site.		TF 2704 4507	Within the 1 km Study Area
MLI122834	Non-designated building	Burfoft House, Wigtoft	Partially extant 19 th century farmstead. Regular courtyard with L- plan range plus detached buildings to the third side of the yard. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Located within a Church and/or Manor farm group. Large modern sheds are located on the site.	Post-medieval	TF 2666 3510	Within the 1 km Study Area
MLI120337	Non-designated building	Ivy Farmhouse, New Leake	Partially extant 19 th century farmstead. Regular courtyard with L- plan range plus detached buildings to the third side of the yard. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Isolated location. Large modern sheds are located on the site	Post-medieval	TF 4066 5979	Within the 1 km Study Area
MLI122866	Non-designated building	Dowdyke Grange, Sutterton	Partially extant 19 th century farmstead. Regular courtyard with linked working buildings to all four sides of the yard. The farmhouse is detached from the main working complex. There has been significant loss (greater than 50%) of traditional buildings. Isolated location. Large modern sheds are located to the side of the site	Post-medieval	TF 2755 3323	Within the 1 km Study Area
MLI120440	Non-designated building	End Cottage, Stickney	Partially extant 19 th century farmstead. Regular courtyard of U plan. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Isolated location.	Post-medieval	TF 3437 5505	Within the 1 km Study Area
MLI120409	Non-designated building	Chapel Farm, Midville	Partially extant 19 th century farmstead. Loose courtyard with three sides of the courtyard formed by working agricultural buildings. The farmhouse is detached from the main working complex. There has been significant loss (greater than 50%) of traditional	Post-medieval	TF 3881 5698	Within the 1 km Study Area

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
			buildings. Isolated location. Large modern sheds are located to the side of the site.			
MLI120250	Non-designated building	Church Farm, Croft	Partially extant 19 th century farmstead. Regular courtyard with multiple regular yards. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 5050 6191	Within the 1 km Study Area
MLI119879	Non-designated building	The Elms, Burgh Le Marsh	Partially extant 19 th century farmstead. Regular courtyard of U plan. The farmhouse is attached to a range of working buildings. There has been a partial loss (less than 50%) of traditional buildings. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 5249 6404	Within the 1 km Study Area
MLI124645	Non-designated building	Green Lane Cottage, Frithville and Westville	Extant 19 th century farmstead. Regular courtyard of L plan. The farmhouse is detached from the main working complex. Isolated location. Large modern sheds are located to the side of the site.	Post-medieval	TF 2916 5276	Within the 1 km Study Area
MLI120355	Non-designated building	Unnamed farmstead, New Leake	Partially extant 19 th century farmstead. Regular courtyard of L plan. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Located within a loose farmstead cluster. Large modern sheds are located on the site	Post-medieval	TF 3807 5509	Within the 1 km Study Area
MLI122992	Non-designated building	Walnut Grange, Kirton	Extant 19 th century farmstead. Regular courtyard with L-plan range plus detached buildings to the fourth side of the yard. The farmhouse is detached from the main working complex. Located within a loose farmstead cluster.	Post-medieval	TF 2656 4157	Within the 1 km Study Area
MLI120011	Non-designated building	Home Farm, Little Steeping	Partially extant 19 th century farmstead. Loose courtyard with two sides of the courtyard formed by working agricultural buildings. The farmhouse is attached to a range of working buildings. There has been a partial loss (less than 50%) of traditional buildings. Isolated location. Large modern sheds are located on the site	Post-medieval	TF 4365 6132	Within the 1 km Study Area
MLI124825	Non-designated building	Poplar Farm, Willoughby with Sloothby	Extant 19 th century farmstead. Regular courtyard with L-plan range plus detached buildings to the third side of the yard. The farmhouse is detached from the main working complex. Located within or in association with a village.	Post-medieval	TF 4979 7082	Within the 1 km Study Area
MLI122330	Non-designated building	Hill Farm, Holland Fen with Brothertoft	Partially extant 19 th century farmstead. Regular courtyard with L- plan range plus detached buildings to the fourth side of the yard. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Isolated location. Large modern sheds are located to the side of the site.	Post-medieval	TF 2662 4661	Within the 1 km Study Area
MLI120381	Non-designated building	Unnamed farmstead, Stickford	Partially extant 19 th century farmstead. Loose courtyard with three sides of the courtyard formed by working agricultural buildings. The farmhouse is detached with the long axis facing on to the yard. There has been a partial loss (less than 50%) of traditional	Post-medieval	TF 3727 5953	Within the 1 km Study Area

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
			buildings. Isolated location. Large modern sheds are located on the site.			
MLI124552	Non-designated building	Farmstead, Sibsey	Partially extant 19 th century farmstead. Regular courtyard with L- plan range plus detached buildings to the third side of the yard. The farmhouse is attached to a range of working buildings. There has been a partial loss (less than 50%) of traditional buildings. Located within or in association with a village	Post-medieval	TF 3472 5326	Within the 1 km Study Area
MLI122831	Non-designated building	Black Sluice Farm, Wigtoft	Partially extant 19 th century farmstead. Regular courtyard of L plan. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Isolated location. Large modern sheds are located to the side of the site	Post-medieval	TF 2522 3500	Within the 1 km Study Area
MLI118890	Non-designated building	Station Farm, Cumberworth	Partially extant 19 th century farmstead. Regular courtyard with L- plan range plus detached buildings to the third side of the yard. The farmhouse is detached from the main working complex. There has been significant loss (greater than 50%) of traditional buildings. Isolated location	Post-medieval	TF 4966 7520	Within the 1 km Study Area
MLI122826	Non-designated building	Guidepost Farm, Wigtoft	Partially extant 19 th century farmstead. Regular courtyard of L plan. The farmhouse is detached from the main working complex. There has been significant loss (greater than 50%) of traditional buildings. Isolated location.	Post-medieval	TF 2491 3560	Within the 1 km Study Area
MLI122317	Non-designated building	Reaches Marsh Farm, Holland Fen with Brothertoft	Partially extant 19 th century farmstead. Regular courtyard with L- plan range plus detached buildings to the third side of the yard. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 2844 4738	Within the 1 km Study Area
MLI124556	Non-designated building	BRIDGE FARM, Sibsey	Partially extant 19 th century farmstead. Loose courtyard with three sides of the courtyard formed by working agricultural buildings. The farmhouse is detached with the gable end facing on to the yard. There has been a partial loss (less than 50%) of traditional buildings. Located within or in association with a village	Post-medieval	TF 3439 5319	Within the 1 km Study Area
MLI120308	Non-designated building	Unnamed farmstead, Thorpe St. Peter	Partially extant 19 th century farmstead. Loose courtyard with three sides of the courtyard formed by working agricultural buildings. The farmhouse is detached with the gable end facing on to the yard. There has been significant loss (greater than 50%) of traditional buildings. Isolated location. Large modern sheds are located to the side of the site	Post-medieval	TF 4473 6165	Within the 1 km Study Area
MLI120354	Non-designated building	Oat Sheaf House (Oat Sheaf Inn), New Leake	Partially extant 19 th century farmstead. Regular courtyard of U plan. The farmhouse is detached from the main working complex. There has been significant loss (greater than 50%) of traditional buildings. Located within a loose farmstead cluster. Large modern sheds are located on the site.	Post-medieval	TF 3806 5504	Within the 1 km Study Area

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
MLI122824	Non-designated building	Bank House, Wigtoft	Partially extant 19 th century farmstead. Regular courtyard with L- plan range plus detached buildings to the third side of the yard. The farmhouse is detached from the main working complex. There has been significant loss (greater than 50%) of traditional buildings. Located within a Church and/or Manor farm group. Large modern sheds are located to the side of the site.	Post-medieval	TF 2468 3680	Within the 1 km Study Area
MLI124657	Non-designated building	The Tree House, Frithville and Westville	Extant 19 th century farmstead. Loose courtyard with two sides of the courtyard formed by working agricultural buildings. The farmhouse is detached with the long axis facing on to the yard. Isolated location.	Post-medieval	TF 2996 5028	Within the 1 km Study Area
MLI122329	Non-designated building	Unnamed farmstead, Holland Fen with Brothertoft	Partially extant 19 th century farmstead. Regular courtyard of L plan. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 2678 4621	Within the 1 km Study Area
MLI124659	Non-designated building	Thornton House, Frithville and Westville	Partially extant 19 th century farmstead. Loose courtyard with three sides of the courtyard formed by working agricultural buildings. The farmhouse is detached from the main working complex. There has been significant loss (greater than 50%) of traditional buildings. Isolated location. Large modern sheds are located to the side of the site.	Post-medieval	TF 3031 5038	Within the 1 km Study Area
MLI118941	Non-designated building	Poplar Farm, Willoughby with Sloothby	Partially extant 19 th century farmstead. Regular courtyard with multiple regular yards. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Located within or in association with a village. Large modern sheds are located on the site.	Post-medieval	TF 4973 7081	Within the 1 km Study Area
MLI120323	Non-designated building	The Farm House, Eastville	Partially extant 19 th century farmstead. Regular courtyard of L plan. The farmhouse is detached from the main working complex. There has been significant loss (greater than 50%) of traditional buildings. Isolated location. Large modern sheds are located on the site	Post-medieval	TF 4053 5811	Within the 1 km Study Area
MLI119951	Non-designated building	Unnamed farmstead, Irby in the Marsh	Partially extant 19 th century farmstead. Regular courtyard of U plan. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Located within a loose farmstead cluster. Large modern sheds are located on the site	Post-medieval	TF 4740 6257	Within the 1 km Study Area
MLI120303	Non-designated building	Pink House Farm, Thorpe St. Peter	Partially extant 19 th century farmstead. Loose courtyard with three sides of the courtyard formed by working agricultural buildings. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Isolated location. Large modern sheds are located on the site	Post-medieval	TF 4456 5998	Within the 1 km Study Area
MLI124663	Non-designated building	Deepes' Barn Frithville and Westville	Extant 19 th century farmstead. Regular courtyard of U plan. The farmhouse is detached from the main working complex. Isolated location. Large modern sheds are located to the side of the site.	Post-medieval	TF 2971 5010	Within the 1 km Study Area

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
MLI123074	Non-designated building	The Walnuts, Frampton	Partially extant 19 th century farmstead. Regular courtyard with L- plan range plus detached buildings to the third side of the yard. The farmhouse is detached from the main working complex. There has been significant loss (greater than 50%) of traditional buildings. Isolated location. Large modern sheds are located on the site	Post-medieval	TF 2868 4179	Within the 1 km Study Area
MLI122316	Non-designated building	Riverside Farm, Holland Fen with Brothertoft	Extant 19 th century farmstead. Loose courtyard with three sides of the courtyard formed by working agricultural buildings. The farmhouse is detached with the gable end facing on to the yard. Isolated location. Large modern sheds are located to the side of the site.	Post-medieval	TF 2623 4777	Within the 1 km Study Area
MLI118902	Non-designated building	Unnamed farmstead, Cumberworth	Partially extant 19 th century farmstead. L-plan. The farmhouse is attached to a range of working buildings. There has been a partial loss (less than 50%) of traditional buildings. Located within or in association with a village.	Post-medieval	TF 5044 7327	Within the 1 km Study Area
MLI122811	Non-designated building	Fleet House, Wigtoft	19 th century farmstead. Regular courtyard of E plan. The farmhouse is detached from the main working complex. The farmhouse is the only surviving historic structure. Isolated location. Large modern sheds are located to the side of the site.	Post-medieval	TF 2472 3699	Within the 1 km Study Area
MLI122324	Non-designated building	Redwood Farm, Holland Fen with Brothertoft	Partially extant 19 th century farmstead. Regular courtyard with L- plan range plus detached buildings to the fourth side of the yard. The farmhouse is detached from the main working complex. There has been significant loss (greater than 50%) of traditional buildings. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 2849 4633	Within the 1 km Study Area
MLI122821	Non-designated building	Asperton Lodge, Wigtoft	Partially extant 19 th century farmstead. Loose courtyard with two sides of the courtyard formed by working agricultural buildings. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Isolated location. Large modern sheds are located to the side of the site.	Post-medieval	TF 2664 3657	Within the 1 km Study Area
MLI122829	Non-designated building	Unnamed farmstead, Wigtoft	19 th century farmstead. Regular courtyard of L plan. The farmhouse is detached from the main working complex. The farmhouse is the only surviving historic structure. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 2499 3523	Within the 1 km Study Area
MLI122825	Non-designated building	Unnamed farmstead (Paradise Farm), Wigtoft	Partially extant 19 th century farmstead. Regular courtyard of E plan. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Isolated location. Large modern sheds are located to the side of the site	Post-medieval	TF 2470 3603	Within the 1 km Study Area
MLI122576	Non-designated building	Coney Garth House, Surfleet	Partially extant 19 th century farmstead. Regular courtyard of L plan. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Isolated location. Large modern sheds are located on the site	Post-medieval	TF 2722 3018	Within the 1 km Study Area

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
MLI124768	Non-designated building	Drove House (Gipsy Drove Barn), Langriville	Partially extant 19 th century farmstead. Loose courtyard with L- plan range plus detached buildings to the fourth side of the yard. The farmhouse is detached from the main working complex. There has been significant loss (greater than 50%) of traditional buildings. Isolated location	Post-medieval	TF 2751 4927	Within the 1 km Study Area
MLI118938	Non-designated building	Bethlem Farm House, Willoughby with Sloothby	Partially extant 19 th century farmstead. Regular courtyard with linked working buildings to all four sides of the yard. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Located within or in association with a village. Large modern sheds are located to the side of the site.	Post-medieval	TF 4961 7087	Within the 1 km Study Area
MLI119960	Non-designated building	Chestnut Farm, Firsby	Partially extant 19 th century farmstead. Loose courtyard with two sides of the courtyard formed by working agricultural buildings. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Isolated location. Large modern sheds are located to the side of the site	Post-medieval	TF 4559 6229	Within the 1 km Study Area
MLI124773	Non-designated building	Ivydene House, Langriville	Partially extant 19 th century farmstead. Regular courtyard of L plan. The farmhouse is attached to a range of working buildings. There has been a partial loss (less than 50%) of traditional buildings. Located within or in association with a village. Large modern sheds are located to the side of the site	Post-medieval	TF 2711 4894	Within the 1 km Study Area
MLI118908	Non-designated building	Unnamed farmstead (Ings Farm), Cumberworth	Partially extant 19 th century farmstead. Regular courtyard with linked working buildings to all four sides of the yard. The farmhouse is detached with the gable end facing on to the yard. There has been significant loss (greater than 50%) of traditional buildings. Isolated location.	Post-medieval	TF 5072 7276	Within the 1 km Study Area
MLI122346	Non-designated building	Orchard Barn, Holland Fen with Brothertoft	Partially extant 19 th century farmstead. Regular courtyard of Z plan. The farmhouse is detached from the main working complex. There has been significant loss (greater than 50%) of traditional buildings. Located within a loose farmstead cluster.	Post-medieval	TF 2867 4584	Within the 1 km Study Area
MLI120280	Non-designated building	Lymn Bank, Thorpe St. Peter	Partially extant 19 th century farmstead. Loose courtyard with two sides of the courtyard formed by working agricultural buildings. The farmhouse is detached from the main working complex. There has been significant loss (greater than 50%) of traditional buildings. Isolated location. Large modern sheds are located to the side of the site.	Post-medieval	TF 4942 6157	Within the 1 km Study Area
MLI124667	Non-designated building	Sycamore House, Frithville and Westville	19 th century farmstead. Regular courtyard of U plan. The farmhouse is detached from the main working complex. The farmhouse is the only surviving historic structure. Located within a loose farmstead cluster	Post-medieval	TF 3049 5035	Within the 1 km Study Area
MLI123064	Non-designated building	Fen Farm, Frampton	Partially extant 19 th century farmstead. Regular courtyard with linked working buildings to all four sides of the yard. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings.	Post-medieval	TF 2865 4289	Within the 1 km Study Area

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
			Isolated location. Large modern sheds are located to the side of the site.			
MLI124756	Non-designated building	Willow Farm, Langriville	19 th century farmstead. Loose courtyard of L plan. The farmhouse is detached from the main working complex. The farmhouse is the only surviving historic structure. Isolated location. Large modern sheds are located on the site.		TF 2636 4802	Within the 1 km Study Area
MLI120309	Non-designated building	Station Farm, Thorpe St. Peter	Partially extant 19 th century farmstead. Regular courtyard with L- plan range plus detached buildings to the third side of the yard. The farmhouse is detached from the main working complex. There has been significant loss (greater than 50%) of traditional buildings. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 4334 6114	Within the 1 km Study Area
MLI124606	Non-designated building	Bishops' Farm Frithville and Westville	Partially extant 19 th century farmstead. Regular courtyard with L- plan range plus detached buildings to the third side of the yard. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Isolated location. Large modern sheds are located to the side of the site.	Post-medieval	TF 3313 5293	Within the 1 km Study Area
MLI119885	Non-designated building	Kirk's Farm (Frogthorpe Hall), Burgh Le Marsh	Partially extant 19 th century farmstead. Regular courtyard of L plan. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 5097 6615	Within the 1 km Study Area
MLI123003	Non-designated building	Sutton House, Kirton	19 th century farmstead. Regular courtyard of F plan. The farmhouse is detached from the main working complex. The farmhouse is the only surviving historic structure. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 2834 4026	Within the 1 km Study Area
MLI120402	Non-designated building	Mexican Farm, Midville	19 th century farmstead. Loose courtyard with two sides of the courtyard formed by working agricultural buildings. The farmhouse is detached from the main working complex. The farmhouse is the only surviving historic structure. Isolated location. Large modern sheds are located to the side of the site.	Post-medieval	TF 3705 5809	Within the 1 km Study Area
MLI120442	Non-designated building	Unnamed farmstead, Stickney	Partially extant 19 th century farmstead. Regular courtyard of L plan. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 3364 5500	Within the 1 km Study Area
MLI120246	Non-designated building	Ivy Cottage, Croft	Partially extant 19 th century farmstead. Linear. The farmhouse is attached to a range of working buildings. There has been a partial loss (less than 50%) of traditional buildings. Located within a loose farmstead cluster.	Post-medieval	TF 5126 6213	Within the 1 km Study Area
MLI123075	Non-designated building	Slate House Farm, Frampton	Partially extant 19 th century farmstead. Regular courtyard of U plan. The farmhouse is detached from the main working complex. There has been significant loss (greater than 50%) of traditional	Post-medieval	TF 2887 4177	Within the 1 km Study Area

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
			buildings. Isolated location. Large modern sheds are located on the site.			
MLI118942	Non-designated building	Field Farm, Willoughby with Sloothby	Partially extant 19 th century farmstead. Regular courtyard of U plan. The farmhouse is detached from the main working complex. There has been significant loss (greater than 50%) of traditional buildings. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 4972 7048	Within the 1 km Study Area
MLI124658	Non-designated building	Grange Farm (Carey's Farm) Frithville and Westville	Partially extant 19 th century farmstead. Loose courtyard with three sides of the courtyard formed by working agricultural buildings. The farmhouse is detached from the main working complex. There has been significant loss (greater than 50%) of traditional buildings. Isolated location.	Post-medieval	TF 3080 5106	Within the 1 km Study Area
MLI119871	Non-designated building	Bristol Farm, Burgh Le Marsh	Partially extant 19 th century farmstead. Loose courtyard with three sides of the courtyard formed by working agricultural buildings. The farmhouse is attached to a range of working buildings. There has been a partial loss (less than 50%) of traditional buildings. Isolated location.	Post-medieval	TF 5303 6626	Within the 1 km Study Area
MLI123065	Non-designated building	Willoughby Farm, Frampton	Extant 19 th century farmstead. Regular courtyard of F plan. The farmhouse is detached from the main working complex. Isolated location. Large modern sheds are located to the side of the site.	Post-medieval	TF 2877 4281	Within the 1 km Study Area
MLI122867	Non-designated building	Willow Farm, Sutterton	Partially extant 19 th century farmstead. Regular courtyard with L- plan range plus detached buildings to the third side of the yard. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Isolated location. Large modern sheds are located to the side of the site	Post-medieval	TF 2794 3397	Within the 1 km Study Area
MLI120281	Non-designated building	Primrose Farm, Thorpe St. Peter	19 th century farmstead. Row. The farmhouse is detached from the main working complex. The farmhouse is the only surviving historic structure. Isolated location. Large modern sheds are located to the side of the site.	Post-medieval	TF 4888 6131	Within the 1 km Study Area
MLI118899	Non-designated building	Unnamed farmstead, Cumberworth	19 th century farmstead. Row. The farmhouse is detached from the main working complex. The farmhouse is the only surviving historic structure. Located within or in association with a village.	Post-medieval	TF 5049 7352	Within the 1 km Study Area
MLI124557	Non-designated building	Farmstead, Sibsey	Partially extant 19 th century farmstead. Loose courtyard with three sides of the courtyard formed by working agricultural buildings. The farmhouse is detached from the main working complex. There has been significant loss (greater than 50%) of traditional buildings. Isolated location. Large modern sheds are located to the side of the site.	Post-medieval	TF 3399 5310	Within the 1 km Study Area
MLI119946	Non-designated building	Lincoln Farm, Bratoft	Partially extant 19 th century farmstead. Regular courtyard with multiple regular yards. The farmhouse is attached to a range of working buildings. There has been a partial loss (less than 50%) of traditional buildings. Located with or in association with a hamlet. Large modern sheds are located on the site.	Post-medieval	TF 4739 6285	Within the 1 km Study Area
HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
---------------	----------------------------	--	--	---------------	--------------	---
MLI122828	Non-designated building	Barnside (Wigtoft Marsh Farm), Wigtoft	19 th century farmstead. Regular courtyard with L-plan range plus detached buildings to the third side of the yard. The farmhouse is detached from the main working complex. The farmhouse is the only surviving historic structure. Isolated location. Large modern sheds are located on the site	Post-medieval	TF 2490 3509	Within the 1 km Study Area
MLI122990	Non-designated building	Unnamed farmstead, Kirton	Partially extant 19 th century farmstead. Regular courtyard with L- plan range plus detached buildings to the third side of the yard. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Located within or in association with a hamlet. Large modern sheds are located on the site.	Post-medieval	TF 2635 4180	Within the 1 km Study Area
MLI120243	Non-designated building	Rookery Farm, Croft	Partially extant 19 th century farmstead. Loose courtyard with four sides of the courtyard formed by working agricultural buildings. The farmhouse is detached with the long axis facing on to the yard. There has been a partial loss (less than 50%) of traditional buildings. Isolated location. Large modern sheds are located on the site	Post-medieval	TF 5218 6283	Within the 1 km Study Area
MLI122442	Non-designated building	Pastures Farm, Swineshead	Partially extant 19 th century farmstead. Regular courtyard of L plan. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Isolated location. Large modern sheds are located to the side of the site.	Post-medieval	TF 2610 3967	Within the 1 km Study Area
MLI118895	Non-designated building	Unnamed farmstead, Cumberworth	Partially extant 19 th century farmstead. Row. The farmhouse is detached with the long axis facing on to the yard. There has been a partial loss (less than 50%) of traditional buildings. Located within or in association with a village. Large modern sheds are located to the side of the site.	Post-medieval	TF 5051 7371	Within the 1 km Study Area
MLI122580	Non-designated building	Bridge House Farm (Bank House Farm), Surfleet	Partially extant 19 th century farmstead. Regular courtyard with multiple regular yards. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Isolated location. Large modern sheds are located to the side of the site	Post-medieval	TF 2630 3164	Within the 1 km Study Area
MLI119851	Non-designated building	Fir Tree Farm (Firtree Farm), Orby	Partially extant 19 th century farmstead. Parallel. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Isolated location. Large modern sheds are located to the side of the site	Post-medieval	TF 5301 6703	Within the 1 km Study Area
MLI118939	Non-designated building	Albion House, Willoughby with Sloothby	Partially extant 19 th century farmstead. Regular courtyard with L- plan range plus detached buildings to the third side of the yard. The farmhouse is detached with the long axis facing on to the yard. There has been a partial loss (less than 50%) of traditional buildings. Located within or in association with a village. Large modern sheds are located to the side of the site.	Post-medieval	TF 4949 7072	Within the 1 km Study Area
MLI122839	Non-designated building	Greylands Farm, Wigtoft	19 th century farmstead. Regular courtyard of L plan. The farmhouse is detached from the main working complex. The	Post-medieval	TF 2555 3387	Within the 1 km Study Area

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
			farmhouse is the only surviving historic structure. Isolated location. Large modern sheds are located on the site.			
MLI120370	Non-designated building	Bank House, New Leake	Partially extant 19 th century farmstead. Regular courtyard with multiple regular yards. The farmhouse is attached to a range of working buildings. There has been a partial loss (less than 50%) of traditional buildings. Isolated location. Large modern sheds are located to the side of the site.	Post-medieval	TF 3789 5466	Within the 1 km Study Area
MLI122563	Non-designated building	Unnamed farmstead, Gosberton	Partially extant 19 th century farmstead. Regular courtyard of L plan. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 2625 3174	Within the 1 km Study Area
MLI122347	Non-designated building	The Limes, Holland Fen with Brothertoft	19 th century farmstead. Regular courtyard with L-plan range plus detached buildings to the third side of the yard. The farmhouse is detached from the main working complex. The farmhouse is the only surviving historic structure. Located within a loose farmstead cluster.	Post-medieval	TF 2883 4576	Within the 1 km Study Area
MLI122991	Non-designated building	Brinsworth Farm, Kirton	19 th century farmstead. Regular courtyard of U plan. The farmhouse is detached from the main working complex. The farmhouse is the only surviving historic structure. Located within or in association with a hamlet. Large modern sheds are located to the side of the site.	Post-medieval	TF 2637 4190	Within the 1 km Study Area
MLI118898	Non-designated building	Blenheim House, Cumberworth	Extant 19 th century farmstead. Row. The farmhouse is detached from the main working complex. Located within or in association with a village.	Post-medieval	TF 5054 7362	Within the 1 km Study Area
MLI122983	Non-designated building	White House, Kirton	19 th century farmstead. Regular courtyard of T plan. The farmhouse is detached from the main working complex. The farmhouse is the only surviving historic structure. Located within or in association with a village. Large modern sheds are located on the site.	Post-medieval	TF 2668 4334	Within the 1 km Study Area
MLI119874	Non-designated building	Halfway House, Burgh Le Marsh	19 th century farmstead. Regular courtyard with L-plan range plus detached buildings to the third side of the yard. The farmhouse is detached from the main working complex. The farmhouse is the only surviving historic structure. Isolated location. Large modern sheds are located to the side of the site.	Post-medieval	TF 5348 6457	Within the 1 km Study Area
MLI122871	Non-designated building	Ivy House, Sutterton	Partially extant 19 th century farmstead. Regular courtyard with multiple regular yards. The farmhouse is detached from the main working complex. There has been significant loss (greater than 50%) of traditional buildings. Isolated location. Large modern sheds are located to the side of the site	Post-medieval	TF 2805 3375	Within the 1 km Study Area
MLI123028	Non-designated building	Unnamed farmstead, Kirton	Partially extant 19 th century farmstead. Regular courtyard of F plan. The farmhouse is attached to a range of working buildings. There has been a partial loss (less than 50%) of traditional	Post-medieval	TF 2849 3865	Within the 1 km Study Area

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
			buildings. Isolated location. Large modern sheds are located to the side of the site			
MLI124691	Non-designated building	Primrose Hill Farm, Thornton Le Fen	Partially extant 19 th century farmstead. Loose courtyard with three sides of the courtyard formed by working agricultural buildings. The farmhouse is detached from the main working complex. There has been significant loss (greater than 50%) of traditional buildings. Isolated location.	Post-medieval	TF 2817 5130	Within the 1 km Study Area
MLI118937	Non-designated building	The Elms, Willoughby with Sloothby	Partially extant 19 th century farmstead. Dispersed clustered plan. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Located within or in association with a village. Large modern sheds are located on the site	Post-medieval	TF 4939 7089	Within the 1 km Study Area
MLI124558	Non-designated building	Farmstead, Sibsey	Partially extant 19 th century farmstead. Loose courtyard with three sides of the courtyard formed by working agricultural buildings. The farmhouse is detached with the long axis facing on to the yard. There has been significant loss (greater than 50%) of traditional buildings. Isolated location.	Post-medieval	TF 3380 5300	Within the 1 km Study Area
MLI119832	Non-designated building	Wilcox Farm, Addlethorpe	Partially extant 19 th century farmstead. Loose courtyard with three sides of the courtyard formed by working agricultural buildings. The farmhouse is detached from the main working complex. There has been significant loss (greater than 50%) of traditional buildings. Isolated location	Post-medieval	TF 5308 6848	Within the 1 km Study Area
MLI118897	Non-designated building	Unnamed farmstead, Cumberworth	Partially extant 19 th century farmstead. Parallel. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Located within or in association with a village. Large modern sheds are located to the side of the site.	Post-medieval	TF 5061 7364	Within the 1 km Study Area
MLI123013	Non-designated building	The Cottage, Kirton	19 th century farmstead. Regular courtyard of L plan. The farmhouse is detached from the main working complex. The farmhouse is the only surviving historic structure. Isolated location. Large modern sheds are located to the side of the site.	Post-medieval	TF 2839 3991	Within the 1 km Study Area
MLI119961	Non-designated building	Unnamed farmstead, Firsby	19 th century farmstead. Loose courtyard with two sides of the courtyard formed by working agricultural buildings. The farmhouse is detached from the main working complex. The farmhouse is the only surviving historic structure. Isolated location. Large modern sheds are located to the side of the site	Post-medieval	TF 4540 6247	Within the 1 km Study Area
MLI118891	Non-designated building	Unnamed farmstead, Cumberworth	Extant 19 th century outfarm. Single building. Isolated location.	Post-medieval	TF 4997 7488	Within the 1 km Study Area
MLI120502	Non-designated building	Unnamed farmstead, Carrington	19 th century farmstead. Loose courtyard with three sides of the courtyard formed by working agricultural buildings. The farmhouse is detached from the main working complex. The farmhouse is the only surviving historic structure. Isolated location	Post-medieval	TF 3130 5218	Within the 1 km Study Area

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
MLI120252	Non-designated building	Vine Cottage, Croft	Partially extant 19 th century farmstead. Loose courtyard with two sides of the courtyard formed by working agricultural buildings. The farmhouse is detached with the gable end facing on to the yard. There has been a partial loss (less than 50%) of traditional buildings. Isolated location.	Post-medieval	TF 5086 6159	Within the 1 km Study Area
MLI124760	Non-designated building	Meer Booth Farm, Langriville	Partially extant 19 th century farmstead. Regular courtyard with L- plan range plus detached buildings to the third side of the yard. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Isolated location. Large modern sheds are located to the side of the site	Post-medieval	TF 2888 4819	Within the 1 km Study Area
MLI120439	Non-designated building	Grange Farm, Stickney	Partially extant 19 th century farmstead. Regular courtyard of Z plan. The farmhouse is attached to a range of working buildings. There has been a partial loss (less than 50%) of traditional buildings. Isolated location. Large modern sheds are located on the site	Post-medieval	TF 3415 5547	Within the 1 km Study Area
MLI122857	Non-designated building	Blackitt's Farm, Sutterton	Partially extant 19 th century farmstead. Regular courtyard of U plan. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Isolated location. Large modern sheds are located to the side of the site	Post-medieval	TF 2733 3499	Within the 1 km Study Area
MLI119896	Non-designated building	Home Farm, Burgh Le Marsh	Partially extant 19 th century farmstead. Loose courtyard with four sides of the courtyard formed by working agricultural buildings. The farmhouse is detached with the long axis facing on to the yard. There has been significant loss (greater than 50%) of traditional buildings. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 5057 6598	Within the 1 km Study Area
MLI118896	Non-designated building	Unnamed farmstead (Caistor School Farm), Cumberworth	Partially extant 19 th century farmstead. Regular courtyard with L- plan range plus detached buildings to the third side of the yard. The farmhouse is detached with the long axis facing on to the yard. There has been significant loss (greater than 50%) of traditional buildings. Located within or in association with a village	Post-medieval	TF 5067 7363	Within the 1 km Study Area
MLI119856	Non-designated building	Ivy House, Orby	Extant 19 th century farmstead. Regular courtyard of U plan. The farmhouse is attached to a range of working buildings. Isolated location. Large modern sheds are located to the side of the site.	Post-medieval	TF 5040 6763	Within the 1 km Study Area
MLI120403	Non-designated building	Duchy Farm, Midville	Duchy Farm, Midville. Partially extant 19 th century farmstead. Regular courtyard of U plan. The farmhouse is detached from the main working complex. There has been significant loss (greater than 50%) of traditional buildings. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 3660 5830	Within the 1 km Study Area
MLI86181	Non-designated building	Wesleyan Methodist Chapel, Langrick Road, Langrick Bridge, Holland Fen with Brothertoft	The chapel is constructed of red brick with gault brick dressings and has a slate roof covering with terracotta ridge tiles and a brick plinth. The pedimented gable has clasping terminal pilasters with imposts, and a moulded gable cornice and pediment, and a central recess containing a date tablet of 1868.	Post-medieval	TF 2660 4747	Within 100 m of the draft Order Limits

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
MLI98274	Non-designated building	Outbuildings, south side of Lymn Bank, Lymn Bank West	An open cart bay, stables and a cart shed, all dating from the late 1800s. They are built of red brick and had original pantile roofs some of which survive. The cart shed to the east is the oldest building.	Post-medieval	TF 4712 6168	Within 100 m of the draft Order Limits
MLI126644	Non-designated building	Former School, Wigtoft	Former school building. Single storey T-plan red brick building, under a pitched gabled slate roof. Dogtooth dentil course at eaves height, small steeply gabled porch on front elevation. Two tall lateral stacks	Post-medieval	TF 2630 3618	Within the 1 km Study Area
ML199089	Non-designated building	Thorpe-Fendikes Wesleyan Methodist Church, Thorpe St Peter	Thorpe-Fendikes Methodist Chapel was built in 1923 to seat 130. The building is of red brick and has a gabled roof. The windows have stained glass and the window on the front elevation is dressed with stone and has tracery.	Modern	TF 45236 60478	Within the 1 km Study Area
MLI124884	Non-designated building	Former Station House, Little Steeping Railway Station	A former station house and ticket office for Little Steeping Railway Station, which was opened in October 1848, and was closed to all traffic in 1964. The building is of two storeys, with several single- storey additions to the north-western side. It is of red brick, now largely whitewashed, and features pitched tile roofs with long protruding eaves, although the covering seems to have been replaced with tiles.	Post-medieval	TF 43710 61156	Within 100 m of the draft Order Limits
ML199088	Non-designated building	Thorpe Bank Primitive Methodist Chapel, Thorpe St Peter	Thorpe Bank Primitive Methodist chapel was built in 1858 to seat 120. In 1874 the chapel was rebuilt on the same site after being damaged by fire. The chapel closed in 1970 and was subsequently converted into a house, named 'Heaven'. The building is rendered grey and has been altered with the addition of windows and a porch.	Post-medieval	TF 42216 60713	Within 100 m of the draft Order Limits
MLI126589	Non-designated building	Former School, Northlands, Sibsey	Former Free School. One and a half storey red brick building in English Garden Wall Bond, under a pitched gabled slate roof. The front elevation is pebbledashed and colourwashed.	Post-medieval	TF 3476 5336	Within the 1 km Study Area
ML199060	Non-designated building	Primitive Methodist Chapel, Northlands, Sibsey	Northlands Primitive Methodist Chapel was built in 1837. The building is of red brick and has a hipped roof and pilasters. The porch is a later addition	Post-medieval	TF 34736 53347	Within the 1 km Study Area
MLI126586	Non-designated building	Primary School, Gipsey Bridge	19 th century school buildings. One and a half storey red brick schoolroom in English Garden Wall Bond, under a pitched gabled roof of slate. Each gable is parapeted and coped in tile, with corbelling at the gable shoulders. There is a dentil course below the eaves. The street-facing elevation has 4 large window openings interspersed with 3 two-tiered brick buttresses with stone coping.	Post-medieval	TF 28057 49847	Within 100 m of the draft Order Limits
MLI98921	Non-designated building	Primitive Methodist Chapel and Schoolroom, Cumberworth	Primitive Methodist chapel and schoolroom, Willoughby Road, Cumberworth. Now forms part of the adjacent house.	Post-medieval	TF 50473 73232	Within the 1 km Study Area

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
MLI98920	Non-designated building	United Methodist Free Chapel, Cumberworth	The United Methodist Free chapel was built in 1853 to seat 60. The building is of red brick with a gabled roof. The chapel closed in 1998 and was sold and converted into a house 2001	Post-medieval	TF 50499 73260	Within the 1 km Study Area
MLI91937	Non-designated building	The Old Chapel, Asperton Road, Wigtoft	The former Wesleyan chapel is now in use as a house named The Old Chapel.The main core of the building is constructed of brownish red brick with an added brick frontage of brighter colour, with a dentil eaves cornice and simulated alternate quoins, and a hipped roof with modern tiles.	Post-medieval	TF 26546 36399	Within the 1 km Study Area
ML199090	Non-designated building	Wesleyan Methodist Chapel, Thorpe St Peter	Thorpe St Peter Wesleyan Methodist chapel was built in 1881 to seat 100. The chapel closed in 1946 and it was intended to become the village hall, but the plan never came to fruition and the building was subsequently converted into a house. The building is of red brick with a gabled roof. It is Classically influenced with a pediment and pilasters.	Post-medieval	TF 48036 61146	Within the 1 km Study Area
MLI91923	Non-designated building	Former Primitive Methodist Chapel, Station Road, Hubberts Bridge, Frampton	The former Primitive Methodist chapel is now in use as a house. It is a gabled building of red brick with a modern tiled roof and gault brick dressings. The front elevation has a pedimented gable with gault brick dentil cornices and terminal pilasters of gault brick and a gabled porch with similar gault brick details	Post-medieval	TF 26890 43536	Within the 1 km Study Area
MLI126602	Non-designated building	Former School, Cumberworth	Former National School building. Possibly originally a single storey, now a two storey building with large modern extension the southeast.	Post-medieval	TF 5053 7330	Within the 1 km Study Area
MLI99044	Non-designated building	East Fen Chapel, New Leake	East Fen Chapel was built in 1831, rebuilt in 1855 and closed in 1969. The building subsequently became a garage. The building is of red brick and has a gabled roof.	Post-medieval	TF 37939 54786	Within the 1 km Study Area
MLI99107	Non-designated building	Wesleyan Methodist Chapel, Sloothby	Sloothby Wesleyan Methodist chapel was built in 1868 to seat 180. The chapel closed in 1969 and has subsequently been used as a warehouse. The building is of yellow brick and has a gabled roof. There are black and red brick string courses and decorative black and red brick arches over the doorway.	Post-medieval	TF 49529 70716	Within the 1 km Study Area
MLI126575	Non-designated building	Former School, Croft	Former school building. Two ranges of the 19 th century structure appear to remain intact. The front range, aligned east-west, is a two storey range of red brick in Flemish Bond, under a pitched gabled slate roof. The front elevation is 3 bays, with 2 three light casement windows either side of a wooden panel door, with 2 three light casement windows above. A datestone above the door is inscribed '1844'.	Post-medieval	TF 50930 61802	Within the 1 km Study Area
MLI99104	Non-designated building	United Methodist Free Chapel, Sloothby	Sloothby United Methodist Free chapel was built in 1852. It is unknown exactly when it closed, but it is not labelled as a chapel on any OS map after 1889. The building is of red brick and has a gabled roof. There is a datestone on the gable	Post-medieval	TF 49426 70991	Within the 1 km Study Area
MLI99382	Non-designated building	Primitive Methodist Chapel, Thornton-le-Fen	Thornton-le-Fen Primitive Methodist chapel was built at some point in the second half of the 19 th century; it is depicted on the 1905 Ordnance Survey County Series map, but is not listed in the	Post-medieval	TF 27927 50243	Within the 1 km Study Area

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
			Census of Religious Worship. The building is of brick with a hipped roof, though has been rendered and re-roofed, which has obscured any decorative elements. It is now in use as a house, named 'The Old Chapel';			
MLI12737	Non-designated building	Dovecote, Hubberts Bridge, Kirton	Small square dovecote on the western side of the road. Recorded on 1956 six inch OS map.	Post-medieval	TF 2664 4334	Within the 1 km Study Area
MLI126103	Non-designated building	The Old Farmhouse, Kirton Holme	Former farmhouse of probable late 18 th or early 19 th century date. The building is thought to be brick-built, though covered by later render. The structure is of two storeys, with a pitched tile roof and brock chimneys stacks to both gables. The exact date of construction is uncertain, though the symettrical arrangement of windows with central doorway on the front elevation would suggest a late Georgian date. Significant alterations to the building are thought to have taken place in the mid 20 th century, including the exterior rendering, the addition of a number of extensions and the probable replacement of the original roof covering.	Post-medieval	TF 26276 41922	Within the 1 km Study Area
MLI86273	Non-designated building	Kirton Holme Christ Church	Built in 1820 with a new chapel erected alongside in 1903, now in Anglican use. Walls of dark brick and hipped pantile roof. All windows altered in 1903 and end entrance covered by porch linking the two buildings, gallery next to entrance	Post-medieval	TF 2625 4195	Within the 1 km Study Area
ML198999	Non-designated building	Wesleyan Methodist Chapel, Langrick Ferry	Langrick Ferry Wesleyan Methodist Chapel is dated 1857. It is of red brick and has a gabled roof. The chapel has had some sympathetic alterations. The date of its closure is unknown, although it has been converted into a house.	Post-medieval	TF 26678 48739	Within the 1 km Study Area
MLI12546	Find Spot	Romano-British Pottery, Kirton Holme, Kirton	Romano-British pottery scatter, mostly grey ware, including colander, mortarium (white fabric, black grits) and some samian.	Roman	TF 2727 4127	Within the draft Order Limits
MLI41946	Monument	Medieval Pottery Found In Hogsthorpe	Assorted medieval pottery found in Hogsthorpe.	Medieval	TF 5190 6880	Within the draft Order Limits
MLI42244	Monument	Medieval/Post Medieval Pottery Scatter, Thorpe St Peter	15 th and 16 th century pottery- jug handles, bungs, pancheon fragments and body sherds- as well as clay pipes.	Medieval	TF 4388 6057	Within the draft Order Limits
MLI41506	Monument	Medieval Pottery Found Ne Of Burgh Le Marsh	Medieval potsherds of pancheons and jugs, all is green glazed and pre-dates 1450.	Medieval	TF 5200 6640	Within the draft Order Limits
MLI12548	Monument	Romano-British Pottery, Kirton	Large area of Romano-British pottery and some tile found	Roman	TF 2770 4079	Within the draft Order Limits
MLI88785	Monument	Iron Age saltern site, Wyche Drain	Fieldwalking across the proposed Orby Marsh windfarm site located a concentrated scatter of Iron Age briquetage adjacent to Wyche Drain. A single sherd of late Iron Age (or possibly medieval) pottery was also recovered. The briquetage included pieces of brine evaporation trays, tray spacers and clips used to join the rims of adjacent trays. The large quantity and restricted distribution of material at this site indicates that it was derived from a hearth or other focus of activity occupying the centre of a	Iron Age	TF 51443 69597	Within the draft Order Limits

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
			saltern site. The material was recovered immediately adjacent to the drain, indicating that it had been dredged from the drain channel during routine maintenance. However, examination of the exposed surfaces of the drain did not reveal any stratified archaeological deposits suggesting that these are situated below the waterline, c.2.4-3 m below the current ground surface.			
MLI88789	Monument	Medieval settlement of Wyche	Earthworks and cropmarks of medieval settlement activity, comprising the remains of a number of enclosures, platforms, trackways and boundaries. Identified on aerial photographs examined as part of the National Mapping Programme. Field walking identified medieval settlement remains probably corresponding with the southern edge of the site of the small, deserted settlement of Wyche. The earliest pottery dates to the 12 th century and this, combined with the absence of a mention in the Domesday Book, suggests that the settlement was founded in the 12 th century at the earliest. No house platforms or other earthworks were discovered which, along with the distribution of cropmarks to the north, suggests that the centre of the settlement lies to the north out with this survey area.	Medieval	TF 51811 69598	Within the draft Order Limits
MLI90849	Monument	Possible medieval earthwork boundary, Thorpe St Peter	Possible medieval earthwork boundary, Thorpe St Peter depicted on the NMP	Medieval	TF 45982 61637	Within the draft Order Limits
MLI42008	Monument	Possible Medieval House Sites	House sites and medieval pottery including an aquamarine spout.	Medieval	TF 5140 6940	Within the draft Order Limits
MLI42907	Monument	Site Of Decoy Pond, Sedgedike	A decoy was located on a small intake in the East Fen, where there was formerly a cell attached to Hagnaby Priory. Extant in 1807, it was owned (or leased?) by Thomas Dowse but presumably went out of use with the drainage of the East Fen after 1810. Decoy Farm is marked on the 6 inch and 1:10,000 Ordnance Survey maps, and appeared on the first edition 1 inch Ordnance Survey map	Post-medieval	TF 4370 6050	Within the draft Order Limits
MLI41486	Monument	Thurlby Deserted Medieval Village	Thurlby is mentioned in Domesday in 1086 and was a parish and rectory dedicated to St Mary. There is no trace of the church. Earthworks are visible from 1946 air photos. Of the moat only the north arm and portion of the eastern arm remain	Medieval	TF 4891 7596	Within the draft Order Limits
MLI87794	Monument	Possible post medieval earthwork enclosure, east of Burgh le Marsh	A post medieval enclosure has been identified from aerial photographs as an earthwork, located to the east of Burgh le Marsh.	Post-medieval	TF 5203 6520	Within the draft Order Limits
MLI90843	Monument	Possible medieval enclosure, Thorpe St Peter	Earthwork medieval enclosure, Thorpe St Peter depicted on the NMP. The field containing the enclosure has recently been ploughed and levelled. However, the enclosure is visible as a distinct cropmark. Seen on Google Maps (web site) aerial photograph layer.	Medieval	TF 45684 61249	Within the draft Order Limits

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
MLI90844	Monument	Possible medieval earthwork enclosure, Thorpe St Peter	Possible medieval earthwork enclosure, Thorpe St Peter. Depicted on the NMP	Medieval	TF 45892 61577	Within the draft Order Limits
MLI12537	Find Spot	Greenstone Axe, Kirton	Finds from Kirton Holme include a polished greenstone axe, found in 1954. The finder is now deceased but his personal 6 inch map (held at Cowley Secondary School, Swineshead) shows the findspot of the axe is shown at TF 2730 4144	Neolithic	TF 2730 4144	Within the draft Order Limits
MLI12539	Find Spot	Mica Schist Whetstone, Kirton	Finds from Kirton Holme include a 12 th -13 th century mica-schist hone. The finder is now deceased but the findspot is shown on his personal 6 inch map (held at Cowley Secondary School, Swineshead), at TF 2730 4144.	Medieval	TF 2730 4144	Within the draft Order Limits
ML197998	Find Spot	Three undated flakes, Cumberworth	Three flint flake of unknown date were found at TF498724	Neolithic	TF 4980 7240	Within the draft Order Limits
ML198002	Find Spot	Five undated flakes, Cumberworth	Five undated flint flakes were found at TF500724	Neolithic	TF 5000 7240	Within the draft Order Limits
ML188788	Monument	Medieval settlement of Ashington in Hogsthorpe parish	A settlement at Ashington is recorded in 1332 when there was a dispute between the inhabitants and Thomas Pilat who had raised a bank over their routeway to the church. The church was probably Hogsthorpe church. In 1345 the settlement is refered to as 'Hassaken' in a document rating the townships of the Lindsey Marshes for sea defence; the settlement is located at Ashington End, in Hogsthorpe. Ashington End is marked on the late 19 th century and early 20 th century Ordnance Survey maps. Field walking and an earthwork survey identified medieval settlement remains probably corresponding with the site of the small deserted settlement of Ashington, and also correlating with the cropmarks in this area. Earthworks representing four house platforms were recorded, and pottery was recovered throughout the site. The earliest pottery dates to the 12 th century and this, combined with the absence of a mention in the Domesday Book, suggests that the settlement was founded in the 12 th century at the earliest. Pottery from the house platforms indicates that they were in use from the 13 th to the late 15 th century, after which the settlement appears to have been deserted	Medieval	TF 51782 68066	Within the draft Order Limits
ML192287	Monument	Casterton House Park, Wigtoft	A historic park recorded on the first edition and 1905 Ordnance Survey maps at Casterton House, Wigtoft.	Post-medieval	TF 25950 36331	Within the draft Order Limits
MLI90848	Monument	Possible medieval earthwork platform, Thorpe St Peter	Possible medieval earthwork platform, Thorpe St Peter depicted on the NMP	Medieval	TF 46076 61491	Within the draft Order Limits
MLI98814	Monument	Possible medieval extractive pits in Irby in the Marsh	Possible medieval extractive pits seen as earthworks in aerial photographs and recorded by the National Mapping Programme	Medieval	TF 47107 61869	Within the draft Order Limits
MLI124888	Monument	Firsby to Boston Railway	Railway line running between Firsby and Boston. It formed part of the larger East Lincolnshire Railway line, which was constructed	Post-medieval	TF 3596 5053	Within the 1 km Study Area

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
			by the Great Northern Railway, with this part being opened in October 1848. Almost all of the route is still in use, with only the short length from Firsby South Junction to the former Firsby Railway Station having been dismantled in the early 1970s			
MLI90850	Monument	Probable medieval earthwork ridge and furrow and field system, Thorpe St Peter	Probable medieval earthwork ridge and furrow and field system, Thorpe St Peter as depicted on the NMP. Well defined earthwork ridge and furrow and field system seen on Google Maps (web site) aerial photograph layer.	Medieval	TF 45883 61545	Within the draft Order Limits
MLI98096	Monument	Medieval ridge and furrow earthworks near Vine Farm, Burgh le Marsh	Probable medieval ridge and furrow earthworks which appear to form a field system were identified by the National Mapping Programme.	Medieval	TF 5206 6377	Within the draft Order Limits
MLI98708	Monument	Ridge and Furrow earthworks, Dryby Farm, Bilsby	Ridge and furrow earthworks seen on aerial photographs and recorded by the National Mapping Programme. Medieval ridge and furrow appears to have been ploughed out and is not visible (in 2013) on Google maps.	Medieval	TF 4847 7649	Within the draft Order Limits
MLI98097	Monument	Medieval ridge and furrow earthworks adjacent to Middlemarsh Road, Croft	Probable medieval ridge and furrow earthworks which appear to form a field system were identified by the National Mapping Programme. A possible enclosure which appears to be part of the same system is also recorded.	Medieval	TF 5129 6322	Within the draft Order Limits
MLI41957	Monument	Possible Iron Age saltern site	Possible site of 2nd century BC ironworks.	Iron Age	TF 5174 6880	Within the draft Order Limits
MLI43154	Monument	Possible Iron Age saltern site	Possible site of BC ironworks.	Iron Age	TF 5190 6880	Within the draft Order Limits
MLI41948	Monument	Possible Iron Age saltern site	Possible site Iron Age ironworks with pottery from the 2nd century	Iron Age	TF 521 688	Within the draft Order Limits
MLI41501	Monument	Medieval settlement remains to the east of Burgh le Marsh	In 1970 this site was drained and deep ploughed. The remains of house platforms and sunken ways are still visible, and in the two fields to the e remains of the site are visible in pasture. Close to the centre there appears to have been a brick building of 15th or 16 th century date. An almost complete late 15 th century green glazed costrel. Other pottery found ranges from 12 th to 17 th century in date. The remains are visible on aerial photographs, and have been recorded as surviving as earthworks	Medieval	TF 5207 6550	Within the draft Order Limits
MLI90854	Monument	Medieval settlement earthworks, Thorpe St Peter	Medieval settlement earthworks, Thorpe St Peter depicted on the NMP.	Medieval	TF 45306 60429	Within the draft Order Limits
MLI90845	Monument	Possible medieval earthwork stack stands, Thorpe St Peter	Possible medieval earthwork stack stands, Thorpe St Peter depicted on the NMP.	Medieval	TF 45779 61178	Within the draft Order Limits
MLI42767	Monument	Northdike Briggs Chapel and Hermitage, Stickney	Northdike Briggs- 14 th century chapel and hermitage were documented in 1399 when a license was granted for celebration. 'Northdike Bridge' is now called 'Bar Bridge'.	Medieval	TF 3515 5410	Within the 1 km Study Area

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
MLI87795	Monument	Possible post medieval earthwork enclosure, east of Burgh le Marsh	A post medieval enclosure has been identified from aerial photographs as an earthwork, located to the east of Burgh le Marsh.	Post-medieval	TF 5237 6508	Within the 1 km Study Area
MLI97997	Find Spot	An undated flake, Cumberworth	An undated flint flake was found at TF497727	Neolithic	TF 4970 7270	Within the 1 km Study Area
MLI87793	Monument	Modern aircraft obstruction, east of Burgh le Marsh	A modern aircraft obstruction is recorded as surviving as an earthwork to the north east of Burgh le Marsh.	Modern	TF 5165 6547	Within the 1 km Study Area
MLI97715	Monument	Probable Post-Medieval Clay Extraction Pits and Enclosures, Irby in the Marsh	Earthworks of probable clay extraction pits and enclosures of uncertain medieval or post-medieval date, to the south of Irby in the Marsh. Identified on aerial photography examined as part of the National Mapping Programme. The former extraction pits and enclosures are clearly visible as earthworks, on the Google Maps aerial photographic layer. They are likely associated with the post-medieval brickworks site located a short distance to the south-west with the extraction pits providing clay to make the bricks.	Post-medieval	TF 4775 6224	Within the 1 km Study Area
MLI88433	Monument	Possible unknown date cropmark enclosure and pits, Firsby	Probable unknown date cropmark enclosure partially surrounding probable unknown date cropmark pits, seen on NMP.	Undated	TF 46415 61628	Within the 1 km Study Area
MLI84121	Monument	Deserted settlement at Bonthorpe	Remains of deserted medieval settlement at Bonthorpe are visible on aerial photographs, and are recorded as surviving as earthworks. The remains include tofts, crofts and boundaries. This area appears to have been under cultivation and subsiquently has argicultural development upon it seen on aerial photographs on google earth	Medieval	TF 4819 7291	Within the 1 km Study Area
ML192254	Monument	Historic Park, Brothertoft	A historic park recorded on the 1907 Ordnance Survey map in Brothertoft.	Post-medieval	TF 27177 46399	Within the 1 km Study Area
MLI88895	Monument	Probable Medieval settlement	Probable Medieval settlement, Burgh le Marsh, depicted as earthwork enclosures, field systems, field boundaries and ridge and furrow on the NMP. The area (except for the small triangle of land surrounding buildings on Ingoldmells Road) has since been under arable cultivation.	Medieval	TF 52593 66474	Within the draft Order Limits
MLI41694	Monument	Saltern Site, Burgh Le Marsh Parish	Saltern site found in deepening a drain c3 m down under silt. Briquetage and pottery also found.	Iron Age	TF 5260 6450	Within the 1 km Study Area
MLI42843	Monument	Iron Age or Roman saltern site, Burgh le Marsh	A saltern site found in deepening a drain c3 m down under silt. Briquetage and pottery also found. Either Iron Age or Roman in date	Roman	TF 526 645	Within the 1 km Study Area
MLI124882	Monument	Former Crossing Keepers Cottage, Bell Water Drain Bank, Thorpe St Peter	A former level crossing keepers cottage at Bell Water Drain Bank. The crossing was on part of the Great Northern Railway's, East Lincolnshire Railway line, this part of which opened in October 1848. The cottage was built to a standardised design that appeared on all the manned crossings of the Boston to Firsby	Post-medieval	TF 4227 5915	Within 100 m of the draft Order Limits

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
			stretch of the ELR. The basic design was L-shaped, with the long arm of the L running parallel to the railway. The cottage was of two storeys, and was constructed of red brick, with pitched slate roofs. The building was depicted on historic Ordnance Survey mapping until the early 1970s, but has since been demolished			
MLI41490	Monument	The site of Thurlby Grange, Bilsby	The site of Thurlby Grange, Bilsby, a 19 th century farmstead and placename evidence for a grange. Site of Thurlby Grange, Bilsby. Demolished 19 th century farmstead. Dispersed clustered plan. Additional, prominent detached elements to the main plan. The farmhouse is detached from the main working complex. Located within a Church and/or Manor farm group.	Post-medieval	TF 4910 7530	Within 100 m of the draft Order Limits
MLI12554	Monument	Linear Earthwork, Kirton	Reports of earth and gravel bank for about 400 yds, running approximately north-west to south-east. Also Romano-British pottery in the area	Unknown	TF 2700 4150	Within the 1 km Study Area
MLI40664	Monument	Roman Pottery Found in Langriville Parish	Romano british and samian ware pottery found beneath modern ground surface.	Roman	TF 2730 4750	Within the 1 km Study Area
MLI83297	Monument	Medieval settlement, Sloothby	During a watching brief in 1999, two ditches were recorded, thought to be field boundary ditches contemporary with those recorded from cropmarks around the settlement. One was aligned north-west/south-east and contained 14 th to 16 th century pottery; the other was aligned east/west and contained 18 th century pottery. An undated natural pool was also recorded. Medieval settlement remains are visible on aerial photographs surrounding Sloothby, and are recorded as surviving as earthworks. The remains include tofts, crofts, enclosures, boundaries and ridge and furrow. At TF494713 is a cluster of linear crop marks representing ditches. They may be post medieval in date.	Medieval	TF 4961 7085	Within the 1 km Study Area
MLI41956	Monument	Saltern Site, Hogsthorpe	Saltern site with hand bricks 4 inches by one-inch, baked clay rods, pieces of pans and bases found during widening of drains, Hogsthorpe	Undated	TF 5200 6920	Within the 1 km Study Area
MLI41992	Find Spot	Roman Coins Found in Willoughby With Sloothby	2 Roman coins found	Roman	TF 4820 7310	Within the 1 km Study Area
ML198000	Find Spot	An undated flake, Cumberworth	An undated flint flake was found at TF501725.	Neolithic	TF 5010 7250	Within the 1 km Study Area
MLI98003	Find Spot	A sherd of medieval pottery, Cumberworth	A sherd of early medieval pottery found at TF505719.	Medieval	TF 5050 7190	Within the 1 km Study Area
MLI41142	Find Spot	Clay Figure Found in Sibsey	Torso of handmade, hard fired clay figure found at Sibsey northlands in garden of last peg cottage. Made of poorly mixed red/yellow streaky clay. Carved probably using knife/sharp stick. Dress suggests 18 th century date. May be product of local brickworks of which old brick pit located at TF 333517 drawing in parish file	Post-medieval	TF 344 536	Within the 1 km Study Area

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
MLI41476	Monument	Moated site at Thurlby in Bigby parish.	Moated site at Thurlby, in Bigby parish. The present house probably stands on the site of an earlier medieval house, which stood within the homestead moat. During a watching brief a ditch was identified which may have been part of the moat complex. It was filled in during the 18 th century and a pit was dug on its line. Post medieval finds include pottery, glass and bone.	Medieval	TF 4869 7608	Within the 1 km Study Area
MLI89119	Monument	Probable late Medieval shrunken village, Farlesthorpe	Probable late Medieval shrunken village, depicted as crofts and tofts, field boundaries and fishponds on the NMP.	Medieval	TF 47393 74198	Within the 1 km Study Area
MLI98001	Find Spot	An undated flake, Cumberworth	A flint flake was found at TF501727	Neolithic	TF 5010 7270	Within the 1 km Study Area
MLI97999	Find Spot	A sherd of Roman pottery, Willoughby	A sherd of Roman grey ware pottery was found at TF498723.	Roman	TF 4980 7230	Within the 1 km Study Area
MLI89121	Monument	Probable shrunken Medieval village, Cumberworth	Possible shrunken Medieval village remains as depicted on the NMP.	Medieval	TF 50388 73314	Within the 1 km Study Area
MLI43666	Monument	Medieval Pottery and Possible Site of a Building, Ingoldmells Road	A thin scatter of locally produced unglazed medieval pottery sherds were found in this field. A small enclosure in the field to the south of the road may mark the site of a demolished house or farm, perhaps the source of this pottery	Medieval	TF 5225 6655	Within the 1 km Study Area
MLI90853	Monument	Undated earthwork bank, Thorpe St Peter	Undated earthwork bank, Thorpe St Peter depicted on the NMP	Undated	TF 45415 60658	Within the 1 km Study Area
MLI116307	Monument	Churchyard at the Church of St Peter, Midville	The churchyard at the Church of St Peter is depicted on the 2nd edition 25 inch Ordnance Survey County Series map. It likely dates to at least 1819, when the church it serves was built	Post-medieval	TF 38449 57028	Within the 1 km Study Area
MLI43665	Find Spot	Medieval Pottery, Ingoldmells Road	Two sherds of medieval pottery were found in field 11 during the watching brief on the Burgh Le Marsh - Ingoldmells Rising Main	Medieval	TF 5157 6575	Within the 1 km Study Area
MLI90851	Monument	Medieval earthwork enclosure, Thorpe St Peter	Undated earthwork enclosure, Thorpe St Peter as depicted on the NMP. Medieval enclosure, within and in alignment with medieval settlement	Medieval	TF 45307 60710	Within the 1 km Study Area
MLI40282	Monument	Saxon Finds, Bonthorpe	Saxon finds picked up while metal detecting. Finds include bronze tweezers with dot and circle decoration. Pins of bronze and silver and bronze strap ends.	Early Medieval	TF 4846 7321	Within the 1 km Study Area
MLI43492	Find Spot	Prehistoric flint, Moat House, Thurlby in Bigby parish	During a watching brief at moat house Thurlby, a prehistoric flint was recovered.	Neolithic	TF 4872 7605	Within the 1 km Study Area
MLI43146	Find Spot	Lead Pilgrim Ampulla	A lead pilgrim ampulla found at Farlesthorpe.	Medieval	TF 4759 7410	Within the 1 km Study Area
MLI81505	Monument	Romano-British finds, north of the old railway line, Langrick	A site approximately 30 yards square (30 sq m) has been noted adjacent to the north side of the old railway line at Langrick. The site has probably been partly obliterated by the embanking works	Roman	TF 2763 4756	Within the 1 km Study Area

HER Reference	Record Type	Name	Description	Period	NGF
			carried out in the 1770s to straighten the course of the Witham. An area of blackened soil was identified, which contained much grey ware pottery, and some Samian ware. Animal bones too, were noted, which possibly comprised mainly chicken bones. A few fragments of roof tile were also noted during one visit.		
MLI86171	Monument	Dispersed settlement of Brothertoft	The settlement is very dispersed and therefore this record has been shown spatially as a point. The name Brothertoft is thought to have first been used around 1531. The name is thought to derive from an Old Danish personal name 'Bothir' and from the Old Norse meaning curtilage. Brothertoft is in the wapentake of Kirton and was not mentioned in Domesday Book. The village maintained a small but consistent population during the 19 th century, in 1801 the population stood at 102 it rose slightly over the next century and in 1901 stood at 137. White's Directory records 123 inhabitants in 1856 and continues that the people 'where the most active rioters against the Enclosure Act of Holland Fen, on which they claimed almost unrestrained right of pasturage, fowling and fishing, but many of them lived to see their folly, in attempting to prevent a great public improvement, which ultimately benefited the poor as well as the rich'. It has been suggested that Brothertoft or Toft was formerly a farming estate (vaccaria) of the abbey of Swineshead. The Church at Brothertoft between 1705 and 1723 had no church minister or endowment, it only had a service every other Sunday, or later on only once a month where the officiating minister was paid 5 shillings by the parishioners. Mr J. Cartwright of Brothertoft started a woad mill in the 18 th century. This was possibly the first woad-mill that was built as a permanent structure. Mr J. Cartwright 'the father of reform' built Brothertoft Hall and set up a woad processing plant on the North of the Forty Foot Drain, accompanied by a long row of cottages for the labourers. The settlement was short lived.	Post-medieval	TF 2
MLI126078	Monument	Former Brickworks, Irby in the Marsh	A former brickworks is depicted in this location on the 1st edition 6" Ordnance Survey County Series map. The depiction shows the site as comprised of a roughly central kiln with other working buildings and likely brick drying sheds nearby. A large brick clay extraction pit is shown at the western edge of the site. The site is depicted on the 2nd edition 25" Ordnance Survey County Series map, although it is depicted as 'disused', indicating the site had stopped production by the time of this survey, at the turn of the 20 th century. The kiln and most of the former brickworks buildings are no longer extant, though the former clay extraction pit at the western edge of the site is clearly visible as earthworks, on the Google Maps aerial photographic layer. Further probable clay extraction pits likely associated with the brickworks lie a short distance to the north-east.	Post-medieval	TF 4



Within the Draft Order Limits or 1km Study Area

2738 4626

Within the 1 km Study Area

4747 6215

Within the draft Order Limits

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
MLI90858	Monument	Probable medieval earthwork enclosure, Thorpe St Peter	Probable medieval earthwork enclosure, Thorpe St Peter depicted on the NMP. Earthwork enclosure, possibly a moat, seen on Google Maps (web site) aerial photograph layer.	Medieval	TF 47987 61657	Within the 1 km Study Area
MLI90836	Monument	Cropmark prehistoric or Romano-British enclosures and ditches, Willoughby with Sloothby	Cropmark prehistoric or Romano-British encloures and ditches, Willoughby with Sloothby. A complex system of ditches, rectangular enclosures, a possible ring ditch and a boundary ditch seen on Google Maps (web site) aerial photograph layer.	Bronze Age	TF 49952 71664	Within the 1 km Study Area
MLI86445	Monument	Post-medieval ditch on land at Main Road, Wigtoft	An archaeological watching brief was undertaken during groundworks at Main Road, Wigtoft. The watching brief identified a ditch 19 th century AD pottery. The ditch may have served as a boundary or to aid drainage of the land.	Post-medieval	TF 26160 36090	Within the 1 km Study Area
MLI86444	Monument	Medieval ditch and pit on land at Main Road, Wigtoft	An archaeological watching brief was undertaken during groundworks at Main Road, Wigtoft. The watching brief identified a ditch and rubbish pit containing 12 th to 13 th century AD pottery. The pit suggests refuse disposal and indicates settlement in the vicinity. The ditch may have served as a boundary or to aid drainage of the land	Medieval	TF 26160 36090	Within the 1 km Study Area
MLI90847	Monument	Probable medieval earthwork enclosure, Thorpe St Peter	Probable medieval earthwork enclosure, Thorpe St Peter depicted on the NMP.	Medieval	TF 46022 61096	Within the 1 km Study Area
MLI90852	Monument	Medieval earthwork fishponds, Thorpe St Peter	Undated earthwork ponds, Thorpe St Peter as depicted on the NMP. Medieval fishponds, within and in alignment with medieval settlement.	Medieval	TF 45304 60699	Within the 1 km Study Area
MLI13404	Monument	Site of Holland House, Wigtoft	A farmhouse dating from about 1660 which was originally built in Fen Artisan Mannerist style from red brick in an English bond. Holland House was demolished at some point between April 1991 and April 2010. As the building was no longer extant and had therefore lost its special interest, the decision was taken by English Heritage to remove it from the National Heritage List for England.		TF 2578 3622	Within the 1 km Study Area
MLI42243	Monument	A Post Medieval Site in Thorpe St Peter	A post medieval site identified from surface finds of pottery, tile and brick and site of a decoy.	Medieval	TF 4365 6065	Within the 1 km Study Area
MLI97716	Monument	Medieval ridge and furrow and other earthworks surrounding Croft village	A probable medieval earthwork ridge and furrow field system surrounding the village of Croft is depicted on the National Mapping Programme. Earthworks of possible medieval enclosures, trackways and a probable medieval building are also visible in the same area. Earthworks can be seen on Google Maps (web site) aerial photograph layer.	Medieval	TF 5052 6198	Within the 1 km Study Area
MLI99481	Find Spot	Medieval Pottery, Bar Bridge Farm	Two sherds of abraded medieval pottery were recovered in May 2011, during systematic field walking along selected parts of the proposed Covenham Water Treatment Works to Boston Transfer pipeline.	Medieval	TF 358 543	Within the 1 km Study Area

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
MLI89118	Monument	Probable undated cropmark enclosure, Farlesthorpe	Probable undated cropmark enclosure as recorded by the National Mapping Programme.	Undated	TF 47612 74235	Within the 1 km Study Area
MLI42917	Monument	Farlesthorpe Decoy, Farlesthorpe Fen	The site of duck decoy. Farlesthorpe Decoy was on the fen two miles south-east of Alford. The decoy is marked on the first edition one inch to the mile OS map of 1824.	Post-medieval	TF 4850 7480	Within the 1 km Study Area
MLI41952	Monument	Possible Prehistoric or Roman saltern site	Saltern site with briquetage, hand bricks, short rods, evaporation dishes, shell gritted pottery and medieval pancheon rims and green glazed sherds. Medieval salterns did not use the poorly fired clay-vessels that are the source of briquetage. If the identification of briquetage is accurate then the saltern site will be Prehistoric or Roman	Bronze Age	TF 5140 6699	Within the 1 km Study Area
MLI12538	Find Spot	Romano British Pottery, Kirton	Finds from Kirton Holme includes 3rd century colour-coated ware and other Roman pottery, from TF 276 414	Roman	TF 2762 4144	Within the 1 km Study Area
MLI43115	Monument	Ridge And Furrow Earthworks	Extensive ridge and furrow earthworks visible in aerial photographs and recorded by the National Mapping Programme. Most appears to have been ploughed on aerial photographs. One field TF 526 642 it is uncertain if the earthworks are still extant.	Medieval	TF 5278 6423	Within the 1 km Study Area
MLI125735	Monument	Churchyard, Church of St Paul, New Leake	The churchyard at the Church of St Paul is depicted on the 2nd edition 25" Ordnance Survey County Series map. It likely dates to at least 1840, when the church it served was consecrated	Post-medieval	TF 4073 5942	Within the 1 km Study Area
MLI43667	Monument	Medieval Pottery, Ingoldmells Road	Five medieval pottery sherds were found in the topsoil during the watching brief on the Burgh Le Marsh - Ingoldmells Rising Main.	Medieval	TF 5242 6677	Within the 1 km Study Area
MLI84134	Monument	A possible Bronze Age barrow and undated enclosures and pits, Willoughby with Sloothby	A probable undated rectangular cropmark enclosure is visible to the south east of Butterbump barrow cemetery, seen on aerial photographs and recorded by the National Mapping Programme. Within the enclosure is a cropmark ring ditch which contains cropmarks pits. The ring ditch has been interpreted as a Bronze Age barrow perhaps an outlier of the Butterbump cemetery and the undated features may be related.	Bronze Age	TF 4988 7209	Within the 1 km Study Area
MLI93251	Monument	Church of St Paul, New Leake	The Church of St Paul is a building of considerable charm and is the last of the six churches commissioned under the Fen Churches Act of 1816. It is currently at risk of structural collapse. Ecclesiastical exemption for the building's demolition was granted on 12 May 2015. The church had been demolished by 9 March 2016, and was subsequently de-listed	Post-medieval	TF 40738 59420	Within 100 m of the draft Order Limits
MLI90859	Monument	Medieval Field System, Thorpe St Peter	Earthworks of a medieval ridge and furrow field system, to the north of Thorpe St Peter. Identified on aerial photography examined as part of the National Mapping Programme. Medieval field system comprising faint earthwork ridge and furrow and field boundaries. Much of the ridge and furrow appears to have been ploughed and levelled, as seen on the Google Maps aerial photographic layer	Medieval	TF 4842 6147	Within the 1 km Study Area

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
MLI40665	Monument	Roman Pottery Found in Langriville Parish	Romano British and Samian ware found under modern ground surface	Roman	TF 2810 4750	Within the 1 km Study Area
MLI12540	Find Spot	Romano British Pottery and Bone Toggle, Kirton	Roman pottery and a bone toggle were recorded at TF 270 416.	Roman	TF 2700 4160	Within the 1 km Study Area
MLI42227	Monument	Remains Of a Churchyard Cross in Farlesthorpe	The octagonal shaft of a cross on a small mound in the churchyard at Farlesthorpe. The base may be buried. Only 0.6 m is visible.	Undated	TF 4752 7400	Within the 1 km Study Area
MLI12547	Monument	Romano-British Pottery, Kirton	Probable late medieval field systems and enclosures, Keddington. The field systems and enclosures appear as cropmarks and earthworks on aerial photographs, and have been mapped by the National Mapping Programme. The features are likely associated with Louth Park Abbey, located to the north.	Roman	TF 2770 4099	Within the 1 km Study Area
MLI42664	Monument	Romano British Pottery Found In Irby In The Marsh	Romano-British greyware potsherds of 3 rd and 4 th century date found about 1 m deep during drainage excavation in 'Applehill' field.	Roman	TF 4703 6217	Within the 1 km Study Area
MLI84135	Monument	Possible medieval cropmark boundary, adjacent to Butterbump barrow cemetery, Willoughby with Sloothby	A possible medieval cropmark boundary is visible on aerial photographs adjacent to the Butterbump barrow cemetery.	Medieval	TF 4928 7248	Within the 1 km Study Area
MLI84140	Monument	Post medieval enclosure, north east of Habertoft, Willoughby with Sloothby	A post medieval cropmark and earthwork enclosure is visible on aerial photographs to the north east of Habertoft.	Post-medieval	TF 5110 6949	Within the 1 km Study Area
MLI97967	Find Spot	Roman pottery sherd, Willoughby	A sherd of Roman pottery found at TF487731.	Roman	TF 4880 7330	Within the 1 km Study Area
MLI97968	Find Spot	Flint flake, Willoughby	A flint flake, of an unknown date, which was found at TF488733	Neolithic	TF 4880 7330	Within the 1 km Study Area
MLI41091	Monument	Cropmark Site, New Leake	Cropmark indicating small square enclosure.	Undated	TF 3725 5475	Within the 1 km Study Area
MLI40660	Find Spot	Coin Hoard at Langrick Ferry, Holland Fen with Brothertoft	Large hoard of silver coins in pot, which were dug up in a garden at Langret [probably Langrick] Ferry in 1830. Coins are of Charles II, James II, William and Mary, William III, Anne and George I and a guinea of George		TF 2649 4749	Within the 1 km Study Area
MLI81652	Monument	Romano-British site, Wildmore Fen	A small area of blackened soil measuring about 30 feet in radius, with one or two sherds of Romano-British greyware was noted in Wildmore Fen. This site appears to be different in that it is in the low-lying part of the field. Other Romano-British sites in the locality are on the higher, drier ground, less prone to flooding	Roman	TF 2683 4770	Within the 1 km Study Area
MLI42245	Monument	Assorted Pottery Found During Drainage Work at Thorpe St Peter	Assorted pottery found during drainage work at Thorpe St Peter, including Romano British sherds.	Roman	TF 4550 6150	Within the 1 km Study Area

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
MLI42246	Monument	Assorted Pottery Found During Drainage Work at Thorpe St Peter	Assorted pottery found during drainage work at Thorpe St Peter, including medieval sherds.	Medieval	TF 4550 6150	Within the 1 km Study Area
MLI42247	Monument	Assorted Pottery Found During Drainage Work at Thorpe St Peter	Assorted pottery found during drainage work at Thorpe St Peter, including post medieval sherds.	Post-medieval	TF 4550 6150	Within the 1 km Study Area
MLI98629	Monument	Anti glider ditch in Orby	An anti-glider ditch dating to the Second World War visible in aerial photographs was recorded by the National Mapping Programme.	Modern	TF 5245 6709	Within the 1 km Study Area
MLI80879	Monument	Post medieval remains, Wigtoft.	A watching brief on a housing plot off Main Road, Wigtoft found levelling and dumping layers containing 18 th /19 th century pottery. Three probable drainage ditches dated to this period were also found.	Post-medieval	TF 2632 3609	Within the 1 km Study Area
MLI81509	Monument	Fifteenth-sixteenth century finds, Wildmore Fen, Langrick	A few fragments of fifteenth to 16 th century pottery and tile were noted in the vicinity of a small mound in a field in Wildmore Fen in April 2001.	Medieval	TF 2713 4770	Within the 1 km Study Area
MLI81508	Monument	Undated mound, Wildmore Fen, Langrick	A small mound, measuring approximately 20 m by 15 m, has been noted in the field, north of the Witham in Wildmore Fen. It has darkened soil around it. A few fragments of $15^{th} - 16^{th}$ century roof tile and pottery have been found in the area of the mound	Undated	TF 2713 4770	Within the 1 km Study Area
MLI86180	Monument	Former Smithy, Brothertoft	A smithy building is depicted in this location on the 1st edition 6" Ordnance Survey County Series map. Later map editions would suggest it was demolished in the mid 20 th century	Post-medieval	TF 2730 4583	Within the 1 km Study Area
MLI41693	Monument	Saltern Site in Burgh Le Marsh Parish	Saltern site including briquetage and pottery found in deepening drain c. 3 m down under silt. The mound measures 17 m long and 40cm deep	Iron Age	TF 5280 6440	Within the 1 km Study Area
MLI42845	Monument	Saltern Site In Burgh Le Marsh Parish	A saltern site including briquetage and pottery found in deepening drain c3 m beneath silt. The mound measures 17 m long and 40cm deep. Either iron age or roman in date.	Roman	TF 528 644	Within the 1 km Study Area
MLI41002	Find Spot	A Palstave from Silver Pit Drain	A looped palstave was found at the bottom of Silver Pit Pool, the largest and deepest of the pools in the East Fen. Silver Pit Drain is now incorporated in modern drainage.	Bronze Age	TF 380 593	Within the 1 km Study Area
MLI98699	Monument	Ridge and Furrow earthworks east of Harrison's Lane, Thorpe St. Peter	Ridge and Furrow earthworks forming part of a medieval field system, seen on aerial photographs and recorded by the National Mapping Programme Medieval ridge and furrow survives as earthworks and is visible (in 2013) on Google maps	Medieval	TF 4606 6074	Within the 1 km Study Area
MLI98098	Monument	Possible Medieval Earthwork Enclosures, The Hollies, Croft	Possible medieval enclosure earthworks were identified by the National Mapping Programme.	Medieval	TF 5018 6312	Within the 1 km Study Area
MLI80625	Monument	Ridge and Furrow, Ancroft Fen, Bilsby	Earthworks of medieval ridge and furrow at Ancroft Fen, to the south-east of Bilsby, identified on aerial photographs examined as part of the National Mapping Programme. Part of the ridge and	Medieval	TF 4805 7566	Within the 1 km Study Area

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
			furrow remains were noted in October 1999, during archaeological monitoring of the installation of a replacement gas pipeline between Trusthorpe and Candlesby. The earthworks were more prominent in the eastern side of the field, but diminished on the western side, closer to the route of the pipeline. A possible old lane and associated hollow ways were also noted as earthworks in the field.			
MLI13299	Monument	Site of a Post Medieval Brick Clamp South Of Leggott's Cottages	A field called 'brick clamp' is marked on the 18 th century brownlow estate map, and is shown as 'brick clamp field' on the 20 th century leggott's farm map.		TF 2612 3408	Within the 1 km Study Area
MLI80877	Find Spot	Stamford Ware pottery sherd, Wigtoft.	An abraded sherd of 9 th -12 th century Stamford Ware found in a deposit dated to the 18 th /19 th centuries. This was considered to suggest Medieval activity in the locality.	Early Medieval	TF 2632 3609	Within the 1 km Study Area
MLI84136	Monument	Undated enclosures and boundaries, Cumberworth Road, Willoughby with Sloothby	Probable and possible undated cropmark enclosures and boundaries are visible on aerial photographs in the Cumberworth Road area.	Unknown	TF 4916 7260	Within the 1 km Study Area
MLI42223	Monument	Assorted Post Medieval Artefacts Found In Farlesthorpe	Nine bronze and steel (?) buckles and fittings found in Farlesthorpe. All are of post-medieval date.	Post-medieval	TF 4750 7390	Within the 1 km Study Area
MLI42224	Find Spot	A Cistercian Ware Flask Found in Farlesthorpe	A Cistercian ware flask found in a field to the south-west of the church in Farlesthorpe.	Medieval	TF 4750 7390	Within the 1 km Study Area
MLI43101	Monument	Prehistoric Salterns, East of Burgh Le Marsh	During a watching brief on the Ingoldmells-Burgh Le Marsh rising main, 7299 briquetage fragments, along with saltworking features were discovered. This included a briquetage disc which had possibly been used as a counter or token. The presence of a late iron age rim sherd tentatively dates the saltworkings	Iron Age	TF 5120 6535	Within the 1 km Study Area
MLI87792	Monument	Modern aircraft obstruction, east of Burgh le Marsh	A modern aircraft obstruction is recorded as surviving as an earthwork to the north east of Burgh le Marsh.	Modern	TF 5152 6520	Within the 1 km Study Area
MLI92271	Monument	Castle Dyke House Park, Frithville	A historic park recorded on the first edition Ordnance Survey map at Castle Dyke House. It is not shown on the 1905 Ordnance Survey map.	Post-medieval	TF 29119 48803	Within the 1 km Study Area
MLI97956	Find Spot	A possible Neolithic scraper, Willoughby	A scraper possibly dating from the Neolithic period were found at TF490733 during field walking.	Neolithic	TF 4900 7330	Within the 1 km Study Area
MLI12514	Find Spot	Medieval Pottery, Wigtoft	Medieval pottery, including glazed ware and gritted jars, found in 1958, when preparing a car park at Burtoft for the County Agricultural Show. In 1965, the site was in pasture and that nothing of archaeological interest was seen. Fieldwalking in the 1970's and 1980's continued to produce medieval pottery from this site.	Medieval	TF 267 348	Within the 1 km Study Area
MLI43102	Monument	Saltmaking Site, West of Ashington End	30 fragments of briquetage were observed close to the western side of the field in the soil at the top of the backfilled trench,	Roman	TF 5250 6688	Within the 1 km Study Area

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
			during the watching brief on the Burgh Le Marsh - Ingoldmells Rising Main). The source of this material was not seen but it is assumed that the trench disturbed part of a saltern site below the marine flood - silt layer. A Romano-British date has been ascribed to this saltern site and examination of the briquetage has found closer affinities with contemporary dated sites on the route.			
MLI98636	Monument	Medieval enclosures in Addlethorpe parish	Medieval enclosures, a drain and a pond seen in aerial photographs and recorded by the National Mapping Programme.	Medieval	TF 5265 6867	Within the 1 km Study Area
MLI41049	Find Spot	Romano British Tettacotta Head	A terracotta head in Roman style.	Roman	TF 3435 5469	Within the 1 km Study Area
MLI12607	Find Spot	Romano-British Jar, Holland Fen with Brothertoft	A Romano-British jar was found in the 1970's. It is complete in two pieces with two parts restored and has a few white inclusions.	Roman	TF 269 454	Within the 1 km Study Area
MLI97996	Find Spot	Two undated flakes, Willoughby	Two secondary flakes of unknown date were found at TF496721.	Neolithic	TF 4960 7210	Within the 1 km Study Area
MLI40663	Monument	Romano British pottery scatter, Holland Fen with Brothertoft	Romano British greyware sherds were found south of the bank of the river Witham.	Roman	TF 2632 4746	Within the 1 km Study Area
MLI97975	Find Spot	Roman pottery sherd, Willoughby	A Roman pottery sherd found at TF493724.	Roman	TF 4930 7240	Within the 1 km Study Area
MLI97957	Monument	Possible later prehistoric cropmarks, Cumberworth	Cropmarks on aerial photographs have been identified at TF505727. They may represent an enclosure with associated linear ditch features. A probable cropmark enclosure of unknown date.	Bronze Age	TF 5050 7264	Within the 1 km Study Area
MLI116028	Monument	Avro Lancaster Aircraft Crash Site and War Memorial, Sibsey Northlands	On the afternoon of 29th January 1943, an Avro Lancaster Bomber, designated ED503 of 9 Squadron, took off from Waddington on an engine and airframe test-flight, but crashed at c.15:30, on open fenland at Sibsey Northlands. All 6 of the crewmen aboard the aircraft died in the crash, the cause of which could not be determined. One of the crewmen was thrown clear of the crash site, and his remains were collected for burial in his hometown of Dalkeith, Scotland. The other 5 bodies remained on the site, and a war memorial was later erected to commemorate the accident. The memorial takes the form of a stone cross, inscribed with the names of the deceased	Modern	TF 3338 5347	Within the 1 km Study Area
MLI41554	Monument	Medieval Pottery Found When Field Was Ploughed, Burgh Le Marsh	Medieval and post medieval pottery, mainly East Lincolnshire wares found on a newly farmed field.	Medieval	TF 5270 6420	Within the 1 km Study Area
MLI42842	Monument	Post Medieval Pottery Found in Plough Soil, Burgh Le Marsh	Medieval and post medieval pottery, mainly East Lincolnshire wares found on a newly farmed field in Burgh Le Marsh.	Post-medieval	TF 527 642	Within the 1 km Study Area

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
MLI97966	Find Spot	Flint flakes, Willoughby	Two flint flakes, of unknown date, were found at TF487731.	Neolithic	TF 4870 7310	Within the 1 km Study Area
MLI43118	Monument	Various Post Medieval Finds, Farlesthorpe	Two thimbles, one silver, one bronze; one bronze buckle; and one pewter button found in Farlesthorpe.	Post-medieval	TF 4740 7390	Within the 1 km Study Area
MLI98813	Monument	Ridge and furrow in Firsby	A field of ridge and furrow seen in aerial photographs and plotted by the National Mapping Programme staff.	Medieval	TF 45945 62185	Within the 1 km Study Area
MLI13430	Monument	Resistance Hide, New Hammond Beck, Frampton	A former Second World War resistance hide has been recorded as being in this vicinity. The structure was built for use by the British Auxiliary Units in the event of a German invasion, although was reportedly demolished in 1995.	Modern	TF 272 426	Within the 1 km Study Area
MLI90833	Monument	Former Manor House, Croft	Site of former manor house, Croft. Area of distinct soilmarks and cropmarks suggesting occupation site. Seen on Google Maps (web site) aerial photograph layer. The Ordnance Survey County Series Map of 1905 show a 'manor house' with an accompanying field system. The manor house was extant in 1964, but was demolished at some point after this. The building is said to have dated to the mid 18 th century, although the finding of 14 th century pottery and window glass on the site, could indicate that the building was a replacement of an earlier manor house in this location	Medieval	TF 50269 61734	Within the 1 km Study Area
MLI13096	Monument	Shrunken Settlement, Asperton, Wigtoft	This site appears to be identified with Osfyrdtune mentioned in a pre-conquest charter and again with Asfortonia. It is potentially an important early settlement site.	Early Medieval	TF 2600 3780	Within the 1 km Study Area
MLI13460	Monument	Medieval Saltern Mound	A saltern mound. There was medieval and post medieval pottery from the general area.	Medieval	TF 2607 3341	Within the 1 km Study Area
MLI98628	Monument	A post medieval enclosure in Orby parish	A post medieval enclosure was seen as an earthwork in aerial photographs and recorded by the National Mapping Programme.	Post-medieval	TF 5138 6675	Within the 1 km Study Area
MLI98646	Monument	Two medieval sheep folds in Hogsthorpe parish	Two possible medieval earthwork sheep folds seen on aerial photographs and recorded by the National Mapping Programme.	Medieval	TF 5115 7152	Within the 1 km Study Area
MLI41514	Monument	Medieval Pottery from Burgh Le Marsh	Many green glazed sherds and wine bottle bases with raised kicks. Teapot Hall.	Medieval	TF 5270 6670	Within the 1 km Study Area
MLI97955	Find Spot	Neolithic scraper and flakes and three undated flakes, Willoughby	A scraper and four flint flakes dating from the Neolithic period were found at TF484728 during field walking. Three flint flakes of unknown date were also found at this location.	Neolithic	TF 4840 7280	Within the 1 km Study Area
MLI92044	Monument	Site of former Primitive Methodist chapel, Wigtoft Bank, Wigtoft	A Primitive Methodist chapel is shown on the 1905 OS County Series map and a Primitive Methodist chapel, built in 1839, at Wigtoft Bank is recorded in the Census of Religious Returns. The chapel is not shown on the 1977 OS 1:10000 Map. The site was visited in 2008. The chapel no longer survives and the site now lies at the edge of a ploughed field.	Post-medieval	TF 25044 35531	Within the 1 km Study Area
MLI84139	Monument	Possible post medieval earthwork enclosure,	A possible post medieval earthwork enclosure is visible on aerial photographs to the north east of Habertoft.	Post-medieval	TF 5065 6972	Within the 1 km Study Area

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
		north west of Habertoft, Willoughby with Sloothby				
MLI41987	Monument	Mill Hill	Placename evidence for a mill.	Undated	TF 5014 7387	Within the 1 km Study Area
MLI97892	Find Spot	Mesolithic or Neolithic flake, Willoughby	A large flint flake possibly dating from the Mesolithic or Neolithic was found during fieldwalking at TF480727, fifty metres east of Wiloughby High Drain.	Mesolithic	TF 480 727	Within the 1 km Study Area
MLI98630	Monument	Post medieval enclosure in Orby parish	A post medieval enclosure visible in aerial photographs was recorded by the National Mapping Programme.	Post-medieval	TF 5265 6755	Within the 1 km Study Area
MLI12516	Find Spot	Chafing Dish, Coriander Cottage, Spion Kop Lane, Wigtoft	A 16 th century chafing dish of Dutch origin, found in the garden of Coriander Cottage, Spion Kop Lane, Wigtoft.	Post-medieval	TF 2646 3620	Within the 1 km Study Area
MLI87791	Monument	Modern aircraft obstruction, east of Burgh le Marsh	A modern aircraft obstruction is visible on aerial photographs as an earthwork, to the north east of Burgh le Marsh.	Modern	TF 5106 6522	Within the 1 km Study Area
MLI97889	Monument	Probable post medieval cropmarks, Willoughby	Cropmarks were identified from aerial photographs which may represent former field boundaries, probably dating from the post medieval period.	Post-medievalPost- medieval	TF 476 726	Within the 1 km Study Area
MLI41949	Monument	Saltern Site, Orby	A 6 m long saltern site with finds of pan fragments, hand bricks including one bearing a cloth impression and hearth edging found 1.5 m down in drainage trench. The grid reference was altered from TF527671 after a watching brief on an Anglian Water pipeline scheme in November 1993.	Undated	TF 527 677	Within the 1 km Study Area
MLI13074	Monument	Fishponds, Dowdyke Grange, Sutterton	Site of grange. Sketch plan of farmyard, fishponds, details in field notebook.	Medieval	TF 2759 3330	Within the 1 km Study Area
MLI81507	Monument	Romano-British finds, west of Willow Farm, Ferry Road, Langrick	An area of blackened soil was noted at some time during the 1980s. It is adjacent to the old course of the Witham at Langrick, west of Willow Farm, Ferry Road. Several sherds of Romano- British grey ware, and some Samian were identified. In the past metal detectorists have been on the site, and several coins were discovered and removed, for which no date or type is known.	Roman	TF 2681 4797	Within the 1 km Study Area
MLI42930	Monument	Possible Western Extension of Butterbump Barrow Cemetery	At least 11 ring-ditch cropmarks and soilmarks seen by Paul Everson in 1976 and 1977 within an arc extending from the western end of the Butterbump barrow cemetery to approximately TF48507255. Also present are parallel linear ditches at TF48657240 and TF49107255 which are possibly enclosure ditches and field boundaries.	Bronze Age	TF 4877 7237	Within the 1 km Study Area
MLI13298	Monument	Middle Saxon Pottery Found at Burtoft	Middle Saxon pottery found in the 1970s and 1980s during fieldwalking.	Early Medieval	TF 2688 3499	Within the 1 km Study Area
MLI98632	Monument	Medieval enclosures south of Marsh Lane, Orby	A group of medieval enclosures off Marsh Lane in Orby visible in aerial photographs were recorded by the National Mapping Programme.	Medieval	TF 5074 6724	Within the 1 km Study Area



HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
MLI84128	Monument	Undated cropmark field system, south of Bonthorpe Road	Undated cropmark enclosures are visible on aerial photographs to the south of Bonthorpe Road. To the south of Bonthorpe is a cluster of cropmarks represending enclosures, double ditched features and a co-axial system of ditches. The features may date from the post medieval period.	Unknown	TF 4837 7258	Within the 1 km Study Area
MLI13075	Monument	Dowdyke Grange, Sutterton	The site of Dowdyke Grange	Medieval	TF 2760 3330	Within the 1 km Study Area
MLI42250	Find Spot	Medieval Pot and Animal Bones, Thorpe St Peter	An almost complete Toynton All Saints jug (of kiln 1 type) found with animal bones.	Medieval	TF 4530 6030	Within the 1 km Study Area
MLI41083	Find Spot	Unlooped Palstave Found In Midville	Unlooped palstave found on Carter's farm	Bronze Age	TF 3730 5810	Within the 1 km Study Area
MLI41999	Find Spot	A Bronze Age socketed axehead, Willoughby with Sloothby	A Bronze Age faceted socketed axehead in very good condition found encased in soft stone deposit in a sugar beet field in about 1959 near Bonthorpe in Willoughby with Sloothby parish.	Bronze Age	TF 4804 7260	Within the 1 km Study Area
MLI87790	Monument	Modern aircraft obstruction, east of Burgh le Marsh	A modern earthwork aircraft obstruction is visible on aerial photographs to the north east of Burgh le Marsh.	Modern	TF 5095 6530	Within the 1 km Study Area
MLI98596	Monument	Ridge and furrow in Hogsthorpe	Ridge and furrow visible in a aerial photograph and recorded by the National Mapping Programme. Medieval ridge and furrow appears to have been ploughed out and is not visible (in 2013) on Google maps.	Medieval	TF 5281 6910	Within the 1 km Study Area
MLI13094	Monument	Medieval Pottery, Burtoft, Wigtoft	Two groups of pottery found when a field near the Manor House was levelled to make a car park for the show. Fieldwalking which took place in 1975 and later revealed Stamford ware and Ipswich wares, and later suveys produced medieval pottery over a large area, mainly east of Burtoft Lane and centred on TF 2690 3545.	Medieval	TF 269 354	Within the 1 km Study Area
MLI13297	Monument	Middle Saxon Pottery Found East Of Burtoft Lane	Fieldwalking which took place in 1975 and later revealed Stamford ware and Ipswich wares, and later suveys produced medieval pottery over a large area, mainly east of Burtoft Lane and centred on TF 2690 3545.	Early Medieval	TF 2683 3523	Within the 1 km Study Area
MLI43664	Monument	Medieval Pottery Scatter, South of Ingoldmells Road	A scatter of medieval pottery was found in field 5 during the watching brief on the Burgh Le Marsh - Ingoldmells Rising Main.	Medieval	TF 5100 6520	Within the 1 km Study Area
MLI43662	Find Spot	Romano-British Tile Fragment, South of Ingoldmells Road	A fragment of Romano-British tile fragment was found during a watching brief on the Burgh Le Marsh - Ingoldmells Rising Main.	Roman	TF 5100 6520	Within the 1 km Study Area
MLI43663	Find Spot	Early Medieval Pottery, South of Ingoldmells Road	A sherd of early medieval pottery was found in field 5 during the watching brief on the Burgh Le Marsh - Ingoldmells Rising Main.	Early Medieval	TF 5100 6520	Within the 1 km Study Area
MLI12640	Find Spot	Roman Pottery, Holland Fen with Brothertoft	Two adjoining 19 th century cottages that were converted into one dwelling. The farm labourers' cottages were constructed at some point between 1848 and 1889. The rear of the cottages were	Roman	TF 2850 4560	Within the 1 km Study Area

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
			originally one-storey high; in the mid to late 20 th century a second storey and a cat slide roof were added to the rear. The building is constructed primarily of local red brick. The hipped roof is made of asbestos with ceramic ridge tiles, the original roof would have been made of pantile; a central chimenystack is also present. The chimney would have mirrored fireplaces to the two original cottages.			
MLI41991	Monument	Medieval Pottery Found Near Sloothby	Medieval pottery including shelly ware, green glaze, 1 bung hole jar, pancheon, sagging base and handle from a possible couvre feu. A scatter of stone rubble also found.	Medieval	TF 4970 7090	Within the 1 km Study Area
MLI84488	Monument	Later Mesolithic flintworking site, Mexican Bridge, Midville	Excavation, test pitting and inspection trenches were carried out as part of the Fenland Management Project. No archaeological features were encountered, but the bulk of the lithic assemblage can be assigned to the later Mesolithic and related to the reduction of blade cores. Along with smaller chips and bladelets, the assemblage contained a number of true blades, and core fragments reflect an emphasis on blade production. A small number of retouched artefacts were also found, including three microliths. The small size of the chips is indicative of in situ working. The remains do not indicate the nature or function of the site apart from somewhere where flint was worked. Whether that working took place within a settlement is not known. Environmental sampling indicated a wooded environment	Mesolithic	TF 3714 5776	Within the 1 km Study Area
MLI41726	Monument	Medieval Pottery, Croft	13 th century potsherds found in Croft.	Medieval	TF 4991 6314	Within the 1 km Study Area
MLI41727	Monument	Skeleton, Croft	Human skeleton found in Croft. The bones have been reinterred.	Undated	TF 4991 6314	Within the 1 km Study Area
MLI41725	Find Spot	Flint Scraper, Croft	Flint scraper found in Croft End.	Neolithic	TF 4991 6314	Within the 1 km Study Area
MLI41951	Monument	Roman Saltern Site, Orby	Roman saltern site with handbricks, pan fragments and sherd of Greyware, found to the east of Orby	Roman	TF 5280 6780	Within the 1 km Study Area
MLI86276	Legend	Danish raiders of Hubberts Bridge	Local Legend about Danish raiders (called Hubba/Ubba or Ubbi?) active around 860 AD. They were meant to have some connection to Hubberts Bridge and the mound close to Hubberts bridge is reputed to have been the site of his fort.	Early Medieval	TF 269 436	Within the 1 km Study Area
MLI88786	Monument	Iron Age saltern site, Hildyke Drain	Fieldwalking across the proposed Orby Marsh windfarm site located a small scatter of Iron Age briquetage adjacent to Hildyke Drain. The briquetage included pieces of brine evaporation trays, tray spacers and clips used to join the rims of adjacent trays.	Iron Age	TF 52440 69552	Within the 1 km Study Area
MLI99129	Monument	Late Iron Age/Roman Settlement Activity, Croft	A magnetometry survey, conducted in August 2012 in advance of the construction of a proposed solar park, revealed an area of intense archaeological activity. A considerable number of linear anomalies, defining at least four major conjoining enclosures of varying size and internal sub-division were clearly identified. The	Iron Age	TF 4982 6328	Within the 1 km Study Area

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
			complexity and density of the recorded features are thought to be highly indicative of Romano-British settlement activity over a prolonged period of time, possibly continuing into early post- Roman dates. A subsequent trial trench evaluation, conducted in September 2012, identified features consistent with an extensive later Iron Age and Roman settlement, including numerous ditches, pits and enclosures. The quantity and alignments of the features suggest continued use of the site over a long period, with the recutting of many of theditches and enclosures, and the extension and addition of new areas of activity. A considerable quantity of late Iron Age and Roman pottery was recovered, and comprised an extremely wide variety of vessels, ranging from coarse wares to imported samian, in a wide variety of recovered, along with a small quantity of flint flakes and tegula fragments. Metal artefacts recovered from the ditches included two copper alloy Colchester Derivative brooches, an iron knife, an iron tumbler lock slide key, and several small iron nails and fittings. A considerable quantity of animal bone was also recovered, comprising cattle, horse, pig, sheep, dog and chicken bones, though dominated by the cattle remains. The recovered finds indicate a rural settlement of moderate influence, with access to relatively high status artefacts and animals. Analysis of environmental samples taken during the evaluation have indicated a mixed cereal economy of wheat, oats and barley, focussing on spelt wheat. Processing of the cereal grains, including the final stages of drying in a corn drier or hearth, were indicated by the presence of spelt wheat chaff. The wide range of different on-site activities, including animal husbandry, cereal cultivation and the processing of different materials, indicate a settlement that was part of an extensive network of agricultural production and industry.			
MLI91795	Monument	Undated ditches on land at Spencer Farm, Croft End	Three undated ditches were uncovered during a watching brief. Two of the ditches appeared to be related, forming part of a rectangular enclosure, and were cut by a pond of possible medieval date. It is suggested that the ditches may form part of an early field system.	Unknown	TF 49524 63058	Within the 1 km Study Area
MLI97890	Monument	Possible cropmark ring ditch, Willoughby	To the southern portion of the field, there is a cropmark circular ditch which may be the ring ditch of a barrow.	Bronze Age	TF 476 725	Within the 1 km Study Area
MLI98638	Monument	Medieval enclosures and a pond in Hogsthorpe	A cluster of probable medieval earthwork enclosures and a possible pond seen in aerial photographs and recorded by the National Mapping Programme.	Medieval	TF 5286 6889	Within the 1 km Study Area
MLI40661	Monument	Romano-British Pottery Found Near Manor Farm	Romano british grey ware sherds found in hill field near Manor Farm in 1979.	Roman	TF 271 483	Within the 1 km Study Area
MLI42256	Find Spot	Polished Stone Axe, Thorpe St Peter	A Neolithic polished stone axe was found in 1956 on land to the north-east of Thorpe St Peter.	Neolithic	TF 4916 6160	Within the 1 km Study Area

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
MLI91796	Monument	Possible medieval pond on land at Spencer Farm, Croft End	A pond filled with a peat deposit was found during a watching brief. A piece of modern tile was found in the fill, however this is thought to be intrusive as peat could not form that quickly. A 12 th century sherd in the fill is thought to give a more likely indication of the feature's date.	Medieval	TF 49525 63058	Within the 1 km Study Area
MLI98633	Monument	Post medieval enclosures in Orby parish	Two post medieval enclosures in Orby visible in aerial photographs were recorded by the National Mapping Programme.	Post-medieval	TF 5083 6769	Within the 1 km Study Area
MLI12524	Monument	Saltworks, Bicke	An extensive saltworking area, where the Old Eau turns through a shallow but broad valley of almost pure sand. Flanking the river are natural mounds enlarged by saltwork and modern drainage spoil. All are ploughed down and some demolished completely except for one amorphous mound at TF 2403 3651.	Undated	TF 2434 3636	Within the 1 km Study Area
MLI97958	Find Spot	Flint flakes, Willoughby	Three flint flakes of unknown date found at TF475735.	Neolithic	TF 4750 7350	Within the 1 km Study Area
MLI23631	Monument	Warren Near Coney Garth House	The site of the farm called Coney Garth House would suggest that there is a rabbit warren in the vicinity	Undated	TF 2727 3019	Within the 1 km Study Area
MLI41086	Find Spot	Barbed And Tanged Arrowhead Found In Midville	An unpatinated barbed and tanged arrowhead found after ploughing in a field to the west Of White House, Midville.	Bronze Age	TF 3730 5710	Within the 1 km Study Area
MLI99383	Monument	Flints found during evaluation at Croft	Seven pieces of flint were found during trial trenching at The Hollies, Croft. All were residual and comprised two cores, a scraper and four flakes. These were a broken secondary flake, a further secondary flake, a thermal flake and a tertiary flake with some use wear apparent along its distal edge. A broken poor- quality flint cobble with some negative removal scars indicating it was once part of a larger core. A core on a small, till-derived flint pebble with eight removal scars from two, roughly opposing, platforms, and finally, a small, broken pebble that has been modified into a rough scraper.	Neolithic	TF 4977 6330	Within the 1 km Study Area
MLI13091	Monument	Medieval Pottery And Saltern Material Found, Wigtoft	In a field just south of Hoffleet stow, a huge lump of burnt clay with saltern material was ploughed out, and also found was a lump of fired clay tempered with grass.	Medieval	TF 2449 3658	Within the 1 km Study Area
MLI81732	Monument	Sheepwash along the northern side of Washdike Lane	Washdyke Lane has a washdyke or sheepwash running along its northern side. It approximately a quarter of a mile in length, and appears to be a large drainage ditch which has been widened out especially to make the sheepwash. It runs from Church Lane to Croft Lane.	Medieval	TF 50660 61770	Within the 1 km Study Area
MLI41089	Find Spot	Neolithic Flint Found In Midville Parish	Early to late neolithic flint found on sandy area on small island around which principle roddon has been deflected. Flints include serrated piece and others with edge gloss. Excavation and test pitting carried out as part of the Fenland Management Project in 1992 recovered a crudely-made late Neolithic oblique arrowhead.	Neolithic	TF 3712 5781	Within the 1 km Study Area

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
MLI13033	Monument	Romano British pottery, Kirton Fen, Holland Fen with Brothertoft	Roman pottery found in a beet field immediately west of Hubberts Bridge Farming Company premises.	Roman	TF 2650 4380	Within the 1 km Study Area
MLI125455	Monument	Undated Enclosures, Willoughby with Sloothby			TF 5107 6852	Within the 1 km Study Area
MLI41723	Monument	Medieval Pottery Found In Croft	Pottery of mainly 14 th century date found along with some window glass at croft manor house in 1954.	Medieval	TF 5026 6172	Within the 1 km Study Area
MLI41090	Monument	PREHISTORIC FLINT SCATTER, MIDVILLE	Mostly late neolithic but some early bronze age flint located on small island surrounded on three sides by silty clay roddon.	Neolithic	TF 3719 5822	Within the 1 km Study Area
MLI125736	· · · · · · · · · · · · · · · · · · ·		A German Luftwaffe Dornier Do 17 crashed to the south-east of Carrington on the 8th of May 1941. The aircraft was designated 2843 (R4+GK) of NJG2 squadron. The plane was shot down by a Beaufighter from 25 Squadron, with all three crew members managing to bail out. A licence to excavate the remains of the aircraft was granted in November 2018, but was not acted upon.	Modern	TF 320 542	Within the 1 km Study Area
MLI41062	Monument	Medieval Soilmark Site S Of Stickney	A soilmark visible on APS of a possible ploughed out earthwork.	Undated	TF 3370 5490	Within the 1 km Study Area
MLI86433	Monument Late Medieval to post- medieval pottery scatter south of Ingoldmells Road, Burgh Le Marsh		An archaeological surface collection survey (systematic fieldwalking) was carried out along the proposed route of the A158 Burgh-le-Marsh bypass. The fieldwalking identified a relatively dense concentration of post-medieval pottery, consisting mainly of red and brown glazed earthen wares and Toynton or Toynton/Bollingbroke ware.	Medieval	TF 50800 65260	Within the 1 km Study Area
MLI92256	Monument	Langrick Grange Park, Langriville	Historic parkland around Langrick Grange is depicted on the 2nd edition 25" Ordnance Survey County Series map.	Post-medieval	TF 2643 4829	Within the 1 km Study Area
MLI40657	Monument	Armtree Deserted Medieval Village, Langriville	Armtree Manor is listed in a document of 1572 as being on the site of an extinct medieval village. It was said to have formed part of the parish of Coningsby at that time. A number of slight mounds were noted in this area, to the south-west of the modern village of Langrick. The mounds were believed to represent part of the remains of the medieval village of Armtree. Considerable quantities of masonry and tile fragments were found in the area of the mounds, along with sherds of 13 th -18 th century pottery and tile. Large quantities of animal bone (pig, sheep) and shell (oyster, cockle and whelk) were identified during a site visit to this area in July 2010. The finds were thought to be of probable medieval date. It was reported that large pieces of stone and fragments of medieval pottery are also regularly found on the site during ploughing.	Medieval	TF 264 483	Within the 1 km Study Area
MLI87276	Monument		37 trial trenching was undertaken on the proposed Burgh le Marsh bypass prior to development. Two pits and a ditch were	Post-medieval	TF 5077 6530	Within the 1 km Study Area

5077 6530	Within the 1 km Study Area

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
			uncovered and dated to the 18 th century by the pottery sherds that they contained. They also contained animal bone.			
MLI98610	Monument	Ridge and Furrow, Lincoln Farm, Bratoft	Medieval ridge and furrow at Lincoln Farm, Bratoft, visible on the aerial photographic plots of the National Mapping Programme.	Medieval	TF 4748 6284	Within the 1 km Study Area
MLI84118	Monument	Undated cropmark enclosure and boundaries, north east of Willoughby	Undated cropmark enclosures and boundaries are visible on aerial photographs to the north east of Willoughby.	Unknown	TF 4793 7234	Within the 1 km Study Area
MLI41535	Monument	Medieval Pottery Found N Of Blands Farm, Burgh Le Marsh	Medieval pottery recorded through field walking in the late 1970s	Medieval	TF 5040 6380	Within the 1 km Study Area
MLI41719	Monument	Post Medieval Pottery From Croft	Scatter of post medieval pottery including Bourne and Toynton All Saints Wares.	Post-medieval	TF 5115 6212	Within the 1 km Study Area
MLI85311	Monument	Medieval ditch, Elm Tree Cottage, Burgh-Le-Marsh	An archaeological watching brief conducted on land at Elm Tree Cottage, Burg-Le-Marsh identified an east to west aligned ditch. The ditch was over 4.4 m long, 1.3 m wide and 0.48 m deep. A single fill of yellowish brown silty clay was recorded, from which pottery of 13 th to 14 th century date and fired clay were retrieved. A single sherd of mid 12 th to mid 14 th century pottery was found in underlying subsoil. The deposits suggest that the land had an agricultural function in the medieval period, with the ditch representing either land division or drainage	Medieval	TF 50503 63880	Within the 1 km Study Area
MLI12605	Monument	Romano-British Farmstead, Cannon's Farm, Brothertoft	The excavations in 1959 show a well defined area of settlement approximately 50 feet square. It formed a complex of occupation floors, drainage ditches and pits. 1 st century and 4 th century pottery was also found. This site at Cannon's Farm, Punchbowl Lane had previously yielded during ploughing a denarius of Septimus Severus, course greyware pottery and animal remains from dark soil	Roman	TF 2875 4561	Within the 1 km Study Area
MLI85312	Find Spot	Medieval pot sherd, Elm Tree Cottage, Burgh-Le- Marsh	An archaeological watching brief conducted on land at Elm Tree Cottage, Burgh-Le-Marsh recovered a single sherd of a mid 12th to mid 14 th century Scarborough ware jug. The sherd was found in subsoil, underlying (cut by) a medieval ditch containing finds dated to the 13 th to 14 th century.	Medieval	TF 50505 63880	Within the 1 km Study Area
MLI42192	Monument	Shrunken Medieval Village Of Firsby	Firsby does not appear in Domesday Book although it is recorded as early as 1125 in other documents. The name of the place means 'village of the Frisians from the Old English 'Frisa' and Old Danish 'by'. This perhaps indicates that the village was originally occupied by Frisians who accompanied the Vikings in their settlement of eastern England. By 1563 there were some 26 families in the village and this remained fairly constant into the early 18 th century with about 25 families recorded in the diocesan census. The population of 117 in 1801 had risen to 270 in 1871 after which it declined slowly to 213 by 1901. Aerial photos show earthworks of old roads and small fields suggesting Firsby village	Medieval	TF 4553 6261	Within the 1 km Study Area



HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
			is now much reduced in size. A site visit was undertaken in October 2007 on the field centred at TF 45524 62726. Settlement earthworks covered the field with at least two banks apparently continuing under the access road and further east			
MLI41085	Find Spot	Flint Axe Found In Midville	Flint axe, polished near ends, found in Midville parish	Neolithic	TF 3730 5680	Within the 1 km Study Area
MLI98402	Monument	Parkland associated with Firsby Manor House, Firsby	A park is recorded on the first and second edition Ordnance Survey maps at Frisby Manor House, Firsby.	Post-medieval	TF 45666 62663	Within the 1 km Study Area
MLI41950	Monument	Saltern Sites In Orby	Five saltern sites with briquetage, hand bricks, pan fragments and baked clay lumps found in Orby.	Undated	TF 5290 6800	Within the 1 km Study Area
MLI90856	Monument	Probable medieval earthwork ridge and furrow and enclosures, Thorpe St Peter	Earthwork ridge and furrow and enclosures seen on Google Maps (web site) aerial photograph layer.	Medieval	TF 47675 61005	Within the 1 km Study Area
MLI98102	Monument	Possible Medieval Trackway and Enclosure, Beechwood House, Burgh le Marsh	Earthworks of a possible medieval trackway and enclosure, to the south of Beechwood House. The trackway was visible as a single wide ditched feature, running for approximately 100 m along a roughly north-west to south-east alignment. The enclosure is visible a right-angled ditched linear feature, forming two sides of a probable rectangular area. Identified on aerial photography examined as part of the National Mapping Programme.	Medieval	TF 5046 6397	Within the 1 km Study Area
MLI13090	Monument	Medieval Pottery Found, Wigtoft	In 1973, pottery was collected from a possible medieval saltern mound to the south of a former brewery in the junction between the A17 and the road through bicker. Locally known as the 'churchyard', much animal bone was dug up. Formerly a pond which is now filled in. Late medieval pottery was also found	Medieval	TF 246 370	Within the 1 km Study Area
MLI125506	Monument	Churchyard, Church of All Saints, Croft	The churchyard at the Church of All Saints is depicted on the 2nd edition 25" Ordnance Survey County Series map. It likely dates to at least the 14 th century, when the church it serves was built. A small quantity of re-deposited, disarticulated human remains were found in June 2018, during archaeological monitoring of groundworks for new drainage at the church. No archaeological features were identified during the monitoring, however, and all of the remains were reburied in the churchyard.		TF 5094 6185	Within the 1 km Study Area
MLI98637	Monument	Post medieval enclosure in Hogsthorpe	A possible post medieval earthwork enclosure seen in aerial photographs and recorded by the National Mapping Programme.	Post-medieval	TF 5298 6915	Within the 1 km Study Area
MLI40658	Monument	Roman Pottery And Coins Found At Langrick	Scatter of Roman coarse wares and samian, including a base stamped 'atis. F' found at Langrick during fieldwalking. Several coins were also found here	Roman	TF 2680 4820	Within the 1 km Study Area
MLI12609	Monument	Roman Settlement Site, Frampton	Roman site exposed by ploughing during 1967, approximately 500 yards from a previously discovered site at Frampton Fen. Romano-British pottery was found in a drainage ditch, at TF 289 414-TF288416. Romano-British greyware, quern fragments,	Roman	TF 288 414	Within the 1 km Study Area

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
			some tile and mortorium material were found. Pottery was recovered from TF 289413. It was mainly grey ware and colour-coated ware, including some white painted sherds.			
MLI40662	Monument	Pottery Found In Hill Field, Manor Farm	Romano British, Romano British, medieval and post medieval pottery found Hill Field, Manor Farm	Roman	TF 269 482	Within the 1 km Study Area
MLI41555	Monument	Post Medieval Pottery Found S Of Burgh Le Marsh	Coarse pottery of the 17 th to 19 th centuries mostly of East Lincolnshire types including slipware, a fragment of a bellarmine face mask and clay pipes of the late 17 th and early 18 th century.	Post-medieval	TF 5048 6399	Within the 1 km Study Area
MLI42012	Monument	Manor House, Sloothby	Placename evidence for Manor House, Sloothby.	Undated	TF 49540 70807	Within the 1 km Study Area
MLI125456	Monument	Possible Saltern, Willoughby with Sloothby	A discreet magnetic anomaly was recorded in this location in August 2015, during geophysical survey of land off Habertoft Lane. It was thought possible that the anomaly represented the remains of a possible saltern, although its exact origins could not be confirmed	Unknown	TF 5095 6866	Within the 1 km Study Area
MLI12624	Monument	Romano-British Farmstead, Wyberton/Frampton	A complex of soilmarks at TF 288 433C are thought to represent a Romano-British farmstead, they are visible on aerial photographs. There are no surface indications of these soilmarks in an area now under plough and crop. No surface finds were made. Romano-British native farmstead type. Ground survey yielded numerous sherds of Romano-British pottery, including the rim of a mortaria with the stamp of the second century potter Brusius. Two trenches were dug to attempt to determine the form and function of the site. The potential remains in the first trench were so plough damaged that interpretation was not possible. Grey ware pottery and mortar were recovered. A second trench was dug which revealed a ditch with several fills, suggesting that the ditch silted up over a long period of time. The site has been interpreted as a Romano-British farmstead	Roman	TF 2879 4331	Within the 1 km Study Area
MLI97893	Monument	Late Neolithic or early Bronze Age scraper and six flakes and an undated flake, Willoughby	A scraper and six flakes probably dating from the late Neolithic to early Bronze Age were found during fieldwalking at TF484724. An undated flint flake was also found at this location.		TF 484 724	Within the 1 km Study Area
MLI90855	Monument	Medieval settlement and field system, Thorpe St Peter	Medieval settlement and associated field system, Thorpe St Peter depicted on the NMP.	Medieval	TF 48359 60771	Within the 1 km Study Area
MLI116052	Monument	Croft War Memorial	Croft war memorial is a rough-hewn grey-granite Celtic cross on an octagonal base with three steps. The memorial was originally unveiled in 1921 with the names of those who fought in the First World War but subsequent names were added after the Second World War. The memorial is situated on the junction of Church Lane and Pinchbeck Lane.	Modern	TF 50866 61763	Within the 1 km Study Area



HER Reference	ER Reference Record Type Name Description		Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
ML190824	Monument	Cropmark Romano-British ditches and possible building, Holland Fen with Brothertoft	Two rectangular enclosures (possibly buildings), a ring ditch and a series of linear features seen on Google Maps (web site) aerial photograph layer	Roman	TF 26157 44389	Within the 1 km Study Area
MLI41518	Find Spot	Roman Coin Found In Burgh Le Marsh	An illegible roman ae found at this location.	Roman	TF 5050 6420	Within the 1 km Study Area
MLI41519	Find Spot	Two Medieval Coins Found In Burgh Le Marsh	Two cut halfpennies of Henry III Long Cross 1246-72.	Medieval	TF 5050 6420	Within the 1 km Study Area
MLI41560	Find Spot	A Bronze Pm Handle Found To SE Of Burgh Le Marsh	A bronze handle or stopper of possible 17 th century date found to SE of Burgh Le Marsh.	Post-medieval	TF 5050 6420	Within the 1 km Study Area
MLI41561	Find Spot	A 15 th Century Ewer Spout, Burgh Le Marsh	A bronze ewer spout of continental 15 th century date	Medieval	TF 5050 6420	Within the 1 km Study Area
MLI40582	Monument	Medieval Site, South Of A158, Burgh Le Marsh	Hump in field. When ploughed medieval potsherds were discovered.	Medieval	TF 5320 6400	Within the 1 km Study Area
MLI97714	Monument	Possible medieval earthwork enclosure, Grove House Farm, Bratoft	A possible medieval earthwork enclosure depicted on the National Mapping Programme.Earthworks can be seen on Google Maps (web site) aerial photograph layer	Medieval	TF 4861 6316	Within the 1 km Study Area
MLI22459	Monument	Bicker Haven, Gosberton	This ancient inlet is very obvious.	Undated	TF 2600 3300	Within the 1 km Study Area
MLI12536	Monument	Romano-British Pottery, Holland Fen with Brothertoft	Pottery fragments and charred material were found during soil testing at TF261 449.	Roman	TF 261 443	Within the 1 km Study Area
MLI41533	Find Spot	Bronze Spur Found S Of Burgh Le Marsh	A bronze chased rowel spur found S of Burgh Le Marsh, other material may suggest a house site.	Post-medieval	TF 5040 6400	Within the 1 km Study Area
MLI13349	Monument	Roman pottery sherds, Holland Fen with Brothertoft	Six sherds of Roman pottery were found during fieldwalking of the site north of Kirton Drive. During work prior to the construction of an agricultural reservoir, several cropmark enclosures said to be Roman were noted and a trench was positioned across part of one enclosure. Environmental evidence indicated the presence of a former stream. The ditch that was uncovered was undated and no occupation debris was recovered.	Roman	TF 2630 4509	Within the 1 km Study Area
ML197894	Find Spot	Neolithic or Bronze Age flint, Willoughby	A Neolithic to early Bronze Age knife, scraper and two flakes were found during fieldwalking at TF487725. A core, a scraper and eight flakes of unknown date were also found at this location.	Neolithic	TF 487 725	Within the 1 km Study Area
MLI98107	Monument	Medieval ridge and furrow near Lymn Bank, Thorpe St Peter	Possible ridge and furrow earthworks were identified by the National Mapping Programme. They are thought to be part of a larger field system	Medieval	TF 4934 6126	Within the 1 km Study Area
MLI84123	Monument	Undated cropmark boundary, south of the	An undated cropmark boundary is visible on aerial photographs to the south of the Butterbump barrow cemetery. A small cropmark	Unknown	TF 4875 7211	Within the 1 km Study Area

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
		Butterbump barrow cemetery, Willoughby with Sloothby	complex centred on TF488721 which may date from the post medieval period.			
MLI43103	Monument	Roman saltmaking remains	This part of the pipeline was not archaeologically monitored (during the watching brief on The Burgh Le Marsh - Ingoldmells Rising Main). However, a large quantity of briquetage (208 fragments), including numerous possible structure fragments, indicated that the trench had disturbed part of a major waste heap. Material was of roman date. Material was spread along a 40 m length of the backfilled trench.	Roman	TF 5299 6716	Within the 1 km Study Area
MLI40659	Monument	Medieval Activity, Langrick	Remains of medieval buildings and activity, thought to date from the 14 th century onwards, and revealed during trial trenching in 1976. The earliest feature on the site was a north to south aligned ditch, located at the western end of the trench. The lowest fill of the ditch contained fragments of wood ash and Shelly ware pottery. Immediately above this was a near complete cooking pot, of a fabric similar to Staxton ware. A later building of 16 th century dressed stone had partially collapsed into the upper fills of the ditch. A robber trench was found running south along this upper fill. A hearth associated with 16 th century sherds was located in the north-eastern corner of the wall, under which was found an incomplete mustard quern of Mayen lava.		TF 266 483	Within the 1 km Study Area
MLI81929	MON	Scatter of Roman pottery, St Helen's Church	An excavation and watching brief recovered 10 sherds of Roman pottery, one of which was samian dating to the mid- to late 2 nd century, and nine of which were greyware dating to the mid-3 rd to 4 th century.	Roman	TF 5062 7373	Within the 1 km Study Area
MLI81932	MON	Flint scatter, St Helen's Church	During an excavation and watching brief, eight fragments of Mesolithic flint work were recovered. No specific tool types were present , but one of the pieces may be a broken microlith.	Mesolithic	TF 5062 7373	Within the 1 km Study Area
MLI81931	MON	A mid- to late Saxon cemetery beneath St Helen's Church, Cumberworth	An excavation recorded a sequence of 26 intercutting burials, thought to represent a period of over a century. The coffins were made from planks which had been charred on the outer surface, a characteristic of Saxon burials. An inscribed lead plaque dating to the 10th or possibly 11 th century was recovered from one of the graves. The cemetery was sealed by a soil platform circa 600 mm thick. A fragment of an Anglo-Saxon grave slab dating to the late 10 th -11 th century and at present embedded in the fireplace of the former nave of St Helen's Church may have originated from this cemetery.		TF 50628 73739	Within the 1 km Study Area
MLI81930	MON	Probable early to mid- Saxon settlement, St Helen's Church	An excavation and watching brief recorded a sunken-featured building, a grubenhaus, dating to the 7th-9th centuries. Finds included pottery, animal bone, an iron knife, fragments of fired clay, charred plant remains, and hammerscale, indicating possible iron working. It is conjectured from these finds and features that an early to mid-Saxon settlement existed in the	Early Medieval	TF 5062 7373	Within the 1 km Study Area

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
			immediate vicinity. The building was sealed by a soil layer thought to date to the 9 th century			
MLI43730	MON	Undated Features, South Of Willoughby Road, Cumberworth	An undated ditch and pit were recorded during a watching brief on land south of Willoughby Road. They may be medieval. The lack of finds from the ditch suggests that may have been for drainage or boundary marking. Charcoal inclusions in the pit may indicate a domestic function.		TF 5063 7349	Within the 1 km Study Area
MLI98815	MON	Cropmark crofts and tofts in Irby in the Marsh	Cropmark crofts and tofts in Irby in the Marsh that are probably the remains of medieval settlement. The cropmarks were seen and recorded by the staff of the National Mapping Programme.	Medieval	TF 4729 6309	Within the 1 km Study Area
MLI43661	MON	Medieval Pottery, East Of Ingoldmells Road	A thin scatter of medieval pottery was found in the topsoil during a watching brief on the Burgh Le Marsh - Ingoldmells Rising Main. There were no signs of archaeological features	Medieval	TF 5068 6505	Within the 1 km Study Area
MLI84122	MON	Undated cropmark boundary, within Butterbump barrow cemetery, Willoughby with Sloothby	An undated cropmark boundary is visible on aerial photographs within the area of the Butterbump barrow cemetery.	Unknown	TF 4851 7228	Within the 1 km Study Area
MLI125901	MON	Milestone, Spalding Road, Sutterton	19 th century milestone at Spalding Road, to the south-west of Sutterton. It is of carved stone, and is inscribed 'LONDON 100 MILES, SUTTERTON'. The milestone is depicted in this location on the 2nd edition 25" Ordnance Survey County Series map. The depiction shows the milestone giving the distance to Boston as 7 miles, and to Spalding as 9 miles. No trace of the milestone was found in early 2020, during inspection visits conducted as part of a condition survey of historic milestones in Boston Borough. The stone is thought to still be extant, though lost within extensive scrub and hedging that has grown in this area.	Post-medieval	TF 2726 3502	Within the 1 km Study Area
MLI41998	MON	Roman Greyware From Sloothby	Roman greyware sherds have been found at different times at this location. In 1975 many were recovered when the mound was ploughed down.	Roman	TF 4950 7050	Within the 1 km Study Area
MLI41524	MON	Various Post Medieval Finds, Farlesthorpe	Roman pottery found south of Burgh Le Marsh.	Roman	TF 5030 6400	Within the 1 km Study Area
MLI41525	MON	Medieval Pottery Found S Of Burgh Le Marsh	Medieval pottery found south of Burgh Le Marsh.	Medieval	TF 5030 6400	Within the 1 km Study Area
MLI41526	MON	Post Medieval Pottery Found S Of Burgh Le Marsh	Post Medieval pottery found south of Burgh Le Marsh.	Post-medieval	TF 5030 6400	Within the 1 km Study Area
MLI42005	Find Spot	Roman Brooch, Pindle's Corner, Sloothby	A Roman brooch of simple T-shape design was found at Pindle's Corner.	Roman	TF 493 712	Within the 1 km Study Area
MLI81504	MON		A small area of blackened soil with numerous Roman course ware sherds were noted on the edge of an area of silt within a	Roman	TF 2685 4906	Within the 1 km Study Area



4950 7050	Within the 1 km Study Area
5030 6400	Within the 1 km Study Area
5030 6400	Within the 1 km Study Area
5030 6400	Within the 1 km Study Area
493 712	Within the 1 km Study Area
2685 4906	Within the 1 km Study Area

HER Reference	Record Type	Name	Description	Period	NG
			field north of Armtree Lane, Langrick. The site is approximately 40 m by 20 m.		
MLI80734	MON	Medieval and post medieval activity at Holly Tree Cottage	A watching brief at Holly Tree Cottage, Thorpe Culvert identified a post medieval pit and post hole. Finds included fourteenth to 19 th century pottery, pig bones, clay pipe, and 18 th century buckle, brick/tile fragment and an iron nail.	Medieval	TF 4
MLI20137	MON	Medieval Salterns, Gosberton	A small area of water filled salt pans; the sharpness of the cuttings suggest a post medieval date. Spoil mounds are adjacent. No finds were made at the time of investigation. Published survey (25 inch) correct. Saltern sites-Bicker Haven. Small area of water filled pits which are probably post medieval with adjacent spoil mounds. No evidence that these pits are salterns. Post medieval pottery from 15 th to 16 th century has been found on some of the mounds. However, there is no reason to associate these finds with the industry, particularly as the fenland economy was in decline from the 14 th century onwards	Medieval	TF 2
MLI22463	MON	Post medieval Salterns, Gosberton	A small area of water filled salt pans; the sharpness of the cuttings suggest a post medieval date. Spoil mounds are adjacent. No finds were made at the time of investigation. Published survey (25 inch) correct. Saltern sites-Bicker Haven. Small area of water filled pits which are probably post medieval with adjacent spoil mounds. No evidence that these pits are salterns. Post medieval pottery from the 15 th to 16 th century has been found on some of the mounds. However, there is no reason to associate these finds with the industry, particularly as the fenland economy was in decline from the 14 th century onwards	Post-medieval	TF 2
MLI98639	MON	Medieval enclosures and a field system in Hogsthorpe parish	Probable earthwork medieval enclosures and a field system seen in aerial photographs and recorded by the National Mapping Programme	Medieval	TF {
MLI88848	MON	Medieval earthwork ridge and furrow, Irby in the Marsh	Medieval earthwork ridge and furrow, Irby in the Marsh, as depicted on the NMP.	Medieval	TF 4
MLI116611	MON	Low Barn Farm, Huttoft	Site of Low Barn Farm, Huttoft. Demolished 19 th century outfarm. Regular courtyard of L plan. Isolated location. Magnetic anomalies, thought to represent the remains of former boundary ditches and drains associated with Low Barn Farm, were identified in October 2013, during magnetometry survey of this area. Other anomalies, very likely representing spreads of brick rubble and ferrous material associated with the demolished farm buildings, were also recorded	Post-medieval	TF 4
MLI41715	MON	Medieval Pottery Found At Croft	Finds of 14 th century including green glazed bowls	Medieval	TF 5
MLI42248	MON	Medieval Pottery From Newly Ploughed Land, Thorpe St Peter	Recently ploughed old grassland over an area of a low mound about 50 m in diameter, produced medieval pottery and some post medieval.	Medieval	TF 4

SR	Within the Draft Order Limits or 1km Study Area
4672 6067	Within the 1 km Study Area
2572 3310	Within the 1 km Study Area
2572 3310	Within the 1 km Study Area
5332 6918	Within the 1 km Study Area
46918 63930	Within the 1 km Study Area
4956 7692	Within the 1 km Study Area

504 614	Within the 1 km Study Area
4783 6078	Within the 1 km Study Area

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
MLI84137	MON	Medieval settlement remains at Habertoft, Willoughby with Sloothby	Medieval settlement remains are visible on aerial photographs at Habertoft, and are recorded as surviving as earthworks. These remains include tofts, crofts and ridge and furrow. Ridge and furrow south of Habertoft Farm is almost entirely ploughed out, surviving only in a narrow strip south of Coppins Cottage.	Medieval	TF 5023 6914	Within the 1 km Study Area
MLI86326	MON	Medieval ditch on land at Plot 10, Station Road, Thorpe St Peter	An archaeological watching brief was undertaken during groundworks for a residential building on land at Plot 10, Station Road, Thorpe St Peter. The watching brief discovered a east to west aligned ditch which contained a single piece of medieval pottery. The feature may well be a continuation of a ditch found during a previous watching brief, on land immediately east of the development site.	Medieval	TF 48301 60769	Within the 1 km Study Area
MLI41559	Find Spot	Fragment Of Bronze Found South Of Burgh Le Marsh	A fragment of bronze furrowed for champleve enamel, perhaps from a medieval crucifix. Limoges enamelled fragment reported.	Medieval	TF 5050 6460	Within the 1 km Study Area
MLI99183	MON	Wesleyan Methodist Chapel, Thorpe St Peter	Thorpe-Fendikes Wesleyan Methodist chapel was built in 1838 to seat 108. It seems to have been demolished by the 1950s.	Post-medieval	TF 44973 60471	Within the 1 km Study Area
MLI99122	MON	Wesleyan Methodist Chapel, Cumberworth	The Wesleyan Methodist chapel was built in 1826 to seat 90. It was closed in 1947 and subsequently converted into a cottage. The building was later demolished and the site used for the construction of a new house, named 'Birdsong Cottage'.	Post-medieval	TF 50684 73367	Within the 1 km Study Area
MLI99124	MON	Wesleyan Methodist Chapel, Firsby	A Wesleyan Methodist chapel was built in Firsby in 1838 to seat 88. The chapel was demolished following the opening of its replacement in 1902.	Post-medieval	TF 4542 6256	Within the 1 km Study Area
MLI124883	MON	Little Steeping Railway Station	Little Steeping Railway Station was opened in October 1848, and was closed to all traffic in 1964. The station was on part of the Great Northern Railway's, East Lincolnshire Railway line, this part of which opened in October 1848. The station was closed for passengers in 1961, and closed to goods in 1964, after which the platforms and sidings were removed and some of the minor station structures were demolished. Structures at the station included the main station office which is still extant, and a weigh machine office and signal box (now demolished).		TF 4365 6107	Within 100 m of the draft Order Limits
MLI43374	MON	Pillbox, Woddys Den Farm, Midville	Type 22 hexagonal pillbox at Woddys Den Farm. The structure was demolished in c.1990.	Modern	TF 3847 5768	Within the 1 km Study Area
MLI126104	MON	Post-Medieval Outbuildings, The Old Farmhouse, Kirton Holme	Foundation courses of several attached brick-built structures were revealed in this location in June 2022, during digging in the garden by the landowner. The foundations appeared to match the shapes of rectangular structures marked in this location on the 2nd edition 25" Ordnance Survey County Series map, likely to be former farm outbuildings. The bricks are hand-made, and the structures are likely to be contemporary with the adjacent Old Farmhouse, thought to be of probable late 18 th or early 19 th century date. A small collection of possibly earlier stonework was found in association with the foundations, suggesting the		TF 2625 4189	Within the 1 km Study Area

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
			structures had been partially built from re-used earlier masonry. An assemblage of post-medieval artefacts were also recovered from midden deposits in close association with the building remains. This assemblage was largely comprised of 18 th and 19 th material, including many pieces of clay smoking pipe, and a largely complete cut-soda glass bottle of possible early 19 th century date.			
MLI83891	Find spot	Thirteenth to fifteenth century pottery, Station Road, Thorpe St Peter	During a watching brief, a scatter of 13 th to 15 th century pottery was recorded. The quantity of pottery was suggestive of occupation rather than manuring.	Medieval	TF 4833 6077	Within the 1 km Study Area
MLI83892	MON	A post medieval boundary ditch, Station Road, Thorpe St Peter	During a watching brief in 2002, a north/south aligned ditch containing 18 th century pottery was recorded, thought to be a boundary ditch. 18 th to 20 th century pottery and 18 th century clay pipe stems were also recovered.	Post-medieval	TF 4833 6077	Within the 1 km Study Area
MLI84699	MON	Medieval ditches and finds, Thorpe St Peter	An archaeological watching brief was undertaken during development on land adjacent to Station Road, Thorpe St Peter (11th October 2002). Two medieval boundary ditches were identified, cutting the natural alluvium. A small amount of abraded pottery was recovered dating to between the 13th and 15th centuries. Overlying the two ditches was an undated layer. A similar layer was identified during previous investigation (LI3816) and identified to the medieval period.	Medieval	TF 48319 60770	Within the 1 km Study Area
87788	MON	Medieval Enclosure, The Hollies, Croft	A medieval cropmark enclosure has been noted on aerial photographs. A magnetometry survey, conducted in August 2012 in advance of the construction of a proposed solar park, confirmed and enhanced the cropmark data for the enclosure. The enclosure appears as a large, almost square-shaped anomaly, indicative of a series of infilled ditches, with an internal L-shaped partition in the northern corner. Several possibly associated discrete features were also recorded within and immediately outside the enclosure, though their exact function and origin remain unclear. A subsequent trial trench evaluation, conducted in September 2012, confirmed the presence of the enclosure, with several ditches and pits being excavated. A large assemblage of animal bone was recovered from the medieval deposits, including cattle, horse, pig, sheep, dog and chicken bones, though dominated by the sheep remains, indicating a possible focus on wool production. A small assemblage of medieval pottery sherds was also recovered, indicating a date for this activity between the 11 th to early/mid 13 th century.	Medieval	TF 4951 6367	Within the 1 km Study Area
MLI87944	MON	Medieval to post medieval pottery scatter on land east of Bicker	Fieldwalking along the route of the proposed water pipeline between Bolle Hall, Bicker and Wykes Manor Farm, Donington produced a range of finds, including a pottery scatter dating to between the 13 th and 19 th century. Artefacts of both periods were numerous in the area around Bolle Hall and also where the pipeline crossed Broad Lane. However, in the absence of any distinct concentrations it is probable that most of the artefactual	Medieval	TF 2397 3710	Within the 1 km Study Area
HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
---------------	-------------	--	--	---------------	----------------	---
			material was deposited on the fields as a component of manuring scatter.			
MLI87950	Find Spot	Medieval to post medieval pottery scatter on land east of Bicker	Fieldwalking along the route of the proposed water pipeline between Bolle Hall, Bicker and Wykes Manor Farm, Donington produced a range of finds, including a pottery scatter dating to between the 13 th and 19 th century. Artefacts of both periods were numerous in the area around Bolle Hall and also where the pipeline crossed Broad Lane. However, in the absence of any distinct concentrations it is probable that most of the artefactual material was deposited on the fields as a component of manuring scatter.	Medieval	TF 2435 3795	Within the 1 km Study Area
MLI88433	MON	Possible unknown date cropmark enclosure and pits, Firsby	Probable unknown date cropmark enclosure partially surrounding probable unknown date cropmark pits, seen on NMP.	Undated	TF 46415 61628	Within the 1 km Study Area
MLI98105	MON	Possible Medieval Enclosure, Croft House, Croft	A possible medieval earthwork enclosure was identified by the National Mapping Programme.	Medieval	TF 4932 6366	Within the 1 km Study Area
MLI119945	MON	The Hundreds, Bratoft	The Hundreds, Bratoft. Redeveloped 19 th century outfarm. Loose courtyard with a single side of the courtyard formed by working agricultural buildings. location is unclear. Isolated location. Large modern sheds are located to the side of the site.	Post-medieval	TF 4963 6235	Within the draft Order Limits
MLI120242	MON	Unnamed farmstead, Croft	Site of a farmstead, Croft. Demolished 19 th century farmstead. Regular courtyard with L-plan range plus detached buildings to the third side of the yard. The farmhouse was detached from the main working complex. Isolated location.	Post-medieval	TF 5064 6316	Within the draft Order Limits
MLI120339	MON	Unnamed farmstead, New Leake	Site of a farmstead, New Leake. Demolished 19 th century farmstead. Regular courtyard of T plan. The farmhouse was detached from the main working complex. Isolated location.	Post-medieval	TF 4064 5904	Within the draft Order Limits
MLI124765	MON	Farmstead, Langriville	Site of farm, Langriville. Demolished 19 th century farmstead. Regular courtyard with L-plan range plus detached buildings to the third side of the yard. The farmhouse was attached to a range of working buildings. Isolated location.	Post-medieval	TF 2799 4882	Within the draft Order Limits
MLI118922	MON	Unnamed farmstead, Willoughby with Sloothby	Site of a farmstead, Willoughby with Sloothby. Demolished 19 th century farmstead. L-plan. The farmhouse is attached to a range of working buildings. Isolated location.	Post-medieval	TF 4886 7356	Within 100 m of the draft Order Limits
MLI120448	MON	(Ivy Cottage), Stickney	Site of (Ivy Cottage), Stickney. Demolished 19 th century farmstead. Regular courtyard with L-plan range plus detached buildings to the third side of the yard. The farmhouse was detached from the main working complex. Located within a loose farmstead cluster.	Post-medieval	TF 3497 5472	Within 100 m of the draft Order Limits
MLI120345	MON	Unnamed farmstead, New Leake	Unnamed farmstead, New Leake. Redeveloped 19 th century farmstead. Loose courtyard with three sides of the courtyard	Post-medieval	TF 3971 5869	Within 100 m of the draft Order Limits

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
			formed by working agricultural buildings. The farmhouse was detached with the long axis facing on to the yard. Located within a loose farmstead cluster. Large modern sheds are located on the site.	l		
MLI118887	MON	(Wyche Farm), Hogsthorpe	Site of (Wyche Farm), Hogsthorpe. Demolished 19 th century farmstead. L-plan. The farmhouse is attached to a range of working buildings. Isolated location.	Post-medieval	TF 5186 6929	Within 100 m of the draft Order Limits
MLI124655	MON	Farmstead, Frithville and Westville	Site of farm, Frithville and Westville. Demolished 19 th century farmstead. Regular courtyard with L-plan range plus detached buildings to the third side of the yard. The farmhouse was detached from the main working complex. Isolated location.	Post-medieval	TF 2968 5080	Within 100 m of the draft Order Limits
MLI124550	MON	Farmstead, Sibsey	Site of farm, Sibsey. Demolished 19 th century outfarm. Regular courtyard of U plan. Isolated location.	Post-medieval	TF 3384 5426	Within 100 m of the draft Order Limits
MLI122999	MON	Unnamed farmstead, Kirton	Site of a farmstead, Kirton. Demolished 19 th century farmstead. Parallel. The farmhouse was detached from the main working complex. Isolated location.	Post-medieval	TF 2700 4009	Within the 1 km Study Area
MLI120305	MON	Site of unnamed farmstead, Thorpe St Peter	Site of a farmstead, Thorpe St Peter. Demolished 19 th century outfarm. Row. Isolated location.	Post-medieval	TF 44057 60524	Within 100 m of the draft Order Limits
MLI124656	MON	BAY COTTAGE, Frithville and Westville	Site of BAY COTTAGE, Frithville and Westville. Demolished 19 th century farmstead. Regular courtyard of L plan. The farmhouse was detached from the main working complex. Isolated location.	Post-medieval	TF 2950 5070	Within the 1 km Study Area
MLI123029	MON	(Bliss's Farm), Kirton	Site of (Bliss's Farm), Kirton. Demolished 19 th century farmstead. Loose courtyard with two sides of the courtyard formed by working agricultural buildings. The farmhouse was detached with the long axis facing on to the yard. Isolated location.	Post-medieval	TF 2733 3844	Within 100 m of the draft Order Limits
MLI123021	MON	Clough Farm, Kirton	Clough Farm, Kirton. Redeveloped 19 th century farmstead. Regular courtyard of U plan. The farmhouse was detached from the main working complex. Isolated location. Large modern sheds are located to the side of the site.	Post-medieval	TF 2687 3992	Within 100 m of the draft Order Limits
MLI120311	MON	(Thorpe Farm), Thorpe St. Peter	Site of (Thorpe Farm), Thorpe St. Peter. Demolished 19 th century farmstead. Regular courtyard with L-plan range plus detached buildings to the third side of the yard. The farmhouse was detached from the main working complex. Isolated location.	Post-medieval	TF 4207 5951	Within 100 m of the draft Order Limits
MLI124766	MON	Farmstead, Langriville	Site of farm, Langriville. Demolished 19 th century farmstead. Regular courtyard with L-plan range plus detached buildings to the third side of the yard. The farmhouse was detached from the main working complex. Isolated location.	Post-medieval	TF 2805 4895	Within 100 m of the draft Order Limits
MLI124553	MON	Farmstead, Sibsey	Site of farm, Sibsey. Demolished 19 th century farmstead. Regular courtyard with L-plan range plus detached buildings to the third side of the yard. The farmhouse was detached from the main working complex. Isolated location.	Post-medieval	TF 3439 5371	Within 100 m of the draft Order Limits

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
MLI120444	MON	Unnamed farmstead, Stickney	Site of a farmstead, Stickney. Demolished 19 th century farmstead. Regular courtyard of L plan. The farmhouse was detached from the main working complex. Isolated location.	Post-medieval	TF 3321 5418	Within 100 m of the draft Order Limits
MLI120500	MON	Unnamed farmstead, Carrington	Site of a farmstead, Carrington. Demolished 19 th century farmstead. Loose courtyard with three sides of the courtyard formed by working agricultural buildings. The farmhouse was detached from the main working complex. Isolated location.	Post-medieval	TF 3044 5309	Within 100 m of the draft Order Limits
MLI120010	MON	Unnamed farmstead, Little Steeping	Site of a farmstead, Little Steeping. Demolished 19 th century outfarm. Regular courtyard of U plan. location is unclear. Isolated location.	Post-medieval	TF 4423 6118	Within 100 m of the draft Order Limits
MLI124764	MON	Farmstead, Langriville	Site of farm, Langriville. Demolished 19 th century farmstead. Regular courtyard with L-plan range plus detached buildings to the third side of the yard. The farmhouse was detached from the main working complex. Isolated location.	Post-medieval	TF 2808 4837	Within the 1 km Study Area
MLI120359	MON	Unnamed farmstead, New Leake	Site of a farmstead, New Leake. Demolished 19 th century farmstead. Regular courtyard of L plan. The farmhouse was attached to a range of working buildings. Isolated location.	Post-medieval	TF 3816 5551	Within the 1 km Study Area
MLI120297	MON	Unnamed farmstead, Thorpe St. Peter	Site of a farmstead, Thorpe St. Peter. Demolished 19 th century farmstead. Regular courtyard with L-plan range plus detached buildings to the third side of the yard. The farmhouse was detached with the gable end facing on to the yard. Located within a loose farmstead cluster.	Post-medieval	TF 4517 6068	Within 100 m of the draft Order Limits
MLI119890	MON	Unnamed farmstead, Burgh Le Marsh	Site of a farmstead, Burgh Le Marsh. Demolished 19 th century outfarm. Single building. location is unclear. Isolated location.	Post-medieval	TF 5164 6456	Within the 1 km Study Area
MLI119830	MON	Unnamed farmstead, Addlethorpe	Site of a farmstead, Addlethorpe. Demolished 19 th century farmstead. Loose courtyard with two sides of the courtyard formed by working agricultural buildings. The farmhouse was detached from the main working complex. Isolated location.	Post-medieval	TF 5203 6786	Within the 1 km Study Area
MLI124755	MON	Farmstead, Langriville	Site of farm, Langriville. Demolished 19 th century farmstead. Loose courtyard with two sides of the courtyard formed by working agricultural buildings. The farmhouse was detached from the main working complex. Isolated location.	Post-medieval	TF 2756 4779	Within the 1 km Study Area
MLI118889	MON	Ashington End, Hogsthorpe	Site of Ashington End, Hogsthorpe. Demolished 19 th century farmstead. Dispersed clustered plan. The farmhouse is detached from the main working complex. Isolated location.	Post-medieval	TF 5167 6798	Within the 1 km Study Area
MLI120310	MON	Unnamed farmstead, Thorpe St. Peter	Site of a farmstead, Thorpe St. Peter. Demolished 19 th century farmstead. Regular courtyard with L-plan range plus detached buildings to the third side of the yard. The farmhouse was detached from the main working complex. Isolated location.	Post-medieval	TF 4356 6002	Within the 1 km Study Area
MLI123018	MON	Unnamed farmstead, Kirton	Site of a farmstead, Kirton. Demolished 19 th century farmstead. Regular courtyard of L plan. The farmhouse was detached from the main working complex. Isolated location.	Post-medieval	TF 2714 3980	Within 100 m of the draft Order Limits

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
MLI124647	MON	Farmstead, Frithville and Westville	Site of farm, Frithville and Westville. Demolished 19 th century farmstead. Regular courtyard of U plan. The farmhouse was detached from the main working complex. Isolated location.	Post-medieval	TF 2906 5215	Within the 1 km Study Area
MLI119891	MON	Unnamed farmstead, Burgh Le Marsh	Site of a farmstead, Burgh Le Marsh. Demolished 19 th century farmstead. Regular courtyard of L plan. The farmhouse was detached from the main working complex. Isolated location.	Post-medieval	TF 5150 6429	Within the 1 km Study Area
MLI119881	MON	Unnamed farmstead, Burgh Le Marsh	Site of a farmstead, Burgh Le Marsh. Demolished 19 th century farmstead. Loose courtyard with a single side of the courtyard formed by working agricultural buildings. The farmhouse was detached from the main working complex. Isolated location.	Post-medieval	TF 5284 6487	Within the 1 km Study Area
MLI122564	MON	(Marsh Place), Gosberton	Site of (Marsh Place), Gosberton. Demolished 19 th century farmstead. Regular courtyard with L-plan range plus detached buildings to the fourth side of the yard. The farmhouse was attached to a range of working buildings. Isolated location.	Post-medieval	TF 2687 3142	Within the 1 km Study Area
MLI118924	MON	(Butterbump), Willoughby with Sloothby	Site of (Butterbump), Willoughby with Sloothby. Demolished 19 th century farmstead. Regular courtyard with linked working buildings to all four sides of the yard. The farmhouse is detached from the main working complex. Isolated location.	Post-medieval	TF 4944 7231	Within the 1 km Study Area
MLI124763	MON	Farmstead, Langriville	Site of farm, Langriville. Demolished 19 th century farmstead. Loose courtyard with four sides of the courtyard formed by working agricultural buildings. The farmhouse was detached with the gable end facing on to the yard. Isolated location.	Post-medieval	TF 2879 4890	Within the 1 km Study Area
MLI122994	MON	Unnamed farmstead, Kirton	Site of a farmstead, Kirton. Demolished 19 th century farmstead. Regular courtyard with L-plan range plus detached buildings to the third side of the yard. The farmhouse was attached to a range of working buildings. Located within a loose farmstead cluster.	Post-medieval	TF 2679 4147	Within the 1 km Study Area
MLI122998	MON	Unnamed farmstead, Kirton	Site of a farmstead, Kirton. Demolished 19 th century farmstead. Parallel with additional detached elements. The farmhouse was detached with the long axis facing on to the yard. Isolated location.	Post-medieval	TF 2674 4048	Within the 1 km Study Area
MLI120307	MON	Unnamed farmstead, Thorpe St. Peter	Site of a farmstead, Thorpe St. Peter. Demolished 19 th century farmstead. Regular courtyard with L-plan range plus detached buildings to the third side of the yard. The farmhouse was detached from the main working complex. Isolated location.	Post-medieval	TF 4470 6142	Within 100 m of the draft Order Limits
MLI118936	MON	Unnamed farmstead, Willoughby with Sloothby	Site of a farmstead, Willoughby with Sloothby. Demolished 19 th century farmstead. L-plan. The farmhouse is attached to a range of working buildings. Isolated location.	Post-medieval	TF 5005 7079	Within the 1 km Study Area
MLI122832	MON	Unnamed farmstead, Wigtoft	Site of a farmstead, Wigtoft. Demolished 19 th century farmstead. Regular courtyard of U plan. The farmhouse was detached from the main working complex. Isolated location.	Post-medieval	TF 2542 3503	Within the 1 km Study Area
MLI122822	MON	Unnamed farmstead, Wigtoft	Site of a farmstead, Wigtoft. Demolished 19 th century farmstead. Loose courtyard with three sides of the courtyard formed by working agricultural buildings. The farmhouse was attached to a	Post-medieval	TF 2639 3609	Within the 1 km Study Area

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
			range of working buildings. Located within or in association with a village.			
MLI120312	MON	Unnamed farmstead, Thorpe St. Peter	Site of a farmstead, Thorpe St. Peter. Demolished 19 th century farmstead. Regular courtyard of L plan. The farmhouse was detached from the main working complex. Isolated location.	Post-medieval	TF 4225 6033	Within the 1 km Study Area
MLI118888	MON	Unnamed farmstead, Hogsthorpe	Site of a farmstead, Hogsthorpe. Demolished 19 th century farmstead. Row. The farmhouse is detached from the main working complex. Isolated location.	Post-medieval	TF 5145 6814	Within the 1 km Study Area
MLI120284	MON	Unnamed farmstead, Thorpe St. Peter	Site of a farmstead, Thorpe St. Peter. Demolished 19 th century farmstead. Regular courtyard of L plan. The farmhouse was detached from the main working complex. Isolated location.	Post-medieval	TF 4705 6146	Within the 1 km Study Area
MLI122343	MON	Unnamed farmstead, Holland Fen with Brothertoft	Site of a farmstead, Holland Fen with Brothertoft. Demolished 19 th century farmstead. Regular courtyard with L-plan range plus detached buildings to the fourth side of the yard. The farmhouse was detached from the main working complex. Isolated location.	Post-medieval	TF 2698 4500	Within the 1 km Study Area
MLI119888	MON	(Australia Cottage), Burgh Le Marsh	Site of (Australia Cottage), Burgh Le Marsh. Demolished 19 th century farmstead. Parallel with additional detached elements. The farmhouse was detached from the main working complex. Isolated location.	Post-medieval	TF 5107 6543	Within the 1 km Study Area
MLI119880	MON	(Sweetbriar Farm), Burgh Le Marsh	Site of (Sweetbriar Farm), Burgh Le Marsh. Demolished 19 th century farmstead. Loose courtyard with three sides of the courtyard formed by working agricultural buildings. The farmhouse was detached from the main working complex. Isolated location.	Post-medieval	TF 5230 6389	Within the 1 km Study Area
MLI120341	MON	Unnamed farmstead, New Leake	Site of a farmstead, New Leake. Demolished 19 th century farmstead. Regular courtyard with L-plan range plus detached buildings to the third side of the yard. The farmhouse was detached from the main working complex. Located within a loose farmstead cluster.	Post-medieval	TF 4027 5852	Within the 1 km Study Area
MLI122422	MON	Unnamed farmstead, Swineshead	Site of a farmstead, Swineshead. Demolished 19 th century farmstead. Regular courtyard of L plan. The farmhouse was detached from the main working complex. Isolated location.	Post-medieval	TF 2643 4016	Within the 1 km Study Area
MLI120313	MON	Unnamed farmstead, Thorpe St. Peter	Site of a farmstead, Thorpe St. Peter. Demolished 19 th century farmstead. Loose courtyard with four sides of the courtyard formed by working agricultural buildings. The farmhouse was detached from the main working complex. Isolated location.	Post-medieval	TF 4227 6049	Within the 1 km Study Area
MLI122567	MON	(Hide's Farm), Surfleet	Site of (Hide's Farm), Surfleet. Demolished 19 th century farmstead. Regular courtyard with L-plan range plus detached buildings to the third side of the yard. The farmhouse was detached from the main working complex. Isolated location.	Post-medieval	TF 2824 3180	Within the 1 km Study Area
MLI124762	MON	Farmstead, Langriville	Site of farm, Langriville. Demolished 19 th century outfarm. Loose courtyard with three sides of the courtyard formed by working agricultural buildings. Isolated location.	Post-medieval	TF 2894 4879	Within the 1 km Study Area

_	_
2	D
	I V

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
MLI120443	MON	Unnamed farmstead, Stickney	Site of a farmstead, Stickney. Demolished 19 th century farmstead. Regular courtyard with multiple regular yards. The farmhouse was detached from the main working complex. Isolated location.		TF 3279 5445	Within the 1 km Study Area
MLI120340	MON	Unnamed farmstead, New Leake	Site of a farmstead, New Leake. Demolished 19 th century farmstead. Regular courtyard with L-plan range plus detached buildings to the third side of the yard. The farmhouse was attached to a range of working buildings. Isolated location.	Post-medieval	TF 4049 5827	Within the 1 km Study Area
MLI118925	MON	Unnamed farmstead, Willoughby with Sloothby	Site of a farmstead, Willoughby with Sloothby. Demolished 19 th century farmstead. Regular courtyard of L plan. The farmhouse is attached to a range of working buildings. Isolated location.	Post-medieval	TF 4943 7204	Within the 1 km Study Area
MLI119883	MON	(Marsh Farm), Burgh Le Marsh	Site of (Marsh Farm), Burgh Le Marsh. Demolished 19 th century farmstead. Regular courtyard with L-plan range plus detached buildings to the third side of the yard. The farmhouse was detached from the main working complex. Isolated location.	Post-medieval	TF 5278 6655	Within the 1 km Study Area
MLI119950	MON	Site of an unnamed farmstead, Irby in the Marsh	Site of a farmstead, Irby in the Marsh. Demolished 19 th century farmstead. Row. The farmhouse was detached from the main working complex. Located within a loose farmstead cluster.	Post-medieval	TF 47289 62484	Within the 1 km Study Area
MLI118917	MON	Unnamed farmstead, Farlesthorpe	Site of a farmstead, Farlesthorpe. Demolished 19 th century farmstead. Regular courtyard of L plan. The farmhouse is detached from the main working complex. Isolated location.	Post-medieval	TF 4813 7493	Within the 1 km Study Area
MLI120362	MON	Unnamed farmstead, New Leake	Site of a farmstead, New Leake. Demolished 19 th century farmstead. Loose courtyard with four sides of the courtyard formed by working agricultural buildings. The farmhouse was attached to a range of working buildings. Isolated location.	Post-medieval	TF 3596 5549	Within the 1 km Study Area
MLI120314	MON	Unnamed farmstead, Thorpe St. Peter	Site of a farmstead, Thorpe St. Peter. Demolished 19 th century farmstead. Loose courtyard with three sides of the courtyard formed by working agricultural buildings. The farmhouse was detached with the gable end facing on to the yard. Isolated location.	Post-medieval	TF 4281 6039	Within the 1 km Study Area
MLI122575	MON	(Rookery Farm), Surfleet	Site of (Rookery Farm), Surfleet. Demolished 19 th century farmstead. Loose courtyard with three sides of the courtyard formed by working agricultural buildings. The farmhouse was detached with the gable end facing on to the yard. Isolated location.	Post-medieval	TF 2748 2994	Within the 1 km Study Area
MLI120367	MON	(Dovecot Farm), New Leake	Site of (Dovecot Farm), New Leake. Demolished 19 th century farmstead. Regular courtyard with L-plan range plus detached buildings to the fourth side of the yard. The farmhouse was detached from the main working complex. Isolated location.	Post-medieval	TF 3496 5531	Within the 1 km Study Area
MLI120302	MON	Unnamed farmstead, Thorpe St. Peter	Site of a farmstead, Thorpe St. Peter. Demolished 19 th century farmstead. Loose courtyard with three sides of the courtyard formed by working agricultural buildings. The farmhouse was attached to a range of working buildings. Isolated location.	Post-medieval	TF 4519 6001	Within the 1 km Study Area

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
MLI118886	MON	Unnamed farmstead, Hogsthorpe	Site of a farmstead, Hogsthorpe. Demolished 19 th century farmstead. Loose courtyard with a single side of the courtyard formed by working agricultural buildings. The farmhouse is detached from the main working complex. Isolated location.	Post-medieval	TF 5212 6989	Within the 1 km Study Area
MLI124546	MON	Farmstead, Sibsey	Site of farm, Sibsey. Demolished 19 th century outfarm. Loose courtyard with two sides of the courtyard formed by working agricultural buildings. Isolated location.	Post-medieval	TF 3208 5423	Within the 1 km Study Area
MLI120315	MON	Thorpe Glebe Farm, Thorpe St. Peter	Site of Thorpe Glebe Farm, Thorpe St. Peter. Demolished 19 th century farmstead. Regular courtyard with L-plan range plus detached buildings to the third side of the yard. The farmhouse was detached from the main working complex. Isolated location.	Post-medieval	TF 4277 6060	Within the 1 km Study Area
MLI122810	MON	Five Bell House, Wigtoft	Site of Five Bell House, Wigtoft. Demolished 19 th century farmstead. Regular courtyard with multiple regular yards. The farmhouse was detached from the main working complex. Isolated location.	Post-medieval	TF 2463 3720	Within the 1 km Study Area
MLI120245	MON	Unnamed farmstead, Croft	Site of a farmstead, Croft. Demolished 19 th century farmstead. Loose courtyard with two sides of the courtyard formed by working agricultural buildings. The farmhouse was detached with the long axis facing on to the yard. Located within a loose farmstead cluster.	Post-medieval	TF 5123 6216	Within the 1 km Study Area
MLI118926	MON	(Sandfield Farm), Willoughby with Sloothby	Site of (Sandfield Farm), Willoughby with Sloothby. Demolished 19 th century farmstead. Regular courtyard of L plan. The farmhouse is detached from the main working complex. Isolated location.	Post-medieval	TF 4892 7227	Within the 1 km Study Area
MLI118934	MON	Unnamed farmstead, Willoughby with Sloothby	Site of a farmstead, Willoughby with Sloothby. Demolished 19 th century farmstead. Regular courtyard of U plan. The farmhouse is attached to a range of working buildings. Isolated location.	Post-medieval	TF 5150 7123	Within the 1 km Study Area
MLI119873	MON	Unnamed farmstead, Burgh Le Marsh	Site of a farmstead, Burgh Le Marsh. Demolished 19 th century farmstead. Regular courtyard of U plan. The farmhouse was detached from the main working complex. Isolated location.	Post-medieval	TF 5337 6505	Within the 1 km Study Area
MLI118945	MON	Unnamed farmstead, Willoughby with Sloothby	Site of a farmstead, Willoughby with Sloothby. Demolished 19 th century farmstead. Regular courtyard of U plan. The farmhouse is detached from the main working complex. Isolated location.	Post-medieval	TF 5023 6973	Within the 1 km Study Area
MLI120078	MON	Unnamed farmstead, Toynton St. Peter	Site of a farmstead, Toynton St. Peter. Demolished 19 th century outfarm. Single building. location is unclear. Isolated location.	Post-medieval	TF 4112 6032	Within the 1 km Study Area
MLI120405	MON	Unnamed farmstead, Midville	Site of a farmstead, Midville. Demolished 19 th century farmstead. Regular courtyard of L plan. The farmhouse was detached from the main working complex. Isolated location.	Post-medieval	TF 3693 5756	Within the 1 km Study Area
MLI122982	MON	Unnamed farmstead, Kirton	Site of a farmstead, Kirton. Demolished 19 th century farmstead. Regular courtyard with linked working buildings to all four sides of the yard. The farmhouse was attached to a range of working buildings. Located within or in association with a village.	Post-medieval	TF 2675 4343	Within the 1 km Study Area

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
MLI122809	MON	Unnamed farmstead, Wigtoft	Site of a farmstead, Wigtoft. Demolished 19 th century farmstead. Regular courtyard with L-plan range plus detached buildings to the third side of the yard. The farmhouse was detached from the main working complex. Isolated location.	Post-medieval	TF 2459 3742	Within the 1 km Study Area
MLI120363	MON	Unnamed farmstead, New Leake	Site of a farmstead, New Leake. Demolished 19 th century farmstead. Row with additional detached elements. The farmhouse was detached from the main working complex. Isolated location.	Post-medieval	TF 3535 5580	Within the 1 km Study Area
MLI122877	MON	(Slate Cottage), Sutterton	Site of (Slate Cottage), Sutterton. Demolished 19 th century farmstead. Regular courtyard of L plan. The farmhouse was attached to a range of working buildings. Isolated location.	Post-medieval	TF 2852 3225	Within the 1 km Study Area
MLI122988	MON	Unnamed farmstead, Kirton	Site of a farmstead, Kirton. Demolished 19 th century farmstead. Parallel. The farmhouse was detached from the main working complex. Isolated location.	Post-medieval	TF 2848 4104	Within the 1 km Study Area
MLI119849	MON	Unnamed farmstead, Orby	Site of a farmstead, Orby. Demolished 19 th century outfarm. Loose courtyard with a single side of the courtyard formed by working agricultural buildings. location is unclear. Isolated location.	Post-medieval	TF 5308 6796	Within the 1 km Study Area
MLI120438	MON	Unnamed farmstead, Stickney	Site of Unnamed farmstead, Stickney. Demolished 19 th century farmstead. Regular courtyard of L plan. The farmhouse was detached from the main working complex. Isolated location.	Post-medieval	TF 3475 5557	Within the 1 km Study Area
MLI120320	MON	Unnamed farmstead, Eastville	Site of a farmstead, Eastville. Demolished 19 th century farmstead. Loose courtyard with two sides of the courtyard formed by working agricultural buildings. The farmhouse was detached with the long axis facing on to the yard. Isolated location.	Post-medieval	TF 4192 5811	Within the 1 km Study Area
MLI118878	MON	Unnamed farmstead, Hogsthorpe	Site of a farmstead, Hogsthorpe. Demolished 19 th century outfarm. Single building.location is unclear. Isolated location.	Post-medieval	TF 5213 7047	Within the 1 km Study Area
MLI119999	MON	Unnamed farmstead, Halton Holegate	Site of Unnamed farmstead, Halton Holegate. Demolished 19 th century farmstead. Regular courtyard of L plan. The farmhouse was detached from the main working complex. Isolated location.	Post-medieval	TF 4269 6096	Within the 1 km Study Area
MLI119944	MON	Unnamed farmstead, Bratoft	Site of a farmstead, Bratoft. Demolished 19 th century farmstead. Loose courtyard with three sides of the courtyard formed by working agricultural buildings. The farmhouse was detached with the long axis facing on to the yard. Isolated location.	Post-medieval	TF 4834 6312	Within the 1 km Study Area
MLI118940	MON	Unnamed farmstead, Willoughby with Sloothby	Site of a farmstead, Willoughby with Sloothby. Demolished 19 th century farmstead. Regular courtyard of L plan. The farmhouse is detached with the long axis facing on to the yard. Located within or in association with a village.	Post-medieval	TF 4941 7059	Within the 1 km Study Area
MLI124662	MON	Farmstead, Frithville and Westville	Site of farm, Frithville and Westville. Demolished 19 th century farmstead. Loose courtyard with three sides of the courtyard formed by working agricultural buildings. The farmhouse was	Post-medieval	TF 3100 5107	Within the 1 km Study Area

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
			detached with the gable end facing on to the yard. Isolated location.			
MLI124690	MON	Farmstead, Thornton Le Fen	Site of farm, Thornton Le Fen. Demolished 19 th century farmstead. Regular courtyard of L plan. The farmhouse was detached from the main working complex. Isolated location.	Post-medieval	TF 2809 5147	Within the 1 km Study Area
MLI122872	MON	Unnamed farmstead, Sutterton	Site of a farmstead, Sutterton. Demolished 19 th century farmstead. Regular courtyard with L-plan range plus detached buildings to the third side of the yard. The farmhouse was detached with the gable end facing on to the yard. Isolated location.	Post-medieval	TF 2818 3373	Within the 1 km Study Area
MLI124559	MON	Farmstead, Sibsey	Site of farm, Sibsey. Demolished 19 th century outfarm. Single building. Isolated location.	Post-medieval	TF 3403 5282	Within the 1 km Study Area
MLI22494	MON	Saltern, Donington	Two mounds under young crop. Despite plough maximum height is 3m, but the slopes are much spread.	Unknown	TF 2446 3528	Within the 1 km Study Area
MLI43460	MON	Thorpe Culvert Station	The site of Thorpe Culvert Station. The railway station was built in 1871 with a signal box and signals added in c.1899. The station consisted of two platforms with single storey buildings.	Post-medieval	TF 4730 6077	Within the 1 km Study Area.
MLI116624	BLD	Unnamed farmstead, Bilsby	Partially extant 19 th century farmstead. Parallel with additional detached elements. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Isolated location.	Post-medieval	TF 4713 7500	Within the 1 km Study Area
MLI116652	BLD	Bollehall, Bicker	19 th century farmstead. Regular courtyard with L-plan range plus detached buildings to the fourth side of the yard. The farmhouse is detached from the main working complex. The farmhouse is the only surviving historic structure. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 2445 3783	Within the 1 km Study Area
MLI116653	MON	Holt House, Bicker	Redeveloped 19 th century farmstead. Regular courtyard with L- plan range plus detached buildings to the third side of the yard. The farmhouse is detached from the main working complex. Located within or in association with a hamlet. Large modern sheds are located on the site.	Post-medieval	TF 2398 3666	Within the 1 km Study Area
MLI119948	BLD	The Elms (Elm Cottage), Irby in the Marsh	19 th century farmstead. Regular courtyard of L plan. The farmhouse is detached from the main working complex. The farmhouse is the only surviving historic structure. Isolated location. Large modern sheds are located to the side of the site.	Post-medieval	TF 4740 6315	Within the 1 km Study Area
MLI119995	MON	Unnamed farmstead, Halton Holegate	Site of a farmstead, Halton Holegate. Demolished 19 th century farmstead. Regular courtyard of L plan. The farmhouse was detached from the main working complex. Isolated location	Post-medieval	TF 4310 6158	Within the 1 km Study Area
MLI120004	BLD	Ivydene, Little Steeping	Extant 19 th century farmstead. Row. The farmhouse is detached from the main working complex. Isolated location. Large modern sheds are located to the side of the site.	Post-medieval	TF 4348 6204	Within the 1 km Study Area

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
MLI120005	MON	Unnamed farmstead, Little Steeping	Site of a farmstead, Little Steeping. Demolished 19 th century farmstead. Regular courtyard with linked working buildings to all four sides of the yard. The farmhouse was detached from the main working complex. Isolated location.	Post-medieval	TF 4332 6205	Within the 1 km Study Area
MLI120289	MON	Codling Cottage, Thorpe St Peter	Redeveloped 19 th century farmstead. Regular courtyard of U plan. The farmhouse was detached from the main working complex. Isolated location.	Post-medieval	TF 4676 6063	Within the 1 km Study Area
MLI120501	BLD	White House Farm, Carrington	19 th century farmstead. Loose courtyard with three sides of the courtyard formed by working agricultural buildings. The farmhouse is detached from the main working complex. The farmhouse is the only surviving historic structure. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 3132 5204	Within the 1 km Study Area
MLI122446	BLD	Drayton House, Swineshead	Partially extant 19 th century farmstead. Loose courtyard with three sides of the courtyard formed by working agricultural buildings. The farmhouse is detached from the main working complex. There has been significant loss (greater than 50%) of traditional buildings. Isolated location. Large modern sheds are located to the side of the site.	Post-medieval	TF 2501 3852	Within the 1 km Study Area
MLI122447	BLD	Golden Grove House, Swineshead	Partially extant 19 th century farmstead. Regular courtyard of F plan. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 2487 3832	Within the 1 km Study Area
MLI122572	MON	Sugar Lees Farm, Surfleet	Site of (Sugar Lees Farm), Surfleet. Demolished 19 th century farmstead. Regular courtyard of L plan. The farmhouse was attached to a range of working buildings. Isolated location.	Post-medieval	TF 2816 3002	Within the 1 km Study Area
MLI122879	BLD	Newstead, Sutterton	Partially extant 19 th century farmstead. Loose courtyard with L- plan range plus detached buildings to the third side of the yard. The farmhouse is detached from the main working complex. There has been significant loss (greater than 50%) of traditional buildings. Isolated location. Large modern sheds are located to the side of the site.	Post-medieval	TF 2876 3263	Within the 1 km Study Area
MLI124695	BLD	Ashtree Farm, Thornton Le Fen	Partially extant 19 th century farmstead. Regular courtyard of plan. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Isolated location.	Post-medieval	TF 2781 5047	Within the 1 km Study Area
MLI120009	MON	Ings Farm, Little Steeping	Demolished 19 th century farmstead. Regular courtyard of U plan. The farmhouse was detached from the main working complex. Isolated location.	Post-medieval	TF 4488 6221	Within the 1 km Study Area
MLI98997	BLD	Primitive Methodist Chapel, Irby-in-the-Marsh	Irby-in-the-Marsh Primitive Methodist chapel was built in 1837 to seat 126. It is of red brick and has a hipped roof. The chapel closed in 1933 and was used as a farm building for many years before being converted into a house in 2006.	Post-medieval	TF 47371 63171	Within the 1 km Study Area

HER Reference	Record Type	Name	Description	Period	NGR	Within the Draft Order Limits or 1km Study Area
MLI122913	MON	Unnamed Farmstead, Weston	Demolished 19 th century farmstead. Regular courtyard of L plan. The farmhouse was detached from the main working complex. Isolated location.	Post-medieval	TF 3036 3108	Within the 1 km Study Area
MLI122569	MON	Surfleet Marsh Farm, Surfleet	Redeveloped 19 th century farmstead. Regular courtyard with L- plan range plus detached buildings to the third side of the yard. The farmhouse was attached to a range of working buildings. Isolated location. Large modern sheds are located on the site.	Post-medieval	TF 2985 3125	Within the 1 km Study Area
MLI122570	BLD	Welland House Farm (Welland House), Surfleet	Partially extant 19 th century farmstead. Regular courtyard with multiple regular yards. The farmhouse is detached from the main working complex. There has been a partial loss (less than 50%) of traditional buildings. Located within a Church and/or Manor farm group. Large modern sheds are located on the site.	Post-medieval	TF 2985 3095	Within the 1 km Study Area

5B. Preliminary Summary of Likely Non-Significant Effects

nationalgrid

Contents

5B	Preliminary Summary of Likely Non-Significant Effects					
5B.1	Introduction					
	Table 5B.1	Preliminary Summary of Likely Non-Significant Effects	2			

5B Preliminary Summary of Likely Non-Significant Effects

5B.1 Introduction

- 5B.1.1 This appendix presents the detailed preliminary summary of non-significant effects on heritage assets identified as a result of construction and/or operational activities within the Study Area for Section 4 New Lincolnshire Connection Substation B to Refined Weston Marsh Substation Siting Zone (Section 4) of the Project.
- 5B.1.2 A number of designated heritage assets, which may experience non-significant effects, have been identified as warranting further explanation of their assessment due to particular sensitivities, such as their high value, designed views, historic setting or their proximity to works proposed within the draft Order Limits. These are reported in **PEI Report Volume 2 Part B Section 4 Chapter 5 Historic Environment**, under section 5.7.
- 5B.1.3 It should be noted that the assessment which has informed the conclusions presented remains ongoing and is subject to change, due to the ongoing survey activities and further design development of the Project. A full detailed assessment will be included within the Environmental Statement submitted with the Development Consent Order application.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
Designated Herit	age Assets within the dra	ft Order Limits			
Bridge Over Twenty Foot Drain (NHLE 1359723) Grade II	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Medium	Small	Minor adverse (Not significant)	The permanency of the infrastructure in the landscape within its setting would cause a slight change on its medium value and how it is appreciated. This would result in a minor adverse effect which would not be significant.
Designated Herit	age Assets within the 3 ki	m Study Area			
Cock Hill, Saxon burial mound scheduled monument (NHLE 1003609)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this	High	No change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This will result in a neutral effect which is not significant.
Swineshead Abbey scheduled monument and grade II listed building (NHLE 1018687; 1165368)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent	High	No change	Neutral (Not significant)	The Project does not form part of the setting of the assets and will not alter their value or way in which they are appreciated or understood. This will result in a neutral effect which is not significant.

Table 5B.1 Preliminary Summary of Likely Non-Significant Effects

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	impact on the setting or value of this asset.				
Churchyard cross, St Thomas of Canterbury's churchyard, scheduled monument (NHLE 1014423), grade II listed (NHLE 1359710)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	High	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.
Manor Farm moated site scheduled monument (NHLE 1016045)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	High	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.
Shrunken medieval village scheduled monument (NHLE 1004933)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	High	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.
Churchyard cross, St	The construction and presence of the Project in	High	No Change	Neutral	The Project does not form part of the setting of the asset and will not alter its

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
Andrew's churchyard, scheduled monument (NHLE 1014939), grade II listed (NHLE 1267205)	the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.			(Not significant)	value or the way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.
Churchyard cross, St Mary's churchyard, scheduled monument (NHLE 1015162), grade II listed (NHLE 1224487)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	High	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.
Stump Cross, scheduled monument (NHLE 1010674), grade II listed (NHLE 1232863)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	High	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.
Sibsey Trader Windmill (NHLE 1013828; 1063535) scheduled monument and	Construction and the presence of the Project will have no impact to the setting or value of this asset.	High	No change	Neutral (Not significant)	The Project does not form part of the setting of the assets and will not alter its value or way in which they are appreciated or understood. This will result in a neutral effect which is not significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
grade I listed building					
Churchyard cross, St Nicholas's churchyard, scheduled monument (NHLE 1014422), grade II listed (NHLE 1204885)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	High	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.
Medieval field system 250m north of Church End Farm scheduled monument (NHLE 1009978)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this	High	No change	Neutral (Not significant)	The Project does not form part of the setting of the assets and will not alter its value or way in which they are appreciated or understood. This will result in a neutral effect which is not significant.
Churchyard cross, Old Church, scheduled monument (NHLE 1013532)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	High	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.
Wigtoft Conservation	The construction and presence of the Project in	High (grade l listed	No Change	Neutral	The Project does not form part of the setting of the assets and will not alter their

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
Area, including Church of St Peter and St Paul (NHLE 1237405) grade I; The Old Vicarage (NHLE 1232868) grade II, Stanhope Cottage (NHLE 1276849) grade II.	the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of these assets.	building); Medium (Conservation area and grade II listed buildings)		(Not significant)	value or way in which they are appreciated or understood. This would result in a neutral effect which would not be significant.
Kirton Holme Conservation Area (includes two grade II listed buildings assessed separately due to different magnitude of impact)	Temporary changes to the setting of the asset arising from construction (such as noise, traffic, mechanical plant).	Medium	Negligible	Negligible adverse (Not significant)	The construction works are anticipated to have a negligible magnitude of impact from construction activities which would have little effect on the setting of the asset and its value and how it is appreciated. This would result in a negligible adverse effect which would not be significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Medium	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting (LW156-LW160) would have a negligible impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect which would not be significant.
Burgh le Marsh Conservation Area, grade I listed Church of St Peter and St	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational	High (grade I listed building); Medium (Conservation	No Change	Neutral (Not significant)	The Project does not form part of the setting of the assets and will not alter their value or way in which they are appreciated or understood. This would

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
Paul (NHLE 1222765) and 16 grade II listed buildings (NHLE 1222674; 1267666; 1450497; 1267571; 1267668; 1222677; 1222948; 1222681; 1222681; 1222683; 1267483; 1223015; 1223015; 1222672; 1267650; 1222671; 1222071;	duration will have no temporary or permanent impact to the setting or value of these assets	area and grade II listed buildings)			result in a neutral effect which would not be significant.
Bicker Conservation Area, one grade I listed building: Church Of St Swithin (NHLE 1062014) and six Grade II listed buildings (NHLE 1360491; 1448483; 1062018; 1165050;	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact to the setting or value of these assets	High (grade I listed building); Medium (Conservation area and grade II listed buildings)	No Change	Neutral (Not significant)	The Project does not form part of the setting of the assets and will not alter their value or way in which they are appreciated or understood. This would result in a neutral effect which would not be significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
1062016; 1062015)					
Kirton Conservation Area, one grade I listed building: Church Of St Peter And St Paul (NHLE 1062022), 11 grade II listed buildings (NHLE 1317387; 1165134; 1317419; 1360496; 1062023; 1360498; 1165199; 1165195; 1062028; 1439370; 1062029)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact to the setting or value of these assets	High (grade I listed building); Medium (Conservation area and grade II listed buildings)	No Change	Neutral (Not significant)	The Project does not form part of the setting of the assets and will not alter their value or way in which they are appreciated or understood. This would result in a neutral effect which would not be significant.
Gosberton Conservation Area, one Grade I listed building: Church of St Peter and St Paul (NHLE 1064425) and two grade II listed buildings	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact to the setting or value of these assets	High (grade I listed building); Medium (Conservation area and grade II listed buildings)	No Change	Neutral (Not significant)	The Project does not form part of the setting of the assets and will not alter their value or way in which they are appreciated or understood. This would result in a neutral effect which would not be significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
(NHLE 1064465; 1454912)					
Wainfleet Conservation Area, two scheduled monuments, one also a grade I listed building (NHLE 1004931/ (1224243), and one also grade II* listed (NHLE 1013530/ 1223766) and 11 grade II listed buildings (1224213; 1223765; 1267129; 1224236; 1223761; 1224142; 1224175; 1223758; 1223758; 1224296; 1226923).	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact to the setting or value of these assets	High (Scheduled monuments, grade I and II* listed buildings); Medium (Conservation area and grade II listed buildings)	No Change	Neutral (Not significant)	The Project does not form part of the setting of the assets and will not alter their value or way in which they are appreciated or understood. This would result in a neutral effect which would not be significant.
Swineshead Conservation Area and one grade I listed	Construction and the presence of the Project in the landscape from the time of construction and	High (grade I listed building) Medium	No Change	Neutral (Not significant)	The Project does not form part of the setting of the assets and will not alter their value or way in which they are appreciated or understood. This would

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
building: Church of St Mary (NHLE 1232860)	throughout its operational duration will have no temporary or permanent impact to the setting or value of these assets.	(Conservation area)			result in a neutral effect which would not be significant.
and Garden	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact to the setting or value of these assets.	High (grade I and II* listed buildings) Medium (grade II RPG and grade II listed building)	No Change	Neutral (Not significant)	The Project does not form part of the setting of the assets and will not alter their value or way in which they are appreciated or understood. This would result in a neutral effect which would not be significant.
Church Of All Saints (NHLE 1223215) Grade I	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting, temporary infrastructure, mechanical plant).	High	Negligible	Minor adverse (Not Significant)	Temporary construction works would have a negligible magnitude of impact which would hardly change the high value of the asset or how it is appreciated. This would result in a minor adverse effect which would not be significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational	High	Negligible	Minor adverse (Not Significant)	The permanency of the infrastructure in the landscape (LW49-LW51 and OHL) within the wider agricultural setting of the church would have a negligible magnitude of impact which would hardly change the value of the asset or how it is appreciated.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	duration in the wider landscape.				This would result in a minor adverse effect which would not be significant.
Listed buildings in Thorpe St Peter Parish. There is one grade I (NHLE 1223796) and four grade II listed buildings (NHLE 1223754; 1434782; 1223745; 1267163).	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact to the setting or value of these assets.	High (grade I listed building) Medium (grade II listed buildings)	No Change	Neutral (Not significant)	The Project does not form part of the setting of the assets and will not alter their value or way in which they are appreciated or understood. This would result in a neutral effect which would not be significant.
Dobson's Windmill (NHLE 1222732) Grade I	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting, temporary infrastructure, mechanical plant)	High	Negligible	Minor adverse (Not significant)	The construction works will have little effect on the setting of the asset which would hardly change the high value of the asset and how it is appreciated. This would result in a minor adverse effect which would not be significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	High	Negligible	Minor adverse (Not significant)	The permanency of the infrastructure in the landscape within the asset's wider setting would have a negligible magnitude of impact causing little effect on its high value and how it is appreciated. This would result in a minor adverse effect which would not be significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
Willoughby	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact to the setting or value of these assets.	High (grade I listed building) Medium (grade II listed buildings)	No Change	Neutral (Not significant)	The Project does not form part of the setting of the assets and will not alter their value or way in which they are appreciated or understood. This would result in a neutral effect which would not be significant.
Listed buildings in Mumby Parish: one grade I listed building: Church of St Thomas of Canterbury (NHLE 1204944) and one grade II listed building (NHLE 1063618)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact to the setting or value of these assets.	High (grade I listed building) Medium (grade II listed building)	No Change	Neutral (Not significant)	The Project does not form part of the setting of the assets and will not alter their value or way in which they are appreciated or understood. This would result in a neutral effect which would not be significant.
Huttoft Parish: one grade I listed building: Church of St Margaret (NHLE 1360009)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent	High (grade I listed building) Medium (grade II listed buildingz)	No Change	Neutral (Not significant)	The Project does not form part of the setting of the assets and will not alter their value or way in which they are appreciated or understood. This would result in a neutral effect which would not be significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
1063008; 1308586)	impact to the setting or value of these assets.				
Listed buildings in Sutterton Parish. There is one grade I (NHLE 1360517) and 10 grade II listed buildings (NHLE 1061993; 1317357; 1062033; 1317371; 1317365; 1061991; 1061992; 1454311; 1360518; 1165317)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact to the setting or value of these assets.	High (grade I listed building) Medium (grade II listed buildings)	No Change	Neutral (Not significant)	The Project does not form part of the setting of the assets and will not alter their value or way in which they are appreciated or understood. This would result in a neutral effect which would not be significant.
Listed buildings within Algarkirk Parish. There is one grade I (NHLE 1164857) and three grade II listed buildings (NHLE 1062043; 1062047; 1062045)	The draft Order Limits do not fall within the parish. Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent	High	No Change	Neutral (Not significant)	The Project does not form part of the setting of the assets and will not alter their value or way in which they are appreciated or understood. This would result in a neutral effect which would not be significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	impact to the setting or value of these assets.				
Hogsthorpe Parish: one grade I listed building, (NHLE 1063615)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact to the setting or value of these assets.	High (grade I listed building) Medium (grade II listed buildings)	No Change	Neutral (Not significant)	The Project does not form part of the setting of the assets and will not alter their value or way in which they are appreciated or understood. This would result in a neutral effect which would not be significant.
Addlethorpe	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact to the setting or value of these assets.	High (grade I listed building) Medium (grade II listed buildings)	No Change	Neutral (Not significant)	The Project does not form part of the setting of the assets and will not alter their value or way in which they are appreciated or understood. This would result in a neutral effect which would not be significant.
Church Of All Saints (NHLE 1223593) Grade II*	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting, temporary	High	Negligible	Minor adverse (Not significant)	The draft Order Limits lie within the historic parish of Irby, which the church was built to serve. There is therefore potential for temporary changes to the setting of this high value asset. This would result in a minor adverse effect which would not be significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	infrastructure, mechanical plant).				
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	High	Negligible	Minor adverse (Not significant)	The permanency of the Project may alter the setting of the church through its position within the historic parish, which would affect the value and the way in which the asset is appreciated or understood. This would result in a minor adverse effect which would not be significant.
Little Steeping	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact to the setting or value of these assets.	High	No Change	Neutral (Not significant)	The Project does not form part of the setting of the assets and will not alter their value or way in which they are appreciated or understood. This would result in a neutral effect which would not be significant.
Orby Parish. There is one grade II* listed building (NHLE 1280972) and	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact to the setting or value of these assets.	High (grade II* listed building) Medium (grade II listed building)	No Change	Neutral (Not significant)	The Project does not form part of the setting of the assets and will not alter their value or way in which they are appreciated or understood. This would result in a neutral effect which would not be significant.
	Temporary changes to the setting of the asset arising from construction	High	No Change	Neutral (Not significant)	There are no changes to the setting of the asset expected during construction of the

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
Wykes Manor (NHLE 1359286) Grade II*	(such as noise, construction traffic, lighting, temporary infrastructure, mechanical plant).				Project. This would result in a neutral effect which would not be significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	High	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within the asset's wider setting (LW177-LW179) would have a negligible impact causing little effect on its high value and how it is appreciated. This would result in a negligible adverse effect which would not be significant.
Listed buildings in Stickford Parish. There is one grade II* listed building (NHLE 1063536) and three grade II listed buildings (NHLE 1168237; 1168240; 1063537)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact to the setting or value of these assets.	High (grade II* listed building) Medium (grade II listed buildings)	No Change	Neutral (Not significant)	The Project does not form part of the setting of the assets and will not alter their value or way in which they are appreciated or understood. This would result in a neutral effect which would not be significant.
Stickney Parish. There is one grade II* listed building (NHLE 1063538) and	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent	High (grade II* listed building) Medium (grade II listed buildings)	No Change	Neutral (Not significant)	The Project does not form part of the setting of the assets and will not alter their value or way in which they are appreciated or understood. This would result in a neutral effect which would not be significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
buildings (NHLE 1416760; 1168251; 1433521; 1359745) *	impact to the setting or value of these assets.				
Church Of St Andrew (NHLE 1267204) Grade II*	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact to the setting or value of this asset.	High	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.
Wainfleet All Saints Parish. One grade II* listed building (NHLE 1224403)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact to the setting or value of these assets.	High (grade II* listed building) Medium (grade II listed buildings)	No Change	Neutral (Not significant)	The Project does not form part of the setting of the assets and will not alter their value or way in which they are appreciated or understood. This would result in a neutral effect which would not be significant.
Church af St Peter and St Paul (NHLE 1267661) Grade II*	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic,	High	Negligible	Minor adverse (Not significant)	The Project falls within the parish of the church, but there would be little effect on the setting of the asset which would not change the ability to understand or appreciate the asset. This would result in

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
Bratoft	lighting, temporary infrastructure, mechanical plant).				a minor adverse effect which would not be significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	High	Negligible	Minor adverse (Not significant)	The permanency of the Project may alter the setting of the church through its position within the historic parish, which would hardly alter its high value and the way in which the asset is appreciated or understood. This would result in a minor adverse effect which would not be significant.
Old Church of All Saints (NHLE 1267241) Grade II*	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact to the setting or value of this asset.	High	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.
Clarey's Bridge (NHLE 1267366) grade II	Temporary changes to the setting of the asset arising from construction activities (such as noise and construction traffic).	Medium	Negligible	Negligible adverse (Not significant)	Potential for temporary changes to the setting of the asset from construction works are anticipated to be negligible which would have little effect on the way in which it is experienced and appreciated. This would result in a negligible adverse effect which would not be significant.
	Permanent changes to the setting of the asset	Medium	Negligible	Negligible adverse	The permanency of the infrastructure in the landscape within its wider setting

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.			(Not significant)	(LW77-LW78) would have a negligible impact with little effect on its value and how it is appreciated. This would result in a negligible adverse effect which would not be significant.
Brick Kiln (NHLE 1063655) Grade II	Temporary changes to the setting of the asset arising from construction (such as noise, traffic, mechanical plant).	Medium	Negligible	Negligible adverse (Not significant)	The construction works are anticipated to have little effect on the setting of the asset and its value and how it is appreciated. This would result in a negligible adverse effect which would not be significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Medium	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting (LW11-LW12) would have a negligible impact causing little effect on its value and how it is appreciated. This would result in a negligible adverse effect which would not be significant.
Casterton House, Ha Ha Wall, Gates And Railings (NHLE 1232910), Coach House, Gin House, Granary, Gate Piers, Gate And Screen At Casterton Farm	Temporary changes to the setting of the assets arising from construction (such as noise, traffic, mechanical plant).	Medium	Negligible	Negligible adverse (Not significant)	The construction works are anticipated to have a negligible magnitude of impact which would have little effect on the setting of the assets and their value and how they are appreciated. This would result in a negligible adverse effect which would not be significant.
	Permanent changes to the setting of the assets arising from the presence	Medium	Negligible	Negligible adverse	The permanency of the infrastructure in the landscape within its wider setting (LW176-LW178) would have a negligible

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
(NHLE 1232867) and Pigeoncote At Casterton Farm, In Gardens East of The House (NHLE 1276845) Grade II	of the Project, from the time of construction and throughout its operational duration in the wider landscape.			(Not significant)	impact causing little effect on their value and how they are appreciated. This would result in a negligible adverse effect which would not be significant.
Church of St Peter (NHLE 1359743), grade II	Temporary changes to the setting of the asset arising from construction (such as noise, traffic, mechanical plant).	Medium	Small	Minor adverse (Not significant)	Potential for temporary changes to the setting of the asset which would slightly alter the way in which it is experienced and appreciated. This would result in a minor adverse effect which would not be significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Medium	Small	Minor adverse (Not significant)	The permanency of the infrastructure in the landscape within its setting would have a small magnitude of impact causing a slight change on its value and how it is appreciated. This would result in a minor adverse effect which would not be significant.
The Gables1146546) Grade II	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting, temporary infrastructure, mechanical plant).	Medium	Small	Minor adverse (Not significant)	The construction works will slightly alter the value of the asset and how it is appreciated. This would result in a minor adverse effect on an asset of medium value which would not be significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Medium	Small	Minor adverse (Not significant)	The permanency of the infrastructure in the landscape within its agricultural setting (LW195-LW196) would have a small impact, partially screened by mature trees at the eastern border of the house's garden, causing a slight change on its value and how it is appreciated. This would result in a minor adverse effect which would not be significant.
Church Of St Andrew (NHLE 1204902) Grade II	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting, temporary infrastructure, mechanical plant).	Medium	Negligible	Negligible adverse (Not significant)	The construction works are anticipated to have a negligible magnitude of impact from noise and traffic which would have little effect on the setting of the asset and its value and how it is appreciated. This would result in a negligible adverse effect which would not be significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Medium	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting (LW11-LW13) would have a negligible impact causing little effect on its value and how it is appreciated. This would result in a negligible adverse effect which would not be significant.
Witham House (NHLE 1307150) Grade II	Temporary changes to the setting of the asset arising from construction (such as noise, traffic, mechanical plant).	Medium	Negligible	Negligible adverse (Not significant)	The construction works are anticipated to have a negligible magnitude of impact from noise and traffic which would have little effect on the setting of the asset and its value and how it is appreciated. This

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
					would result in a negligible adverse effect which would not be significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Medium	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting (LW141-LW142) would have a negligible impact, partially screened by mature trees around the house's garden, causing little effect on its value and how it is appreciated. This would result in a negligible adverse effect which would not be significant.
Bridge Over Barlode Drain Next Bell Water Bridge (NHLE 1168163)	Temporary changes to the setting of the asset arising from construction (such as noise, traffic, mechanical plant).	Medium	Small	Minor adverse (Not significant)	Potential for temporary changes to the setting of the assets which would have little effect to the way in which they are experienced and appreciated. This would result in a minor adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Medium	Small	Minor adverse (Not significant)	The permanency of the infrastructure in the landscape within its setting would have a small impact causing a slight change on its value and how it is appreciated. This would result in a minor adverse effect on an asset of medium value that is not significant.
Milepost South of Green Lane (NHLE 1264133)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no	Medium	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	temporary or permanent impact on the setting or value of this asset.				
Ivy House (NHLE 1359281) Grade II	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting, temporary infrastructure, mechanical plant).	Medium	Negligible	Negligible adver se (Not significant)	Potential for temporary changes to the setting of the building which would have little effect to the way in which it is experienced and appreciated. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Medium	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting (LW193-LW194) would have a negligible impact causing little effect on its value and how it is appreciated. This would result in a negligible adverse effect which would not be significant.
Brothertoft Hall (NHLE 1147406) Grade II and Church of St Gilbert (NHLE 1360445) Grade II	Temporary changes to the setting of these assets arising from construction (such as noise and traffic).	Medium	Negligible	Negligible adverse (Not significant)	Potential for temporary changes to the setting of the assets which would have little effect to the way in which they are experienced and appreciated. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of these assets arising from the presence of the Project, from the time of construction and	Medium	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting (LW144-LW146) would have a negligible impact causing little effect on the assets' value and how they are appreciated. This
Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
---	---	-------------------	------------------------	--	---
	throughout its operational duration in the wider landscape.				would result in a negligible adverse effect that is not significant.
Old Marsh Chapel (NHLE 1223096) Grade II	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting, temporary infrastructure, mechanical plant).	Medium	Small	Minor adverse (Not significant)	The construction works will slightly alter the value of the asset and how it is appreciated. This would result in a minor adverse effect which is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape	Medium	Small	Minor adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider agricultural setting (LW41-LW44) would have a small magnitude of impact causing a slight change on its value and how it is appreciated. This would result in a minor adverse effect which would not be significant.
Holmes Farmhouse (NHLE 1360497) grade II	Temporary changes to the setting of the asset arising from construction activities (such as noise and construction traffic).	Medium	Negligible	Negligible adverse (Not significant)	Potential for temporary changes to the setting of the asset would have little effect to the way in which it is experienced and appreciated. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational	Medium	Negligible	Negligible adverse (Not significance)	The permanency of the infrastructure in the landscape within its wider setting (LW159-LW161) would have a negligible impact causing little effect on its value and how it is appreciated, resulting in a

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	duration in the wider landscape.				negligible adverse effect that is not significant.
Barn at Elms Farm (NHLE 1360472) and Stable and Store at Elms Farm (NHLE 1062057) Grade II	Temporary changes to the setting of the assets arising from construction (such as noise and traffic)	Medium	Negligible	Negligible adverse (Not significant)	Potential for temporary changes to the setting of the assets which would have little effect to the way in which they are experienced and appreciated. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the assets arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape	Medium	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within their wider setting (LW152-LW154) would have a negligible impact causing little effect on their value and how they are appreciated. This would result in a negligible adverse effect which would not be significant.
Easthorpe Court (NHLE 1232864) and Coach House at Easthorpe Court (NHLE 1232900) Grade II	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact to the setting or value of these assets.	Medium	No Change	Neutral (Not significant)	The Project does not form part of the setting of the assets and will not alter their value or way in which they are appreciated or understood. This would result in a neutral effect which is not significant.
The Hollies Farmhouse (NHLE 1267487) Grade II	Temporary changes to the setting of the asset arising from construction (such as noise and traffic)	Medium	Negligible	Negligible adverse (Not significant)	Potential for temporary changes to the setting of the asset which would have little effect to the way in which it is experienced and appreciated. This would result in a negligible adverse effect that is not significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Medium	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting (LW49-LW51) would have a negligible impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect that is not significant.
Northlands Bridge (NHLE 1168221) Grade II	Temporary changes to the setting of the asset arising from construction (such as noise and traffic)	Medium	Negligible	Negligible adverse (Not significant)	Temporary changes to the setting of the asset arising from construction would hardly affect the asset's value or how it is appreciated. This would result in a negligible adverse effect which would not be significant.
	The presence of the infrastructure in the landscape from the time of construction and throughout its operational duration will have no permanent impact on the setting or value of the asset.	Medium	No Change	Neutral (Not significant)	The permanency of the infrastructure in the landscape would not change the setting of the asset or its value This would result in a neutral effect which would not be significant.
Kitchen Garden Wall to Hubberts Bridge Farmhouse (NHLE 1360495) Grade II	Temporary changes to the setting of the asset arising from construction (such as noise and traffic)	Medium	Negligible	Negligible adverse (Not significant)	Potential for temporary changes to the setting of the asset which would have little effect to the way in which it is experienced and appreciated. This would result in a negligible adverse effect that is not significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Medium	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting (LW152-LW154) would have a negligible impact causing little effect on its value and how it is appreciated. This would result in a negligible adverse effect which would not be significant.
Hubbert's Bridge Farmhouse (NHLE 1232947) Grade II	Temporary changes to the setting of the asset arising from construction (such as noise and traffic)	Medium	Negligible	Negligible adverse (Not significant)	Potential for temporary changes to the setting of the asset which would have little effect to the way in which it is experienced and appreciated. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Medium	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting (LW152-LW154) would have a negligible impact causing little effect on its value and how it is appreciated. This would result in a negligible adverse effect which would not be significant.
Burtoft Manor Farmhouse (NHLE 1232866) Grade II	Temporary changes to the setting of the asset arising from construction (such as noise and traffic)	Medium	Negligible	Negligible adverse (Not significant)	Potential for temporary changes to the setting of the asset which would have little effect to the way in which it is experienced and appreciated. This would result in a negligible adverse effect that is not significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Medium	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting (LW181-LW182) would have a negligible impact causing little effect on its value and how it is appreciated. This would result in a negligible adverse effect which would not be significant.
Mile Stone East Of Baker's Bridge (NHLE 1308503) grade II	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact to the setting or value of this asset.	Medium	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would have a neutral effect which is not significant.
Barn To Hubbert's Bridge Farm (NHLE 1165111) Grade II	Temporary changes to the setting of the asset arising from construction (such as noise and traffic)	Medium	Negligible	Negligible adverse (Not significant)	Potential for temporary changes to the setting of the asset which would have little effect to the way in which it is experienced and appreciated. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Medium	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting (LW152-LW154) would have a negligible impact causing little effect on its value and how it is appreciated. This would result in a negligible adverse effect which would not be significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
Bland's Farmhouse (NHLE 1224571) grade II	Temporary changes to the setting of the asset arising from construction activities (such as noise and construction traffic, mechanical plant).	Medium	Small	Minor adverse (Not significant)	The construction works will slightly alter the value of the asset and how it is appreciated. This would result in a minor adverse effect which is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Medium	Small	Minor adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider agricultural setting (LW48-LW50) would have a small magnitude of impact causing a slight change on its value and how it is appreciated. This would result in a minor adverse effect that is not significant.
Mile Stone (Midway Between Frampton Lane and Baker's Bridge) (NHLE 1062092) grade II	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact to the setting or value of this asset.	Medium	No change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would have a neutral effect that is not significant.
Lymm Bank Farmhouse (NHLE 1223830) grade II	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting, temporary infrastructure, mechanical plant)	Medium	Negligible	Negligible adverse (Not significant)	Potential for temporary changes to the setting of the asset which would have little effect to the way in which it is experienced and appreciated. This would result in a negligible adverse effect that is not significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape	Medium	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider agricultural setting (LW52-LW54) would have a negligible magnitude of impact hardly changing the value of the asset and how it is appreciated. This would result in a negligible adverse effect that is not significant.
The Old Vicarage (NHLE 1267406) Grade II	Temporary changes to the setting of the asset arising from construction (such as noise and traffic)	Medium	Negligible	Negligible adverse (Not significant)	Potential for temporary changes to the setting of the asset which would have little effect to the way in which it is experienced and appreciated. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Medium	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting (LW49-LW51) would have a negligible magnitude of impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect that is not significant.
Corner Cottage (NHLE 1062054) Grade II	Temporary changes to the setting of the asset arising from construction (such as noise and traffic)	Medium	Negligible	Negligible adverse (Not significant)	Potential for temporary changes to the setting of the asset which would have little effect to the way in which it is experienced and appreciated. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence	Medium	Negligible	Negligible adverse	The permanency of the infrastructure in the landscape within its wider setting (LW153-LW155) would have a negligible

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	of the Project, from the time of construction and throughout its operational duration in the wider landscape.			(Not significant)	impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect that is not significant.
Bridge House (NHLE 1267365) Grade II	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting, temporary infrastructure, mechanical plant)	Medium	Small	Minor adverse (Not significant)	The construction works will slightly alter the value of the asset and how it is appreciated. This would result in a minor adverse effect which is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape	Medium	Small	Minor adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider agricultural setting (LW49-LW50) would have a small magnitude of impact causing a slight change on its value and how it is appreciated, resulting in a minor adverse effect that is not significant.
The Cottage (to The West of No 8) (NHLE 1223749) grade II	Temporary changes to the setting of the asset arising from construction activities (such as noise and construction traffic).	Medium	Small	Minor adverse (Not significant)	The construction works will slightly alter the value of the asset and how it is appreciated. This would result in a minor adverse effect which is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and	Medium	Small	Minor adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider agricultural setting (LW71-LW74) would have a small magnitude of impact causing a slight change to its value and how it is

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	throughout its operational duration in the wider landscape.				appreciated, resulting in a minor adverse effect that is not significant.
Church Of St Helen (NHLE 1204901) Grade II	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact to the setting or value of this asset.	Medium	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.
Lade Bank Lock, Pumping Station And Chimney (NHLE 1360501) Grade II	Temporary changes to the setting of the asset arising from construction (such as noise, light and traffic).	Medium	Negligible	Negligible adverse (Not significant)	Potential for temporary changes to the setting of the asset which would have little effect to the way in which it is experienced and appreciated. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Medium	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting (LW100-LW105) would have a negligible magnitude of impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect that is not significant.
Listed buildings in Firsby Parish. There are six	These six listed buildings in Firsby form a group. Construction and the presence of the Project in the landscape from the	Medium	No Change	Neutral (Not significant)	The Project does not form part of the setting of these assets, as their setting is formed by their relationship with the village and each other. The Project will not alter their value or way in which they are

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
grade II listed buildings (NHLE 1267350, 1223351, 1223275, 1223276, 1267317, 1223277)	time of construction and throughout its operational duration will have no temporary or permanent impact to the setting or value of these asset.				appreciated or understood. This would result in a neutral effect which would not be significant.
Holme House (NHLE 1062024) and associated stable block (NHLE 1165222) grade II	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of these assets.	Medium	No Change	Neutral (Not significant)	The Project does not form part of the setting of the assets and will not alter their value or the way in which they are appreciated or understood. This would result in a neutral effect which would not be significant.
Listed buildings in Croft Parish. There are four grade II listed buildings (NHLE 1223172; 1223940; 1223035; 1223036)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact to the setting or value of these assets	Medium	No Change	Neutral (Not significant)	The Project does not form part of the setting of the assets and will not alter their value or the way in which they are appreciated or understood. This would result in a neutral effect which would not be significant.
Swineshead Parish. There are	Construction and the presence of the Project in the landscape from the time of construction and	Medium	No Change	Neutral (Not significant)	The Project does not form part of the setting of the assets and will not alter their value or way in which they are appreciated or understood. This would

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
buildings (NHLE 1232852; 1317352; 1232862; 1360519)	throughout its operational duration will have no temporary or permanent impact to the setting or value of these assets				result in a neutral effect which would not be significant.
Listed buildings in Kirton Parish. There are 10 grade II listed buildings (NHLE 1062021; 1062032; 1062030; 1062031; 1317400; 1062025; 1165228; 1062026; 1165248; 1165248; 1165295)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact to the setting or value of these assets	Medium	No Change	Neutral (Not significant)	The Project does not form part of the setting of the assets and will not alter their value or way in which they are appreciated or understood. This would result in a neutral effect which would not be significant.
New Leake, Eastville, And Midville War Memorial (NHLE 1450521) Grade II	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact to the setting or value of this asset	Medium	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
<u> </u>	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact to the setting or value of these assets	Medium	No Change	Neutral (Not significant)	The Project does not form part of the setting of the assets and will not alter their value or way in which they are appreciated or understood. This would result in a neutral effect which would not be significant.
Church Of St Peter (NHLE 1307173) Grade II	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact to the setting or value of this asset	Medium	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.
Pigeoncote At Dovecote Farm (NHLE 1360482) Grade II	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact to the setting or value of this asset	Medium	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.
Carrington Parish. There are	Construction and the presence of the Project in the landscape from the time of construction and	Medium	No Change	Neutral (Not significant)	The Project does not form part of the setting of the assets and will not alter their value or way in which they are appreciated or understood. This would

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
buildings (NHLE 1147909; 1359721; 1413112; 1063567)	throughout its operational duration will have no temporary or permanent impact to the setting or value of these assets				result in a neutral effect which would not be significant.
Gosberton Parish. There are	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact to the setting or value of these assets	Medium	No Change	Neutral (Not significant)	The Project does not form part of the setting of the assets and will not alter their value or way in which they are appreciated or understood. This would result in a neutral effect which would not be significant.
Hanson's Windmill (NHLE 1223034) Grade II	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact to the setting or value of this asset	Medium	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.
Quadring Parish. There is one grade I (NHLE	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational	High (grade I listed building) Medium (grade II listed buildings)	No Change	Neutral (Not significant)	The Project does not form part of the setting of the assets and will not alter their value or way in which they are appreciated or understood. This would

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
grade II listed buildings (NHLE 1359280; 1308671)	duration will have no temporary or permanent impact to the setting or value of these assets				result in a neutral effect which would not be significant.
Listed buildings in Old Leake Parish. There are six grade II listed buildings (NHLE 1308385; 1360500; 1147808; 1062036; 1308374; 1062035)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact to the setting or value of these assets	Medium	No Change	Neutral (Not significant)	The Project does not form part of the setting of the assets and will not alter their value or way in which they are appreciated or understood. This would result in a neutral effect which would not be significant
Anton's Gowt Lock (NHLE 1062085) Grade II	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact to the setting or value of this asset	Medium	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.
Milestone Beside Wortley's Lane (NHLE 1307179) Grade II	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational	Medium	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	duration will have no temporary or permanent impact to the setting or value of this asset				
Traphouse And Pigeoncote To Wykes Manor Farm (NHLE 1166255) Grade II	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact to the setting or value of this asset	Medium	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.
Donington Parish. There is one grade I (NHLE 1064449) two grade II* (NHLE 1064448; 1064450) and	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact to the setting or value of these assets.	High (grade I and grade II* listed buildings) Medium (grade II listed building)	No Change	Neutral (Not significant)	The Project does not form part of the setting of the assets and will not alter their value or way in which they are appreciated or understood. This would result in a neutral effect which would not be significant.
Bowles Farmhouse (NHLE 1062050) Grade II	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no	Medium	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	temporary or permanent impact to the setting or value of this asset				
Listed buildings in Frampton Parish. There is one grade I (NHLE 1360476), four grade II* (NHLE 1360477; 1062062; 1147586; 1360474) and three grade II listed buildings (NHLE 1147659; 1062053; 1147673)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact to the setting or value of these assets	High (grade I and grade II* listed building) Medium (grade II listed buildings)	No Change	Neutral (Not significant)	The Project does not form part of the setting of the assets and will not alter their value or way in which they are appreciated or understood. This would result in a neutral effect which would not be significant.
Pigeoncote At Waite Farm (NHLE 1215325) Grade II	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact to the setting or value of this asset	Medium	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.
The Lilacs (NHLE 1359718) Grade II	Construction and the presence of the Project in the landscape from the time of construction and	Medium	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	throughout its operational duration will have no temporary or permanent impact to the setting or value of this asset				understood. This would result in a neutral effect which would not be significant.
Wexham Farm (NHLE 1063002) Grade II	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact to the setting or value of this asset	Medium	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.
Grade II listed buildings in Bratoft Parish (NHLE 1222666; 1267659; 1224572; 1267660; 1222670)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact to the setting or value of these assets	Medium	No Change	Neutral (Not significant)	The Project does not form part of the setting of the assets and will not alter their value or way in which they are appreciated or understood. This would result in a neutral effect which would not be significant.
Listed buildings in Fosdyke parish. There are three grade II listed buildings (NHLE 1317488; 1317493; 1062020)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent	Medium	No Change	Neutral (Not significant)	The Project does not form part of the setting of the assets and will not alter their value or way in which they are appreciated or understood. This would result in a neutral effect which would not be significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	impact to the setting or value of these assets				
Westfield Farmhouse (NHLE 1146816) Grade II	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact to the setting or value of this asset	Medium	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.
Church of St Helen in West Keal (NHLE 1146806) Grade II*	The construction works of the Project would not have any temporary impact on the setting of value of this asset.	High	No Change	Neutral (Not significant)	The temporary construction works would not affect the setting or value of the asset. This would result in a neutral effect which would not be significant.
	Permanent changes to the setting of the asset arising from the presence of the overhead lines within the wider landscape.	High	Negligible	Minor adverse (Not significant)	Potential for limited, permanent visual intrusion within the setting of this high value asset that would hardly alter the character of the asset and the way in which it is appreciated or understood. This would result in a minor adverse effect which would not be significant.
Listed buildings in Welton le Marsh Parish. There is one grade II* (NHLE 1063626) and one grade II listed building (NHLE 1063625).	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent	High (grade II* listed building) Medium (grade II listed building)	No Change	Neutral (Not significant)	The Project does not form part of the setting of the assets and will not alter their value or way in which they are appreciated or understood. This would result in a neutral effect which would not be significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	impact to the setting or value of these assets.				
Designated Herit	age Assets within the 3 - {	5 km Study A	rea		
Butter cross, Swineshead, scheduled monument (NHLE 1009218)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	High	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.
Churchyard cross, St Andrew's churchyard, scheduled monument (NHLE 1014424)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	High	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.
Churchyard cross, St Margaret's churchyard, scheduled monument (NHLE 1010677)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	High	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
Churchyard cross, St Peter's churchyard, scheduled monument (NHLE 1013535)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	High	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.
Bratoft Hall moated site, 550m north of Manor Farm scheduled monument (NHLE 1017392)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	High	No change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This will result in a neutral effect which is not significant.
Bowl barrow at Mill Hill Quarry, 350m north west of Claxby church scheduled monument (NHLE 1015769)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	High	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.
Churchyard cross, St Mary's churchyard, Winthorpe,	The construction and presence of the Project in the landscape from the time of construction and	High	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which it is appreciated or understood. This would result in a

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
scheduled monument (NHLE 1014427)	throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.				neutral effect which would not be significant.
Decoy Wood decoy pond scheduled monument (NHLE 1019098)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	High	No change	Neutral (Not significant)	The Project does not form part of the setting of the assets and will not alter its value or way in which it is appreciated or understood. This will result in a neutral effect which is not significant.
Neolithic long barrow 525m north east of Valley House: one of a group known as Deadmen's Graves scheduled monument (NHLE 1017464)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	High	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.
Neolithic long barrow 495m north of Moon Wood, one of a pair of long barrows known	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no	High	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
as Deadmen's Graves scheduled monument (NHLE 1013923)	temporary or permanent impact on the setting or value of this asset.				
Neolithic long barrow 575m NNW of Moon Wood, one of a pair of long barrows known as Deadmen's Graves scheduled monument (NHLE 1013921)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	High	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.
Churchyard cross, All Saints' churchyard, scheduled monument (NHLE 1010678)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	High	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.
King's Hill motte and bailey castle scheduled monument (NHLE 1018398)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no	High	No change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This will result in a neutral effect which is not significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	temporary or permanent impact on the setting or value of this asset.				
Moated site 480m north east of Wyberton West Hospital scheduled monument (NHLE 1019528)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	High	No change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This will result in a neutral effect which is not significant.
Medieval salt workings scheduled monument (NHLE 1004930)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	High	No change	Neutral (Not significant)	The Project does not form part of the setting of the assets and will not alter its value or way in which they are appreciated or understood. This will result in a neutral effect which is not significant.
Medieval moated site and post- medieval gardens at Cressy Hall scheduled monument (NHLE 1019526)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	High	No change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This will result in a neutral effect which is not significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
Neolithic long barrow 320m north west of Skendleby Psalter scheduled monument (NHLE 1013918)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	High	No change	Neutral (Not significant)	The Project does not form part of the setting of the assets and will not alter its value or way in which they are appreciated or understood. This will result in a neutral effect which is not significant.
Abbey Hills moated site scheduled monument (NHLE 1016044)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact to the setting or value of this asset	High	No change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This will result in a neutral effect which is not significant.
Sibsey Parish. There is one grade I (NHLE 1063533) and	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact to the setting or value of these assets	High (grade I listed building) Medium (grade II listed buildings)	No Change	Neutral (Not significant)	The Project does not form part of the setting of the assets and will not alter their value or way in which they are appreciated or understood. This would result in a neutral effect which would not be significant.
Listed buildings in the Skegness	Construction and the presence of the Project in	High	No Change	Neutral (Not significant)	The Project does not form part of the setting of the assets and will not alter their

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
Parish. There is one grade I (NHLE 1229941) and one grade II* listed building (NHLE 1229943).	the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact to the setting or value of these assets.				value or way in which they are appreciated or understood. This would result in a neutral effect which would not be significant.
Church Of St Peter and St Paul (NHLE 1204941) grade I listed building	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact to the setting or value of this asset.	High	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.
Listed buildings in Wyberton Parish. There is one grade I (NHLE 1147881) and one grade II* listed buildings (NHLE 1062042).	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact to the setting or value of these assets.	High	No Change	Neutral (Not significant)	The Project does not form part of the setting of the assets and will not alter their value or way in which they are appreciated or understood. This would result in a neutral effect which would not be significant.
Claxby Hall (NHLE 1063661) grade II* listed building	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no	High	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	temporary or permanent impact to the setting or value of this asset.				
Baptist Chapel (NHLE 1223592) grade II* and Total Submersion Font Approximately 23 Metres East Of Chapel (NHLE 1267243) Grade II* listed building	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact to the setting or value of these assets.	High	No Change	Neutral (Not significant)	The Project does not form part of the setting of the assets and will not alter their value or way in which they are appreciated or understood. This would result in a neutral effect which would not be significant.
Church Of St Andrew (NHLE 1359727) grade II* listed building	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact to the setting or value of this asset.	High	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.
Parish Church of St Botolph, Boston (NHLE 1388844), grade I listed building	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting, temporary infrastructure, mechanical plant)	High	Negligible	Minor adverse (Not significant)	Potential for temporary changes to the setting of the asset which would have little effect to the way in which it is experienced and appreciated. This would result in a minor adverse effect that is not significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
Listed buildings in Boston Parish. There are two grade I (NHLE 1389007; 1388995) and 11 grade II* listed buildings (NHLE 1388976; 1388945; 1389012; 1389000; 1388998; 1388941; 1388955; 1388955; 1388991; 1388991; 1388894; 1388896; 1388898).	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact to the setting or value of these assets.	High	No Change	Neutral (Not significant)	The Project does not form part of the setting of the assets and will not alter their value or way in which they are appreciated or understood. This would result in a neutral effect which would not be significant.
Gunby Hall (NHLE 1063656) grade I listed building, Church of St Peter (NHLE 1359687) grade I listed building, Stable Block (NHLE 1063657) grade II* listed building, Gunby Hall grade II	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact to the setting or value of these assets	High	No Change	Neutral (Not significant)	The Project does not form part of the setting of the assets and will not alter their value or way in which they are appreciated or understood. This would have a neutral effect that is not significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
registered park and garden (NHLE 1000979)					
Designated Herita	age Assets of High Value	beyond the 5	km Study Area		
Tattershall Castle and College (NHLE 1018394) scheduled monument, grade I listed buildings; Tattershall Castle (NHLE 1215317), Round Towers, Tattershall Castle (NHLE 1216195), Kitchen Ruins to Tattershall Castle (NHLE 1288162), Moat Walls at Tattershall Castle (NHLE 1215318), Stable Ruins at Tattershall Castle (NHLE 1215319) and Ticket Office and Shop, Tattershall Castle (NHLE 1287738).	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact to the setting or value of these assets	High	No Change	Neutral (Not significant)	The Project does not form part of the setting of the assets and will not alter their high value or way in which they are appreciated or understood. This would have a neutral effect that is not significant.

Non-designated heritage assets within the draft Order Limits

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
Ridge and Furrow earthworks, Dryby Farm, Bilsby (MLI98708)	Whilst the asset is located within the draft Order Limits, it is anticipated that there will be no intrusive activities or physical impacts to the asset from construction of the maintenance trackway.	Low	No change	Neutral (Not significant)	No impacts (No Change) to this non- designated heritage asset of low value would result in a neutral effect, which is not significant.
Thurlsby deserted medieval village (MLI41486)	Topsoil stripping and groundworks associated with the construction of the bellmouth access will result in the partial truncation of the asset.	Medium	Small	Negligible adverse (Not significant following additional mitigation)	Partial removal or disturbance (small adverse magnitude of impact) of this non- designated heritage asset of medium value would result in a minor adverse effect to the asset, which is not significant. The use of archaeological mitigation measures i.e. appropriate archaeological investigation and recording would result in a negligible adverse effect which would not be significant.
	Temporary changes to the setting of the asset arising from construction (noise, construction traffic, lighting and scaffolds) of the Project.	Medium	Small	Minor Adverse (Not significant)	Potential for temporary visual intrusion (small magnitude of impact) within the setting of this medium value asset that would affect the value of the asset and the way in which it is appreciated or understood. This would result in a minor adverse effect, which would not be significant.
	Permanent changes to the setting of the asset arising from the presence of the Project within the	Medium	Small	Minor adverse (Not significant)	Potential for permanent visual intrusion (small magnitude of impact) within the setting of this medium value asset that would affect the value of the asset and the

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	wider landscape from the time of construction and throughout its operational duration.				way in which it is appreciated or understood. This would result in a minor adverse effect, which would not be significant.
Iron Age saltern site, Wyche Drain (MLI88785)	Topsoil stripping associated with construction of the SUDS drainage basin would result in partial truncation of the asset.	Low	Small	Negligible adverse (Not significant following additional mitigation)	Partial removal or disturbance (small magnitude of impact) of this non- designated heritage asset of medium value would result in a minor adverse effect, which is not significant. The use of archaeological mitigation measures i.e. appropriate archaeological investigation and recording would reduce the significance of the effect to negligible adverse which would not be significant.
Medieval settlement of Wyche (MLI88789)	Whilst the asset is located within the draft Order Limits, it is anticipated that there will be no intrusive activities or physical impacts to the asset from construction of the Project.	Medium	No change	Neutral (Not significant)	No impacts (No Change) to this non- designated heritage asset of low value would result in a neutral effect, which is not significant.
	Temporary changes to the setting of the asset arising from construction (noise, construction traffic, lighting and scaffolds) of the Project.	Medium	Small	Minor Adverse (Not significant)	Potential for temporary visual intrusion (small magnitude of impact) within the setting of this medium value asset that would affect the value of the asset and the way in which it is appreciated or understood. This would result in a minor adverse effect, which would not be significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	Permanent changes to the setting of the asset arising from the presence of the Project within the wider landscape from the time of construction and throughout its operational duration.	Medium	Small	Minor Adverse (Not significant)	Potential for permanent visual intrusion (small magnitude of impact) within the setting of this medium value asset that would affect the value of the asset and the way in which it is appreciated or understood. This would result in a minor adverse effect, which would not be significant.
Possible medieval house sites (MLI42008)	Topsoil stripping and groundworks for the construction of the working area for pylon LW28 will result in partial truncation of the asset.	Low	Small	Negligible adverse (Not significant following additional mitigation)	Partial removal or disturbance (small adverse magnitude of impact) of this non- designated heritage asset of low value would result in a negligible adverse effect to the asset, which is not significant. The use of archaeological mitigation measures i.e. appropriate archaeological investigation and recording would offset the significance of the effect to negligible adverse which would not be significant.
Possible Iron Age saltern site (MLI41948)	Whilst the asset is located within the draft Order Limits, it is anticipated that there will be no intrusive activities or physical impacts to the asset from OHL stringing activities or during operation of the Project.	Low	No change	Neutral (Not significant)	No impacts (no change) to this non- designated heritage asset of low value would result in a neutral effect, which is not significant.
Possible Iron Age saltern site (MLI41957)	Whilst the asset is located within the draft Order Limits, it is anticipated that there will be no	Low	No change	Neutral (Not significant)	No impacts (no change) to this non- designated heritage asset of low value would result in a neutral effect, which is not significant

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	intrusive activities or physical impacts to the asset from OHL stringing activities or during operation of the Project.				
Possible Iron Age saltern site (MLI43154)	Whilst the asset is located within the draft Order Limits, it is anticipated that there will be no intrusive activities or physical impacts to the asset from OHL stringing activities or during operation of the Project.	Low	No change	Neutral (Not significant)	No impacts (no change) to this non- designated heritage asset of low value would result in a neutral effect, which is not significant
Medieval settlement of Ashington in Hogsthorpe parish (MLI88788)	Topsoil stripping and groundworks associated with installation of the construction access haul road and the working area for pylons GL31 and GL32, has the potential to remove or disturb part of this asset	Medium	Small	Negligible adverse (Not significant following additional mitigation)	Partial removal or disturbance (small magnitude of impact) of this non- designated heritage asset of medium value would result in a minor adverse effect, which is not significant. The use of archaeological mitigation measures i.e. appropriate archaeological investigation and recording would reduce the significance of the effect to negligible adverse which would not be significant.
	Temporary changes to the setting of the asset arising from construction (noise, construction traffic, lighting and scaffolds) of the Project.	Medium	Small	Minor adverse (Not significant)	Potential for temporary visual intrusion (small magnitude of impact) within the setting of this medium value asset that would affect the value of the asset and the way in which it is appreciated or understood. This would result in a minor

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
					adverse effect, which would not be significant.
	Permanent changes to the setting of the asset arising from the presence of the Project within the wider landscape	Medium	Small	Minor adverse (Not significant)	Potential for permanent visual intrusion (small magnitude of impact) within the setting of this medium value asset that would affect the value of the asset and the way in which it is appreciated or understood. This would result in a minor adverse effect, which would not be significant.
Probable medieval settlement (MLI88895)	Whilst the asset is located within the draft Order Limits, it is anticipated that there will be no intrusive works or physical impacts to the asset associated with any construction activities.	Low	No change	Neutral (Not significant)	No impacts (no change) to this non- designated heritage asset of low value would result in a neutral effect, which is not significant.
Medieval settlement remains to the east of Burgh Le Marsh (MLI41501)	Topsoil stripping and groundworks associated with installation of the construction access haul road and the working area for pylon LW40, and 3 rd party mitigation areas has the potential to remove or disturb part of this asset.	Low	Small	Negligible adverse (Not significant following additional mitigation)	Partial removal or disturbance (small magnitude of impact) of this non- designated heritage asset of low value would result in a negligible adverse effect, which is not significant. The use of archaeological mitigation measures i.e. appropriate archaeological investigation and recording would offset the significance of the effect to negligible adverse which would not be significant.
Possible post medieval earthwork	Topsoil stripping and groundworks with installation of the	Low	Small	Negligible adverse	Partial removal or disturbance (small magnitude of impact) of this non- designated heritage asset of low value

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
enclosure, east of Burgh le Marsh (MLI87794)	construction access haul road has the potential to remove or disturb part of this asset			(Not significant following additional mitigation)	would result in a negligible adverse effect, which is not significant. The use of archaeological mitigation measures i.e. appropriate archaeological investigation and recording would offset the significance of the effect to negligible adverse which would not be significant.
Medieval ridge and furrow earthworks near Vine Farm, Burgh Le Marsh (MLI98096)	Whilst the asset is located within the draft Order Limits, it is anticipated that there will be no intrusive activities or physical impacts to the asset arising from the construction or operation of the Project.	Low	No change	Neutral (Not significant)	No impacts (no change) to this non- designated heritage asset of low value would result in a neutral effect, which is not significant
Medieval ridge and furrow earthworks adjacent to Middlemarsh Road, Croft (MLI98097)	Topsoil stripping and groundworks associated with construction of the working area for pylon LW48 and 3 rd party mitigation areas, has the potential to remove or disturb part of this asset.	Low	Small	Negligible adverse (Not significant following additional mitigation)	Partial removal or disturbance (small magnitude of impact) of this non- designated heritage asset of low value would result in a negligible adverse effect, which is not significant. The use of archaeological mitigation measures i.e. appropriate archaeological investigation and recording would offset the significance of the effect to negligible adverse which would not be significant.
Possible medieval extractive pits in Irby in the Marsh (MLI98814)	Topsoil stripping and groundworks associated with construction of the working area for pylon LW62 and SUDS	Low	Small	Negligible adverse (Not Significant prior to the implementation	Partial removal or disturbance (small magnitude of impact) of this non- designated heritage asset of low value would result in a negligible adverse effect, which is not significant. The use of

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	drainage basins has the potential to remove or disturb part of this asset.			of additional mitigation measures)	archaeological mitigation measures i.e. appropriate archaeological investigation and recording would offset the significance of the effect to negligible
	It is anticipated there will be no intrusive activities related to activities within the stringing areas.			Negligible adverse (Not Significant following additional mitigation)	adverse which would not be significant.
Possible medieval earthwork boundary, Thorpe St Peter (MLI90849)	Whilst the asset is located within the draft Order Limits, it is anticipated that there will be no intrusive activities or physical impacts to the asset from the maintenance trackway and crossing protection during construction, or operation of the Project.	Low	No change	Neutral (Not significant)	No impacts (no change) to this non- designated heritage asset of low value would result in a neutral effect, which is not significant.
Possible medieval earthwork enclosure, Thorpe St Peter (MLI90844)	Topsoil stripping and groundworks associated with construction of the SUDS drainage basin and the working area for pylon LW64 has the potential to remove or disturb part of this asset.	Medium	Small adverse	Negligible adverse (Not Significant following additional mitigation)	Partial removal or disturbance (small magnitude of impact) of this non- designated heritage asset of medium value would result in a minor adverse effect, which is not significant. The use of archaeological mitigation measures i.e. appropriate archaeological investigation and recording would reduce the significance of the effect to negligible adverse which would not be significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	It is anticipated there will be no intrusive works related to activities within the stringing areas.				
Probable medieval earthwork ridge and furrow and field system, Thorpe St (MLI90850)	Whilst the asset is located within the draft Order Limits, it is anticipated that there will be no intrusive works related to activities within the stringing areas.	Medium	No Change	Neutral (Not significant)	No impacts (no change) to this non- designated heritage asset of medium value would result in a neutral effect, which is not significant.
Possible medieval earthwork platform, Thorpe St Peter (MLI90848)	Topsoil stripping for the installation of SUDS drainage basins will result in the partial truncation of the asset.	Medium	Small	Negligible adverse (Not Significant following additional mitigation)	Partial removal or disturbance (small magnitude of impact) of this non- designated heritage asset of medium value would result in a minor adverse effect, which is not significant. The use of archaeological mitigation measures i.e. appropriate archaeological investigation and recording would reduce the significance of the effect to negligible adverse which would not be significant.
Possible medieval enclosure, Thorpe St Peter (MLI90843)	Topsoil stripping for the installation of SUDS drainage basins will result in the partial truncation of the asset.	Medium	Small	Negligible adverse (Not Significant following additional mitigation)	Partial removal or disturbance (small magnitude of impact) of this non- designated heritage asset of medium value would result in a minor adverse effect, which is not significant. The use of archaeological mitigation measures i.e. appropriate archaeological investigation and recording would reduce the
Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
--	--	-------------------	------------------------	---	--
					significance of the effect to negligible adverse which would not be significant.
Possible medieval earthwork stack stands, Thorpe St (MLI90845)	Ground reduction associated with the installation of the construction access haul road, SUDS drainage basins and replacement woodland planting has the potential to remove or disturb part of this asset. It is anticipated there will be no intrusive works related to activities within the stringing areas.	Medium	Small	Negligible adverse (Not Significant following additional mitigation)	Partial removal or disturbance (small magnitude of impact) of this non- designated heritage asset of medium value would result in a minor adverse effect, which is not significant. The use of archaeological mitigation measures i.e. appropriate archaeological investigation and recording would reduce the significance of the effect to negligible adverse which would not be significant.
Medieval settlement earthworks, Thorpe St Peter (MLI90854)	Whilst the asset extends into the draft Order Limits, it is anticipated that there will be no intrusive activities or physical impacts to the asset during construction of the Project.	Low	No change	Neutral (Not significant)	No impacts (no change) to this non- designated heritage asset of low value would result in a neutral effect, which is not significant.
Site of Decoy Pond, Sedgedike (MLI42907)	Whilst the asset is located within the draft Order Limits, Whilst the asset extends into the draft Order Limits, it is anticipated that there will be no intrusive activities	Low	No change	Neutral (Not significant)	No impacts (No Change) to this non- designated heritage asset of low value would result in a neutral effect, which is not significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	or physical impacts to the asset during construction.				
Firsby to Boston Railway (MLI124888)	Whilst the asset crosses the draft Order Limits, it is anticipated that there will be no intrusive activities or physical impacts to the asset associated with construction of the Project.	Low	No change	Neutral (Not significant)	No impacts (no change) to this non- designated heritage asset of low value would arise from construction of the Project. This would result in a neutral effect, which is not significant.
Former Brickworks, Irby in the Marsh (MLI126078)	Topsoil stripping and groundworks associated with water vole mitigation areas would result in partial truncation of the asset.	Low	Small	Negligible (Not significant)	Partial removal or disturbance (small adverse magnitude of impact) of this non- designated heritage asset of low value would result in a negligible adverse effect to the asset, which is not significant.
Casterton House Park, Wigtoft (MLI92287)	Whilst the asset is located within the draft Order Limits, it is anticipated that there will be no intrusive works or physical impacts to the asset associated with construction.	Low	No change	Neutral (Not significant)	No impacts (No Change) to this non- designated heritage asset of low value would result in a neutral effect, which is not significant.
	Temporary changes to the setting of the asset arising from construction (noise, construction traffic, plant movement	Low	Medium	Minor adverse (Not Significant)	Potential for temporary change (medium magnitude of impact) to the setting of this low value asset that would affect its value and the way in which it is appreciated or understood. This would result in a minor

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	and scaffolds) of the Project.				adverse effect, which would not be significant.
	Permanent changes to the setting of the asset arising from the presence of the Project within the wider landscape.	Low	Medium	Minor adverse (Not Significant)	Potential for permanent visual intrusion (medium magnitude of impact) within the setting of this low value asset that would affect its value and the way in which it is appreciated or understood. This would result in a minor adverse effect, which would not be significant.
The Hundreds, (MLI119945)	Whilst the asset is located within the draft Order Limits, it is anticipated that there will be no intrusive activities or physical impacts to the asset associated with any construction activities	Low	No change	Neutral (Not significant)	No physical impacts (No Change) to this non-designated heritage asset of low value would result in a neutral effect, which is not significant
Unnamed farmstead, Croft (MLI120242)	This asset has been demolished. Whilst its site is located within the draft Order Limits, it is anticipated that there will be no intrusive activities or physical impacts to any potentially remaining archaeology associated with the asset during construction activities.	Negligible	No change	Neutral (Not significant)	No physical impacts (No Change) to this non-designated heritage asset of negligible value would result in a neutral effect, which is not significant
Unnamed farmstead, New	Ground reduction associated with the access road will result in	Negligible	Small	Negligible adverse	Partial removal or disturbance (small adverse magnitude of impact) of this non- designated heritage asset of negligible

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
Leake (MLI120339)	partial truncation across the site of the demolished farmstead.			(Not significant - following additional mitigation)	value would result in a negligible adverse effect to the asset, which is not significant. The use of archaeological mitigation measures i.e. appropriate archaeological investigation and recording would reduce the significance of the effect to negligible adverse which would not be significant.
Farmstead, Langriville (MLI124765)	This asset has been demolished. Whilst its site is located within the draft Order Limits, it is anticipated that there will be no intrusive activities or physical impacts to any potentially remaining archaeology associated with the asset during construction activities.	Negligible	No change	Neutral (Not significant)	No physical impacts (No Change) to this non-designated heritage asset of negligible value would result in a neutral effect, which is not significant
	heritage assets within the	1 km Study A			
Lade Bank Pumping Station and Lock, Old Leake (MLI88887)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.
Avro Lancaster Aircraft Crash Site and War	Temporary changes to the setting of the asset arising from construction	Low	Medium	Minor adverse (Not significant)	Temporary changes to the setting of this low value asset would have a noticeable effect on the value of the asset or the way

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
Memorial, Sibsey Northlands (MLI116028)	(such as noise and traffic).				in which it is appreciated or understood. This would have a minor adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Small	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape would alter the setting having a slight effect on its value and the way it is appreciated. This would result in a negligible adverse effect on an asset of low value, which would not be significant.
Little Steeping Railway Station (MLI124883)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.
Former School, Bilsby (MLI126598)	Temporary changes to the setting of the asset arising from construction activities (such as noise and construction traffic, mechanical plant).	Low	Medium	Minor adverse (Not significant)	Temporary changes to the setting of this low value asset would have a noticeable effect on the value of the asset or the way in which it is appreciated or understood. This would have a minor adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project within Section 3 and Section 4,	Low	Small	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape would alter the setting having a slight effect on its value and the way it is appreciated. This would result in

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	from the time of construction and throughout its operational duration in the wider landscape.				a negligible adverse effect on an asset of low value, which would not be significant.
Post Medieval Bridge (MLI43379)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting of value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect that is not significant.
Chantry, Easthorpe, Wigtoft (MLI13093)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting of value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect that is not significant.
Mumby Road Railway Station in Bilsby parish (MLI43413)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would have a neutral effect that is not significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	impact on the setting of value of this asset.				
Pillbox, Cumberworth Road, Bonthorpe (MLI125954)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting of value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would have a neutral effect that is not significant.
Pillbox, Lade Bank Lock, Old Leake (MLI43376)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting of value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect that is not significant.
Pillbox, Midville (MLI43375)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Small	Negligible adverse (Not significant)	Slight, temporary changes to the setting of this low value asset that would hardly affect the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible impact causing little effect on its value and how it is

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	time of construction and throughout its operational duration in the wider landscape.				appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Pillbox, Hemholme Bridge (MLI82729)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Negligible	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset that would have little effect on the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Pillbox, Sloothby (MLI43277)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Negligible	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset that would have little effect on the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible impact causing little effect on its value and how it is appreciated, resulting in a negligible

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	throughout its operational duration in the wider landscape.				adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Pillbox, Bridge House, Midville (MLI43373)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Negligible	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset would result in a negligible magnitude of impact to the way in which the building is experienced and appreciated. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Pillbox, Short's Corner (MLI43382)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Negligible	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset would result in a negligible magnitude of impact to the way in which the building is experienced and appreciated. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible impact causing little effect on its value and how it is

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	time of construction and throughout its operational duration in the wider landscape.				appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Redland, Stickney (MLI120449)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Small	Negligible adverse (Not significant)	Slight, temporary changes to the setting of this low value asset that would hardly affect the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Southview, Willoughby with Sloothby (MLI118933)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Small	Negligible adverse (Not significant)	Slight, temporary changes to the setting of this low value asset that would hardly affect the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible impact causing little effect on its value and how it is

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	time of construction and throughout its operational duration in the wider landscape.				appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Hobhole Farm, Midville (MLI120407)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project	Low	Negligible	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset would have little effect on the value of the asset or the way in which it is appreciated or understood. This would have a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Elsom Farm, Willoughby with Sloothby (MLI118928)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Negligible	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset that would have little effect on the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and	Low	No change	Neutral (Not significant)	There will be no permanent changes to the setting of this low value asset. This would have a neutral effect that is not significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	throughout its operational duration in the wider landscape.				
Grange Farm (The Grange), Midville (MLI120400)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Small	Negligible adverse (Not significant)	Slight, temporary changes to the setting of this low value asset that would hardly affect the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Poplars Farm, Kirton (MLI123017)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Negligible	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset would have little effect on the value of the asset or the way in which it is appreciated or understood. This would have a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	duration in the wider landscape.				This would result in a negligible adverse effect that is not significant.
Holme Lodge Farm, Kirton (MLI122997)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Negligible	Negligible adverse (Not significant)	Temporary changes to the setting of this negligible value asset would have little effect on the value of the asset or the way in which it is appreciated or understood. This would have a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Willow Farm, Thorpe St. Peter (MLI120294)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Small	Negligible adverse (Not significant)	Slight, temporary changes to the setting of this low value asset that would hardly affect the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	duration in the wider landscape.				This would result in a negligible adverse effect that is not significant.
Rabbit Breeding Farm, Holland Fen with Brothertoft (MLI122352)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Small	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset would have a small magnitude of impact on the value of the asset and the way in which it is appreciated or understood. This would have a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	No change	Neutral (Not significant)	There will be no permanent changes to the setting of this low value asset. This would have a neutral effect that is not significant.
Grove Farm, Bilsby (MLI116613)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the access route and overhead lines.	Low	Medium	Minor adverse (Not significant)	Temporary changes to the setting of this low value asset would have a noticeable effect on the value of the asset or the way in which it is appreciated or understood. This would have a minor adverse effect that is not significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Small	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape would alter the setting having a slight effect on its value and the way it is appreciated. This would result in a negligible adverse effect on an asset of low value, which would not be significant.
Arkendale, Stickney (MLI120446)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Negligible	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset that would have little effect on the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value that is not significant.
Chapel Farm, Stickney (MLI120445)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic,	Low	Small	Negligible adverse (Not significant)	Slight, temporary changes to the setting of this low value asset that would hardly affect the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	lighting and scaffolds) of the Project.				
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value that is not significant.
Poplar Farm, Cumberworth (MLI118912)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Negligible	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset that would have little effect on the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a low impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Cherry Tree House, Sibsey (MLI124548)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic,	Low	Medium	Minor adverse (Not significant)	Temporary changes to the setting of this low value asset would noticeably alter its setting which would have a medium impact, resulting in a minor adverse effect that is not significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	lighting and scaffolds) of the Project.				
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Small	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within the wider setting would have a small impact causing a slight change, resulting in a negligible adverse effect on an asset of low value that would not be significant.
Westville Farm, Frithville and Westville (MLI124651)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Negligible	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset would have little effect on the value of the asset or the way in which it is appreciated or understood. This would have a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a low impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Engine Farm, Stickford (MLI120382)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic,	Low	Negligible	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset that would have little effect on the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	lighting and scaffolds) of the Project.				
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value that is not significant.
Unnamed farmstead, Frampton (MLI123066)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Small	Negligible adverse (Not significant)	Slight, temporary changes to the setting of this low value asset that would hardly affect the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a low impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Spring Cottage, Wigtoft (MLI122815)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic,	Low	Small	Negligible adverse (Not significant)	Slight, temporary changes to the setting of this low value asset that would hardly affect the value of the asset or the way in which it is appreciated or understood. This

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	lighting and scaffolds) of the Project.				would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value that is not significant.
Meryland, Kirton (MLI123016)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Small	Negligible adverse (Not significant)	Slight, temporary changes to the setting of this low value asset that would hardly affect the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Small	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape would alter the setting having a slight effect on its value and the way it is appreciated. This would result in a negligible adverse effect on an asset of low value, which would not be significant.
Unnamed farmstead, New Leake (MLI120344)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic,	Low	Negligible	Negligible adverse (Not significant)	Temporary changes to the setting of this negligible value asset would have little effect on the value of the asset or the way in which it is appreciated or understood.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	lighting and scaffolds) of the Project.				This would have a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a low impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Wydal, New Leake (MLI120369)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Small	Negligible adverse (Not significant)	Slight, temporary changes to the setting of this low value asset that would hardly affect the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a low impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Home Farm House, Croft (MLI120249)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic,	Low	Small	Negligible adverse (Not significant)	Slight, temporary changes to the setting of this low value asset that would hardly affect the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	lighting and scaffolds) of the Project.				
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Ivy House, Kirton (MLI122995)	Construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no impact to the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect which is not significant.
Rojan, New Leake (MLI120343)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Negligible	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset would have little effect on the value of the asset or the way in which it is appreciated or understood. This would have a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a low impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	duration in the wider landscape.				This would result in a negligible adverse effect that is not significant.
Unnamed farmstead, Thorpe St. Peter (MLI120298)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Small	Negligible adverse (Not significant)	Slight, temporary changes to the setting of this low value asset that would hardly affect the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible impact causing little effect on its value and how it is appreciated. This would result in a negligible adverse effect that is not significant.
Peart's Farm Cottages (Peart's Farm), Holland Fen with Brothertoft (MLI122328)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Negligible	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset that would have little effect on the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value that is not significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	duration in the wider landscape.				
Unnamed farmstead, Midville (MLI120399)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Negligible	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset would have little effect on the value of the asset or the way in which it is appreciated or understood. This would have a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a low impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Middle Farm, Frampton (MLI123057)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Small	Negligible adverse (Not significant)	Slight, temporary changes to the setting of this low value asset that would hardly affect the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a low impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	duration in the wider landscape.				This would result in a negligible adverse effect that is not significant.
Westville Farm, Frithville and Westville (MLI124653)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Negligible	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset would have little effect on the value of the asset or the way in which it is appreciated or understood. This would have a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a low impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Flatters, Holland Fen with Brothertoft (MLI122341)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Negligible	Negligible adverse (Not significant)	Temporary changes to the setting of this negligible value asset would have little effect on the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational	Low	No Change	Neutral (Not significant)	There will be no permanent changes to the setting of this low value asset. This would have a neutral effect that is not significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	duration in the wider landscape.				
Unnamed farmstead, Carrington (MLI120505)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no impact on the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect that is not significant.
St Michael's Farm, Burgh Le Marsh (MLI119889)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no impact on the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect that is not significant.
Avondale, Wigtoft (MLI122827)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Small	Negligible (Not significant)	Slight, temporary changes to the setting of this low value asset that would hardly affect the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a low impact causing little effect on its value and how it is appreciated, resulting in a negligible

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	throughout its operational duration in the wider landscape.				adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
St. Catherine's Farm, Eastville (MLI120321)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no impact on the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect that is not significant.
Neals Old Farm, Sibsey (MLI124594)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Small	Negligible adverse (Not significant)	Slight, temporary changes to the setting of this low value asset that would hardly affect the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a low impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Boston Corporation	Temporary changes to the setting of the asset arising from construction (such as noise,	Low	Negligible	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset would have little effect on the value of the asset or the way in which it is appreciated or understood. This would

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
Farm, New Leake (MLI120336)	construction traffic, lighting and scaffolds) of the Project.				result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Pick's Barn, Kirton (MLI123030)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Negligible	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset would have little effect on the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Wragg Hall Farm, Carrington (MLI120499)	Construction and presence of the Project in the landscape from the time of construction and	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	throughout its operational duration will have no impact to the setting or value of this asset.				understood. This would result in a neutral effect which would be not significant.
School Farm Cottage, Thorpe St Peter (MLI120286)	Construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no impact on the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect which would be not significant.
Timberland, Swineshead (MLI122444)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Negligible	Negligible (Not significant)	Temporary changes to the setting of this low value asset would have little effect on the value of the asset or the way in which it is appreciated or understood. This would have a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Pear Tree Farm (Peartree House), Burgh Le Marsh (MLI119886)	Construction and the presence of the Project in the landscape from the time of construction and	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	throughout its operational duration will have no impact on the setting or value of this asset.				understood. This would result in a neutral effect which is not significant.
Barley Close, Holland Fen with Brothertoft (MLI122345)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Negligible	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset that would have little effect on the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Unnamed farmstead, Swineshead (MLI122445)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which it is appreciated or understood. This would result in a neutral effect which would be not significant.
Chestnut Lodge, Thornton Le Fen (MLI124694)	The construction and presence of the Project in the landscape from the	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which it is appreciated

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.				or understood. This would result in a neutral effect which would be not significant.
Unnamed farmstead, Kirton (MLI122989)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which it is appreciated or understood. This would result in a neutral effect which would be not significant.
Non-designated buildings in Farlesthorpe (MLI118913; MLI118914; MLI118915)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact to the setting or value of these assets.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of these assets and will not alter their value or the way in which they are appreciated or understood. This would result in a neutral effect that is not significant.
Non-designated buildings in Cumberworth (MLI118894; MLI118895; MLI118896; MLI118897;	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of these assets and will not alter their value or the way in which they are appreciated or understood. This would result in a neutral effect that is not significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
MLI118898; MLI118899; MLI118900; MLI11893; MLI126602; MLI126602; MLI18902; MLI18902; MLI98920; MLI18901; MLI98921)	impact to the setting or value of these assets.				
Non-designated buildings in Sloothby (MLI99104; MLI118937; MLI118938; MLI124825; MLI124825; MLI118941; MLI118939; MLI99107; MLI99107;	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact to the setting or value of these assets.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of these assets and will not alter their value or the way in which they are appreciated or understood. This would result in a neutral effect that is not significant.
Non-designated buildings in Croft (MLI120246; MLI120247; MLI120248; MLI126575; MLI116052; MLI120252; MLI120251 MLI120250)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact to the setting or value of these assets.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of these assets and will not alter their value or the way in which they are appreciated or understood. This would result in a neutral effect that is not significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
Non-designated buildings in Thorpe St Peter (MLI99089; MLI120296; MLI120299; MLI120300; MLI120301)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact to the setting or value of these assets.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of these assets and will not alter their value or the way in which they are appreciated or understood. This would result in a neutral effect that is not significant.
Non-designated buildings in Northlands (MLI124551; MLI126589; MLI124554; MLI99060; MLI124552; MLI124555; MLI124555;	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact to the setting or value of these assets.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of these assets and will not alter their value or the way in which they are appreciated or understood. This would result in a neutral effect that is not significant.
Non-designated buildings in Hubbert's Bridge (MLI12737; MLI122983; MLI91923; MLI89010)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact to the setting or value of these assets.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of these assets and will not alter their value or the way in which they are appreciated or understood. This would result in a neutral effect that is not significant.
Non-designated buildings in Wigtoft	Construction and the presence of the Project in the landscape from the	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of these assets and will not alter their value or the way in which they are

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
(MLI122821; MLI91937; MLI126644; MLI122823)	time of construction and throughout its operational duration will have no temporary or permanent impact to the setting or value of these assets.				appreciated or understood. This would result in a neutral effect that is not significant.
Non-designated buildings in Langrick Bridge (MLI122315; MLI122314; MLI126014; MLI126014; MLI86181; MLI122313)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact to the setting or value of these assets.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of these assets and will not alter their value or the way in which they are appreciated or understood. This would result in a neutral effect that is not significant.
Manor Farm, Langriville (MLI124757)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no impact to the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect that is not significant.
Woodlands Cottage, Thorpe St. Peter (MLI120282)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no impact to the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect that is not significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
Vicarage Farm, Sutterton (MLI122878)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no impact to the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect that is not significant.
Creasey's Farm, Holland Fen with Brothertoft (MLI122351)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Negligible	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset that would have little effect on the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value that is not significant.
Kesten Lodge, New Leake (MLI120335)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no impact to the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect that is not significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
Bass Farm, Stickford (MLI120379)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no impact to the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect that is not significant.
Catchwater Cottage, New Leake (MLI120366)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no impact to the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect that is not significant.
Unnamed farmstead, New Leake (MLI120334)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no impact to the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect that is not significant.
Unnamed farmstead, New Leake (MLI120365)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect that is not significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	impact to the setting or value of this asset.				
Middlemarsh Farm, Burgh Le Marsh (MLI119877)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no impact to the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect that is not significant.
Unnamed farmstead, Kirton (MLI123004)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no impact to the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect that is not significant.
Woodbine Cottage, Kirton (MLI123027)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no impact to the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in neutral effects that are not significant.
Skirbeck Farm (Skirbeck Allotment), Sibsey (MLI124545)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in neutral effects that are not significant.
Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
---	---	-------------------	------------------------	--	--
	duration will have no impact to the setting or value of this asset.				
Slate House Farm, Frampton (MLI123058)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no impact to the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in neutral effects that are not significant.
Unnamed farmstead, Wigtoft (MLI122808)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no impact to the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect that is not significant.
Slate House, Wigtoft (MLI122816)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Negligible	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset that would have little effect on the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact causing little effect on its value and how it is appreciated, resulting in a

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	throughout its operational duration in the wider landscape.				negligible adverse effect on an asset of low value that is not significant.
Unnamed farmstead, Wigtoft (MLI122833)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Negligible	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset would have little effect on the value of the asset or the way in which it is appreciated or understood. This would have a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value that is not significant.
West Royalty Farm (Royalty Farm), Eastville (MLI120318)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Small	Negligible adverse (Not significant)	Slight, temporary changes to the setting of this low value asset that would hardly affect the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact causing little effect on its value and how it is appreciated, resulting in a

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	throughout its operational duration in the wider landscape.				negligible adverse effect on an asset of low value that is not significant.
Bilsby Farm, Bilsby (MLI116616)	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Small	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within the setting of the asset would have a negligible magnitude of impact causing a slight effect on its setting and how it is appreciated, resulting in a negligible adverse effect on an asset of low value that is not significant.
Moat House, Bilsby (MLI116615)	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Small	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape would alter the setting having a slight effect on its value and the way it is appreciated. This would result in a negligible adverse effect on an asset of low value, which would not be significant.
Unnamed Farmstead, Orby (MLI119853)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the access route and overhead lines.	Low	Medium	Minor adverse (Not significant)	Temporary changes to the setting of this low value asset would have a noticeable effect on the value of the asset or the way in which it is appreciated or understood. This would have a minor adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	of the Project, from the time of construction and throughout its operational duration in the wider landscape.				impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value that is not significant.
Vicarage Farm, Holland Fen with Brothertoft (MLI122327)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Small	Negligible adverse (Not significant)	Slight, temporary changes to the setting of this low value asset that would hardly affect the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value that is not significant.
Moonraker, Thorpe St. Peter (MLI120316)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Small	Negligible adverse (Not significant)	Slight, temporary changes to the setting of this low value asset that would hardly affect the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact causing little effect on its value and

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	time of construction and throughout its operational duration in the wider landscape.				how it is appreciated, resulting in a negligible adverse effect on an asset of low value that is not significant.
Thurlby House (Thurlby Grove), Bilsby (MLI116612)	Temporary changes to the setting of the asset arising from construction activities (such as noise and construction traffic).	Low	Small	Negligible adverse (Not significant)	Slight, temporary changes to the setting of this low value asset that would hardly affect the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Hill's Farm), Gosberton (MLI122565)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Small	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset that would slightly affect the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape would hardly alter the setting of the asset or the way it is appreciated. This would result in a

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	duration in the wider landscape.				negligible adverse effect on an asset of low value, which would not be significant.
Unnamed farmstead, Wigtoft (MLI122812)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Small	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset that would slightly affect the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Barbridge House, Sibsey (MLI124595)	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Field House Farm, Cumberworth (MLI118905)	Temporary changes to the setting of the asset arising from construction (such as noise,	Low	Negligible	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset that would have little effect on the value of the asset or the way in which it is appreciated or understood.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	construction traffic, lighting and scaffolds) of the Project.				This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Decoy Farm, Thorpe St. Peter (MLI120304)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Small	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset that would slightly affect the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value that is not significant.
School Farm, Farlesthorpe (MLI118918)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic,	Low	Small	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset that would slightly affect the value of the asset or the way in which it is appreciated or understood. This would

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	lighting and scaffolds) of the Project				result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value that is not significant.
Lloyds Farm (Marsh Farm), Burgh Le Marsh (MLI119892)	Temporary changes to the setting of the asset arising from construction (such as noise and traffic)	Low	Medium	Minor adverse (Not significant)	Temporary changes to the setting of this low value asset would have a noticeable effect on the value of the asset or the way in which it is appreciated or understood. This would have a minor adverse effect that is not significant.
the set arising of the time of throug duratic	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Small	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape would alter the setting having a slight effect on its value and the way it is appreciated. This would result in a negligible adverse effect on an asset of low value, which would not be significant.
Hemholme Farm, Eastville (MLI120322)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic,	Low	Negligible	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset that would have little effect on the value of the asset or the way in which it is appreciated or understood.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	lighting and scaffolds) of the Project.				This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value that is not significant.
East Royalty Farm (Royalty Farm East), Eastville (MLI120317)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Small	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset that would slightly affect the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to Low Negligible the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value that is not significant.	
Cumberworth West Farm, Cumberworth (MLI118906)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic,	Low	Small	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset that would slightly affect the value of the asset or the way in which it is appreciated or understood. This would

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	lighting and scaffolds) of the Project.				result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value that is not significant.
The Laurels, New Leake (MLI120360)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Medium	Minor adverse (Not significant)	Temporary changes to the setting of this low value asset would have a noticeable effect on the value of the asset or the way in which it is appreciated or understood. This would have a minor adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Small	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a small magnitude of impact causing a slight effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value that is not significant.
The Moletrap, Kirton (MLI122996)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic,	Low	Small	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset that would slightly affect the value of the asset or the way in which it is appreciated or understood. This would

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	lighting and scaffolds) of the Project.				result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magntidue of impact that would hardly effect its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value that is not significant.
Woad Farm, Surfleet (MLI122578)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Small	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset that would slightly affect the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to Low Negligible Negligible the setting of the asset adverse	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value that is not significant.		
Fieldside, Kirton (MLI122986)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic,	Low	Medium	Minor adverse (Not significant)	Temporary changes to the setting of this low value asset that would noticeably alter its setting and the way in which it is experienced. This would result in a minor adverse effect that is not significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	lighting and scaffolds) of the Project.				
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Small	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a small magnitude of impact causing a slight change to its setting and how it is appreciated, resulting in a negligible adverse effect on an asset of low value that is not significant.
Sycamore Farm, Sibsey (MLI124547)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Medium	Minor adverse (Not significant)	Temporary changes to the setting of this low value asset would have a noticeable effect on the value of the asset or the way in which it is appreciated or understood. This would have a minor adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Small	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a small magnitude of impact causing a slight effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value that is not significant.
Bamber's Farm, Holland Fen with Brothertoft (MLI122325)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic,	Low	Small	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset that would slightly affect the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	lighting and scaffolds) of the Project.				
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value that is not significant.
Goosegreen Farm (Belton Farm), Wigtoft (MLI122840)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Negligible	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset that would have little effect on the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Small	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a small magnitude of impact causing a slight effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value that is not significant.
Marsh House Farm, Orby (MLI119854)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic,	Low	Negligible	Negligible adverse (Not significant)	Potential for temporary changes to the setting of the asset which would have little effect to the way in which it is experienced and appreciated. This would result in a negligible adverse effect that is not significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	lighting and scaffolds) of the Project.				
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value that is not significant.
Bank House Farm, Sutterton (MLI122865)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Small	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset that would slightly affect the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value that is not significant.
Millhill Farm, Irby in the Marsh (MLI119952)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic,	Low	Small	Negligible adverse (Not significant)	Temporary changes to the setting of this negligible value asset would result in a small magnitude of impact to the way in which the building is experienced and appreciated. This would result in a

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	lighting and scaffolds) of the Project.				negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Small	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a small magnitude of impact causing a slight effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value that is not significant.
Unnamed farmstead, Kirton (MLI122987)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Small	Negligible adverse (Not significant)	Temporary changes to the setting of this negligible value asset would result in a small magnitude of impact to the way in which the building is experienced and appreciated. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value that is not significant.
The Firs, Frampton (MLI123063)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic,	Low	Small	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset that would slightly affect the value of the asset or the way in which it is appreciated or understood. This would

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	lighting and scaffolds) of the Project.				result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value that is not significant.
The Cottage, Stickney (MLI120447)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Small	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset that would slightly affect the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Rose Cottage, Cumberworth (MLI118904)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic,	Low	Negligible	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset would have little effect on the value of the asset or the way in which it is appreciated or understood. This would

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	lighting and scaffolds) of the Project.				result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Waite's Farm, Midville (MLI120408)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Negligible	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset that would have little effect on the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value that is not significant.
Saratoga, Thornton Le Fen (MLI124702)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic,	Low	Small	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset that would slightly affect the value of the asset or the way in which it is appreciated or understood. This would

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	lighting and scaffolds) of the Project.				result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value that is not significant.
Unnamed farmstead (Parr's Cottages), Wigtoft (MLI122836)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Small	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset that would slightly affect the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Small	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a small magnitude of impact causing a slight effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value that is not significant.
Sunnyside Farm, Kirton (MLI123000)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic,	Low	Small	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset that would slightly affect the value of the asset or the way in which it is appreciated or understood. This would

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	lighting and scaffolds) of the Project.				result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value that is not significant.
Lymn Bank Farm, Thorpe St. Peter (MLI120283)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Negligible	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset would have little effect on the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Willow Lodge, Burgh Le Marsh (MLI119887)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic,	Low	Small	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset that would slightly affect the value of the asset or the way in which it is appreciated or understood. This would

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	lighting and scaffolds) of the Project.				result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Farlesthorpe House Farm, Farlesthorpe (MLI118916)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Negligible	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset would have little effect on the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value that is not significant.
Gee's Farm, Holland Fen with Brothertoft (MLI122326)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic,	Low	Small	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset that would slightly affect the value of the asset or the way in which it is appreciated or understood. This would

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	lighting and scaffolds) of the Project.				result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Unnamed farmstead, Surfleet (MLI122579)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Negligible	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset would result in a negligible magnitude of impact to the way in which the building is experienced and appreciated. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value that is not significant.
Riggals Farm, Frithville and Westville (MLI124654)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic,	Low	Small	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset that would slightly alter its setting and the way in which it is appreciated or understood. This would

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	lighting and scaffolds) of the Project.				result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact causing little effect on its value and how it is appreciated. This would result in a negligible adverse effect on an asset of low value, which would not be significant.
Marsh Farm, Orby (MLI119855)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Negligible	Negligible adverse (Not significant)	Potential for temporary changes to the setting of this low value asset which would have little effect on the way in which it is experienced and appreciated. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value that is not significant.
Jubilee Farm, Kirton (MLI123001)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic,	Low	Small	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset that would slightly affect the value of the asset or the way in which it is appreciated or understood. This would

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	lighting and scaffolds) of the Project.				result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Small	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a small magnitude of impact causing a slight effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value that is not significant.
Holme Farm, Langriville (MLI124767)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Small	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset that would slightly affect the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Small	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a small magnitude of impact causing a slight effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value that is not significant.
Bonthorpe Farm, Willoughby with Sloothby (MLI118927)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect that is not significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	impact to the setting or value of this asset.				
Unnamed farmstead, Willoughby with Sloothby (MLI118923)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no impact to the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect that is not significant.
The Old Barn, Croft (MLI120241)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project	Low	Small	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset that would slightly affect the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
The Shrubbery, New Leake (MLI120342)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic,	Low	Negligible	Negligible adverse (Not significant)	Potential for temporary changes to the setting of this low value asset which would have little effect on the way in which it is experienced and appreciated. This would result in a negligible adverse effect that is not significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	lighting and scaffolds) of the Project.				
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
The Mantles, Kirton (MLI123002)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the access route and overhead lines.	Low	Small	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset that would slightly affect the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Small	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a small magnitude of impact causing a slight effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value that is not significant.
Bellwater Farm, Eastville (MLI120319)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic,	Low	Small	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset that would slightly affect the value of the asset or the way in which it is appreciated or understood. This would

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	lighting and scaffolds) of the Project.				result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value that is not significant.
Asperton Farm, Wigtoft (MLI122814)	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Small	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a small magnitude of impact causing a slight effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value that is not significant.
Thorpe House, Thorpe St. Peter (MLI120295)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Small	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset that would slightly affect the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact causing little effect on its value and how it is appreciated, resulting in a

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	throughout its operational duration in the wider landscape.				negligible adverse effect on an asset of low value that is not significant.
Old Three Tuns Farm, Surfleet (MLI122568)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Small	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset that would slightly affect the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Silver Pit Farm, Stickford (MLI120380)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Medium	Minor adverse (Not significant)	Temporary changes to the setting of this low value asset would have a noticeable effect on the value of the asset or the way in which it is appreciated or understood. This would have a minor adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational	Low	Small	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a small magnitude of impact causing a slight effect on its value and how it is appreciated, resulting in a

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	duration in the wider landscape				negligible adverse effect on an asset of low value that is not significant.
Cottage Farm (The Cottage), Kirton (MLI123015)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Small	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset that would slightly affect the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Farmstead, Thornton Le Fen (MLI124701)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Small	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset that would slightly affect the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	duration in the wider landscape				low value. This would result in a negligible adverse effect that is not significant.
Ickle Cottage, Kirton (MLI123019)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Small	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset that would slightly affect the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Small	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a small magnitude of impact causing a slight effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value that is not significant.
Hackerley Bridge Farm, Carrington (MLI120504)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Negligible	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset would have little effect on the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact casing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	duration in the wider landscape.				low value. This would result in a negligible adverse effect that is not significant.
The Orchards, Frampton (MLI123061)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Negligible	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset would have little effect on the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Middle Farm House, Thornton Le Fen (MLI124700)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Negligible	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset would have little effect on the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	duration in the wider landscape.				low value. This would result in a negligible adverse effect that is not significant.
White House Farm, Bilsby (MLI116614)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which it is appreciated or understood. This would result in a neutral effect which would be not significant.
Glebe Farm, Halton Holegate (MLI119998)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no impact to the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.
Newham Farm, Thornton Le Fen (MLI124693)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Negligible	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset would have little effect on the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact causing little effect on its value and how it is appreciated, resulting in a

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	throughout its operational duration in the wider landscape				negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Sycamore Farm, Burgh Le Marsh (MLI119884)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.
Unnamed farmstead, Swineshead (MLI122441)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Small	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset that would slightly affect the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Unnamed farmstead, Thorpe St. Peter (MLI120293)	Construction and the presence of the Project in the landscape from the time of construction and	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	throughout its operational duration will have no impact to the setting or value of this asset.				understood. This would result in a neutral effect which would not be significant.
Conifer Cottage, Frithville and Westville (MLI124650)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Negligible	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset would have little effect on the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Pippinhall, Kirton (MLI123020)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Small	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset that would slightly affect the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact causing little effect on its value and how it is appreciated, resulting in a

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	throughout its operational duration in the wider landscape.				negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Oakleigh, Cumberworth (MLI118903)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Negligible	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset would have little effect on the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact casing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Winslow, New Leake (MLI120347)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Small	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset that would slightly affect the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact casing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	duration in the wider landscape.				low value. This would result in a negligible adverse effect that is not significant.
Home Farm, Kirton (MLI123014)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Small	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset that would slightly affect the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact casing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Barford Farm, Kirton (MLI122985)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Negligible	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset would have a noticeable effect on the value of the asset and the way in which it is appreciated or understood. This would have a negligible adverse effect which is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact casing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	duration in the wider landscape.				low value. This would result in a negligible adverse effect that is not significant.
Rectory Farm, Langriville (MLI124758)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Small	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset that would slightly affect the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Small	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a small magnitude of impact causing a slight effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value that is not significant.
Pape's Farm, Thorpe St. Peter (MLI120306)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no impact to the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.
Harvest Man Inn, Carrington (MLI120503)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic,	Low	Small	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset that would slightly affect the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
--	--	-------------------	------------------------	--	---
	lighting and scaffolds) of the Project.				
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact casing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Glebe Farm, Cumberworth (MLI118910)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Negligible	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset would have little effect on the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact casing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Unnamed farmstead, Thorpe St. Peter (MLI120292)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	impact to the setting or value of this asset.				
Tree Farm, Croft (MLI120240)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no impact to the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.
Vine Farm (Vine Cottage), Burgh Le Marsh (MLI119878)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no impact to the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.
Blackjack Farm, Swineshead (MLI122443)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Small	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset that would slightly affect the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational	Low	Small	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a small magnitude of impact causing a slight effect on its value and how it is appreciated, resulting in a

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	duration in the wider landscape.				negligible adverse effect on an asset of low value that is not significant.
Ranson's Farm, Thornton Le Fen (MLI124698)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Negligible	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset would have a noticeable effect on the value of the asset and the way in which it is appreciated or understood. This would have a negligible adverse effect which is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact casing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Bridge Farm (Red House), Wigtoft (MLI122820)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no impact to the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.
Castle Dyke House, Frithville and Westville (MLI124641)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic,	Low	Negligible	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset would have little effect on the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	lighting and scaffolds) of the Project.				
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact casing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Woddys Den, New Leake (MLI120348)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Small	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset that would slightly affect the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact casing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Thornton Lodge, Thornton Le Fen (MLI124699)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic,	Low	Negligible	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset would have a noticeable effect on the value of the asset and the way in which it is appreciated or understood. This would have a negligible adverse effect which is not significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	lighting and scaffolds) of the Project.				
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact casing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Whitehouse, New Leake (MLI120356)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Negligible	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset would have little effect on the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact casing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Unnamed farmstead, Surfleet (MLI122577)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect which would be not significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	impact to the setting or value of this asset.				
Hollutrix Farm, Bilsby (MLI116625)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Small	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset that would slightly affect the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Small	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a small magnitude of impact causing a slight effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value that is not significant.
White House Farm, Midville (MLI120406)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no impact to the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect which would be not significant.
Unnamed farmstead, Wigtoft (MLI122813)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic,	Low	Medium	Minor adverse (Not significant)	Temporary changes to the setting of this low value asset would have a noticeable effect on the value of the asset or the way in which it is appreciated or understood. This would have a minor adverse effect that is not significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	lighting and scaffolds) of the Project.				
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Small	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a small magnitude of impact causing a slight effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value that is not significant.
Hakerley Bridge, Frithville and Westville (MLI124602)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Negligible	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset would have little effect on the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
The Old Farmhouse, Frampton (MLI123059)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic,	Low	Negligible	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset would have little effect on the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	lighting and scaffolds) of the Project.				
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Home Farm, Frithville and Westville (MLI124652)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Negligible	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset would have little effect on the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact casing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
White House Farm (White Cottage), Thorpe St. Peter (MLI120285)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect which would be not significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	impact to the setting or value of this asset.				
Clough Farm, Firsby (MLI119959)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no impact to the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect which would be not significant.
Yewtree Farmhouse, Kirton (MLI122993)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no impact to the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect which would be not significant.
Yewtree House, Wigtoft (MLI122830)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Negligible	Negligible (Not significant)	Temporary changes to the setting of this low value asset would have little effect on the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact casing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	duration in the wider landscape.				low value. This would result in a negligible adverse effect that is not significant.
Dovecote Farm House (Dovecote Farm), Midville (MLI120401)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Negligible	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset would have little effect on the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact casing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Midville House Farm (Midville House), Midville (MLI120410)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project	Low	Negligible	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset that would have little effect on the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	duration in the wider landscape.				low value. This would result in a negligible adverse effect that is not significant.
Laurels, Irby in the Marsh (MLI119949)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which it is appreciated or understood. This would result in a neutral effect which would be not significant.
Orchard Farm, Thorpe St. Peter (MLI120291)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which it is appreciated or understood. This would result in a neutral effect which would be not significant.
White House, Wigtoft (MLI122835)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which it is appreciated or understood. This would result in a neutral effect which would be not significant.
Ivy House, Holland Fen with	Temporary changes to the setting of the asset	Low	Small	Negligible	Temporary changes to the setting of this low value asset that would slightly affect

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
Brothertoft (MLI122342)	arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.			adverse (Not significant)	the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Burfoft House, Wigtoft (MLI122834)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which it is appreciated or understood. This would result in a neutral effect which would be not significant.
Ivy Farmhouse, New Leake (MLI120337)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which it is appreciated or understood. This would result in a neutral effect which would be not significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
End Cottage, Stickney (MLI120440)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which it is appreciated or understood. This would result in a neutral effect which would be not significant.
Chapel Farm, Midville (MLI120409)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which it is appreciated or understood. This would result in a neutral effect which would be not significant.
The Elms, Burgh Le Marsh (MLI119879)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.
Green Lane Cottage, Frithville	Temporary changes to the setting of the asset arising from construction (such as noise,	Low	Negligible	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset would have little effect on the value of the asset or the way in which it is appreciated or understood. This would

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
and Westville (MLI124645)	construction traffic, lighting and scaffolds) of the Project.				result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact casing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Unnamed farmstead, New Leake (MLI120355)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which it is appreciated or understood. This would result in a neutral effect which would be not significant.
Walnut Grange, Kirton (MLI122992)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
Home Farm, Little Steeping (MLI120011)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which it is appreciated or understood. This would result in a neutral effect which would be not significant.
Hill Farm, Holland Fen with Brothertoft (MLI122330)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which it is appreciated or understood. This would result in a neutral effect which would be not significant.
Unnamed farmstead, Stickford (MLI120381)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which it is appreciated or understood. This would result in a neutral effect which would be not significant.
Black Sluice Farm, Wigtoft (MLI122831)	The construction and presence of the Project in the landscape from the time of construction and	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which it is appreciated or understood. This would result in a

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.				neutral effect which would be not significant.
Station Farm, Cumberworth (MLI118890)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which it is appreciated or understood. This would result in a neutral effect which would be not significant.
Guidepost Farm, Wigtoft (MLI122826)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Negligible	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset would have little effect on the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact casing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Reaches Marsh Farm, Holland	Temporary changes to the setting of the asset	Low	Negligible	Negligible adverse	Temporary changes to the setting of this low value asset would have little effect on

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
Fen with Brothertoft (MLI122317)	arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.			(Not significant)	the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact casing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Unnamed farmstead, Thorpe St. Peter (MLI120308)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.
Oat Sheaf House (Oat Sheaf Inn), New Leake (MLI120354)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which it is appreciated or understood. This would result in a neutral effect which would be not significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
Bank House, Wigtoft (MLI122824)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Negligible	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset would have little effect on the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact casing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
The Tree House, Frithville and Westville (MLI124657)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which it is appreciated or understood. This would result in a neutral effect which would be not significant.
Unnamed farmstead, Holland Fen with Brothertoft (MLI122329)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which it is appreciated or understood. This would result in a neutral effect which would be not significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	impact on the setting or value of this asset.				
Thornton House, Frithville and Westville (MLI124659)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which it is appreciated or understood. This would result in a neutral effect which would be not significant.
The Farm House, Eastville (MLI120323)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which it is appreciated or understood. This would result in a neutral effect which would be not significant.
Unnamed farmstead, Irby in the Marsh (MLI119951)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
Pink House Farm, Thorpe St. Peter (MLI120303)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.
Deepes Barn, Frithville and Westville (MLI124663)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Negligible	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset would have little effect on the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact casing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
The Walnuts, Frampton (MLI123074)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	impact on the setting or value of this asset.				
Riverside Farm, Holland Fen with Brothertoft (MLI122316)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.
Fleet House, Wigtoft (MLI122811)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Small	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset that would slightly affect the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact casing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Redwood Farm, Holland Fen with Brothertoft (MLI122324)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic,	Low	Negligible	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset would have little effect on the value of the asset or the way in which it is appreciated or understood. This would

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	lighting and scaffolds) of the Project.				result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact casing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Unnamed farmstead, Wigtoft (MLI122829)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting of value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.
Unnamed farmstead (Paradise Farm), Wigtoft (MLI122825)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Negligible	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset would have little effect on the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact casing little effect on its value and how it is appreciated, resulting in a

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	throughout its operational duration in the wider landscape.				negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Coney Garth House, Surfleet (MLI122576)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting of value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.
Drove House (Gipsy Drove Barn), Langriville (MLI124768)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Negligible	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset would have little effect on the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Chestnut Farm, Firsby (MLI119960)	The construction and presence of the Project in the landscape from the time of construction and	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	throughout its operational duration will have no temporary or permanent impact on the setting of value of this asset.				understood. This would result in a neutral effect which would not be significant.
Ivydene House, Langriville (MLI124773)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Negligible	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset would have little effect on the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Unnamed farmstead (Ings Farm), Cumberworth (MLI118908)	The asset appears to have been demolished and has not been redeveloped with no historic buildings remaining extant. The value of the asset has been lost and impacts from the proximity of construction activities and the permanency of the	Negligible	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which it is appreciated or understood. This would result in a neutral effect which is not significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	infrastructure in the landscape has no impact upon it and it is not included for assessment.				
Orchard Barn, Holland Fen with Brothertoft (MLI122346)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Negligible	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset would have little effect on the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact casing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Lymn Bank, Thorpe St. Peter (MLI120280)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Negligible	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset would have little effect on the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact casing little effect on its value and how it is appreciated, resulting in a

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	throughout its operational duration in the wider landscape.				negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Sycamore House, Frithville and Westville (MLI124667)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no impact to the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect that is not significant.
Fen Farm, Frampton (MLI123064)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no impact to the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect that is not significant.
Willow Farm, Langriville (MLI124756)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no impact to the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect that is not significant.
Station Farm, Thorpe St. Peter (MLI120309)	Construction and the presence of the Project in the landscape from the time of construction and	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	throughout its operational duration will have no impact to the setting or value of this asset.				understood. This would result in a neutral effect that is not significant.
Bishop's Farm, Frithville and Westville (MLI124606)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Negligible	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset would have little effect on the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Kirk's Farm (Frogthorpe Hall), Burgh Le Marsh (MLI119885)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no impact to the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect that is not significant.
Sutton House, Kirton (MLI123003)	Construction and the presence of the Project in the landscape from the time of construction and	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	throughout its operational duration will have no impact to the setting or value of this asset.				understood. This would result in a neutral effect that is not significant.
Mexican Farm, Midville (MLI120402)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no impact to the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect that is not significant.
Unnamed farmstead, Stickney (MLI120442)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no impact to the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect that is not significant.
Slate House Farm, Frampton (MLI123075)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no impact to the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect that is not significant.
Grange Farm (Carey's Farm), Frithville and	Construction and the presence of the Project in the landscape from the	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
Westville (MLI124658)	time of construction and throughout its operational duration will have no impact to the setting or value of this asset.				understood. This would result in a neutral effect that is not significant.
Bristol Farm, Burgh Le Marsh (MLI119871)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no impact to the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect that is not significant.
Willoughby Farm, Frampton (MLI123065)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no impact to the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect that is not significant.
Willow Farm, Sutterton (MLI122867)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no impact to the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect that is not significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
Primrose Farm, Thorpe St. Peter (MLI120281)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no impact to the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect that is not significant.
Farmstead, Sibsey (MLI124557)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no impact to the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect that is not significant.
Lincoln Farm, Bratoft (MLI119946)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no impact to the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect that is not significant.
Barnside (Wigtoft Marsh Farm), Wigtoft (MLI122828)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect that is not significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	impact to the setting or value of this asset.				
Unnamed farmstead, Kirton (MLI122990)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no impact to the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect that is not significant.
Rookery Farm, Croft (MLI120243)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no impact to the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect that is not significant.
Pastures Farm, Swineshead (MLI122442)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no impact to the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect that is not significant.
Bridge House Farm (Bank House Farm), Surfleet (MLI122580)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect that is not significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	duration will have no impact to the setting or value of this asset.				
Fir Tree Farm (Firtree Farm), Orby (MLI119851)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no impact to the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect that is not significant.
Greylands Farm, Wigtoft (MLI122839)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no impact to the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect that is not significant.
Bank House, New Leake (MLI120370)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no impact to the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect that is not significant.
Unnamed farmstead, Gosberton (MLI122563)	Construction and the presence of the Project in the landscape from the time of construction and	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	throughout its operational duration will have no impact to the setting or value of this asset.				understood. This would result in a neutral effect that is not significant.
The Limes, Holland Fen with Brothertoft (MLI122347)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no impact to the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect that is not significant.
Brinsworth Farm, Kirton (MLI122991)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no impact to the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect that is not significant.
Halfway House, Burgh Le Marsh (MLI119874)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no impact to the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect that is not significant.
Ivy House, Sutterton (MLI122871)	Construction and the presence of the Project in the landscape from the	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	time of construction and throughout its operational duration will have no impact to the setting or value of this asset.				understood. This would result in a neutral effect that is not significant.
Unnamed farmstead, Kirton (MLI123028)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no impact to the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect that is not significant.
Primrose Hill Farm, Thornton Le Fen (MLI124691)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which it is appreciated or understood. This would result in a neutral effect which would be not significant.
Farmstead, Sibsey (MLI124558)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Negligible	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset would have little effect on the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset	Low	Negligible	Negligible adverse	The permanency of the infrastructure in the landscape within its wider setting

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.			(Not significant)	would have a negligible magnitude of impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Wilcox Farm, Addlethorpe (MLI119832)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no impact to the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect that is not significant.
The Cottage, Kirton (MLI123013)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no impact to the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect that is not significant.
Unnamed farmstead, Firsby (MLI119961)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no impact to the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect that is not significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
Unnamed farmstead, Cumberworth (MLI118891)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no impact to the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.
Unnamed farmstead, Carrington (MLI120502)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.
Meer Booth Farm, Langriville (MLI124760)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no impact to the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.
Grange Farm, Stickney (MLI120439)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.
Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
--	---	-------------------	------------------------	------------------------------	--
	impact to the setting or value of this asset.				
Blackitt's Farm, Sutterton (MLI122857)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no impact to the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.
Home Farm, Burgh Le Marsh (MLI119896)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no impact to the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.
Ivy House, Orby (MLI119856)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no impact to the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.
Duchy Farm, Midville (MLI120403)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	duration will have no impact to the setting or value of this asset.				
Surfleet Marsh Farm, Surfleet (MLI122569)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project in Section 4 and Section 5.	Low	Small	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset would slightly affect the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project in Section 4 and Section 5, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	Potential for permanent changes to the the setting of this low value asset that would hardly affect the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
Welland House Farm (Welland House), Surfleet (MLI122570)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project in Section 4 and Section 5.	Low	Small	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset would slightly affect the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence	Low	Negligible	Negligible adverse	Potential for permanent changes to the setting of this low value asset that would hardly affect the value of the asset or the

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	of the Project in Section 4 and Section 5, from the time of construction and throughout its operational duration in the wider landscape.			(Not significant)	way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
Outbuildings, south side of Lymn Bank, Lymn Bank West (MLI98274)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Negligible	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset would have little effect on the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Former Station House, Little Steeping Railway Station (MLI124884)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no impact to the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.
Thorpe Bank Primitive	Construction and the presence of the Project in	Low	No Change	Neutral	The Project does not form part of the setting of the asset and will not alter its

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
Methodist Chapel, Thorpe St Peter (MLI99088)	the landscape from the time of construction and throughout its operational duration will have no impact to the setting or value of this asset.			(Not significant)	value or way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.
Primary School, Gipsey Bridge (MLI126586)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no impact to the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect which would be not significant.
Wesleyan Methodist Chapel, Thorpe St Peter (MLI99090)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no impact to the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect which would be not significant.
East Fen Chapel, New Leake (MLI99044)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no impact to the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect which would be not significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
Primitive Methodist Chapel, Thornton-le-Fen (MLI99382)	Construction and the presence of the Project in the landscape from the time of construction and throughout its operational duration will have no impact to the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect which would be not significant.
The Old Farmhouse, Kirton Holme (MLI126103)	The Project does not form part of the setting of the asset and will not alter its value or the way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect which would be not significant.
Kirton Holme Christ Church (MLI86273)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.
Wesleyan Methodist Chapel, Langrick Ferry (MLI98999)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which it is appreciated or understood. This would result in a

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	duration will have no temporary or permanent impact on the setting or value of this asset.				neutral effect which would not be significant.
Unnamed Farmstead, New Leake (MLI120345)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting and scaffolds) of the Project.	Low	Small	Negligible adverse (Not significant)	Temporary changes to the setting of this low value asset that would slightly affect the value of the asset or the way in which it is appreciated or understood. This would result in a negligible adverse effect that is not significant.
	Permanent changes to the setting of the asset arising from the presence of the Project, from the time of construction and throughout its operational duration in the wider landscape.	Low	Negligible	Negligible adverse (Not significant)	The permanency of the infrastructure in the landscape within its wider setting would have a negligible magnitude of impact causing little effect on its value and how it is appreciated, resulting in a negligible adverse effect on an asset of low value. This would result in a negligible adverse effect that is not significant.
Milestone, Spalding Road, Sutterton (MLI125901)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	Low	No Change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which it is appreciated or understood. This would result in a neutral effect which would not be significant.
Moated site at Thurlby in Bigby	Temporary changes to the setting of the asset arising from construction	Medium	Small	Minor adverse (Not significant)	Potential for temporary visual intrusion (small magnitude of impact) within the setting of this medium value asset that

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
parish. (MLI41476)	(such as noise, construction traffic, lighting, and scaffolds) during construction of the Project.				would affect the value of the asset and the way in which it is appreciated or understood. This would result in a minor adverse effect, which would not be significant.
	Permanent changes to the setting of the asset arising from the presence of the Project within the wider landscape.	Medium	Small	Minor adverse (Not significant)	Potential for limited, permanent visual intrusion (small magnitude of impact) within the setting of this medium value asset that would slightly affect the value of the asset or the way in which it is appreciated or understood. This would result in a minor adverse effect, which would not be significant.
Probable medieval earthwork ridge and furrow and field system, Thorpe St Peter (MLI90850)	Topsoil stripping and groundworks associated with installation of the construction access haul road and SUDS drainage basins and access road, will result in the partial truncation of the asset.	Medium	Small	Negligible adverse (Not significant following additional mitigation)	Partial removal or disturbance (small magnitude of impact) of this non- designated heritage asset of medium value would result in a minor adverse effect, which is not significant. The use of archaeological mitigation measures i.e. appropriate archaeological investigation and recording would reduce the significance of the effect to negligible adverse which would not be significant.
Deserted settlement at Bonthorpe (MLI84121)	Temporary changes to the setting of the asset arising from construction (such as noise, construction traffic, lighting, and scaffolds) of the Project.	Medium	Small	Minor adverse (Not significant)	Potential for temporary changes (small magnitude of impact) to the setting of this medium value asset that would affect its value and way in which it is appreciated or understood. This would result in a minor adverse effect, which would not be significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	Permanent changes to the setting of the asset arising from the presence of the Project within the wider landscape.	Medium	Small	Minor adverse (Not significant)	Potential for permanent visual intrusion (small magnitude of impact) within the setting of this medium value asset that would affect its value and the way in which it is appreciated or understood. This would result in a minor adverse effect, which would not be significant.
Armtree Deserted Medieval Village, Langriville (MLI40657)	Temporary changes to the setting of the asset arising from construction (noise, construction traffic, and scaffolds) of the Project.	Medium	Small	Minor adverse (Not significant)	Potential for temporary changes (small magnitude of impact) to the setting of this medium value asset that would affect its value and way in which it is appreciated or understood. This would result in a minor adverse effect, which would not be significant.
	Permanent changes to the setting of the asset arising from the presence of the Project within the wider landscape.	Medium	Small	Minor adverse (Not significant)	Potential for permanent visual intrusion (small magnitude of impact) within the setting of this medium value asset that would affect its value and the way in which it is appreciated or understood. This would result in a minor adverse effect, which would not be significant
The shrunken medieval village of Firsby (MLI42192)	Temporary changes to the setting of the asset arising from construction (construction traffic, and scaffolds) of the Project.	Medium	Small	Minor adverse (Not significant)	Potential for temporary changes (small magnitude of impact) to the setting of this medium value asset that would affect its value and way in which it is appreciated or understood. This would result in a minor adverse effect, which would not be significant.
	Permanent changes to the setting of the asset arising from the presence	Medium	Small	Minor adverse (Not significant)	Potential for permanent visual intrusion (small magnitude of impact) within the setting of this medium value asset that

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	of the Project within the wider landscape.				would affect its value and the way in which it is appreciated or understood. This would result in a minor adverse effect, which would not be significant
Parkland associated with Firsby Manor House, Firsby (MLI98402)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	Low	No change	Neutral (Not significant)	The Project does not form part of the setting of the parkland and will not alter its value or way in which they are appreciated or understood (no change). This will result in a neutral effect which is not significant.
Probable shrunken Medieval village, Cumberworth (MLI89121)	Temporary changes to the setting of the asset arising from construction (noise, construction traffic, plant movement and scaffolds) of the Project.	Medium	Small	Minor adverse (Not significant)	Potential for temporary change (small magnitude of impact) within the setting of this medium value asset that would affect its value and the way in which it is appreciated or understood. This would result in a minor adverse effect, which would not be significant.
	Permanent changes to the setting of the asset arising from the presence of the Project within the wider landscape.	Medium	Small	Minor adverse (Not significant)	Potential for permanent changes (small magnitude of impact) to the setting of this medium value asset that would affect its value and the way in which it is appreciated or understood. This would result in a minor adverse effect, which would not be significant.
Probable late Medieval shrunken village,	Temporary changes to the setting of the asset arising from construction (noise, construction	Medium	Small	Minor adverse (Not significant)	Potential for temporary change (small magnitude of impact) within the setting of this medium value asset that would affect its value and the way in which it is

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
Farlesthorpe (MLI19119)	traffic, plant movement and scaffolds) of the Project.				appreciated or understood. This would result in a minor adverse effect, which would not be significant.
	Permanent changes to the setting of the asset arising from the presence of the Project within the wider landscape.	Medium	Small	Minor adverse (Not significant)	Potential for permanent changes (small magnitude of impact) to the setting of this medium value asset that would affect its value and the way in which it is appreciated or understood. This would result in a minor adverse effect, which would not be significant.
Medieval settlement, Sloothby (MLI83297)	Temporary changes to the setting of the asset arising from construction (noise, construction traffic, plant movement and scaffolds) of the Project.	Medium	Small	Minor adverse (Not significant)	Potential for temporary change (small magnitude of impact) within the setting of this medium value asset that would affect its value and the way in which it is appreciated or understood. This would result in a minor adverse effect, which would not be significant.
	Permanent changes to the setting of the asset arising from the presence of the Project within the wider landscape.	Medium	Small	Minor adverse (Not significant)	Potential for permanent changes (small magnitude of impact) to the setting of this medium value asset that would affect its value and the way in which it is appreciated or understood. This would result in a minor adverse effect, which would not be significant.
Medieval settlement and field system,	Temporary changes to the setting of the asset arising from construction (noise, construction traffic, plant	Medium	Small	Minor adverse (significant)	Potential for temporary change (small magnitude of impact) within the setting of this medium value asset that would affect its value and the way in which it is appreciated or understood. This would

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
Thorpe St Peter (MLI90855)	movement and scaffolds) of the Project.				result in a minor adverse effect, which would not be significant.
	Permanent changes to the setting of the asset arising from the presence of the Project within the wider landscape.	Medium	Small	Minor adverse (Not significant)	Potential for permanent changes (small magnitude of impact) to the setting of this medium value asset that would affect its value and the way in which it is appreciated or understood. This would result in a minor adverse effect, which would not be significant
Possible Western Extension of Butterbump Barrow Cemetery (MLI42930)	Temporary changes to the setting of the asset arising from construction (noise, construction traffic, plant movement and scaffolds) of the Project.	Medium	Small	Minor adverse (Not significant)	Potential for temporary change (small magnitude of impact) within the setting of this medium value asset that would affect its value and the way in which it is appreciated or understood. This would result in a minor adverse effect, which would not be significant.
	Permanent changes to the setting of the asset arising from the presence of the Project within the wider landscape.	Medium	Small	Minor adverse (Not significant)	Potential for permanent changes (small magnitude of impact) to the setting of this medium value asset that would affect its value and the way in which it is appreciated or understood. This would result in a minor adverse effect, which would not be significant
Castle Dyke House Park, Frithville (MLI92271)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent	Low	No change	Neutral (Not significant)	The Project does not form part of the setting of the parkland and will not alter its value or way in which they are appreciated or understood (no change). This will result in a neutral effect which is not significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	impact on the setting or value of this asset.				
Historic Park, Brothertoft (MLI92254)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	Low	No change	Neutral (Not significant)	The Project does not form part of the setting of the parkland and will not alter its value or way in which they are appreciated or understood (no change). This will result in a neutral effect which is not significant.
Thorpe Culvert Station (MLI43460)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	Low	No change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which they are appreciated or understood (no change). This will result in a neutral effect which is not significant.
Unnamed farmstead, Bilsby (MLI116624)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	Low	No change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which they are appreciated or understood (no change). This will result in a neutral effect which is not significant.
Bollehall, Bicker (MLI116652)	The construction and presence of the Project in	Low	No change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.				value or the way in which they are appreciated or understood (no change). This will result in a neutral effect which is not significant.
Holt House (MLI116653)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	Low	No change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which they are appreciated or understood (no change). This will result in a neutral effect which is not significant.
The Elms, Irby in the Marsh (MLI119948)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	Low	No change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which they are appreciated or understood (no change). This will result in a neutral effect which is not significant.
Ivydene, Little Steeping (MLI120004)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no	Low	No change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which they are appreciated or understood (no change). This will result in a neutral effect which is not significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
	temporary or permanent impact on the setting or value of this asset.				
Codling Cottage, Thorpe St Peter (MLI120289)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	Low	No change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which they are appreciated or understood (no change). This will result in a neutral effect which is not significant.
White House Farm, Carrington (MLI120501)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	Low	No change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which they are appreciated or understood (no change). This will result in a neutral effect which is not significant.
Drayton House, Swineshead (MLI122446)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	Low	No change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which they are appreciated or understood (no change). This will result in a neutral effect which is not significant.

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
Golden Grove House, Swineshead (MLI122447)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	Low	No change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which they are appreciated or understood (no change). This will result in a neutral effect which is not significant.
Newstead, Sutterton (MLI122879)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	Low	No change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which they are appreciated or understood (no change). This will result in a neutral effect which is not significant.
Ashtree Farm (MLI124695)	The construction and presence of the Project in the landscape from the time of construction and throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.	Low	No change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which they are appreciated or understood (no change). This will result in a neutral effect which is not significant.
Primitive Methodist Chapel, Irby-in-	The construction and presence of the Project in the landscape from the time of construction and	Low	No change	Neutral (Not significant)	The Project does not form part of the setting of the asset and will not alter its value or the way in which they are appreciated or understood (no change).

Heritage Asset	Impact	Value of Asset	Magnitude of Impact	Significance of Effect	Rationale
the-Marsh (MLI98997)	throughout its operational duration will have no temporary or permanent impact on the setting or value of this asset.				This will result in a neutral effect which is not significant.

National Grid plc National Grid House, Warwick Technology Park, Gallows Hill, Warwick. CV34 6DA United Kingdom

Registered in England and Wales No. 4031152 nationalgrid.com